

**ENTEK CONSULTING GROUP, INC.  
ASSESSMENT OF TSI and/or FRIABLE MATERIAL**

District: Chico Unified School District

Date: June 25, 2010

School: Rosedale Elementary School

Inspector: Jack DeLay

Building & Location(s): Unit A - Kitchen Water Heater Closet

ECG-

% Asbestos - Assumed

Homogeneous Mat. #112

Material description: 3" O.D. Pipe Runs

Total amount of material this location: 3 Each

Amount of friable material this location: 3 Each

Damage	Local		Distributed	X	Damaged	5%
Type of Damage	Air Erosion		Water		Flaking	
	Deterioration	X	Physical		Delamination	

Probable cause(s) of damage:

POTENTIAL FOR DISTURBANCE			RESPONSE ACTIONS		PREVENTIVE MEASURES	
	H	M	L			
				Isolate/Restrict		Fix leaks
Accessibility	X			Repair/Cleanup	X	Prevent water contact X
Vibration			X	Enclose		Do not drill, cut, sand, or grind X
Air Erosion			X	Remove	X	Do not affix signs
Water			X	Encapsulate	X	Avoid contact X
Occupancy		X		O & M	X	

**Assessment of Material Condition**

Significantly Damaged (Poor)

Damaged (Fair)

Not damaged (Good)




Potential Damage: High

High Mod Low

High Mod Low

Hazard Ranking:

1 2 3 4 5 6 7

		X						
--	--	---	--	--	--	--	--	--

Comments & Observations: