

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1994

SCHOOL Sierra View Elementary INSPECTOR Ron Jones *RJ*

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill plas	1-5	All rooms	(7)
A	PW Cnr	35-65	Boiler room	(7)
A	PW Str	5-45	Boiler room	(7)
B	9" VFT Bg	1-5	All rooms	(7)
B	PW Str Air cell	Assumed	Classrooms 1 & 3 at radiator	(7)
C	9" VFT Bg	1-5	Rm 5 - A,B,C,D classrooms	(7)
C	PW Str Air cell	Assumed	Rms 7 & 5 at radiator	(7)
D	9" VFT Bg	1-5	Rms 7,10,11,12,13	(7)
D	Ceill Plas	1-5	Rms 3,4,11,12,13	(7)
D	Ceill Plas	1-5	Rms 9, 8	(7)
D	PW	5-10	Rm 11 storage, off MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1994

SCHOOL Sierra View Elementary INSPECTOR Ron Jones



BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Mud Cnr	15-20		Rm 11 storage	(7)
D	PW Air cell	15-20		Rm 8, mechanical room	(7)
D	TSI debrs	Assumed		Rm 13, behind radiator	(7)
D	Tran pipe	Assumed		Rm 8	(1) (4)
E	Mud Jnt	60-65		Boiler room	(1) (4)
E	Ceill plas	1-5		RR, custodial closet	(7)
F	9" VFT Gr	10-15		Rms 3 & 4	(2) (5) Broken tiles @ doors
F	9" VFT Gn	1-5		Rm 2	(2) (4) 9 tiles broken at doors
F	Ceill plas	1-5		Rms 3 & 4	(1) (4)
G	9" VFT Gn	1-5		Rm 5,11,12,13,14	(2) (4) Broken tiles @ doors
G	Ceill plas	1-5		Rm 6 - RR, custodial	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1994

SCHOOL Sierra View Elementary INSPECTOR Ron Jones



HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	9" VFT Gr	10-15	Rm 6, RR lounge	(1) (4)
I		9" VFT Bn	1-5	Classrooms	(7)
I		Ceill plas	1-5	Storage area	(7)
*				No letter on portables	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

UNIT

- (A) Boy's Restroom
- (1) Water damage 9' x 12'
 - (2) 4 holes (1) 3" across
 - (3) 4" across
 - (4) 4" across
 - (5) 3" across
- (A) Girl's Restroom
- (1) Water damage - 20% of area
 - (2) 2 holes (1) 7" x 4"
 - (3) 1" across
- (D) Nurse's office
- (1) A number of small cracks - various lengths
- (D) Hallway
- (1) 20% of hallway water damaged
 - (2) 2 holes (1) 3" across
 - (3) 2" across
- (A) Boiler room
- (1) Water damage 30% of area
 - (2) Hole 5" across where it's dropped
 - (3) 4 cracks - various lengths
 - (4) Small amount of debris on floor & top of boilers

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 7, 1994

SCHOOL Sierra View Elementary INSPECTOR Ron Jones



HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill plas	1-5	All rooms	(7)
A	PW Cnr	35-65	Boiler room	(7)
A	PW Str	5-45	Boiler room	(7)
B	9" VFT Bg	1-5	All rooms	(7)
B	PW Str Air cell	Assumed	Classrooms 1 & 3 at radiator	(7)
C	9" VFT Bg	1-5	Rm 5 - A,B,C,D classrooms	(7)
C	PW Str Air cell	Assumed	Rms 7 & 5 at radiator	(7)
D	9" VFT Bg	1-5	Rms 7,10,11,12,13	(7)
D	Ceill Plas	1-5	Rms 3,4,11,12,13	(7)
D	Ceill Plas	1-5	Rms 9, 8	(7)
D	PW	5-10	Rm 11 storage, off MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 7, 1994

SCHOOL Sierra View Elementary INSPECTOR Ron Jones



BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Mud Cnr	15-20	Rm 11 storage	(7)
D	PW Air cell	15-20	Rm 8, mechanical room	(7)
D	TSI debrs	Assumed	Rm 13, behind radiator	(7)
D	Tran pipe	Assumed	Rm 8	(1) (4)
E	Mud Jnt	60-65	Boiler room	(1) (4)
E	Ceill plas	1-5	RR, custodial closet	(7)
F	9" VFT Gr	10-15	Rms 3 & 4	(2) (5) Broken tiles @ doors
F	9" VFT Gn	1-5	Rm 2	(2) (4) 9 tiles broken at doors
F	Ceill plas	1-5	Rms 3 & 4	(1) (4)
G	9" VFT Gn	1-5	Rm 5,11,12,13,14	(2) (4) Broken tiles @ doors
G	Ceill plas	1-5	Rm 6 - RR, custodial	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 7, 1994
 SCHOOL Sierra View Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
G	9" VFT Gr	10-15	Rm 6, RR lounge	(1) (4)
I	9" VFT Bn	1-5	Classrooms	(7)
I	Ceill plas	1-5	Storage area	(7)
*			No letter on portables	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

UNIT

- (A) Boy's Restroom
- (1) Water damage 9' x 12'
 - (2) 4 holes (1) 3" across
 - (2) 4" across
 - (3) 4" across
 - (4) 3" across
- (A) Girl's Restroom
- (1) Water damage - 20% of area
 - (2) 2 holes (1) 7" x 4"
 - (2) 1" across
- (D) Nurse's office
- (1) A number of small cracks - various lengths
- (D) Hallway
- (1) 20% of hallway water damaged
 - (2) 2 holes (1) 3" across
 - (2) 2" across
- (A) Boiler room
- (1) Water damage 30% of area
 - (2) Hole 5" across where it's dropped
 - (3) 4 cracks - various lengths
 - (4) Small amount of debris on floor & top of boilers