

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Sierra View Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill plas	1-5	All rooms	(7)
A	PW Cnr	35-65	Boiler room	(7)
A	PW Str	5-45	Boiler room	(7)
B	9" VFT Bg	1-5	All rooms	(7)
B	PW Str Air cell	Assumed	Classrooms 1 & 3 at radiator	(7)
C	9" VFT Bg	1-5	Rm 5 - A,B,C,D classrooms	(7)
C	PW Str Air cell	Assumed	Rms 7 & 5 at radiator	(7)
D	9" VFT Bg	1-5	Rms 7,10,11,12,13	(7)
D	Ceill Plas	1-5	Rms 3 - Custodial Room	1-4
D	Ceill Plas	1-5	Rms 9, 8	1-4
D	PW	5-10	Rm 11 storage, off MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Sierra View Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Mud Cnr	15-20	Rm 11 storage	(7)
D	PW Air cell	15-20	Rm 8, mechanical room	1-4
D	TSI debrs	Assumed	Rm 13, behind radiator	(7)
D	Tran pipe	Assumed	Rm 8	(1) (4)
E	Mud Jnt	60-65	Boiler room	(1) (4)
E	Ceill plas	1-5	RR, custodial closet	(7)
F	9" VFT Gr	10-15	Rms 3 & 4	(1) (4)
F	9" VFT Gn	1-5	Rm 2	(1) (4)
F	Ceill plas	1-5	Rms 3 & 4	(1) (4)
G	9" VFT Gn	1-5	Rm 5,11,12,13,14	(1) (4)
G	Ceill plas	1-5	Rm 6 - RR, custodial	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999

SCHOOL Sierra View Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
G	9" VFT Gr	10-15	Rm 6, RR lounge	(1) (4)
I	9" VFT Bn	1-5	Classrooms	(7)
I	Ceill plas	1-5	Storage area	(7)
B,C,FG	Transite panels	Assumed	Under Windows	(1) (4)
H	Drywall	Trace in skim coat	Both Rooms	(1) (4)
*			No letter on portables	
Port	12" VRTs	Assumed	Next to Sink Areas	(1) (4)
Port	Drywall	Assumed	Behind Tagboard	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE August 11, 1999SCHOOL Sierra View Elementary INSPECTOR Robert Peters

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

UNIT

(A) Boy's Restroom
 (1) Water damage 9' x 12'
 (2) 4 holes (1) 3" across
 (2) 4" across
 (3) 4" across
 (4) 3" across

(A) Girl's Restroom
 (1) Water damage - 20% of area
 (2) 2 holes (1) 7" x 4"
 (2) 1" across

(D) Nurse's office
 (1) A number of small cracks - various lengths

(D) Hallway
 (1) 20% of hallway water damaged
 (2) 2 holes (1) 3" across
 (2) 2" across

(A) Boiler room
 (1) Water damage 30% of area
 (2) Hole 5" across where it's dropped
 (3) 4 cracks - various lengths
 (4) Small amount of debris on floor & top of boilers

DISTRICT Chico Unified School District DATE 2/25/99

SCHOOL Sierra View Elementary INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
MAT.#				
A	Ceill plas	1-5	All rooms	(7)
A	PW Cnr	35-65	Boiler room	(7)
A	PW Str	5-45	Boiler room	(7)
B	9" VFT Bg	1-5	All rooms	(7)
B	PW Str Air cell	Assumed	Classrooms 1 & 3 at radiator	(7)
C	9" VFT Bg	1-5	Rm 5 - A,B,C,D classrooms	(7)
C	PW Str Air cell	Assumed	Rms 7 & 5 at radiator	(7)
D	9" VFT Bg	1-5	Rms 7,10,11,12,13	(7)
D	Ceill Plas	1-5	Rms 3 - Custodial Room	1-4
D	Ceill Plas	1-5	Rms 9, 8	1-4
D	PW	5-10	Rm 11 storage, off MPR	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

POSTED
Ward

DISTRICT Chico Unified School District DATE 2/25/99

SCHOOL Sierra View Elementary INSPECTOR Rob Peters

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Mud Cnr	15-20	Rm 11 storage	(7)
D	PW Air cell	15-20	Rm 8, mechanical room	1-4
D	TSI debrs	Assumed	Rm 13, behind radiator	(7)
D	Tran pipe	Assumed	Rm 8	(1) (4)
E	Mud Jnt	60-65	Boiler room	(1) (4)
E	Ceill plas	1-5	RR, custodial closet	(7)
F	9" VFT Gr	10-15	Rms 3 & 4	(1) (4)
F	9" VFT Gn	1-5	Rm 2	(1) (4)
F	Ceill plas	1-5	Rms 3 & 4	(1) (4)
G	9" VFT Gn	1-5	Rm 5,11,12,13,14	(1) (4)
G	Ceill plas	1-5	Rm 6 - RR, custodial	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE 2/25/99

SCHOOL Sierra View Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
G	9" VFT Gr	10-15	Rm 6, RR lounge	(1) (4)
I	9" VFT Bn	1-5	Classrooms	(7)
I	Ceill plas	1-5	Storage area	(7)
B,C,FG	Transite panels	Assumed	Under Windows	(1) (4)
H	Drywall	Trace in skim coat	Both Rooms	(1) (4)
*			No letter on portables	
Port	12" VRTs	Assumed	Next to Sink Areas	(1) (4)
Port	Drywall	Assumed	Behind Tagboard	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District

DATE

2-25-99SCHOOL Sierra View ElementaryINSPECTOR Rob Peters

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTEDMISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

UNIT

- (A) Boy's Restroom
 (1) Water damage 9' x 12'
 (2) 4 holes (1) 3" across
 (2) 4" across
 (3) 4" across
 (4) 3" across
- (A) Girl's Restroom
 (1) Water damage - 20% of area
 (2) 2 holes (1) 7" x 4"
 (2) 1" across
- (D) Nurse's office
 (1) A number of small cracks - various lengths
- (D) Hallway
 (1) 20% of hallway water damaged
 (2) 2 holes (1) 3" across
 (2) 2" across
- (A) Boiler room
 (1) Water damage 30% of area
 (2) Hole 5" across where it's dropped
 (3) 4 cracks - various lengths
 (4) Small amount of debris on floor & top of boilers