

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: A

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET (New sheet in R/C of restroom)	(1) (4) Same	N

School: Sierra View Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

(4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) <i>Same</i>	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) All Rooms Reconstructed	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN & STORAGE	(1) (4)	N
T	PIPE WRAP AIR CELL	8	15-20%	13 L	MECHANICAL ROOM	(1) (4) <i>Same</i>	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) Reconstructed	N
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) Reconstructed	N
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4) <i>Same</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4) <i>Same</i>	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOM	(1) Reconstructed	N

School: Sierra View Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1) (4) <i>Same</i>	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4) ↑	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) Same	N
M	2' X 4' FCP	95	ASSUMED	900 S	ROOM 12 (PORTABLE)	(1)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) ↓	N

School: Sierra View Elementary School

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	ROOM 6 (LAB) & ROOM 7 (RSP)	(1)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) Relocatables	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: 1

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(1) Same	N
M	12" VFT	105	ASSUMED	200 S	ROOMS 22, 23, & WORKROOM	(1) THESE ROOMS ARE PORTABLES WITH UNREADABLE I.D'S.	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	ROOMS 22, 23, & WORKROOM	(1)	N

School: Sierra View Elementary School

Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	300 S	PORTABLES 24-26 (NEXT TO SINKS)	(1) (4) Same	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLES 24-26	(1) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLES 24-26	(1) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE 27	(1) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' x 4' FCP	85	ASSUMED	900 S	PORTABLE 27	(1) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: A

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET (New sheet in R/C of restroom)	(1) (4) Same	N

School: Sierra View Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

CONDITION CODE

General Condition:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No (5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) All Rooms Reconstructed	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN & STORAGE	(1) (4)	N
T	PIPE WRAP AIR CELL	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) Reconstructed	N
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) Reconstructed	N
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4) <i>Same</i>	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOM	(1) Reconstructed	N

School: Sierra View Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1) (4) <i>Same</i>	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4) ←	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) Same	N
M	2' X 4' FCP	95	ASSUMED	900 S	ROOM 12 (PORTABLE)	(1)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) →	N

School: Sierra View Elementary School

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	ROOM 6 (LAB) & ROOM 7 (RSP)	(1)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) Relocatables	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(1) Same	N
M	12" VFT	105	ASSUMED	200 S	ROOMS 22, 23, & WORKROOM	(1) THESE ROOMS ARE PORTABLES WITH UNREADABLE I.D'S.	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	ROOMS 22, 23, & WORKROOM	(1)	N

School: Sierra View Elementary School

Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	300 S	PORTABLES 24-26 (NEXT TO SINKS)	(1) (4) Same	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLES 24-26	(1) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLES 24-26	(1) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE 27	(1) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' x 4' FCP	85	ASSUMED	900 S	PORTABLE 27	(1) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: A

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET (New sheet in R/C of restroom)	(1) (4)	N

School: Sierra View Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN & STORAGE	(1) (4)	N
T	PIPE WRAP AIR CELL	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) Reconstructed	N
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) Reconstructed	N
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4)	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOM	(1) Reconstructed	N

School: Sierra View Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	2' X 4' FCP	95	ASSUMED	900 S	ROOM 12 (PORTABLE)	(1)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

School: Sierra View Elementary School

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	ROOM 6 (LAB) & ROOM 7 (RSP)	(1)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) Relocatables	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(1)	N
M	12" VFT	105	ASSUMED	200 S	ROOMS 22, 23, & WORKROOM	(1) THESE ROOMS ARE PORTABLES WITH UNREADABLE I.D'S.	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	ROOMS 22, 23, & WORKROOM	(1)	N

School: Sierra View Elementary School

Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	300 S	PORTABLES 24-26 (NEXT TO SINKS)	(1) (4)	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLES 24-26	(1) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLES 24-26	(1) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 01/07/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE 27	(1) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' x 4' FCP	85	ASSUMED	900 S	PORTABLE 27	(1) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS