

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET	(2) (6) MINOR CRACKS IN CEILING TAPE.	N
T	TSI	98	ASSUMED	12 L	BOILER ROOM	(1) (4)	N

Unit K

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(7) REPLACED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) COULD NOT LOCATE.	N
M	2' X 4' FCP	150	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP	150	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	LINOLEUM	151	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN, STORAGE, AND MPR CHAIR STORAGE	(1) (4) (2) (4) (6) CRACKED AROUND AIR REGISTER.	N
T	PIPE WRAP	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4)	N/A
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4)	N/A
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N
M	LINOLEUM TAN	152	ASSUMED	100 S	KITCHEN RESTROOM	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	DRYWALL	153	ASSUMED	UNDETERMINED	OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT BLUE/WHITE	154	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" ACT	155	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit J

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4)	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(12) UNABLE TO LOCATE	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	DRYWALL & JOINT COMPOUND	150	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(2) (6) HOLES IN SPEECH ROOM	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit I & F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	2' X 4' FCP	95	ASSUMED	900 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1) (4) STAINS	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) UNABLE TO LOCATE.	N
M	12" VFT WHITE	110	ASSUMED	250 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N

Unit E, C & A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	CLASSROOM 6 (LAB) & CLASSROOM 7 (RSP)	(1) (4)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1) (4)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit L

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(12) CANNOT LOCATE	N
M	12" VFT	105	ASSUMED	200 S	CLASSROOMS 22 & 23 AND WORKROOM	(2) LOOSE TILE ROOM 22	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
	12" ACT		ASSUMED		RESTROOM		

Unit M Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED NON DETECTED	300 S	PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS)	(13) SAMPLE COLLECTED 03/22/2005	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLE CLASSROOMS 24-26	(1) (4) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLE CLASSROOMS 24-26	(1) (4) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

Unit N Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	85	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET	(1) (4)	N
T	TSI	98	ASSUMED	12 L	BOILER ROOM	(1) (4)	N

Unit K

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(7) REPLACED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) COULD NOT LOCATE.	N
M	2' X 4' FCP	150	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP	150	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	LINOLEUM	151	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN, STORAGE, AND MPR CHAIR STORAGE	(1) (4)	N
T	PIPE WRAP	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4)	N/A
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4)	N/A
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N
M	LINOLEUM TAN	152	ASSUMED	100 S	KITCHEN RESTROOM	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	DRYWALL	153	ASSUMED	UNDETERMINED	OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT BLUE/WHITE	154	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" ACT	155	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit J

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4)	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(12) UNABLE TO LOCATE	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	DRYWALL & JOINT COMPOUND	150	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit I & F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	2' X 4' FCP	95	ASSUMED	900 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1) (4) STAINS	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) UNABLE TO LOCATE.	N
M	12" VFT WHITE	110	ASSUMED	250 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N

Unit E, C & A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	CLASSROOM 6 (LAB) & CLASSROOM 7 (RSP)	(1) (4)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(12) FULLY CARPETED	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit L

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(12) CANNOT LOCATE	N
M	12" VFT	105	ASSUMED	200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
	12" ACT		ASSUMED		RESTROOM	(1)	

Unit M Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED NON DETECTED	300 S	PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS)	(13) SAMPLE COLLECTED 03/22/2005	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLE CLASSROOMS 24-26	(1) (4) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLE CLASSROOMS 24-26	(1) (4) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

Unit N Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	85	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS



Forensic Analytical

Final Report

Bulk Asbestos Analysis (EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Leroy Christopher

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B071143
Date Received: 03/24/05
Date Analyzed: 03/28/05
Date Printed: 03/28/05
First Reported: 03/28/05

Job ID/Site: Sierra View School

Date(s) Collected: 03/22/2005

FASI Job ID: 2921-82
Total Samples Submitted: 2
Total Samples Analyzed: 2

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
SV1	10403338						
Layer: Off-White Tile			ND				
Layer: Yellow Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							
SV2	10403339						
Layer: Beige Tile			ND				
Layer: Yellow Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921-82

Forensic Analytical

Analysis Request Form



Client Name & Address: Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		P.O. #: 050289 Date: 3/23/05
Contact: Leroy Christophersen Phone #: 530-891-3195 Fax#: (530) 891-3190		Turn Around Time: ___ hr / 12hr / 24hr (48 hr) ext: ___ Due Date: / / Due Time: : am/pm <input checked="" type="checkbox"/> PLM: <input checked="" type="checkbox"/> Standard / <input type="checkbox"/> Point Count <input type="checkbox"/> PCM: NIOSH 7400
Site: Sierra View School		<input type="checkbox"/> TEM Air: <input type="checkbox"/> AHERA / <input type="checkbox"/> Yamate2 / <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> TEM Bulk: <input type="checkbox"/> Quantitative / <input type="checkbox"/> Qualitative / <input type="checkbox"/> Chatfield <input type="checkbox"/> TEM Water: <input type="checkbox"/> Potable / <input type="checkbox"/> Non-Potable / <input type="checkbox"/> Wt % <input type="checkbox"/> TEM Microvac <input type="checkbox"/> Special Project:
Job:		<input type="checkbox"/> Metals Analysis: Method _____ Matrix: _____ Analytes: _____

Comments: For mgmt plan

Sample ID	Date/Time	Sample Location/Description	FOR AIR SAMPLES ONLY				Sample Area or Air Volume
			Type	Time On/Off	Avg. CFM	Flow Rate	
SV1	3/22	off white tile Rm 25 near sink	A P C				
SV2	3/22	Rm 25 beige	A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				

Sampled by: Leroy Christophersen Date: 3/22/05 Time: :
 Shipped via: Fed Ex Airborne UPS US Mail Courier Drop Off Other:

Relinquished by: Date / Time:	Relinquished by: Date / Time:	Relinquished by: Date / Time:
Received by: Date / Time: Condition Acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Received by: Date / Time: Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Received by: Date / Time: Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No



SIERRA VIEW ELEMENTARY SCHOOL

1000/cvsd/spl/cvsd/spl.db/Coos 5 Terry 3/99

NTS.