

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET	(1) (4)	N
T	TSI	98	ASSUMED	12 L	BOILER ROOM	(1) (4)	N

Unit K

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(7) REPLACED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) COULD NOT LOCATE.	N
M	2' X 4' FCP	150	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP	150	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	LINOLEUM	151	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN, STORAGE, AND MPR CHAIR STORAGE	(1) (4)	N
T	PIPE WRAP	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4)	N/A
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4)	N/A
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N
M	LINOLEUM TAN	152	ASSUMED	100 S	KITCHEN RESTROOM	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	DRYWALL	153	ASSUMED	UNDETERMINED	OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT BLUE/WHITE	154	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" ACT	155	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit J

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4)	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(12) UNABLE TO LOCATE	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	DRYWALL & JOINT COMPOUND	150	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit I & F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	2' X 4' FCP	95	ASSUMED	900 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1) (4) STAINS	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) UNABLE TO LOCATE.	N
M	12" VFT WHITE	110	ASSUMED	250 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N

Unit E, C & A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	CLASSROOM 6 (LAB) & CLASSROOM 7 (RSP)	(1) (4)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(12) FULLY CARPETED	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit L

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(12) CANNOT LOCATE	N
M	12" VFT	105	ASSUMED	200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
	12" ACT		ASSUMED		RESTROOM	(1)	

Unit M Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED NON DETECTED	300 S	PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS)	(13) SAMPLE COLLECTED 03/22/2005	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLE CLASSROOMS 24-26	(1) (4) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLE CLASSROOMS 24-26	(1) (4) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

Unit N Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	85	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET	(1) (4)	N
T	TSI	98	ASSUMED	12 L	BOILER ROOM	(1) (4)	N

Unit K

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(7) REPLACED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) COULD NOT LOCATE.	N
M	2' X 4' FCP	150	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	LINOLEUM	100	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(7) RECONSTRUCTED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP	150	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	LINOLEUM	151	ASSUMED	50 S	MEN'S & WOMEN'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN, STORAGE, AND MPR CHAIR STORAGE	(1) (4)	N
T	PIPE WRAP	8	15-20%	13 L	MECHANICAL ROOM	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4)	N/A
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4)	N/A
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4)	N
M	LINOLEUM TAN	152	ASSUMED	100 S	KITCHEN RESTROOM	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	DRYWALL	153	ASSUMED	UNDETERMINED	OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT BLUE/WHITE	154	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" ACT	155	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit J

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4)	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(12) UNABLE TO LOCATE	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	DRYWALL & JOINT COMPOUND	150	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOMS	(1) (4) DISTRICT MUST CERTIFY AS NON ASBESTOS CONTAINING BUILDING MATERIAL.	N

Unit B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, AND SPEECH ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit I & F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	2' X 4' FCP	95	ASSUMED	900 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1) (4) STAINS	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(12) UNABLE TO LOCATE.	N
M	12" VFT WHITE	110	ASSUMED	250 S	CLASSROOM 12 (PORTABLE)	(1) (4)	N

Unit E, C & A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	CLASSROOM 6 (LAB) & CLASSROOM 7 (RSP)	(1) (4)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(12) FULLY CARPETED	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	CLASSROOM 6 (LAB), CLASSROOM 7 (RSP), AND CLASSROOM 1	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Sierra View Elementary School

Unit L

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(12) CANNOT LOCATE	N
M	12" VFT	105	ASSUMED	200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	CLASSROOMS 22 & 23 AND WORKROOM	(1) (4)	N
	12" ACT		ASSUMED		RESTROOM	(1)	

Unit M Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED NON DETECTED	300 S	PORTABLE CLASSROOMS 24-26 (NEXT TO SINKS)	(13) SAMPLE COLLECTED 03/22/2005	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLE CLASSROOMS 24-26	(1) (4) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) (4) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLE CLASSROOMS 24-26	(1) (4) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

Unit N Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	85	ASSUMED	900 S	PORTABLE CLASSROOM 27	(1) (4) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS