

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: A - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
						BUILDING A - BURNED DOWN 10-06-00, REBUILT IN 2001. CERTIFICATION LETTER ON FILE DATED 11-1-01.	

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: B - Classrooms 3, 6, & 7 (FKA 6, 9, & 10)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	1	NONE DETECTED	4,500 S	LIBRARY (922) AND CLASSROOMS 3 (FKA 6), 6 (FKA 9), AND 7 (FKA 10)	(13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	2,500 S	ENTIRE WING	(1) (4)	N
M	DRYWALL	80	ASSUMED	1,500 S	ENTIRE WING	(11) COVERED WITH TAGBOARD.	N
M	TRANSITE PANEL	99	ASSUMED	100 S	OUTSIDE BUILDING	(1) (4)	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: C - Classrooms 4, 5, & 8-10 (FKA 7, 8, & 11-13)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	1	NONE DETECTED	7,000 S	OFFICE (915) AND CLASSROOMS 4 (FKA 7), 5 (FKA 8), 8 (FKA 11), 9 (FKA 12), AND 10 (FKA 13)	(13) SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT CREAM	2	TRACE	600 S	OFFICE (915) AND PRINCIPAL OFFICE	(1) (4) (11) CARPET OVER TILE IN PRINCIPAL OFFICE.	N
S	PLASTER	86	ASSUMED	250 S	MEN'S (912) & WOMEN'S (914) RESTROOM CEILINGS	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	200 S	OUTSIDE BUILDING	(1) (4)	N
M	DRYWALL	112	ASSUMED	UNDETERMINED	THROUGHOUT	(1) (11) COVERED WITH TAGBOARD IN ALL CLASSROOMS.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: D - Portables 13, 13A, & 14 (FKA Portables 14, 14A, and 15)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S FIBERGLASS	60	NON-SUSPECT	2,200 S	PORTABLES 13, 13A, AND 14	(13)	N/A
M	12" VFT WHITE	70	ASSUMED	2,300 S	PORTABLES 13, 13A, AND 14	(11) COULD BE UNDER CARPET.	N

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: E - Classroom 15 (FKA 16)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 15 (FKA 16)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 15 (FKA 16)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 15 (FKA 16)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: F - Classroom 16 (FKA Portable 17)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 16 (FKA 17)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 16 (FKA 17)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 16 (FKA 17)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: G - Classroom 17 (FKA Portable 18)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 17 (FKA 18)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: H - Classrooms 19-21

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	88	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOMS 19-21	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.) CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A
M	12" VFT WHITE/BLUE	89	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOMS 19-21	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.) CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: I - Classrooms 22 & 23 (FKA PORTABLES 22-24)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	87	CERTIFIED NON-ASBESTOS	2,800 S	CLASSROOMS 22 & 23	(13) THESE PORTABLES HAVE A 1/98 MFG. DATE. CERTIFICATION LETTER ON FILE DATED 8-19-98.	N/A
M	DRYWALL	111	CERTIFIED NON-ASBESTOS	3,000 S	CLASSROOMS 22 & 23	(13) CERTIFICATION LETTER ON LETTER DATED 8-19-98. (11) COULD BE BEHIND TAGBOARD.	N/A

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: J - Classroom 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	87	CERTIFIED NON-ASBESTOS	2,800 S	CLASSROOM 24	(13) THESE PORTABLES HAVE A 1/98 MFG. DATE. CERTIFICATION LETTER ON FILE DATED 8-19-98.	N/A
M	DRYWALL	111	CERTIFIED NON-ASBESTOS	3,000 S	CLASSROOM 24	(13) CERTIFICATION LETTER ON FILE DATED 8-19-98. (11) COULD BE BEHIND TAGBOARD.	N/A

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: K - Classroom 18 (FKA Portable 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	88	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOM 18 (FKA 4)	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.). CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A
M	12" VFT WHITE/BLUE	89	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOM 18 (FKA 4)	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.). CERTIFICATION LETTER ON FILE 9-24-97.	N/A

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 1/22/08

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: L-Classrooms 11 & 12 (From Former Fair View/Cal Campus)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					(PORTABLE 12- C5 from former Fair View	(12) Manufactures date 1989.	
M	DRYWALL		None Detected		CLASSROOMS 11 & 12	(13) CUSD samples SH 01-03 7/29/2005	N
M	2' x 4' FCP's		Non Detected		CLASSROOMS 11 & 12	(13) CUSD samples #SH01 & SH03 7/29/2005	N
M	12" VFT GREY		Non Detected		CLASSROOMS 11 & 12	(13) CUSD sample #sh01 & sh03 7/29/2005	

School: Shasta Elementary

Building: Unit M (Restroom)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N
M	2' X 4' FCP		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N
M	12" VFT GREY		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: A - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
						BUILDING A - BURNED DOWN 10-06-00, REBUILT IN 2001. CERTIFICATION LETTER ON FILE DATED 11-1-01.	

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: B - Classrooms 3, 6, & 7 (FKA 6, 9, & 10)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	1	NONE DETECTED	4,500 S	LIBRARY (922) AND CLASSROOMS 3 (FKA 6), 6 (FKA 9), AND 7 (FKA 10)	(13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	2,500 S	ENTIRE WING	(1) (4)	N
M	DRYWALL	80	ASSUMED	1,500 S	ENTIRE WING	(11) COVERED WITH TAGBOARD.	N
M	TRANSITE PANEL	99	ASSUMED	100 S	OUTSIDE BUILDING	(1) (4)	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: C - Classrooms 4, 5, & 8-10 (FKA 7, 8, & 11-13)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	1	NONE DETECTED	7,000 S	OFFICE (915) AND CLASSROOMS 4 (FKA 7), 5 (FKA 8), 8 (FKA 11), 9 (FKA 12), AND 10 (FKA 13)	(13) SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT CREAM	2	TRACE	600 S	OFFICE (915) AND PRINCIPAL OFFICE	(1) (4) (11) CARPET OVER TILE IN PRINCIPAL OFFICE.	N
S	PLASTER	86	ASSUMED	250 S	MEN'S (912) & WOMEN'S (914) RESTROOM CEILINGS	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	200 S	OUTSIDE BUILDING	(1) (4)	N
M	DRYWALL	112	ASSUMED	UNDETERMINED	THROUGHOUT	(1) (11) COVERED WITH TAGBOARD IN ALL CLASSROOMS.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: D - Portables 13, 13A, & 14 (FKA Portables 14, 14A, and 15)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S FIBERGLASS	60	NON-SUSPECT	2,200 S	PORTABLES 13, 13A, AND 14	(13)	N/A
M	12" VFT WHITE	70	ASSUMED	2,300 S	PORTABLES 13, 13A, AND 14	(11) COULD BE UNDER CARPET.	N

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: E - Classroom 15 (FKA 16)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 15 (FKA 16)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 15 (FKA 16)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 15 (FKA 16)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: F - Classroom 16 (FKA Portable 17)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 16 (FKA 17)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 16 (FKA 17)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 16 (FKA 17)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: G - Classroom 17 (FKA Portable 18)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 17 (FKA 18)	(11) DRYWALL BEHIND TAGBOARD.	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: H - Classrooms 19-21

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	88	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOMS 19-21	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.) CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A
M	12" VFT WHITE/BLUE	89	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOMS 19-21	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.). CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: I - Classrooms 22 & 23 (FKA PORTABLES 22-24)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	87	CERTIFIED NON-ASBESTOS	2,800 S	CLASSROOMS 22 & 23	(13) THESE PORTABLES HAVE A 1/98 MFG. DATE. CERTIFICATION LETTER ON FILE DATED 8-19-98.	N/A
M	DRYWALL	111	CERTIFIED NON-ASBESTOS	3,000 S	CLASSROOMS 22 & 23	(13) CERTIFICATION LETTER ON LETTER DATED 8-19-98. (11) COULD BE BEHIND TAGBOARD.	N/A

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: J - Classroom 24

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	87	CERTIFIED NON-ASBESTOS	2,800 S	CLASSROOM 24	(13) THESE PORTABLES HAVE A 1/98 MFG. DATE. CERTIFICATION LETTER ON FILE DATED 8-19-98.	N/A
M	DRYWALL	111	CERTIFIED NON-ASBESTOS	3,000 S	CLASSROOM 24	(13) CERTIFICATION LETTER ON FILE DATED 8-19-98. (11) COULD BE BEHIND TAGBOARD.	N/A

Campus was renumbered in August 2006

School: Shasta Elementary School

Building: K - Classroom 18 (FKA Portable 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	88	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOM 18 (FKA 4)	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.). CERTIFICATION LETTER ON FILE DATED 9-24-97.	N/A
M	12" VFT WHITE/BLUE	89	CERTIFIED NON-ASBESTOS	3,200 S	CLASSROOM 18 (FKA 4)	(13) THESE PORTABLES HAVE A MFG. DATE OF 4/97 (DMSI MFG.). CERTIFICATION LETTER ON FILE 9-24-97.	N/A

Campus was renumbered in August 2006

CONDITION CODE

General Condition:(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:(4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/15/2008

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: L-Classrooms 11 & 12 (From Former Fair View/Cal Campus)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					(PORTABLE 12- C5 from former Fair View	(12) Manufactures date 1989.	
M	DRYWALL		None Detected		CLASSROOMS 11 & 12	(13) CUSD samples SH 01-03 7/29/2005	N
M	2' x 4' FCP's		Non Detected		CLASSROOMS 11 & 12	(13) CUSD samples #SH01 & SH03 7/29/2005	N
M	12" VFT GREY		Non Detected		CLASSROOMS 11 & 12	(13) CUSD sample #sh01 & sh03 7/29/2005	

School: Shasta Elementary

Building: Unit M (Restroom)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N
M	2' X 4' FCP		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N
M	12" VFT GREY		Certified Non-Asbestos		RESTROOM	(13) Letter on file dated 10/6/06	N

Campus was renumbered in August 2006

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS