District: Chico Unified School District

Date of Inspection: August 12, 2019

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Admin Building and MPR (FKA Unit A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	TRANSITE PIPE FLUE	99	ASSUMED POSITIVE	1 EACH	KITCHEN AND BOILER ROOM	(1) (4)	Ν
М	DRYWALL	103	ASSUMED	200 S	KITCHEN - NEAR TRAY WASH	(1) (4)	Ν
М	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	104	ASSUMED POSITIVE	3,500 S	MPR, KITCHEN, ADMINISTRATION, COUNSELING, NURSES OFFICE, STAFF DINING ROOM AND KITCHEN	(1) (4)	Ν
т	BOILER INSULATION	152	ASSUMED POSITIVE	1 UNIT	BOILER ROOM	(1) (4)	Y
т	6" MUDDED FITTINGS	153	ASSUMED POSITIVE	13 EACH	BOILER ROOM	(1) (4)	Y
м	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	300 S	STAFF ROOM, ADMINISTRATION, OFFICES, CONFERENCE ROOM	(1) (4)	Ν
м	CARPET ADHESIVE	251	ASSUMED POSITIVE	900 S	STAFF ROOM, ADMINISTRATION, OFFICES, CONFERENCE ROOM	(1) (4)	N
S	STUCCO	252	ASSUMED POSITIVE	500 S	COVERED WALKWAY	(1) (4)	Ν
S	WALL PLASTER	503	NONE DETECTED	3,000 S	THROUGHOUT	(13)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(1) Good (4) No (5) Yes (If Yes, explain under comments) (7) Removed (8) Encapsulated (6) Repaired

Abated: Miscellaneous: (11) Inaccessible, no inspection data

(9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

(14) Non AHERA/Not Inspected

Date of Inspection: August 12, 2019

District: Chico Unified School District

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Admin Building and MPR (FKA Unit A) (Continued)

						(-	onunada)
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	ROUGH CEILING PLASTER	506	ASSUMED POSITIVE	800 S	STAFF LOUNGE AND ENTRY FOYER	(1) (4)	Ν
М	12" ACOUSTIC CEILING TILE (1/8" HOLE PATTERN)	507	ASSUMED POSITIVE	4,200 S	MPR	(1) (4)	Ν
т	3" OD MUDDED FITTINGS	508	ASSUMED POSITIVE	5 EACH	BOILER ROOM	(1) (4)	Y
М	2' X 2' VINYL FLOOR TILE (TAN WITH BROWN/GRAY STREAKS)	607	ASSUMED POSITIVE	5,000 S	ADMIN, ROOM 917, 918, AND MPR	(1) (4)	Ν
М	VINYL BASE COVE ADHESIVE	608	ASSUMED POSITIVE	500 L	ADMIN AREA, ADMIN OFFICES	(1) (4)	Ν
М	2' X 2' CARPET SQUARE ADHESIVE	609	ASSUMED POSITIVE	2,500 S	ADMIN AREA, ROOM 902, ROOM 907, SPEECH	(1) (4)	Ν
М	DRYWALL AND JOINT COMPOUND	610	ASSUMED POSITIVE	7,500 S	ROOMS 902, 906, 907, 908, 914, 916, SPEECH, GIRLS AND BOYS RESTROOM	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(11) Inaccessible, no inspection data(12) Other (Explain under comments)(11) Non AHERA/Not Inspected

District: Chico Unified School District

Date of Inspection: August 12, 2019

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Admin Building and MPR (FKA Unit A)

(Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/N
S	DRYWALL TEXTURE	611	ASSUMED POSITIVE	7,500 S	ROOMS 902, 906, 907, 908, 914, 916, SPEECH, GIRLS AND BOYS RESTROOM	(1) (4)	N
М	SHEET VINYL FLOORING (BLUE)	612	ASSUMED POSITIVE	100 S	ROOM 914	(7)	N
М	SHEET VINYL FLOORING (TAN WITH GRAY AND BROWN LINES)	613	ASSUMED POSITIVE	5000 S	ROOM 917 RESTROOM AND BOYS AND GIRLS RESTROOMS	(1) THROUGHOUT ADMIN OFFICE AND MPR	N
М	2' X 4' DROP-IN ACOUSTICAL CEILING PANELS	614	ASSUMED POSITIVE	1,200 S	ROOM 916, 917, 910, 909, 913, 912, 917, AND SPEECH	(7)	N
S	PLASTER CEILING	615	ASSUMED POSITIVE	150 S	ROOM 929A, MECHANICAL ROOM IN MPR, AND STORAGE 924	(1) COVERED WALKWAY(2) DAMAGED IN STORAGE ROOM	N
М	SHEET VINYL FLOORING (YELLOW)	616	ASSUMED POSITIVE	100 S	MPR	(1) (4)	N
S	PLASTER WALLS AND CEILING	617	ASSUMED POSITIVE	2,500 S	KITCHEN	(7)	Ν

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(11) Inaccessible, no inspection data(12) Other (Explain under comments)(11) Non AHERA/Not Inspected

District: Chico Unified School District

School: Bidwell Junior High School

Ft²/L.F. Material Material Homo. % Asb. Location Condition: Code & Comments Friable Class Mat. # Yes /No **12" ACOUSTIC CEILING TILE** 109 ASSUMED 2.200 S LIBRARY, OFFICES, AND COMPUTER ROOM Ν Μ (1)(4)(1/8" HOLE PATTERN) POSITIVE 2,000 S S SMOOTH WALL PLASTER 110 ASSUMED THROUGHOUT UNIT (1)(4)Ν POSITIVE COVE BASE ADHESIVE 250 ASSUMED 400 S THROUGHOUT UNIT Μ (1)(4)Ν POSITIVE Μ 2' X 2' CARPET SQUARE AND 251 ASSUMED 1.000 S **OFFICES & COMPUTER ROOM** (1)(4)Ν ADHESIVE POSITIVE S STUCCO 252 ASSUMED 2.000 S COVERED WAI KWAYS (1)(4)Ν POSITIVE 2' x 2' CEILING TILES TAN 600 ASSUMED 1.200 S THROUGHOUT LIBRARY Υ Μ (1)(4)POSITIVE WITH GRAY/BROWN LINES DRYWALL AND JOINT 601 ASSUMED 500 S TEXTBOOK STORAGE, COMPUTER ROOM, 901 Μ (1)(4)Ν POSITIVE STORAGE COMPOUND

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous: (1) Good

(4) No

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: August 12, 2019

Inspector: Matt Reilly

Building: Library (FKA Unit B)

Date of Inspection: August 12, 2019

District: Chico Unified School District

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Classrooms 101-107 and 201-207 (FKA Units C&D)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	Condition: Code & Comments	
S	ACOUSTICAL CEILING & UPPER WALL ROUGH PLASTER	5	1-5 %	30,000 S	ALL ROOMS, CLOSET (C), CLASSROOM 204, AND HALLWAY, 105A, AND 250	(1) (4)	WATER STAINS ARE PRESENT. SOME AREAS HAVE 1' X 1' PENETRATIONS WHERE SKY LIGHTS ARE GOING TO BE PLACED. MATERIALS 5&6 MERGED INTO MATERIAL 5	N
М	DRYWALL	90	ASSUMED POSITIVE	4,000 S	CLASSROOMS 250 & 406A, CORRIDORS, AND RESTROOMS	(13)	REPRESENTED BY SAMPLE HMS-R1304- 03 COLLECTED ON 3-30-04.	Ν
М	3" TRANSITE PIPE	107	ASSUMED POSITIVE	10 L	CLOSET OF CLASSROOM 405	(1) (4)		Ν
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	2,800 L	THROUGHOUT CLASSROOMS	(1) (4)		N
S	STUCCO	252	ASSUMED POSITIVE	8,000 S	COVERED WALKWAYS	(1) (4)		N
S	DRYWALL TEXTURE	602	ASSUMED POSITIVE	4,000 S	CLASSROOMS 250 & 406A, CORRIDORS, AND RESTROOMS	(1) (4)		N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd CONDITION CODE

General Condition: (1) Good Change in Condition: (4) No (6) Repaired Abated:

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous:

Date of Inspection: August 12, 2019

District: Chico Unified School District

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Classrooms 101-107 and 201-207 (FKA Units C&D) (Continued)

				-		(8	onunucu
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	509	ASSUMED POSITIVE	6,765 S	CLASSROOMS 101-107	(1) (4)	N
М	12" VINYL FLOOR TILE (ORANGE) & ADHESIVE	510	ASSUMED POSITIVE	4,230 S	CLASSROOMS 201-205	(1) (4)	N
М	12" VINYL FLOOR TILE (GRAY) & ADHESIVE	511	ASSUMED POSITIVE	14,650 S	CLASSROOMS 250, 301-307 AND 401-407	(1) (4)	N
М	12" ACOUSTIC CEILING TILE (FISSURE PATTERN)	512	ASSUMED POSITIVE	5,070 S	CLASSROOMS 107 AND 206-207	(1) (4)	N
М	SHEET VINYL FLOORING (GRAY PEBBLE PATTERN)	513	ASSUMED POSITIVE	2,535 S	CLASSROOMS 206 & 207, 106	(1) (4)	N
S	PLASTER CEILING	603	ASSUMED POSITIVE	750 S	CLASSROOM 101	(1) (4)	N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:	(1) Good	(2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition:	(4) No	(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
Abated:	(6) Repaired	(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous:	(11) Inaccessib	le, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 12, 2019

District: Chico Unified School District

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Classrooms 108, 109, 208, 209 (FKA Unit F)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	500 S	THROUGHOUT	(1) (4)	N
S	STUCCO	252	ASSUMED POSITIVE	1,200 S	COVERED WALKWAY	(1) (4)	N
М	2'X4' CEILING PANEL (FISSURE PATTERN)	255	ASSUMED POSITIVE	1,800 S	ROOMS 108 & 208	(1) (4)	Y
М	DRYWALL & JOINT COMPOUND	514	ASSUMED POSITIVE	3,400 S	PERIMETER WALLS - THROUGHOUT	(1) (4)	N
М	SHEET VINYL FLOORING (GRAY PEBBLE PATTERN)	515	ASSUMED POSITIVE	5,040 S	THROUGHOUT	(1) (4)	N
М	12" ACOUSTIC CEILING TILE (1/8" HOLE PATTERN)	516	ASSUMED POSITIVE	5,040 S	THROUGHOUT EXCEPT ROOMS 109 & 209	(1) (4)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Abated:
Miscellaneous:(4) No(5) Yes (If Yes, explain under comments)(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(11) Inaccessible, no inspection data(12) Other (Explain under comments)(11) Non AHERA/Not Inspected

Date of Inspection: August 12, 2019

District: Chico Unified School District

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: Classrooms 301-307 and 401-407 (FKA Unit I)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	STUCCO	252	ASSUMED POSITIVE	1,200 S	COVERED WALKWAY	(1) (4)	N
М	2'X4' CEILING PANEL (SOLID PATTERN)	260	ASSUMED POSITIVE	3,600 S	ROOMS 308, 309, 408, & 409	(1) (4)	Y
М	DRYWALL AND JOINT COMPOUND	500	NONE DETECTED	400 S	GIRL'S AND BOY'S RESTROOM	(13) REPRESENTED BY SAMPLE HMS- R1304-02 COLLECTED ON 3-30-04.	Ν
М	12" VINYL FLOOR TILE (GRAY) & ADHESIVE	517	ASSUMED POSITIVE	5,248 S	CLASSROOMS 308, 309, 408, AND 409	(1) (4)	Ν
М	PLASTER	518	ASSUMED POSITIVE	200 S	WASHROOM/CLOSET	(1) (4)	Ν
М	VINYL BASE COVE ADHESIVE	604	ASSUMED POSITIVE	300 L	THROUGHOUT UNIT	(1)	Ν
S	DRYWALL TEXTURE	605	ASSUMED POSITIVE	400S	GIRL'S AND BOY'S RESTROOM	(1)	Ν

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition: Change in Condition: Abated: Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)

(1) Good

(4) No

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(7) Removed (8) Encapsulated (6) Repaired (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District

Date of Inspection: August 12, 2019

Inspector: Matt Reilly

School: Bidwell Junior High School

Building: 501 & 502 (FKA Unit J)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACOUSTIC CEILING TILE (1/8" HOLE)	108	ASSUMED POSITIVE	1,400 S	CLASSROOMS 501& 502, OFFICE, AND PRACTICE ROOMS	(1) (4)	Y
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	500 S	ALL ROOMS	(1) (4)	N
М	BUR UNDER GRAVEL	501	NONE DETECTED	200 S	NORTH END, SOUTH END, AND MIDDLE	(13) REPRESENTED BY SAMPLES 34A-C COLLECTED ON 4-5-04.	N
М	ROOF MASTIC (GRAY)	502	5-10% CHRYSOTILE	3,200 S	EXHAUST FAN ROOF JACK	 (1) (4) REPRESENTED BY SAMPLES 32A & B COLLECTED ON 4-5-04. (12) 	N
м	12" VINYL FLOOR TILE (GRAY) & ADHESIVE	519	ASSUMED POSITIVE	3,420 S	ALL ROOMS	(1) (4)	N

C:Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:	(1) Good	(2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition:	(4) No	(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
Abated:	(6) Repaired	(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous:	(11) Inaccessit	ble, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: August 12, 2019

Inspector: Matt Reilly

District: Chico Unified School District School: Bidwell Junior High School

Building: Boys and Girls Locker Rooms (FKA Unit K)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	on: Code & Comments	Friable Yes/No
М	CEMENTITIOUS TRANSITE PANELS	98	ASSUMED POSITIVE	UNDETERMINED	PANELS IN BOTH LOCKER ROOMS	(12)	COULD NOT LOCATE.	N
S	WALL PLASTER	504	NONE DETECTED	5,000 S	COACHES ROOM 112	(13)	REPRESENTED BY SAMPLE HMS- R1304-01 COLLECTED ON 3-30-04.	N
М	4"x4" CERAMIC TILES (YELLOW)	700	ASSUMED POSITIVE	UNDETERMINED	IN BOTH LOCKER ROOMS	(1)		N

C:\Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

CONDITION CODE

General Condition:
Change in Condition:(1) Good(2) Damaged(3) Significantly Damaged (25% or more)Change in Condition:
Abated:(4) No(5) Yes (If Yes, explain under comments)(13) Non-Asbestos/Not InspectedAbated:
Miscellaneous:(6) Repaired(7) Removed(8) Encapsulated(9) Enclosed(10) Isolated & RestrictedMiscellaneous:(11) Inaccessible, No inspection data(12) Other (Explain under comments)(13) Non-Asbestos/Not Inspected

District: Chico Unified School District

School: Bidwell Junior High School

BOILER

INSULATION

520

Т

C:Users\bstevens\Entek Consulting Group, Inc\Entekgroup - Documents\Clients\Chico USD\19-5263 3 Year Reinspections\Sites\Bidwell JHS\Bidwell HMR.wpd

1 BOILER

ASSUMED

POSITIVE

CONDITION CODE

(9)

General Condition:	(1) Good	(2) Damaged (Significantly Damage	ed (25% or more	e)	
Change in Condition:	(4) No	(5) Yes (If Yes, e	explain under comments) (13) Non-	Asbestos/Not I	nspected
Abated:	(6) Repaired	(7) Removed (8) Encapsulated	(9) Enclosed	(10) Isolated &	Restricted
Miscellaneous:	(11) Inaccessib	le, No inspection c	ata (12) Other (Ex	kplain under con	nments) (13	Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

BOILER ROOM

Material Material Homo. % Asb. Ft²/L.F. Location Class Mat. #	Condition: Code & Comments
M 12" ACOUSTIC CEILING TILE 111 ASSUMED 10,000 S GYM	(1) (4) SOME TILES HAVE BEEN REMOVED. THE MASTIC IS SHOWING. THE WALLS ARE CONCRETE & THE CEILING IS

Inspector: Matt Reilly

Friable

Yes/No

Υ

Υ

Building: Gym (FKA Unit L)

Date of Inspection: August 12, 2019