School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 100

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST 3 Year Inspect Condition of M Change in Cond Comments:Not f	ion Notes aterial: ition? No	GOOD Abated? NO	01-05	3496 S	1-4
PW STR 3 Year Inspect Condition of M Change in Cond Comments:	ion Notes aterial:	GOOD	30-35	50 L	1-4
BLR LINING 3 Year Inspect Condition of M Change in Cond Comments:	aterial:	GOOD	60-65	125 S	1-4
PW CNR 3 Year Inspect Condition of MacChange in Condition	aterial:	GOOD	01-99 (Assumed)	20 Ј	1-4
FAN UNIT INS 3 Year Inspecti Condition of Ma Change in Condi Comments:Caution pipewo	on Notes terial: (tion? NO on should	GOOD	01-99 (ASSUMED) items next	100 S	1-4
9" vfts 3 Year Inspecti Condition of Ma Change in Condi Comments:	terial: (GOOD	01-99 (ASSUMED)	3000 S	1-4

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 100

Homoq.

Material Mat. # Locations % Asb Footage Codes 99 KITCHEN BLR RM TRANSITE PIPE 01-99 10 L 1-4 3 Year Inspection Notes: (ASSUMED) Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

Comments:

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 200

Homog.

Change in Condition? NO Abated? NO

Material	Mat. #	Locations	% Asb	Footage	Codes
PLASTER 3 Year Inspection of Change in Comments:	f Material:		01-05	17600 S	1-4
9" VFTS 3 Year Inspection of			01-99 (Assumed)	13560 S	1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 300

TT	_	-	_	~	
п	u	ш	v	u	•

Mat. # Material Locations % Asb Footage Codes CEILING PLAST ALL RMS but N. WING 01-05 6 16500 S 1-4 3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments: Small amount of damage seen where ceiling fixture

has been removed from south hallway.

DRYWALL

90 RM 250 01-99

3000 S 1-4

3 Year Inspection Notes:

(ASSUMED)

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments: Samples #90A,B,C collected to determine whether this drywall is asbestos or not.

DRYWALL

90

TEACHERS RM

01-99

0 S 1-4

3 Year Inspection Notes:

(ASSUMED)

Condition of Material: GOOD

Change in Condition? NO Abated? NO

Comments: Samples #90A, B, and C represent this material.

9" VFTs

95

ALL ROOMS

01-99

16490 S 1-4

3 Year Inspection Notes:

Condition of Material: GOOD

(ASSUMED)

Change in Condition? NO Abated? NO

Comments:

TRANSITE PIPE

CLOSET OF RM 405

01-99

12 L 1-4

3 Year Inspection Notes:

(ASSUMED)

Condition of Material: GOOD

Change in Condition? NO Abated? NO

99

Comments:

Codes:

General Condition: Change in Condition:

(1) Good (2) Damaged (3) Sig. Damaged (N or 4) No (Y) Yes (Please explain)

Abated:

(R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 400

Material	Homog. Mat. #	Locations	% Asb	Footage Codes
PW JNTs 3 Year Inspection of Change in Comments:	ection Notes f Material:		01-99 (Assumed)	50 J 1-4
TANK WRAP 3 Year Inspectondition of Change in Comments:	ection Notes ! Material:	3:	01-99 (Assumed)	150 S 1-4
TRANS PANELS 3 Year Inspe Condition of	ection Notes	::	01-99 (ASSUMED)	1000 S 1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain) Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

Comments:

Change in Condition? NO Abated? NO

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 500

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
3 Year Inspect Condition of Change in Con	tion Notes Material: dition? NO	NO SURVEILLANCE DATA	90-95	0 S	0-
9" VFTs 3 Year Inspectondition of Change in Concomments:	tion Notes Material:	GOOD	01-99 (ASSUMED)	3420 S	1-4
DRYWALL 3 Year Inspection of Change in Condition Comments:	tion Notes Material:	GOOD	01-01	4000 S	1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 600

Material	Homog. Mat. #	Locations	% Asb	_	
3 Year Inspection o	ection Notes f Material: ondition? No		01-05	2 Ј	1-4
Condition of	ection Notes f Material:		01-99 (Assumed)	1100 s	1-4
Condition of	ection Notes f Material:		01-99 (Assumed)	360 S	1-4
Condition o	95 ection Notes f Material: ondition? No		01-99 (ASSUMED)	960 S	1-4
3 Year Inspe Condition o Change in Co	IN 96 ection Notes f Material: ondition? No	GOOD Abated? NO	01-99 (Assumed)	40 S	1-4
TRANS PANELS 3 Year Inspection of Change in Comments:	ection Notes f Material:		01-99 (Assumed)	400 S	1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 600

Homog.

Material Mat. # Locations % Asb Footage Codes

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old

HMRs.

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 700

Material	Homog. Mat. #	Locations		Footage	
MUD JNTs 3 Year Inspection of Change in Comments:	ection Note: f Material:	409 B:	01-05	4 S	
MUD JNTs 3 Year Inspectondition of Change in Co	ection Note: f Material:	3:	01-05	4 S	1-4
3 Year Inspection of	ection Note: f Material:		01-99 (assumed)	5220 S	1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)

Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 800

Homog

Material	Mat. #	Locations	% Asb	Footage Codes	
9" VFTs 3 Year Inspection of Change in Correction Corre	Material:	GOOD	01-99 (Assumed)	3000 S 1-4	

Codes:

General Condition: Change in Condition:

(1) Good (2) Damaged (3) Sig. Damaged (N or 4) No (Y) Yes (Please explain) (R) Repaired (M) Removed (E) Enclsd

Abated:

(I) Isolated and Restricted

Inspected By: Mike Sharp

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 900

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
Condition	17 spection Notes of Material: (Condition? NO	GOOD	15-20 NO	100 L	1-4
Condition	17 spection Notes of Material: (Condition? NO	GOOD	15-20 د NO	400 L	1-4
Condition	17 spection Notes of Material: (Condition? NO	GOOD	15-20 NO	50 L	1-4
Condition	18 spection Notes of Material: (Condition? NO	GOOD	05-19 NO	10 L	1-4
Condition	18 spection Notes of Material: (Condition? NO	GOOD	05-19 NO	15 J	1-4
Condition	18 spection Notes of Material: (Condition? NO	GOOD	05-19 NO	5 L	1-4

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged

Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 900

Homog.

Material Mat. # Locations % Asb Footage Codes

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old

HMRs.



School Dist: Chico USD School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: PORTABLES

Homog.

Material Mat. # Locations % Asb Footage Codes

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd

(I) Isolated and Restricted

Inspected By: Mike Sharp

NUMBER OF BUILDINGS

12

				CHEC	X ONE	•
UNE	BUILDING NAME (Indicate Address if Different From Above)		AC	ME	ASSUME	MEDA C
	(mucate Accress a Date and From Above)	NONE	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	100			х		X.
2	200			x		Х
2	300			х		х
4	400					х
5.	500		}	х		х
•	600			х		х
7.	700			х		х.
	800					х
•	900			х		
10.	MAINTENANCE SHED	х				
11.	. GREEN HOUSE	, x				•
12.	METAL STORAGE SHED	x				
12	PORTABLES (2)	х				
14,						
15.						
16.						1
17.					·	1
18.			<u></u>		<u> </u>	
18.			<u> </u>			
20.						<u> </u>

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 100

Material	Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
CEILING PLAST	6	ALL RMS EXCEPT KIT	01-05	3496 S	N
PW STR	8	CHAIR STRG & Fan Rm	30-35	50 L	N
PW CNR	10	UNDER KIT DISHWASHER	00-00	12	
PW STR	11	UNDER KIT DISHWASHER	00-00	15	******
BLR LINING	12	KITCHEN BLR RM	60-65	125 S	N
PW CNR	13	KITCHEN BLR RM	99-99 ASSUMED	20 Ј	N
FAN UNIT INS	94	FAN ROOMS	99-99 ASSUMED	100 S	N
9" vfts	95	ALL RMS EXCEPT STRRM	99-99 ASSUMED	3000 S	N
TRANSITE PIPE	99	KITCHEN BLR RM	99-99 ASSUMED	10 L	N
WALL PLASTER	100	ALL ROOMS	00-00	10000 S	N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 200

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N	?
PLASTER	5	ALL ROOMS	01-05	17600 S N	
9" VFTS	95	ALL ROOMS	99-99 ASSUMED	13560 S N	

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 200

Material Mat.	# Locations	% Asb	Friable? Footage Y or N	
DRYWALL 90	ROOM 250	00-00	400 S N	_

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 300

Material	Homog. Mat. #	Locations	% Asb	Footage	riable? Y or N
CEILING PLAST	6	ALL RMS but N. Wing	01-05	16500 S	N
9" VFTs	95	ALL ROOMS	99-99 ASSUMED	16490 S	N
TRANSITE PIPE	99	CLOSET OF RM 405	99-99 ASSUMED	12 L	N
WALL PLASTER	100	ALL ROOMS	00-00	3500 S	N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 300

Material	Homog. Mat. #	Locations	% Asb	Footage	riable? Y or N
DRYWALL	90	RM 250	99-99 ASSUMED	3000 S	N
DRYWALL	90	TEACHERS RM	99-99 ASSUMED	0 S	N
DRYWALL	90	ROOM 350	00-00	400 S	N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 400

Material	Homog. Mat. #	Locations	% Asb	F: Footage	riable? Y or N
PW JNTs	14	PE BLR RM & TUNNEL	99-99 ASSUMED	50 J	N
TANK WRAP	15	PE BLR RM	99-99 ASSUMED	150 S	N
TRANS PANELS	98	LOCKER RMS	99-99 ASSUMED	1000 S	N
WALL PLASTER	100	COACHES OFFICES	00-00	1500 S	N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 500

Ma	terial	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
A	DUCT INS	0	ON DUCT IN WALL & CL	90-95	0 S N
9"	vfts	95	All Rooms	99-99 ASSUMED	3420 S N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 500

Material	Homog. Mat. #	Locations		Friable? Footage Y or N
DRYWALL	100	ALL RMS	01-01	4000 S N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 600

Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
1	RM 208 NEAR SINK	01-05	2 J N
93	RM 9	99-99 ASSUMED	1100 S N
95	OFFICE AREA	99-99 ASSUMED	360 S N
95	RM 8	99-99 ASSUMED	960 S N
96	METAL SHOP	99-99 ASSUMED	40 S N
98	METAL SHOP	99-99 ASSUMED	400 S N
101	RM 8 AND 9	00-00	2296 S N
	93 95 96 98	1 RM 208 NEAR SINK 93 RM 9 95 OFFICE AREA 95 RM 8 96 METAL SHOP 98 METAL SHOP	Mat. # Locations % Asb 1 RM 208 NEAR SINK 01-05 93 RM 9 99-99 ASSUMED 95 OFFICE AREA 99-99 ASSUMED 95 RM 8 99-99 ASSUMED 96 METAL SHOP 99-99 ASSUMED 98 METAL SHOP 99-99 ASSUMED

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 600

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
DRYWALL	103	ALL ROOMS EXCP SHOP	00-00	5000 S N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 700

Material	Homog. Mat. #	Locations	% Asb	Footage	riable? Y or N
MUD JNTs	1	409	01-05	4 S	N
MUD JNTs	1	RM 408	01-05	4 S	N
9" VFTs	95	ALL CLS RMS	99-99 ASSUMED	5220 S	N
FCP	101	ALL CLASSROOMS	00-00	5220 S	N
WALL PLASTER	104	RESTROOMS / OFFICE	00-00	700 S	N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 800

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
9" VFTs	95	LIBRARY	99-99 ASSUMED	3000 S N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 800

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
DRYWALL	102	ALL ROOMS	00-00	5000 S N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 900

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
PW STR	17	BLR RM	15-20	100 L N
PW STR	17	GYM	15-20	400 L N
PW STR	17	STR RM	15-20	50 L N
PW JNTs	18	BLR RM	05-19	10 L N
PW JNTs	18	GYM	05-19	15 J N
PW JNTs	18	STR RM	05-19	5 L N

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: PORTABLES

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
CERTIFIED	0	8 PORTABLES	00-00	0

Hazard Management Services, Inc. Bulk Sample Analysis Request Form
AHERA THREE YEAR REINSPECTION SAMPLES

Please Send Results To: P.O. Box 576848 Modesto, CA 95357-6848

Samples Collected by: Michael Sharp on 04/15/92

Client: Chico Unified S.D. Site: Bidwell Junior High

Turn Atround Time: Extended, Results Needed By April 30th, if possible.

Sample Number	Material	Location		
HMS-CUSD-BJR -90A	Drywall	Teacher's Rm at door jam Unit 300.		
Result:	None Detected	Jam Onic 300.		
HMS-CUSD-BJR -90B	Drywall	Rm 250 North wall at		
Result	None Detected	Door jam.		
HMS-CUSD-BJR -90C	Drywall	Rm 250 South wall in west corner floor level.		
Result:	None Detected.			



Forensic Analytical Analytical Report

Bulk Material Analysis

Client:

Hazard Management Services, Inc.

Modesto Location

P.O. Box 576848

Modesto, CA 95357-6848

Client Number: 1146

Report Number: 177335

Date Received: 04/21/92

Date Collected: 04/15/92

Lab Number: 19220548

Sample Number: HMS-CUSD-BJR-90A

P.O. Num:

Job ID: Chico Unified School District

Site: Bidwell Junior High

Location: Teacher's room at door jam Unit 300, drywall.

Gross Description: White fibrous plaster with paint, fibrous backing

and a trace of skim coat.

Comments:

roscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile Amosite

Non-Det.%

Non-Det.%

9

TOTAL NON-ASBESTCS FIBROUS MATERIAL PRESENT:

Cellulose

Fibrous Glass Talc

1 - 5

10-15 ş Ş Trace Ŷ.

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85 %

Non-Det.%

15-20 %

Director of Laboratory Services, Rayward Laboratory

Analyptical replicit 40 CEL TOD, Subpart E, Appendix & (ANIDA)



Bulk Material Analysis

Client:

Hazard Management Services, Inc.

Modesto Location

P.O. Box 576848

Modesto, CA 95357-6848

Client Number: 1146 Report Number: 177335

Date Received: 04/21/92

Date Collected: 04/15/92

Lab Number: 19220549

Sample Number: HMS-CUSD-BJR-90B

P.O. Num:

Job ID: Chico Unified School District

Site: Bidwell Junior High

Location: Room 250 north wall at door jam, drywall.

Gross Description: White fibrous powder with a trace of skim coat and

fibrous backing.

Comments:

roscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Amosite

Non-Det.%

Non-Det.%

Sto - 050

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose

Fibrous Glass

10-15

1 - 5

ુ જ

ę,

9

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85

15-20 %

Dabis Seichban Director of Laboratory Services, Hayward Laboratory

Analytical sechod: 40 CTR Tes, Eubpart F, Appendix & (ABERA)

Bulk Material Analysis

Client:

Hazard Management Services, Inc.

Modesto Location

P.O. Box 576848

Modesto, CA 95357-6848

Client Number: 1146

Report Number: 177335
Date Received: 04/21/92

Date Collected: 04/15/92

Lab Number: 19220550

Sample Number: HMS-CUSD-BJR-90C

P.O. Num:

Job ID: Chico Unified School District

Site: Bidwell Junior High

Location: Room 250 south wall in west corner, floor level, drywall.

Gross Description: White fibrous powder with paint and fibrous backing.

Comments:

proscopic Description

TOTAL ASBESTOS PRESENT:

Chrysotile

Amosite

Non-Det.%

ş

Non-Det.%

TOTAL NON-ASBESTOS FIBROUS MATERIAL PRESENT:

Cellulose

Fibrous Glass

10-15

1 - 5

15-20 %

Non-Det. %

TOTAL NON-ASBESTOS NON-FIBROUS MATERIAL PRESENT:

80-85

Janis Decaman

Tanis Teichan, Director of Laboratory Services, Hayward Laboratory

Abelytical bethod: 40 CDR 763, Subject F, Appendix A (AMERA)

See Reverse for Explanation of Terms and Reporting Practices

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 100

Homog. Mat. #	Locations	% Asb	Footage	Friable? Y or N
6	ALL RMS EXCEPT KIT	01-05	3496 S	N
8	CHAIR STRG & Fan Rm	30-35	50 L	N
10	UNDER KIT DISHWASHER	00-00	12	
11	UNDER KIT DISHWASHER	00-00	15	
12	KITCHEN BLR RM	60-65	125 S	N
13	KITCHEN BLR RM	99-99 ASSUMED	20 J	N
94	FAN ROOMS	99-99 ASSUMED	100 S	N
95	ALL RMS EXCEPT STRRM	99-99 ASSUMED	3000 S	N
99	KITCHEN BLR RM	99-99 ASSUMED	10 L	N
100	ALL ROOMS	00-00	10000 s	N
	Mat. # 6 8 10 11 12 13 94 95	6 ALL RMS EXCEPT KIT 8 CHAIR STRG & Fan Rm 10 UNDER KIT DISHWASHER 11 UNDER KIT DISHWASHER 12 KITCHEN BLR RM 13 KITCHEN BLR RM 94 FAN ROOMS 95 ALL RMS EXCEPT STRRM 99 KITCHEN BLR RM	Mat. # Locations % Asb 6 ALL RMS EXCEPT KIT 01-05 8 CHAIR STRG & Fan Rm 30-35 10 UNDER KIT DISHWASHER 00-00 11 UNDER KIT DISHWASHER 00-00 12 KITCHEN BLR RM 60-65 13 KITCHEN BLR RM 99-99 ASSUMED 94 FAN ROOMS 99-99 ASSUMED 95 ALL RMS EXCEPT STRRM 99-99 ASSUMED 99 KITCHEN BLR RM 99-99 ASSUMED	Mat. # Locations % Asb Footage 6 ALL RMS EXCEPT KIT 01-05 3496 S 8 CHAIR STRG & Fan Rm 30-35 50 L 10 UNDER KIT DISHWASHER 00-00 12 11 UNDER KIT DISHWASHER 00-00 15 12 KITCHEN BLR RM 60-65 125 S 13 KITCHEN BLR RM 99-99 ASSUMED 20 J ASSUMED 94 FAN ROOMS 99-99 ASSUMED 100 S ASSUMED 95 ALL RMS EXCEPT STRRM 99-99 ASSUMED 3000 S ASSUMED 99 KITCHEN BLR RM 99-99 ASSUMED 10 L ASSUMED

School Dist: Chico USD

School: BIDWELL JUNIOR HIGH

Date Inspected: 04/15/92

BUILDING: 200

Material	Homog. Mat. #	Locations	% Asb	Friable? Footage Y or N
PLASTER	5	ALL ROOMS	01-05	17600 S N
9" VFTS	95	ALL ROOMS	99-99 ASSUMED	13560 S N

Inspected By: Mike Sharp