

Inspector: Robert Baughman

Building: 100

District: Chico Unified School District

School: Bidwell Junior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
s	CEILING PLASTER	6	1-5 %	UNDETERMINED	ALL ROOMS EXCEPT KITCHEN	(1) (4) ½ - Test ceiling in storage rms in MP_SAME 11/21/03	N
T	PIPEWRAP STRAIGHT	8	30-35%	UNDETERMINED	CHAIR STORE ROOM	(1) (4) SAME 11/21/03	N
М	FAN VENT INSULATION	94	ASSUMED	UNDETERMINED	FAN ROOMS	(12) COULD NOT FIND THIS ROOM (5) LOCATED IN CHAIR STOREROOM	N
M	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS EXCEPT NORTH CHAIR STORE	(1) (4) SAME 11/21/03	N
M	TRANSITE PIPE	99	ASSUMED	UNDETERMINED	KITCHEN AND BOILER ROOMS 1 & 2	(1) (4) SAME 11/21/03	N
М	2 X 4 FCP'S	102	ASSUMED1	UNDETERMINED	ROOM 108	(1) SAME 11/21/03	N
М	DRYWALL	103	ASSUMED	UNDETERMINED	KITCHEN	(1) (4) SAME 11/21/03	N
М	12" VFT	104	ASSUMED	UNDETERMINED	MULTI-PURPOSE ROOM, ROOMS 105, 106, 107, 109 & OFFICE IN ROOM 109	(1) SAME 11/21/03	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)

(13) Non-Asbestos/Not Inspected

Change in Condition: Abated:

(4) No (6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



District: Chico Unified School District

Inspector: Robert Baughman

School: Bidwell Junior High School

Building: 200 (AKA 600)

Material	l	I	I			
	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOM 208 NEAR THE SINK	(11) SAME 11/21/03	N
PLASTER	5	1-5 %	UNDETERMINED	ALL ROOMS, CLOSET (C), ROOM 204, HALLWAY, ROOM 250, AND GIRLS RESTROOM	(1) (4) WATER STAINS ARE PRESENT. SOME AREAS HAVE 1' X 1' PENETRATIONS WHERE SKY LIGHTS ARE GOING TO BE PLACED. SAME 11/21/03	N
DRYWALL	90	ASSUMED	UNDETERMINED	ROOM 250 & RESTROOM	(1) SAME 11/21/03	N
12" VFT	93	ASSUMED	UNDETERMINED	ROOM 208	(1) SAME 11/21/03	N
9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS, HALLWAY 200, ROOM 250, & GIRLS RESTROOM	(1) (4) SAME 11/21/03	N
TRANSITE	98	ASSUMED	UNDETERMINED	METAL SHOP	(7)	N
12" ACT	105	ASSUMED	UNDETERMINED	ROOMS 206, 207, & 209	(1) CHECK PLAN (2) (5) RM 203-202 DAMAGED 11/21/03	N
, , , , , , , , , , , , , , , , , , , ,	DRYWALL 12" VFT 9" VFT TRANSITE PANEL	MUDDED 1 LIGINTS PLASTER 5 DRYWALL 90 12" VFT 93 9" VFT 95 TRANSITE 98 PANEL	MUDDED 1 1-5% IOINTS PLASTER 5 1-5 % DRYWALL 90 ASSUMED 12" VFT 93 ASSUMED 9" VFT 95 ASSUMED TRANSITE 98 ASSUMED PANEL	MUDDED 1 1-5% UNDETERMINED 10INTS PLASTER 5 1-5% UNDETERMINED DRYWALL 90 ASSUMED UNDETERMINED 12" VFT 93 ASSUMED UNDETERMINED 9" VFT 95 ASSUMED UNDETERMINED TRANSITE 98 ASSUMED UNDETERMINED TRANSITE 98 ASSUMED UNDETERMINED	MUDDED 1 1 1-5% UNDETERMINED ROOM 208 NEAR THE SINK PLASTER 5 1-5 % UNDETERMINED ALL ROOMS, CLOSET (C), ROOM 204, HALLWAY, ROOM 250, AND GIRLS RESTROOM DRYWALL 90 ASSUMED UNDETERMINED ROOM 250 & RESTROOM 12" VFT 93 ASSUMED UNDETERMINED ROOM 208 9" VFT 95 ASSUMED UNDETERMINED ALL ROOMS, HALLWAY 200, ROOM 250, & GIRLS RESTROOM TRANSITE 98 ASSUMED UNDETERMINED METAL SHOP	MUDDED IONTS 1 1-5% Undetermined ROOM 208 NEAR THE SINK (11) SAME 11/21/03 PLASTER 5 1-5 % Undetermined ALL ROOMS, CLOSET (C), ROOM 204, HALLWAY, ROOM 250, AND GIRLS RESTROOM (1) (4) WATER STAINS ARE PRESENT. SOME AREAS HAVE 1' X 1' PENETRATIONS WHERE SKY LIGHTS ARE GOING TO BE PLACED. SAME 11/21/03 DRYWALL 90 ASSUMED Undetermined ROOM 250 & RESTROOM (1) SAME 11/21/03 12" VFT 93 ASSUMED Undetermined ROOM 208 (1) SAME 11/21/03 9" VFT 95 ASSUMED Undetermined ALL ROOMS, HALLWAY 200, ROOM 250, & (1) (4) SAME 11/21/03 (1) (4) SAME 11/21/03 TRANSITE PANFIL 98 ASSUMED Undetermined METAL SHOP (7) 12" ACT 105 ASSUMED Undetermined ROOMS 206, 207, & 209 (1) CHECK PLAN

CONDITION CODE

General Condition: Change in Condition: (1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Bidwell Junior High School

Building: 300

Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	CEILING PLASTER	6	1-5%	UNDETERMINED	ALL CLASSROOMS AND HALLWAY 300	(1) (4) same 5/12/03 (2) (5) 11/21/03	N
М	2 X 4 FCP'S	106	ASSUMED	UNDETERMINED	ROOMS 308 & 309	(1) CHECK PLAN SAME 5/12/03 (2) (5) loose matt hanging 11/21/03	N
М	9" VFT	300	ASSUMED	UNDETERMINED	ALL CLASSROOMS, HALLWAY 300, AND GIRLS RESTROOM	(1) SAME 11/21/03	N

CONDITION CODE

Damage in Rms 305, 305A, 307 * 308

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No (6) Repaired

(5) Yes (If Yes, explain under comments) (7) Removed (8) Encapsulated

(13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

Abated:

(11) Inaccessible, No inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected



Inspector: Robert Baughman

District: Chico Unified School District

School: Bidwell Junior High School

Building: 400 (AKA 700)

Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOMS 408 & 409	(11) COULD NOT FIND THE JOINTS DURING THE TIME OF INSPECTION. (2) (5) 11/21/03	N/A
PIPE WRAP	14	ASSUMED	UNDETERMINED	PE BOILER ROOM & TUNNEL	(1) (4) SAME 11/21/03	N
TANK WRAP	15	ASSUMED	UNDETERMINED	PE BOILER ROOM	(1) (4) SAME 11/21/03	N
9" VFT	95	ASSUMED	UNDETERMINED	ALL CLASSROOMS	(1) (4) SAME 5/12/03 (2) (5) RM 407 CRACKED & BROKEN 11/21/03	N
TRANSITE PANFLS	98	ASSUMED	UNDETERMINED	PANELS IS BOTH LOCKER ROOMS	(1) (4) SAME 11/21/03	N
2 X 4 FCP'S	101	ASSUMED	UNDETERMINED	ROOMS 408, 408A, & 409	(1) SAME 5/12/03 (2) (5) BROKEN 11/21/03	N
TRANSITE PIPE	107	ASSUMED	UNDETERMINED	CLOSET OF ROOM 405	(1) (4) SAME 11/21/03	N
	MUDDED JOINTS PIPE WRAP TANK WRAP 9" VFT TRANSITE PANFLS 2 X 4 FCP'S	Mat. # MUDDED JOINTS PIPE WRAP 14 TANK WRAP 15 9" VFT 95 TRANSITE PANELS 2 X 4 FCP'S 101	Mat. # MUDDED	Mat. # MUDDED JOINTS 1 1-5% UNDETERMINED PIPE WRAP 14 ASSUMED UNDETERMINED TANK WRAP 15 ASSUMED UNDETERMINED 9" VFT 95 ASSUMED UNDETERMINED TRANSITE 98 ASSUMED UNDETERMINED 2 X 4 FCP'S 101 ASSUMED UNDETERMINED	MUDDED JOINTS 1 1-5% UNDETERMINED ROOMS 408 & 409 PIPE WRAP 14 ASSUMED UNDETERMINED PE BOILER ROOM & TUNNEL TANK WRAP 15 ASSUMED UNDETERMINED PE BOILER ROOM 9" VFT 95 ASSUMED UNDETERMINED ALL CLASSROOMS TRANSITE PANELS 98 ASSUMED UNDETERMINED PANELS IS BOTH LOCKER ROOMS 2 X 4 FCP'S 101 ASSUMED UNDETERMINED ROOMS 408, 408A, & 409	MUDDED JOINTS 1 1-5% UNDETERMINED ROOMS 408 & 409 (11) COULD NOT FIND THE JOINTS DURING THE TIME OF INSPECTION. (2) (5) 11/21/03 PIPE WRAP 14 ASSUMED UNDETERMINED PE BOILER ROOM & TUNNEL (1) (4) SAME 11/21/03 TANK WRAP 15 ASSUMED UNDETERMINED PE BOILER ROOM (1) (4) SAME 11/21/03 9° VFT 95 ASSUMED UNDETERMINED ALL CLASSROOMS (1) (4) SAME 5/12/03 (2) (5) RM 407 CRACKED & BROKEN 11/21/03 TRANSITE PANFLS 98 ASSUMED UNDETERMINED PANELS IS BOTH LOCKER ROOMS (1) (4) SAME 11/21/03 2 X 4 FCP'S 101 ASSUMED UNDETERMINED ROOMS 408, 408A, & 409 (1) SAME 5/12/03 (2) (5) BROKEN 11/21/03

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

Inspector: Robert Baughman

District: Chico Unified School District

School: Bidwell Junior High School

Building: 500

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS	(2) CRACKED TILE IN ROOM 502. (1) – 1/2/02 SAME 11/21/03	N
М	DRYWALL	100	1%	UNDETERMINED	ALL ROOMS	(1) (4) SAME 11/21/03	N
М	12" ACT	108	ASSUMED	UNDETERMINED	ROOMS 501, 502, OFFICE, AND PRACTICE	(1) SAME 11/21/03	N
Т	DUCT INSULATION	109	90-95%	UNDETERMINED	DUCT WORK-CEILING AND WALLS	(11) COULD FIND DURING THE TIME OF INSPECTION.	N

School: Bidwell Junior High School

Building: 800

	T	3 00007		T	T	·	Building: 800
Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Y / N
M	9" VFT	95	ASSUMED	UNDETERMINED	LIBRARY	(1) (4) SAME 11/21/03	N
М	12" ACT	109	ASSUMED	UNDETERMINED	LIBRARY, OFFICES, & AUDIO VISUAL	(1) SAME 11/21/03	N
М	PLASTER	110	ASSUMED	UNDETERMINED	THROUGHOUT THE UNIT	(1) SAME 11/21/03	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(6) Repaired

(5) Yes (If Yes, explain under comments)

(7) Removed (8) Encapsulated

(13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

Abated:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



Inspector: Robert Baughman

District: Chico Unified School District

School: B	idwell Junior Hi	gh School	·			T	Building: 900
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	PIPE WRAP STRAIGHT	17	15-20%	UNDETERMINED	GYM & STOREROOM	(1) (4) SAME 11/21/03	N
Т	PIPE WRAP CORNER	18	5-10%	UNDETERMINED	GYM, BOILER ROOM, & STOREROOM	(1) (4) SAME SAME 11/21/03	N
М	12" ACT	111	ASSUMED	UNDETERMINED	GYM	(1) SOME TILES HAVE BEEN REMOVED. THE MASTIC IS SHOWING. (1) (6) SAME 11/21/03	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: Abated:

(4) No (6) Repaired (5) Yes (If Yes, explain under comments)

(7) Removed (8) Encapsulated

(13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



District: Chico Unified School District

Inspector: Robert Peters

Building: 100

School: Bidwell Junior High School

Material Class	Material	Homo. Mat.#	% Asb.	Fť/L.F.	Location	Condition: Code & Comments	Friable Yes/No
s	CEILING PLASTER	6	1-5 %	UNDETERMINED	ALL ROOMS EXCEPT KITCHEN	(1) (4) ½ - Test ceiling in storage rms in MP	N
Т	PIPEWRAP STRAIGHT	8	30-35%	UNDETERMINED	CHAIR STORE ROOM	(1) (4) SAME 5/12/03	N
М	FAN VENT INSULATION	94	ASSUMED	UNDETERMINED	FAN ROOMS	(12) COULD NOT FIND THIS ROOM (5) LOCATED IN CHAIR STOREROOM	N
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS EXCEPT NORTH CHAIR STORE	(1) (4) SAME 5/12/03	N
М	TRANSITE PIPE	99	ASSUMED	UNDETERMINED	KITCHEN AND BOILER ROOMS 1 & 2	(1) (4) SAME 5/12/03	N
М	2 X 4 FCP'S	102	ASSUMED1 -5 %900 S	UNDETERMINED	ROOM 108	(1) SAME 5/12/03	N
М	DRYWALL	103	ASSUMED	UNDETERMINED	KITCHEN	(1) (4) SAME 5/12/03	N
M	12" VFT	104	ASSUMED	UNDETERMINED	MULTI-PURPOSE ROOM, ROOMS 105, 106, 107, 109, & OFFICE IN ROOM 109	(1) SAME 5/12/03	N

CONDITION CODE

General Condition: Change in Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

(4) No

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



District: Chico Unified School District

Inspector: Robert Peters

School: Bidwell Junior High School

Building: 200 (AKA 600)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOM 208 NEAR THE SINK	(11) SAME 5/12/03	N
М	PLASTER	5	1-5 %	UNDETERMINED	ALL ROOMS, CLOSET (C), ROOM 204, HALLWAY, ROOM 250, AND GIRLS RESTROOM	(1) (4) WATER STAINS ARE PRESENT. SOME AREAS HAVE 1' X 1' PENETRATIONS WHERE SKY LIGHTS ARE GOING TO BE PLACED. SAME 5/12/03	N
М	DRYWALL	90	ASSUMED	UNDETERMINED	ROOM 250 & RESTROOM	(1) SAME 5/12/03	N
М	12" VFT	93	ASSUMED	UNDETERMINED	ROOM 208	(1) SAME 5/12/03	N
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS, HALLWAY 200, ROOM 250, & GIRLS RESTROOM	(1) (4) SAME 5/12/03	N
М	TRANSITE PANEL	98	ASSUMED	UNDETERMINED	METAL SHOP	(7)	N
М	12" ACT	105	ASSUMED	UNDETERMINED	ROOMS 206, 207, & 209	(1) CHECK PLAN	N
				=			

CONDITION CODE

General Condition: Change in Condition: (1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 05/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Bidwell Junior High School

Building: 300

Material Class	Material	Home. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	CEILING PLASTER	6	1-5%	UNDETERMINED	ALL CLASSROOMS AND HALLWAY 300	(1) (4) SAME 5/12/03	N
М	2 X 4 FCP'S	106	ASSUMED	UNDETERMINED	ROOMS 308 & 309	(1) CHECK PLAN SAME 5/12/03	N
М	9" VFT	300	ASSUMED	UNDETERMINED	ALL CLASSROOMS, HALLWAY 300, AND GIRLS RESTROOM	(1) SAME 5/12/03	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Change in Condition: Abated:

(4) No (6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



District: Chico Unified School District

Inspector: Robert Peters

School: Bidwell Junior High School

Buildina: 400 (AKA 700)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	MUDDED JOINTS	1	1-5%	UNDETERMINED	ROOMS 408 & 409	(11) COULD NOT FIND THE JOINTS DURING THE TIME OF INSPECTION.	N/A
Т	PIPE WRAP	14	ASSUMED	UNDETERMINED	PE BOILER ROOM & TUNNEL	(1) (4) SAME 5/12/03	N
Т	TANK WRAP	15	ASSUMED	UNDETERMINED	PE BOILER ROOM	(1) (4) SAME 5/12/03	N
М	9* VFT	95	ASSUMED	UNDETERMINED	ALL CLASSROOMS	(1) (4) SAME 5/12/03	N
М	TRANSITE PANELS	98	ASSUMED	UNDETERMINED	PANELS IS BOTH LOCKER ROOMS	(1) (4) SAME 5/12/03	N
М	2 X 4 FCP'S	101	ASSUMED	UNDETERMINED	ROOMS 408, 408A, & 409	(1) SAME 5/12/03	N
М	TRANSITE PIPE	107	ASSUMED	UNDETERMINED	CLOSET OF ROOM 405	(1) (4) SAME 5/12/03	N
							

CONDITION CODE

General Condition: Change in Condition: (1) Good (4) No

(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)

(13) Non-Asbestos/Not Inspected

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



Inspector: Robert Peters

District: Chico Unified School District

School: Bidwell Junior High School

Building: 500

Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	95	ASSUMED	UNDETERMINED	ALL ROOMS	(2) CRACKED TILE IN ROOM 502. (1) – 1/2/02 SAME 5/12/03	N
М	DRYWALL	100	1%	UNDETERMINED	ALL ROOMS	(1) (4) SAME 5/12/03	N
М	12" ACT	108	ASSUMED	UNDETERMINED	ROOMS 501, 502, OFFICE, AND PRACTICE	(1) SAME 5/12/03	N
Т	DUCT INSULATION	109	90-95%	UNDETERMINED	DUCT WORK-CEILING AND WALLS	(11) COULD FIND DURING THE TIME OF INSPECTION.	Z

School: Bidwell Junior High School

Building: 800

Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Y / N
М	9" VFT	95	ASSUMED	UNDETERMINED	LIBRARY	(1) (4) SAME 5/12/03	N
М	12" ACT	109	ASSUMED	UNDETERMINED	LIBRARY, OFFICES, & AUDIO VISUAL	(1) SAME 5/12/03	N
М	PLASTER	110	ASSUMED	UNDETERMINED	THROUGHOUT THE UNIT	(1) SAME 5/12/03	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(6) Repaired

(7) Removed (8) Encapsulated

(5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted

Abated: Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected



District: Chico Unified School District

Inspector: Robert Peters

School: Bidwell Junior High School

Building: 900

		· · · · · · · · · · · · · · · · · · ·		,			
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	PIPE WRAP STRAIGHT	17	15-20%	UNDETERMINED	GYM & STOREROOM	(1) (4) SAME 5/12/03	N
Т	PIPE WRAP CORNER	18	5-10%	UNDETERMINED	GYM, BOILER ROOM, & STOREROOM	(1) (4) SAME 5/12/03	N
М	12" ACT	111	ASSUMED	UNDETERMINED	GYM	(1) SOME TILES HAVE BEEN REMOVED. THE MASTIC IS SHOWING. (1) (6)	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: Abated:

(4) No (6) Repaired (5) Yes (If Yes, explain under comments)

(7) Removed (8) Encapsulated

(13) Non-Asbestos/Not Inspected (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, No inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected