HOMOGENEOUS ACBM RECORDS

Date of Inspection:

District: Chico Unified School District

Building: Unit A (FKA G)

School: Chapman Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	MUD JOINT	1	1-5%	UNDETERMINED	THROUGHOUT	(11) SAMPLE HMS-CPM-03 COLLECTED ON 4/9/88.	Y
М	TRANSITE PANELS	2	ASSUMED	UNDETERMINED	THROUGHOUT	(1) (2) By door room 21 4 silicaned	N
М	12" VFT CREAM	3	None Detectedb	400 S	CLASSROOMS 1, 2, 6, & 7	(13) CUSD sample taken 12/26/07 chp01-chp 04	N

School: Chapman Elementary School

Building: Unit D (FKA F)

Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	4	1-5%	UNDETERMINED	THROUGHOUT EXCEPT IN LIBRARY	(1) (4)	N/A
М	9" VFT	5	1-5%	UNDETERMINED	THROUGHOUT EXCEPT IN LIBRARY	(1) (4)	N/A
М	TRANSITE PANELS	6	ASSUMED	400 S	EXTERIOR	(1) (4)	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated

(12) Other (Explain under comments)

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE **HOMOGENEOUS ACBM RECORDS**

Date of Inspection:	
Inspector: Dan H	to Al

District: Chico Unified School District

School: Chapman Elementary School

Building: Unit E (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	TRANSITE PANELS	7	ASSUMED	400 S	EXTERIOR	(1) (4)	N
М	12" VFT CREAM	8	None Detected	3,600 S	CLASSROOMS 15-18	(13) CUSD sample 12/26/07 chp 01-04 MODERNIZATION 1989	N

School: Chapman Elementary School

Building: Unit F (FKA A)

Material Class	Material	Homo. Mat.#	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BROWN	9	10-15%	UNDETERMINED	KITCHEN	(1) (2) 21 TILES MISSING	N
М	12" VFT CREAM	10	None Detected	3,600 S	MPR, CORRIDOR, AND OFFICES	(13) CUSD sample on 12/26/07 chp 01-04 MODERNIZATION 1989	N
М	12" ACT	11	NON ASBESTOS	3,600 S	MPR, CORRIDOR, AND OFFICES	(13) CUSD SAMPLE COLLECTED ON 7/8/08	N
S	PLASTER	12	NONE DETECTED	UNDETERMINED	KITCHEN	(11) CUSD SAMPLE Chp01COLLECTED 2/22/06	N/A

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

Abated:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE **HOMOGENEOUS ACBM RECORDS**

Date of Inspection:	
11	1

District: Chico Unified School District

Inspector: Dan Hun

School: Chapman Elementary School

Building: Unit H (FKA B)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	TRANSITE PANELS	13	ASSUMED	400 S	EXTERIOR	(1) (4)	N
М	12" VFT cream	14	None Detected	3,600 S	CLASSROOMS 19-22	(13) CUSD sample on 12/26/07 chp 01- chp 04 MODERNIZATION 1989	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(5) Yes (If Yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

Abated:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS