District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: A (1st Floor)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS FISSURE PATTERN	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA & CLASSROOMS 110- 111,113-130	(13) SAMPLE HMS-CHS-01 COLLECTED ON 3-28-88.	N/A
М	12" VINYL FLOOR TILE (BEIGE) & ADHESIVE	2	TRACE	5,700 S	RECEPTION AREA & CLASSROOMS	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, 120, AND CLASSROOMS 102-107	(13) SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88. (2) DAMAGED WHERE VISIBLE	N/A
Т	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (CLASSROOM 111)	(11) INACCESSIBLE.	Υ
Т	MESH WRAP	8	12-20%	½ L	DARK ROOM ATTIC (CLASSROOM 111)	(11) INACCESSIBLE.	Y
М	TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, AND STAIRWELLS	(1) (4) PANELS PAINTED WHITE 11/19/03.	N
М	DRYWALL & JOINT COMPOUND	166	ASSUMED POSITIVE	8,000 S	THROUGHOUT INTERIOR WALLS	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	700 S	THROUGHOUT INTERIOR	(1) (4)	N
S	STUCCO	251	ASSUMED POSITIVE	2,500 S	COVERED WALKWAYS	(1) (4)	N
М	CARPET ADHESIVE	501	ASSUMED POSITIVE	200 S	ADMIN AREA, PRINCIPAL'S OFFICE	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Inspector:

School: Chico Senior High School

Building: A (2ND Floor)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VINYL FLOOR TILE (BEIGE) & ADHESIVE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4)	N
М	2' X 4' CEILING PANELS	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88.	N/A
М	CEMENTITIOUS TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	COVERED WALKWAYS	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	167	ASSUMED POSITIVE	8,000 S	THROUGHOUT INTERIOR WALLS	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	700 S	CLASSROOMS & COVERED WALKWAYS	(1) (4)	Ν
S	STUCCO	251	ASSUMED POSITIVE	2,800 S	STAIRS & COVERED WALKWAYS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

District: Chico Unified School District

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS	13	NONE DETECTED	10, 000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON 3-28-88.	N/A
М	CEMENTITIOUS TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, AND STAIRWAYS	(1) (4) PANELS PAINTED WHITE 11/19/03.	N
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	152	CERTIFIED ASBESTOS FREE	9,430 S	THROUGHOUT	(13) CERTIFICATION LETTER ON FILE.	N/A
М	DRYWALL & JOINT COMPOUND	168	ASSUMED POSITIVE	7,500 S	THROUGHOUT	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	650 S	THROUGHOUT	(1) (4)	N
S	STUCCO	251	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	252	ASSUMED POSITIVE	800 S	CORRIDORS AT ROOMS 2 & 10, B-3	(1) (4)	N
S	DRYWALL TEXTURE	502	ASSUMED POSITIVE	7, 500 S	THROUGHOUT	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Chico Senior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	TRANSITE PANELS	95	ASSUMED POSITIVE	1,300 S	EXTERIOR OF BUILDING	(1) (4) PANELS PAINTED WHITE 11/19/03.	N
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	150	CERTIFIED ASBESTOS FREE	9,513 S	CLASSROOMS 1-11	(13) LETTER IN FILE AS OF 6/2005.	N/A
М	DRYWALL & JOINT COMPOUND	169	ASSUMED POSITIVE	7,500 S	THROUGHOUT	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	650 S	THROUGHOUT	(1) (4)	N
S	STUCCO	251	ASSUMED POSITIVE	1,500 S	COVERED WALKWAYS	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	252	ASSUMED POSITIVE	800 S	CORRIDORS AT ROOMS C1 & C10	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good

Change in Condition: (5) Yes (If Yes, explain under comments) (4) No

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: (6) Repaired

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

Building: C

District: Chico Unified School District

Inspector:

School: Chico Senior High School

Building: D & H

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	38	1-5%	300 S	934 & 935, CORRIDOR BETWEEN D&H, AND BAND ROOM OFFICE	(1) (4) TROWELED ON CEILING.	N
М	12" VINYL FLOOR TILE (OFF WHITE) & ADHESIVE	150	CERTIFIED ASBESTOS FREE	1,200 S	MUSIC WING HALL, BAND ROOM D1, ROOM 938A	(13) CERTIFICATION LETTER ON FILE AS OF 6/2005.	N/A
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	CLASSROOMS H1, H2, & H3, D4-D5	(1) (4)	N
М	12" ACOUSTIC CEILING TILE 1/8" HOLE PATTERN	255	ASSUMED POSITIVE	3,500 S	CLASSROOMS H1, H2, & H3, D4-D5, RESTROOMS	(1) (4)	N
М	SHEET VINYL FLOORING (GRAY MARBLED) & ADHESIVE	256	ASSUMED POSITIVE	3,000 S	CLASSROOMS H1, H2, & H3, D4-D5	(1) (4)	N
М	DRYWALL	257	ASSUMED POSITIVE	3,000 S	CLASSROOMS H1, H2, & H3	(1) (4)	N
М	12" ACOUSTIC CEILING TILE FISSURE PATTERN	258	ASSUMED POSITIVE	600 S	CORRIDOR BETWEEN D&H, BAND ROOM D1, CHORAL ROOM D2, ROOM 938A	(1) (4)	N
М	CEMENTITIOUS TRANSITE PIPE	259	ASSUMED POSITIVE	10 L	STORAGE (936) AT WATER HEATER	(1) (4)	N

(1	12" VINYL FLOOR TILE (DARK GRAY) & ADHESIVE	260	ASSUMED POSITIVE	1,800 S	CHORAL ROOM D2	(1) (4)	Ν
----	---	-----	---------------------	---------	----------------	---------	---

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Inspector:

School: Chico Senior High School

Building: L

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' CEILING PANELS FISSURE PATTERN	17	NONE DETECTED	11,155 S	ALL ROOMS	(13) SAMPLE HMS-CHS-17 COLLECTED ON 3-28-88.	N/A
Т	MUD JOINTS	19	5-10%	20 JOINTS	LIBRARY ATTIC	(11) NOT ACCESSIBLE	Υ
М	12" VINYL FLOOR TILE (BEIGE MOTTLED) & ADHESIVE	151	CERTIFIED ASBESTOS FREE	850 S	LIBRARY ENTRANCE/OFFICE	(13) CERTIFICATION LETTER ON FILE AS OF 6/2005.	N/A
М	DRYWALL & JOINT COMPOUND	170	ASSUMED POSITIVE	10,000 S	THROUGHOUT	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	800 S	THROUGHOUT	(1) (4)	N
М	CARPET ADHESIVE	264	ASSUMED POSITIVE	5,000 S	LIBRARY	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

District: Chico Unified School District

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

Building: F

District: Chico Unified School District Inspector:

School: Chico Senior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(12) UNABLE TO LOCATE	Y
M	2' X 4' CEILING PANELS FISSURE PATTERN	59	NONE DETECTED	4,500 S	CLASSROOMS 1-5	(13) SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	N/A
Т	MUD JOINTS	60	5-10%	12 L	CLASSROOM 1	(12) UNABLE TO LOCATE	Y
M	KILN BRICK, TAN	151	NONE DETECTED	10.5 S	INSIDE OLDER TRANSITE PANELS ENCASED KILN	(13) SAMPLE HMS-R1303-01A COLLECTED ON 4-13-04.	N/A
М	KILN BRICK, WHITE	152	NONE DETECTED	10.5 S	LARGER OLDER TRANSITE PANEL ENCASED KILN	(13) SAMPLE HMS-R1303-02A COLLECTED ON 4-13-04.	N/A
М	KILN BRICK, WHITE	153	NONE DETECTED	10.5 S	METAL ENCASED CRESS ELECTRIC KILN MODEL A-22-H	(13) SAMPLE HMS-R1303-03A COLLECTED ON 4-13-04.	N/A
М	KILN BRICK	154	NONE DETECTED	10.5 S	SMALL KILN APPROXIMATELY 2' HIGH BY 14" SQUARE WITH B-19 ON SIDE	(13) SAMPLE HMS-R1303-04A COLLECTED ON 4-13-04.	N/A
М	KILN BRICK	155	NONE DETECTED	10.5 S	3' SQUARE KILN	(13) SAMPLE HMS-R1303-05A COLLECTED ON 4-13-04.	N/A
S	STUCCO	156	<1% CHRYSOTILE	220 S	EXTERIOR WALL AT SOUTH SIDE OF CERAMICS LAB ROOM 505	(1) (4) SAMPLE HMS-R1303-06A COLLECTED ON 4-13-04.	N
М	VINYL COVERED TAGBOARD	157	NONE DETECTED	800 S	CERAMICS LAB ROOM 505D	(13) SAMPLE HMS-R1303-07A COLLECTED ON 4-13-04.	N/A
M	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	400 S	THROUGHOUT	(1) (4)	N

M	12" X 12" GRAY VINYL FLOOR TILE	503	ASSUMED POSITIVE	200 S	STUDIO 999	(1)	N
	AND MASTIC						

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: S

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments Friab Yes/N	
М	2' X 4' CEILING PANELS	22	NONE DETECTED	8,000 S	ROOMS 1-7	(13) SAMPLE HMS-CHS-22 COLLECTED ON N/A 3-28-88.	/A
Т	MUD JOINTS	23	5-10%	40 JOINTS	ROOMS 1-7	(12) UNABLE TO LOCATE Y	1
М	9" VINYL FLOOR TILE (BEIGE MARBLED) & ADHESIVE	24	1-5%	8,100 S	SCIENCE LAB/STORAGE	(1) (5) MISSING TILES N	1
М	12" VINYL FLOOR TILE (TAN) & ADHESIVE	171	ASSUMED POSITIVE	8,000 S	ALL ROOMS EXCEPT SCIENCE LAB/STORAGE	(1) (4) N	1
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	500 S	THROUGHOUT	(1) (4) N	1

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: G (Gym)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88.	N/A
						ADDITIONAL SAMPLES HMS-93103- 03A-C COLLECTED ON 7-8-93.	
Т	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM AND BOILER ROOM CRAWL SPACES	(10) ISOLATED & RESTRICTED (11) INACCESSIBLE	Y
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	150 S	COACH OFFICE (GIRLS & BOYS)	(1) (4)	N
М	12" VINYL FLOOR TILE (RED, WHITE, AND BLACK) & ADHESIVE	264	ASSUMED POSITIVE	500 S	COACH OFFICE (GIRLS & BOYS)	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District Inspector:

School: Chico Senior High School

Building: IA

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	500 S	THROUGHOUT	(1) (4)	N
М	DRYWALL	257	ASSUMED POSITIVE	8,000 S	ROOMS 1, 2, 4, & 5	(1) (4)	N
М	12" VINYL FLOOR TILE (LIGHT GRAY MOTTLED) & ADHESIVE	261	ASSUMED POSITIVE	4,500 S	ROOMS 1, 4, & 5	(1) (4)	N
М	2'X4' CEILING PANELS - SOLID PATTERN	270	ASSUMED POSITIVE	4,500 S	THROUGHOUT, EXCEPT WOOD SHOP	(1) (4)	N
М	12" X 12" ACOUSTICAL CEILING TILE	505	ASSUMED POSITIVE	3,000 S	WOOD SHOP	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Senior High School

Building: AG-1100

Material Class	Material	Homo Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	46	1-5%	950 S	CLASSROOM 2	(1) (4)	N
М	WALL PLASTER	160	NONE DETECTED	150 S	SOUTH WEST CORNER AREA BY DOOR OF TOILET ROOM OF CLASSROOM 1	(13) SAMPLE HMS-R1303-15A COLLECTED ON 4-13-04.	N/A
S	STUCCO	161	NONE DETECTED	1,000 S	EXTERIOR SOUTH ENTRY DOOR AND EAST WALL BY COKE MACHINE	(13) SAMPLES HMS-R1303-16A & B COLLECTED ON 4-13-04.	N/A
М	LINOLEUM LIKE COUNTER TOP W/ASPHALT LIKE BACKING - GREEN	162	NONE DETECTED	100 S	CLASSROOM 3	(13) SAMPLE HMS-R1303-17A COLLECTED ON 4-13-04.	N/A
М	BROWN COLORED GLOSS LIKE FLOOR FINISH	163	NONE DETECTED	300 S	HALLWAY BY CLASSROOM 2	(13) SAMPLE HMS-R1303-13A COLLECTED ON 4-13-04.	N/A
М	GREEN COLORED GLOSS LIKE FLOOR FINISH	164	NONE DETECTED	50 S	TOILET ROOM OFF CLASSROOM 1	(13) SAMPLE HMS-R1303-14A COLLECTED ON 4-13-04.	N/A
М	12" X 12" TAN MOTTLED VINYL FLOOR TILE	506	ASSUMED POSITIVE	2,300 S	AG 1-2	(1)	N
М	VINYL BASE COVE ADHESIVE	507	ASSUMED POSITIVE	250 L	AG 1-2	(1)	N

М	GRAY SHEET VINYL FLOORING	508	ASSUMED POSITIVE	100 S	TOILET 987A AND RESTROOM	(1)	N	
---	------------------------------	-----	---------------------	-------	--------------------------	-----	---	--

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico HS\Chico HS 6 month.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected