District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: P (MPR)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	6,500 S	TEACHER'S DINING ROOM, MPR, AND REST OF THE WING	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	106	ASSUMED POSITIVE	5,000 S	THROUGHOUT UNIT - ALL WALLS, KITCHEN CEILING, AND FACULTY RESTROOMS	(1) (4)	N
М	NON-SLIP LINOLEUM (DARK GRAY) & ADHESIVE	107	ASSUMED POSITIVE	2,200 S	KITCHEN, KITCHEN OFFICE, AND JANITOR'S CLOSET	(1) (4)	N
М	12" VINYL FLOOR TILE (BLUE MOTTLED) & ADHESIVE	108	ASSUMED POSITIVE	5,570 S	MPR AND STAFF DINNING	(1) (4)	N
S	DRYWALL TEXTURE	109	ASSUMED	1,400 S	NURSE OFFICE, CONFERENCE ROOM, AND	(1) (4)	N
М	12" VINYL FLOOR TILE (GRAY/BLUE) & ADHESIVE	110	ASSUMED POSITIVE	200 S	NURSE OFFICE	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

Date of Inspection:

(12) Other (Explain under comments) (13) Non-Asb

(13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

Building: P (MPR) School: Chico Junior High School

(Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	SHEET VINYL FLOORING - (GRAY/ WHITE PEBBLED)	111	ASSUMED POSITIVE	50 S	NURSE RESTROOMS	(1) (4)	N
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	700 L	THROUGHOUT UNIT	(1) (4)	N
М	CARPET ADHESIVE	252	ASSUMED POSITIVE	500 S	NURSE OFFICE & CONFERENCE ROOM	(1) (4)	N
М	SINK UNDERCOATING	500	ASSUMED POSITIVE	5 S	STAFF DINING ROOM	(1)	N
S	STUCCO	254	ASSUMED POSITIVE	1,200 S	COVERED WALKWAY	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### **CONDITION CODE**

**General Condition:** (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

(7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Abated: (6) Repaired

Miscellaneous:

(11) Inaccessible, no inspection data

(13) Non-Asbestos/Not Inspected (12) Other (Explain under comments)

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: O (Classrooms 200, 202, 204, 206 & 208)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	500 S	TITLE ONE OFFICE	(1) (4) MINOR CRACKS IN THE MIDDLE	N
М	CEMENTITIOUS	96	ASSUMED	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	(1) (4) (11) TITLE ONE OFFICE COVERED WITH CARPET.	N
М	2' X 4' CEILING PANELS FISSURE PATTERN	99	ASSUMED POSITIVE	4,000 S	THROUGHOUT CLASSROOM WING	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOM WING	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL	255	ASSUMED POSITIVE	800 S	CLASSROOMS 202-208 AT LOWER WALLS	(1) APPEARS TO BE PAINTED WOOD PANELS. (12) FURTHER INVESTIGATION REQUIRED	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

**General Condition:** 

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Date of Inspection:

Change in Co	<u>naition:</u> (4) No	(5) YE	es (ii Yes, explain und	er comments) (1	13) Non-Aspestos/Not inspected	
Abated:	(6) Repaired	(7) Removed	(8) Encapsulated	(9) Enclosed	(10) Isolated & Restricted	
Miscellaneous	<u>s:</u>					
						(11) Inaccessible, no inspection data
					(12) Other (Explain under comments	s) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Junior High School

Building: O (Classrooms 200, 202, 204, 206 & 208)

(Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	SALT AND PEPPER EPOXY FLOORING	501	ASSUMED POSITIVE	500 S	TITLE 1 OFFICE	(1)	Ν
М	CARPET ADHESIVE	502	ASSUMED POSITIVE	200 S	RESTROOMS	(1)	N
М	DRYWALL AND JOINT COMPOUND	503	ASSUMED POSITIVE	1,500 S	RESTROOMS	(1)	N
S	KNOCKDOWN TEXTURE	504	ASSUMED POSITIVE	1, 500 S	RESTROOMS	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

General Condition: (1) Good (2) Damaged

(3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: N (Classrooms 300, 302, 304 & 306)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VINYL FLOOR TILE (RED) & ADHESIVE	2	1-5%	70 S	JANITOR'S CLOSET (ROOM 310)	(1) (4)	N
S	CEILING PLASTER	8	1-5%	200 S	JANITOR'S CLOSET (ROOM 310)	(1) (4)	N
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	2,000 S	CLASSROOMS 300, 302	(1) (4)	N
М	2' X 4' CEILING PANELS - FISSURE PATTERN	99	ASSUMED POSITIVE	4,000 S	THROUGHOUT CLASSROOMS AND SCIENCE PREP	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOMS & JANITOR CLOSET	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

Date of Inspection:

(12) Other (Explain under comments)	(13) Non-Asbestos/Not Inspected
-------------------------------------	---------------------------------

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: N (Classrooms 300, 302, 304 & 306)

(Continued)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAYS	(1) (4)	N
М	ADHESIVE ASSOCIATED WITH VINYL BASE COVE	506	ASSUMED POSITIVE	250 L	CLASSROOMS 304-306 AND SCIENCE PREP	(1)	N
S	KNOCKDOWN TEXTURE	507	ASSUMED POSITIVE	2,900	CLASSROOMS 304-06, SCIENCE PREP, AND GIRL'S RESTROOM	(1)	N
М	SALT AND PEPPER EPOXY FLOORING	505	ASSUMED POSITIVE	200 S	GIRL'S RESTROOM	(1)	N
М	DRYWALL	255	ASSUMED POSITIVE	2,900 S	CLASSROOMS 300-306, SCIENCE PREP, AND GIRL'S RESTROOM	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: M (Classrooms 400, 402, 404, 406 & 408)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	112	ASSUMED POSITIVE	175 S	PSYCHOLOGIST OFFICE & STAFF RESTROOM	(1) (4)	N
М	TRANSITE PANELS	113	ASSUMED POSITIVE	640 S	EXTERIOR	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	114	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	(1) NO LONGER COVERED WITH CARPET. IN GOOD CONDITION.  (1) (4)  (11) CLASSROOM 402 AND PSYCHOLOGIST OFFICE ARE COVERED WITH CARPET.	N
М	2' X 4' CEILING PANELS PINHOLE/GASH PATTERN	115	ASSUMED POSITIVE	4,000 S	ALL CLASSROOMS	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	600 S	THROUGHOUT CLASSROOMS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

Date of Inspection:

(12) Other (Explain under comments)	(13) Non-Asbestos/Not Inspected
-------------------------------------	---------------------------------

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Junior High School Building: M (Classrooms 400, 402, 404, 406 & 408)

(Continued)

Materia 1 Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F	Location	Condition: Code & Comments	Friabl e Yes / No
М	CARPET ADHESIVE	252	ASSUMED POSITIVE	450 S	PSYCHOLOGIST	(1) (4) CARPET REMOVED FROM ROOM 402.	N
М	SALT AND PEPPER EPOXY FLOORING	508	ASSUMED POSITIVE	400 S	STAFF AND BOYS RESTROOMS	(1)	N
S	KNOCKDOWN TEXTURE	509	ASSUMED POSITIVE	500 S	STAFF AND BOYS RESTROOMS	(1)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL AND JOINT	255	ASSUMED POSITIVE	1,500 S	CLASSROOMS 400-408 AT LOWER NORTH WALLS, STAFF AND BOYS RESTROOMS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: L (Classrooms 500, 502, 504 & 506)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VINYL FLOOR TILE	2	1-5%	70 S	MIGRANT EDUCATION OFFICE	(1) (4)	N
М	ADHESIVE ASSOCIATED WITH RED VINYL BASE COVE	509	ASSUMED POSITIVE	25 L	MIGRANT'S EDUCATION OFFICE	(1)	N
S	CEILING PLASTER	8	1-5%	100 S	MIGRANT EDUCATION OFFICE'S	(1) (4) REMOVED FROM GIRL'S RESTROOM	N
Т	PIPE WRAP STRAIGHT	26	40-45%	UNDETER-	CLASSROOM 502	(1) VISIBLE IN STORAGE @ MISSING 12"	Y
Т	PIPE WRAP STRAIGHT	95	ASSUMED POSITIVE	UNDETER- MINED	CLASSROOM 506	(11) UNABLE TO LOCATE MATERIAL	Υ
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	640 S	EXTERIOR OF UNIT	(1) (4)	N
М	12" VINYL FLOOR TILE (LIGHT GRAY /BEIGE) & ADHESIVE	98	ASSUMED POSITIVE	975 S	CLASSROOMS 500	(1) (4)	Ν
М	2' X 4' CEILING PANELS - FISSURE PATTERN	116	ASSUMED POSITIVE	975 S	CLASSROOM 500	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: L (Classrooms 500, 502, 504 & 506)

(Continued)

						,	· · · · · · · · · · · · · · · · · ·
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	100 L	CLASSROOM 500	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAYS	(1) (4)	N
М	DRYWALL AND JOINT COMPOUND	255	ASSUMED POSITIVE	3,000 S	ROOM 500 ATT LOWER NORTH WALLS ROOMS 502-506 AND GIRL'S AND STAFF RESTROOM	(1) (4)	N
S	KNOCKDOWN TEXTURE	510	ASSUMED POSITIVE	2,000 S	ROOMS 502-506 AND GIRL'S AND STAFF RESTROOMS	(1)	N
М	SALT AND PEPPER EPOXY FLOORING	511	ASSUMED POSITIVE	3,000 S	ROOMS 502-506 AND GIRLS AND STAFF RESTROOMS	(1)	N
М	12" ACOUSTIC CEILING TILE 256		ASSUMED POSITIVE	50 S	ROOM 502 STORAGE 2	(1)	
S	PLASTER	257	ASSUMED POSITIVE	300 S	ROOM 502 STORAGE 1 & 2	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

Building: J (Maintenance) School: Chico Junior High School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CARPET ADHESIVE	512	ASSUMED POSITIVE	25 S	MAINTENANCE	(1)	N
М	2' X 4' DROP-IN CEILING PANEL (PINHOLE/GASH)	513	ASSUMED POSITIVE	100 S	MAINTENANCE	(1)	N
Т	BOILER REFRACTORY	100	ASSUMED POSITIVE	UNDETERMINED	TWO BOILER UNITS	(7) REPLACED (1) (4)	Y

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### **CONDITION CODE**

**General Condition:** (2) Damaged (3) Significantly Damaged (25% or more) (1) Good Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

(13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

## **SIX MONTH SURVEILLANCE**

Date of Inspection:

## **HOMOGENEOUS ACBM MATERIAL RECORDS**

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: H & I (Classrooms 503 & 505)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" ACOUSTIC CEILING TILE	17	NONE DETECTED	4,300 S	WOOD SHOP, DURST THEATER, MUSIC CLASSROOM, & PRACTICE CLASSROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988. DURST THEATER & MUSIC CLASSROOM ARE SAME AREA	N/A
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	100 S	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	N
М	12" VINYL FLOOR TILE (CREAM) & ADHESIVE	97	ASSUMED POSITIVE	2,200 S	COMPUTER ROOM, MATERIAL STORAGE, STORAGE, & STAFF OFFICE, DURST THEATER, OFFICES, MUSIC CLASSROOM, AND PRACTICE CLASSROOMS 1-5	(1) (4) DURST THEATER & MUSIC CLASSROOM ARE SAME AREA	N
S	CEILING PLASTER	117	ASSUMED POSITIVE	700 S	OFFICES, STORAGE ROOMS, AND WOODSHOP CLASSROOM	(1) (4)	Z
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	200 S	CLASSROOM	(1) (4)	Ν
М	GRAY 12" X 12" VINYL FLOOR TILE	513	ASSUMED POSITIVE	120 S	OFFICE	(1)	Ν

S	STUCCO	254	ASSUMED POSITIVE	1,500 S	COVERED WALKWAY	(1) (4)	N
---	--------	-----	---------------------	---------	-----------------	---------	---

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: A (Main Office)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	2,500 S	LIBRARY	(1) (4)	N
М	12" VINYL FLOOR TILE (GRAY) & ADHESIVE	97	ASSUMED POSITIVE	600 S	ADMINISTRATION OFFICES, HALLWAY, AND LIBRARY	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	101	ASSUMED POSITIVE	14,100 S	THROUGHOUT UNIT AND LIBRARY	(1) (4) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000.	N
S	DRYWALL TEXTURE	118	ASSUMED POSITIVE	14,100 S	THROUGHOUT UNIT	(1) (4)	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	800 S	THROUGHOUT UNIT	(1) (4)	N
М	12" VINYL FLOOR TILE (DARK GRAY) & ADHESIVE	251	ASSUMED POSITIVE	100 S	ROOM 908	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscel	laneous:

(11) Inaccessible, no inspection data(13) Non-Asbestos/Not Inspected

(12) Other (Explain under comments)

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: A (Main Office)

(Continued)

Date of Inspection:

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	WHITE/BLUE PEBBLED SHEET VINYL FLOORING	514	ASSUMED POSITIVE	30 S	CONFERENCE ROOM RESTROOM	(1)	N
М	2' X 2' TAN/BROWN CARPET SQUARES AND ADHESIVE	515	ASSUMED POSITIVE	320 S	LIBRARY	(1)	N
М	2' X 2' GRAY VINYL FLOOR TILE	516	ASSUMED POSITIVE	750 S	LIBRARY AND LIBRARIANS OFFICE	(1)	N
М	CARPET ADHESIVE	252	ASSUMED POSITIVE	4,000 S	OFFICES & LIBRARY	(1) (4)	N
М	12" VINYL FLOOR TILE (LIGHT GRAY) & ADHESIVE	253	ASSUMED POSITIVE	700 S	HALLWAY	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: B (Classrooms 201-211)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	700 S	EXTERIOR OF UNIT AT WINDOWS	(1) (4)	N
М	2' X 4' CEILING PANELS - PINHOLE/GASH PATTERN	99	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VINYL FLOOR TILE (LIGHT GRAY) & ADHESIVE	102	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	BASE COVE ADHESIVE	250	ASSUMED POSITIVE	720 S	THROUGHOUT CLASSROOMS	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL	255	ASSUMED POSITIVE	2,000 S	CLASSROOMS AT LOWER NORTH WALLS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Junior High School

Building: C (Classrooms 301-311)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	CEMENTITIOUS TRANSITE PANELS	96	ASSUMED POSITIVE	700 S	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' CEILING PANELS - PINHOLE/GASH PATTERN	99	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VINYL FLOOR TILE (LIGHT GREY MOTTLED) & ADHESIVE	103	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	720 S	THROUGHOUT CLASSROOMS	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
M	DRYWALL	255	ASSUMED POSITIVE	2,000 S	CLASSROOMS AT LOWER NORTH WALLS	(7) REMOVED PRIOR TO INSPECTION.  DRYWALL NOT VISIBLE. DRYWALL  POTENTIALLY BEHIND PRESSED  WOOD.	N
М	PRESSED WOOD	517	ASSUMED POSITIVE	2,000 S	CLASSROOMS AT LOWER NORTH WALLS	(1)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District

Inspector:

School: Chico Junior High School

Building: D (Classrooms 401, 403, 405, 407 & 409)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	TRANSITE PANELS	96	ASSUMED POSITIVE	700 S	EXTERIOR OF UNIT	(1) (4)	N
М	2' X 4' CEILING PANELS PINHOLE/GASH PATTERN	99	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	12" VINYL FLOOR TILE (LIGHT GREY MOTTLED) & ADHESIVE	103	ASSUMED POSITIVE	4,800 S	THROUGHOUT CLASSROOMS	(1) (4) RENOVATED DURING THE SUMMER OF 2000.	N
М	COVE BASE ADHESIVE	250	ASSUMED POSITIVE	650 S	THROUGHOUT CLASSROOMS	(1) (4)	N
М	GRAY/BLUE PEBBLED SHEET VINYL FLOORING	516	ASSUMED POSITIVE	130 S	CUSTODIAL CLOSET	(1)	N
S	STUCCO	254	ASSUMED POSITIVE	250 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL	255	ASSUMED POSITIVE	1,800 S	CLASSROOMS AT LOWER NORTH WALLS AND CUSTODIAL CLOSET	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

**CONDITION CODE** 

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: E (Gymnasium)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	12" CEILING TILE	119	ASSUMED POSITIVE	5,000 S	GYM	(1) (4)	N
S	STUCCO	254	ASSUMED POSITIVE	2,200 S	CORRIDOR	(1) (4)	N
S	TEXTURE ON CONCRETE & PLASTER WALLS	300	ASSUMED POSITIVE	1,800 S	COVERED WALKWAY	(1) (4)	N
М	DRYWALL & JOINT COMPOUND	301	ASSUMED POSITIVE	400 S	RESTROOMS	(1) (4)	N
S	TEXTURE ON DRYWALL	302	ASSUMED POSITIVE	400 S	RESTROOMS	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

Date of Inspection:

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPP	I FMFNTARY INSPECT	ION REPORTS FOR MA	TERIALS WITH TRACE A	MOUNTS OF ASBESTOS
SONOGET ORIGINAL AND COLL	ELMENTANT INOI EOTI	ON REI ONTO I ON MA	TENIALS WITH TRACE A	MICONTO CI AGBESTOS

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: F (Locker Rooms)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
М	9" VINYL FLOOR TILE (GREEN) & ADHESIVE	5	1-5%	UNDETER-	CLASSROOM 18 STORAGE	(12) GIRL'S LOCKER ROOM	N
Т	PIPE WRAP	105	ASSUMED	UNDETER-	IN CEILING PIPE CHASE	(10)	Y
М	12" X 12" VINYL FLOOR	217	ASSUMED	50 S	OFFICE OF GIRL'S LOCKER ROOM	(1)	N
S	STUCCO	254	ASSUMED	800 S	COVERED WALKWAY	(1) (4)	N
S	PLASTER	260	ASSUMED POSITIVE	5,000 S	THROUGHOUT UNIT	(1) (4)	Z

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

#### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection:

District: Chico Unified School District Inspector:

School: Chico Junior High School

Building: Q (Main Corridor)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	PLASTER	8	1-5%	10,000 S	CEILINGS & WALLS	(1) (4)	N
М	12" VINYL FLOOR TILE	97	ASSUMED	500 S	THROUGHOUT CORRIDOR AT BORDERS	(1) (4)	N
М	12" VINYL FLOOR TILE (LIGHT GRAY) & ADHESIVE	253	ASSUMED POSITIVE	3,000 S	THROUGHOUT CORRIDOR	(1) (4)	N
М	COVE BASE ADHESIVE	261	ASSUMED POSITIVE	1,000 S	THROUGHOUT CORRIDOR	(1) (4)	N

Z:\Clients\Chico USD\16-4066 3 Year Reinspections\Sites\Chico JHS\Chico JHS- 6 Month.wpd

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments) (13) Non-As

(13) Non-Asbestos/Not Inspected