District: Chico Unified School District

Inspector: Leroy Christophersen

School: Partridge Elementary School Units: C, D & E

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	4	1-5%	9,000 S	ALL ROOMS	(1) (4)	N
S	AC PLASTER	5	1-5%	3,488 S	ALL ROOMS (1) (4)		N
Т	LARGE MUD JOINT	6	ASSUMED	22 JOINTS	BOILER ROOM	(1) (4)	N
Т	SMALL MUD JOINT	7	ASSUMED	26 JOINTS	BOILER ROOM	(1) (4)	N
М	TRANSITE PANELS	60	ASSUMED	8 PANELS	UNDER ENTRY WINDOWS	(1) (4)	N

Unit: G

Date of Inspection: 06/02/2005

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	4	1-5%	2,800 S	ALL CLASSROOMS	(1) (4)	N
S	PLASTER	5	1-5%	1,600 S	ALL CLASSROOMS, BOTH RESTROOMS, AND CUSTODIAN	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Inspector: Leroy Christophersen

School: Partridge Elementary School

Unit: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	PIPE WRAP STRAIGHT	3	70-75%	150 L	KITCHEN, WATER HEATER ROOM, AND MULTI- PURPOSE ROOM STORAGE	(1) (4) NEEDS SIGNAGE	N
М	9" VFT	4	1-5%	6,000 S	ENTIRE WING	(1) (4)	
S	AC PLASTER	5	1-5%	1,400 S	HALLWAY OUTSIDE MULTI-PURPOSE ROOM	(1) (4)	N
Т	MUD JOINT	7	ASSUMED	4 JOINTS	KITCHEN (BY DISHWASHER)	(1) (4)	N
М	TRANSITE PIPE	99	ASSUMED	6 L	KITCHEN WATER HEATER ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

District: Chico Unified School District

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Partridge Elementary School

Units H, I & J

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	n: Code & Comments	Friable Yes/No
М	LINOLEUM BEIGE	10	NONE DETECTED	200 S	GIRL S & BOY S RESTROOMS	(13)	SAMPLE HMS-PAR-08 COLLECTED ON 3-30-88.	N/A
М	2' X 8' ACT	50	ASSUMED	480 S	SFA TRAILER & SPEECH TRAILER	(1) (4)	WOOD - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
М	2' X 4' FCP S	65	NONE DETECTED	900 S	LIBRARY, COMPUTER ROOM, AND ROOMS 15-17	(13)	SAMPLE HMS-CUSD-PART-200A COLLECTED 4-11-95.	N/A
М	DRYWALL	66	NONE DETECTED	400 S	COMPUTER ROOM	(13)	SAMPLE HMS-CUSD-PART-201A COLLECTED 4-11-95.	N/A
М	12" VFT WHITE	103	ASSUMED	600 S	ROOMS 15-17	(1) (4)		N

School: Partridge Elementary School Building: Portables 18 & 19

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location Condition: Code & Comments		Friable Yes/No
М	12" VFT	51	ASSUMED	300 S	PORTABLES 18 & 19	(1) (4)	N
М	2' X 4' FCP S	52	ASSUMED	1,000 S	PORTABLES 18 & 19	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Partridge Elementary School Building: Portables 1, 2, & 20

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP S	53	ASSUMED	600 S	PORTABLE #1	(1) (4)	N
М	2' X 4' FCP S	54	ASSUMED	600 S	PORTABLE #20	(1) (4) FIBERGLASS - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
М	2' X 4' FCP S	55	ASSUMED	600 S	ROOM #2	(12) CANNOT FIND	N
М	12" VFT	61	ASSUMED	600 S	PORTABLE #1	(2) (4) SLIGHT CRACKS AT ENTRY WAY.	N
М	12" VFT	62	ASSUMED	600 S	PORTABLE #20	(1) (4)	N
М	9" VFT	63	ASSUMED	200 S	ROOM #2	(1) (4)	N
М	LINOLEUM TAN	100	ASSUMED	60 S	STORAGE AND GIRL S & BOY S RESTROOMS	(1) (4)	N
М	GYPSUM BOARD	101	ASSUMED	300 S	STORAGE AND GIRL S & BOY S RESTROOMS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/02/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Fair View High School - (Formerly Jay Partridge Elementary School)

1 1.4 14 4 4	\sim	-0	
Units:		D 8	

Date of Inspection: __12/27/2005_

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	4	1-5%	9,000 S	ALL ROOMS	(1) (4)	N
S	AC PLASTER	5	1-5%	3,488 S	ALL ROOMS	(1) (4)	N
Т	LARGE MUD JOINT	6	ASSUMED	22 JOINTS	BOILER ROOM	(1) (4)	N
Т	SMALL MUD JOINT	7	ASSUMED	26 JOINTS	BOILER ROOM	(1) (4)	N
М	TRANSITE PANELS	60	ASSUMED	8 PANELS	UNDER ENTRY WINDOWS	(1) (4)	N

Unit: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	4	1-5%	2,800 S	ALL CLASSROOMS	(1) (4)	N
S	PLASTER	5	1-5%	1,600 S	ALL CLASSROOMS, BOTH RESTROOMS, AND CUSTODIAN ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District Inspector: Leroy Christophersen

School: Fair View High School - (Formerly Jay Partridge Elementary School)

llس	.:4.	_
ıır		

Date of Inspection: 12/27/2005

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Т	PIPE WRAP STRAIGHT	3	70-75%	150 L	KITCHEN, WATER HEATER ROOM, AND MULTI- PURPOSE ROOM STORAGE	(1) (4)	N
М	9" VFT	4	1-5%	6,000 S	ENTIRE WING	(1) (4)	N
S	AC PLASTER	5	1-5%	1,400 S	HALLWAY OUTSIDE MULTI-PURPOSE ROOM	(1) (4)	N
Т	MUD JOINT	7	ASSUMED	4 JOINTS	KITCHEN (BY DISHWASHER)	(1) (4)	N
М	TRANSITE PIPE	99	ASSUMED	6 L	KITCHEN WATER HEATER ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Fair View High School - (Formerly Jay Partridge Elementary School)

Units H, I & J

Date of Inspection: __12/27/2005_

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	n: Code & Comments	Friable Yes/No
М	LINOLEUM BEIGE	10	NONE DETECTED	200 S	GIRL'S & BOY'S RESTROOMS	(13)	SAMPLE HMS-PAR-08 COLLECTED ON 3-30-88.	N/A
М	2' X 8' ACT	50	ASSUMED	480 S	SFA TRAILER & SPEECH TRAILER	(1) (4)	WOOD - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
М	2' X 4' FCP'S	65	NONE DETECTED	900 S	COMPUTER LAB & OFFICE (FKA LIBRARY & COMPUTER ROOM) AND ROOMS 15-17	(13)	SAMPLE HMS-CUSD-PART-200A COLLECTED 4-11-95.	N/A
М	DRYWALL	66	NONE DETECTED	400 S	OFFICE (FKA COMPUTER ROOM)	(13)	SAMPLE HMS-CUSD-PART-201A COLLECTED 4-11-95.	N/A
М	12" VFT WHITE	103	ASSUMED	600 S	ROOMS 15-17	(1) (4)		N

Building: Portables 18 & 19

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	51	ASSUMED	300 S	PORTABLES 18 & 19	(1) (4)	N
М	2' X 4' FCP'S	52	ASSUMED	1,000 S	PORTABLES 18 & 19	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Inspector: Leroy Christophersen District: Chico Unified School District

School: Fair View High School - (Formerly Jay Partridge Elementary School) Building: Portable							
Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	53	ASSUMED	600 S	PORTABLE #1	(1) (4)	N
М	2' X 4' FCP'S	54	ASSUMED	600 S	PORTABLE #20	(1) (4) FIBERGLASS - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
М	2' X 4' FCP'S	55	ASSUMED	600 S	ROOM #2	(12) CANNOT FIND	N
М	12" VFT	61	ASSUMED	600 S	PORTABLE #1	(2) (4) SLIGHT CRACKS AT ENTRY WAY.	N
М	12" VFT	62	ASSUMED	600 S	PORTABLE #20	(1) (4)	N
М	9" VFT	63	ASSUMED	200 S	ROOM #2	(1) (4)	N
М	LINOLEUM TAN	100	ASSUMED	60 S	STORAGE AND GIRL'S & BOY'S RESTROOMS	(1) (4)	N
М	GYPSUM	101	ASSUMED	300 S	STORAGE AND GIRL'S & BOY'S RESTROOMS	(1) (4)	N

CONDITION CODE

General Condition: (2) Damaged (3) Significantly Damaged (25% or more) (1) Good

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

BOARD

(7) Removed (8) Encapsulated Abated: (6) Repaired (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: __12/27/2005_





Chica Unified School Dist

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Officed School Dist					Client ID:	2921		
Leroy Christophersen					Report Num	ber: B0738	306	
					Date Receive	ed: 06/08/	05	
2455 Carmichael Drive						ed: 06/08/	06/08/05	
Chico, CA 95928					Date Printed	l: 06/09/	05	
					First Report	ed: 06/09/	05	
Job ID/Site: Jay Partridge - Sc	hool Closure - PO# 05028	39	-		FASI Job ID	2921-	85	
Data(s) Callasted: 06/07/2005					Total Sample	es Submitted	: 2	
Date(s) Collected: 06/07/2005			-		Total Sample	es Analyzed:	2	
Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	
JP1	10421182							
Layer: Black Tar			ND			-		
Layer: Black Felt			ND (V	/		-		
Total Composite Values of Fil	orous Components: A	sbestos (ND)	Spring Commence					

TD4

10421183

Layer: White Drywall

ND

Layer: Off-White Skimcoat/Joint Compound

ND

Total Composite Values of Fibrous Components:

Asbestos (ND)

lulose (20 %)

Jin Hors

C. askertus birders

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'. ytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, re or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) upporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is soic..., responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

5 Forensic Analy	rtical	29	21-8	5	· Aı	nalvsis F	Request	Form				
Client Name & Address	P.O. #: 050289 Pate: /al @ 1000											
Chico Unified Sc	011103											
2455 Carmichael	2455 Carmichael Drive					Turn Around Time:hr/ 12hr / 24hr / 48 hr / ext:						
Chico, CA 95928	Chico, CA 95928					PLM: Standard / Point Count PCM: NIOSH 7400						
Leron			TEM Air: AHERA / Yamate2 / NIOSH 7402									
Phone #:	2100		☐ TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield ☐ TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Wt %									
530 - 89(-			☐ TEM Microvac ☐ Special Project:									
(530) 891-33 Site:	190		☐ Metals Analysis: Method									
Job: Tay Partie	dge		Matrix:	Anaiysis: Me	thod							
School C	(seus o		Analytes:									
Comments:	921000		Analytes.									
Sample ID	Date/ Time	Sample Location/Des	scription		FOR AIR SA ime On/Off	MPLES ONLY Avg. LPM	Total	Sample Area or Air				
JPI	6/7 F	ortable I Felt p Green paper i	aper	AP		·	Time	Volume				
	61			A	77							
JP2	6/7 6	Green paper u	vallboas	A C		*						
		• •		A _P	•							
	<u> </u>											
				P _C								
			-	A								
			· · · · · · · · · · · · · · · · · · ·	C A								
				Р —								
,				A _P								
<u> </u>				A C								
				P C								
				C C	*******							
Sampled by: Mike	weils	to Witczek	Date:		105	Time:	:					
Shipped via: Fed Ex	☐ Airborne	UPS USM	— lail □ Co		Orop Off (☑ Other:		-				
Relinquished by:			Relinquis									
Date / Time:		Date / Time:										
Received by: WINEA		Received by:										
Date / Time:			Date / Time:									
Condition Acceptable? 20 Ye	le? 🛘 Yes	□ No	No Condition Acceptable? Yes No									

Maintenance and Operations 2455 Carmichael Drive Chico, CA 95928 Phone: (530) 891-3195 Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 0827

June 7, 2005

Forensic Analytical Specialties, Inc. 3777 Depot Road, Suite 409 Hayward, CA 94545

Re: Jay Partridge Elementary School

To Whom It May Concern:

Please test the enclosed samples from Jay Partridge Elementary School Room 1 and Room 2 for asbestos. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled:

Jay Partridge Elementary School

Location:

Portable 1 - Felt Paper

Date Sampled:

June 7, 2005

Number of Samples:

One (#JP1)

Location:

Portable 2 - Green Paper Wallboard

Date Sampled:

Berry Christopheisen

June 7, 2005

Number of Samples:

One (#JP2)

Thank you for your prompt response to this request.

Sincerely,

Leroy Christophersen

Safety & Loss Coordinator

LC:dlg

Enclosures (2)