

July 31, 2007

Mr. Leroy A. Christophersen, PHR Safety & Loss Control Coordinator Chico Unified School District 2455 Carmichael Drive Chico, CA 95928

RE:

Triennial AHERA Three-Year Reinspection

Dear Mr. Christophersen:

Enclosed is the data obtained from the AHERA Three-Year Reinspections Entek Consulting Group (Entek) conducted between April 11, 2007 and May 10, 2007. The documents included with this letter are the "Three-Year Reinspection Homogeneous ACBM Material Records" covering all buildings known from the original inspection to contain ACBM. The sites inspected were Academy for Change, Bidwell Junior High, Chapman Elementary, Chico Country Day, Chico Junior High School, Chico Senior High School, Citrus Elementary, Cohasset Elementary, Corporation Yard, District Office, Fair View High School, Hooker Oak Elementary, Loma Vista Elementary, Marigold Elementary, McManus Elementary, Neal Dow Elementary, Nord Elementary, Parkview Elementary, Pleasant Valley High School, Rosedale Elementary, Shasta Elementary, and Sierra View Elementary Schools. These are also provided on the enclosed diskette as per our contract. In an effort to assist with your Six-Month Surveillances, Entek has included on the CD blank forms with the current data from the Three-Year Reinspections.

Fax (916) 632-6812

You should review the updated Homogeneous Materials Reports to familiarize yourself with the current status of asbestos containing materials and identified suspect asbestos materials. It is the District's responsibility to assure that the school's site copy of the Management Plan is up to date and consistent with the District's Management Plan for that site. This is very important, and if not done can cause the District to be penalized during an EPA site visit or investigation.

Entek wants to remind you that materials containing "trace" amounts of asbestos must be considered in the event of renovations or demolitions. Although building materials containing trace amounts of asbestos (<1%) are not regulated under EPA, Cal/OSHA does regulate work practices with materials containing 0.1% asbestos. The original AHERA inspection contains information regarding materials with trace amounts of asbestos.

Entek collected two (2) asbestos bulk samples during the reinspections. One sample was collected at Loma Vista Elementary School and one at Chico High School. See the results of each sample in the following tables.

Loma Vista Elementary School; Unit A, North Building

Suspe	ct Materials Found or A	Assumed TO Contain >1% Asbestos Cor	ntent (RACM)
Material	Asbestos Content	Location	Entek Sample Number
White 12" Floor Tile	1-5% Chrysotile	South East Corner of Room 16 Near Room 13	ECG-07-465-01A

Su	spect Materials Fo	und NOT TO Contain Asbestos or Considered N	on-Suspect
Material	Asbestos Content	Location	Entek Sample Number
Yellow Mastic	None Detected	South East Corner of Room 16 Near Room 13	ECG-07-465-01A

ASBESTOS LEAD MOLD INDOOR AIR QUALITY NOISE MONITORING TRAINING HEALTH AND SAFETY AUDITS



Mr. Leroy A. Christophersen, PHR Safety & Loss Control Coordinator Chico Unified School District July 31, 2007 Page Two

Chico High School, Building LH-800, MPR

Suspect Materials Fo	und NOT TO Conta	in Asbestos or Considered N	Non-Suspect
Material	Asbestos Content	Location	Entek Sample Number
White Linoleum on Columns	None Detected	Building LH-800, MPR	ECG-07-465-02A
Yellow Mastic	None Detected	Building LH-800, MPR	ECG-07-465-02A

When you provide your annual notification to parents and staff, include information regarding this three-year reinspection. Enclosed is a suggested format for your notification letter. Please note that you must include in your Management Plans a description of the steps you take to notify. It is also important that your Management Plans be updated after any and all actions conducted which impact asbestos containing materials.

Please remember that Entek did not inspect new buildings or portable classrooms which were placed on the District sites since the original EPA AHERA inspection. It is the District's responsibility to obtain letters of certification from the Architect, Construction Superintendent, or manufacturer of new building materials, indicating there is no asbestos in the new buildings (constructed after October 12, 1988) or new building materials. A copy of these certification letters must be included in your Management Plans, both at the school site and at the LEA Designees office site. It is still required of School Districts to send a copy of these certification letters to the US EPA AHERA unit; Region IX in San Francisco.

It is not necessary to send a copy of the three-year reinspection to the OPSC or EPA. However, the report should be included in your Management Plan. I want to thank you for your cooperation. If you have any questions, please feel free to contact me at (916) 632-6800.

Sincerely,

William Esparza

Certified Asbestos Consultant

William Esparzatz

DOSH #99-2579

Enclosures

Z:\Shannon\3-YEAR REINSPECTIONS\Chico USD\2007\Final.Ltr7-31-07.wpd

Below is a suggested letter to district personnel, building occupants, and parents that meets the AHERA requirement of annual notification. Regardless of the notification letter used, a signed and dated copy should be included in the Management Plan. The AHERA designee must also include in the Management Plan a brief statement describing the steps taken to notify. Include the date(s) of the six-month surveillances, and include any other actions taken with regards to asbestos.

Date:			
То:	Parents, PTA, Teachers, Maintenance, Staff		
From:	AHERA Designee		
RE:	Asbestos Hazard Emergency Response Act (AHERA) Asbestos Inspections and Management Plans.		
required three-y reinspections for Country Day, Ch Elementary, Co Loma Vista Ele Nord Elementar Shasta Elemen 2007 and May	chool District has hired Entek Consulting Group, Inc. (Entek), to complete the ear reinspection of all asbestos-containing building materials in the District. The or Academy for Change, Bidwell Junior High, Chapman Elementary, Chico nico Junior High School, Chico Senior High School, Citrus Elementary, Cohasset reporation Yard, District Office, Fair View High School, Hooker Oak Elementary, mentary, Marigold Elementary, McManus Elementary, Neal Dow Elementary, y, Parkview Elementary, Pleasant Valley High School, Rosedale Elementary, tary, and Sierra View Elementary Schools were completed between April 11, 10, 2007 by an accredited inspector, and the reinspection data has been of the Management Plan.		
Also, during the Plan.	past year the District has performed the required six-month surveillances on This information is also incorporated into the Management		
A copy of the District's Management Plan is available for review during normal office hours in the office of the If copies of the plan are desired, a nominal duplicating fee may be charged.			
Authorized Sign	ature		
Date			

State of California Division of Occupational Safety and Health

Certified Asbestos Consultant

William Esparza

Name

Certification No. 99–2579

05/03/08

Expires on.

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code



COE E GENTER FOR OCCUPATIONAL

8 ENVIRONMENTAL HEALTH

SANDERS IN THE SELECTION OF THE SELECTIO

University of California Berkeley

This certifies that

William Esparza

has attended the eight hour course

AHERA Refresher for Asbestos Inspectors & Management

February 5, 2007

and has completed the requisite training for asbestos accreditation under TSCA Title II

Planners

Course Date

Barbara (Blog

COEH Director

god R. Blu-

Date of Exam: February 5, 2007

Expiration Date: February 5, 2008

Continuing Education Director

Cal/OSHA Approval Number: CA-002-06 / CA-002-08

Fax: (510) 643-7291 Center for Occupational and Environmental Health Continuing Education Program UC Berkeley Mailcode 5120, 2223 Fulton Street, 2nd Floor, Berkeley, CA 94720-5120 Ph. (510) 643-7277 ASBESTECH 6825 Fair Oaks Blvd., Suite 103 Carmichael, California 95608 Tel.(916) 481-8902 Fax (916) 481-3975

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

07-465 Chico USD Loma Vista Elementary Unit A, North Bldg., Chico, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 50277

Date/Time Collected: 5/10/07 Date Received: 5/21/07 NVLAP # 101442 DOHS # 1153

Date Analyzed: 5/22/07

Sample No.

Color/Description

% Type Asbestos

Other Materials

ECG-07-465-

01A

White 12" floor tile, SE corner of room

1-5 CHRYSOTILE

Granular Mins.

16 near room 13

Yellow mastic

LABORATORY DIRECTOR: TOM CONLON

NONE DETECTED

Synthetics

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)(2)(A), THE MCL IS 1 %. SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.

NVLAP

ANALYST: JIM JUNGLES

Jun John

50277

BULK ASBESTOS MATERIAL Analysis Request Form for Entek Consulting Group, Inc.

4200 ROCKLIN ROAD, STE. 7 ROCKLIN, CA 95677 (916) 632-6800 FAX (916) 632-6812

JOB I.D.: 07-465

CLIENT: Chico Unified School District

COLLECTED BY: William Esparza

DATE COLLECTED: 05/10/07

DATE SUBMITTED: 05/21/07

LAB SUBMITTED TO: Asbestech

SPECIAL INSTRUCTIONS:

ANALYSIS REQUESTED: PLM with Dispersion Staining

TURNAROUND TIME: 24 Hours

JOB SITE:

Loma Vista Elementary School

Unit A (North Building) 2404 Marigold Avenue, Chico, California 95926

SAMPLE#	MATERIAL DESCRIPTION/LOCATION
ECG-07-465-01A	12" Floor Tile and Mastic, SE Corner of Room 16, Near Room 13

C:\Entek\Clients\Chico USD\07-465 Chico 3 Year Inspections\Bulk Asbestos Request 05-10-07.wpd

DELIVERED BY: MAINING MANNEY DATE: 5-21-0)

RECEIVED BY: DATE: 5/21/7

ASBESTECH 6825 Fair Oaks Blvd., Suite 103 Carmichael, California 95608 Tel.(916) 481-8902 Fax (916) 481-3975

Client:

Entek Consulting Group, Inc. 4200 Rocklin Rd., Suite 7 Rocklin, CA 95677

Job:

07-465 Chico USD Chico HS, Bldg. LH-800, MPR Chico, Ca

BULK ASBESTOS ANALYSIS REPORT

LAB JOB # 50276

Date/Time Collected: 5/11/07 Date Received: 5/21/07 NVLAP # 101442 DOHS # 1153

Date Analyzed: 5/22/07

Sample No.

Color/Description

% Type Asbestos

Other Materials

ECG-07-465-

02A

White linoleum on columns

LABORATORY DIRECTOR: TOM CONLON

NONE DETECTED

Vinyl Cellulose

Yellow mastic

NONE DETECTED

Synthetics

THE ANALYSIS USES POLARIZED LIGHT MICROSCOPY AND DISPERSION STAINING FOLLOWING E.P.A. METHOD 600/R-93/116. NON-FRIABLE MATERIALS WERE ANALYZED APPLYING THE SAME METHOD. THE LOWER DETECTION LIMIT IS <1 % WITH THE PROVISO THAT PLM MAY NOT DETECT FIBERS <0.25 MICRONS IN DIAMETER THAT MAY BE PRESENT IN SAMPLES SUCH AS FLOOR TILES. IN ACCORDANCE WITH TITLE 22, CCR, SECTION 66261.24(a)/(2)/(A), THE MCL IS 1 % SAMPLES WERE NOT COLLECTED BY ASBESTECH. THIS REPORT MUST NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE APPROVAL OF ASBESTECH. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT MUST NOT BE USED TO CLAIM PRODUCT ENDORSEMENT BY N.V.L.A.P. OR ANY AGENCY OF THE U.S. GOVERNMENT. ASBESTECH ACCEPTS TECHNICAL RESPONSIBILITY FOR THIS REPORT AND DATE OF ISSUE.

NVLAP

ANALYST: JIM JUNGLE

es Jon Jalie

50276

BULK ASBESTOS MATERIAL Analysis Request Form for Entek Consulting Group, Inc.

4200 ROCKLIN ROAD, STE. 7 ROCKLIN, CA 95677 (916) 632-6800 FAX (916) 632-6812

JOB I.D.: 07-465

CLIENT: Chico Unified School District

COLLECTED BY: William Esparza

DATE COLLECTED: 05/11/07

DATE SUBMITTED: 05/21/07

LAB SUBMITTED TO: Asbestech

SPECIAL INSTRUCTIONS:

ANALYSIS REQUESTED; PLM with Dispersion Staining

TURNAROUND TIME: 24 Hours

JOB SITE:

Chico Senior High School

Building LH-800, Multi-Purpose Room

901 The Esplanade, Chico, California 95926

SAMPLE#	MATERIAL DESCRIPTION/LOCATION
ECG-07-465-02A	Linoleum on Columns

C:\Entek\Clients\Chico USD\07-465 Chico 3 Year Inspections\Bulk Asbestos Request 05-11-07.wpd

RECEIVED BY: MANISM WARMON DATE: 521-07

RECEIVED BY: DATE: 5/2/7 1/072

Page 1 of 1

RECORD OF FRIABLE AND NON-FRIABLE ACM (FORM B)

Inspection Date(s) May 10, 2007

THREE-YEAR REINSPECTION

		TITALE TEXAS	KEMOI EOMON		
				CDS CODE 04-61424-6003016	
SCHOOL Fair View High Schoo	I (FKA Partridge El	ementary School)		SCHOOL PHONE NUMBER (530) 891-3124	
ADDRESS 290 East Avenue	(NUMBER)	(STREET)	(CITY) Chico, CA	(ZIP) 95973	

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of <u>FORM C</u> (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

		CHI	ECK O	ΝE		CHEC	K ONE	
LINE	BUILDING NAME & FUNCTIONAL SPACE	SUR-			AC	вм	. ASSUME	D ACBM
	(Indicate Address if Different From Above)	FACING	TSI	MISC	FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1	UNIT A			Х				Х
2.	UNIT B			Х				Х
3.	UNIT C (FKA A)	Х		Х		X		X
4.	UNIT D	х	Х					X
5.	UNIT E	х		Х				X
6.	UNIT F (FKA C)	х	X	Х		Х		X
7.	UNIT G (FKA B)	х		Х		Х		X
8.	UNIT H (FKA D)			Х				X
9.	UNIT I (FKA D)			Х				X
10	UNIT J			Х				X
11.	UNIT K			Х				X
12.	UNIT L			Х				X
13.				٠	1,			
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

Z:\Shannon\3-YEAR REINSPECTIONS\Chico USD\2007\Fair View HS (FKA Partridge)\FormB.wpd

Date of Inspection: May 10, 2007

Inspector: William Esparza

School: Fair View High School (FKA Partridge Elementary School)

District: Chico Unified School District

Building: C - Classrooms 3-6 (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
N	9" VFT	4	1-5%	4,500 S	4,500 S CLASSROOMS 3-6 AND STAFF ROOM	(1) (4)	Z
S	ACOUSTIC CEILING PLASTER	5	1-5%	5,000 S	5,000 S CLASSROOMS 3-6 AND STAFF ROOM	(1)	z
Σ	TRANSITE PANELS	09	ASSUMED	8 PANELS	8 PANELS UNDER ENTRY WINDOWS, UNIT D	(2)	N/A

CONDITION CODE

General Condition: Change in Condition:	(1) Good (4) No	(2) Damaged (5) Yes (If Yes,	ige (Sir
Abated:	(6) Kepaired	(/) Kemoved	ğ
Miscellaneous:	(11) Inaccessi	(11) Inaccessible, no inspection data	data (12) Other (Explain under comm

Date of Inspection: May 10, 2007

Inspector: William Esparza

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Building: D - Restrooms & Custodial Room (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	ACOUSTIC CEILING PLASTER	. 5	1-5%	1,000 \$	1,000 S RESTROOMS, CUSTODIAL ROOMS, AND BOILER ROOM	(1)	Z
⊢	LARGE MUD JOINT	9	ASSUMED	22	BOILER ROOM	(1) (4)	z
⊢	SMALL MUD JOINT	2	ASSUMED	26 JOINTS	BOILER ROOM	(1) (4)	z
ဟ	WALL PLASTER	31	ASSUMED	400 S	400 S RESTROOMS	(1)	z

CONDITION CODE

(2)
(1) Good
General Condition:

Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (4) No (5) Yes (If Yes, explain under comments) (6) Repaired (7) Removed (8) Encapsulated (11) Inaccessible, no inspection data (12) Other (Exp

Miscellaneous:

Abated:

District: Chico Unified School District

Date of Inspection: May 10, 2007

Inspector: William Esparza

School: Fair View High School (FKA Partridge Elementary School)

Building: E - Classrooms 7-10 (FKA A)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT BEIGE	4	1-5%	4,500 S	4,500 S CLASSROOMS 7-10, WORK ROOM AND STAFF RESTROOMS	(1) (4)	z
ω	ACOUSTIC CEILING PLASTER	5	1-5%	5,000 S	5,000 S CLASSROOMS 7-10, WORK ROOM, AND STAFF (1) (4) RESTROOMS	(1) (4)	z

CONDITION CODE

(1) Good (4) No (6) Repaired Change in Condition: General Condition:

Miscellaneous:

Abated:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (10)

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

ZNShamonis-YEAR REINSPECTIONSIChico USD2007/Fair View HS (FKA Partridge)NHMR wpd

District: Chico Unified School District

Inspector: William Esparza

Date of Inspection: May 10, 2007

School: Fair View High School (FKA Partridge Elementary School)

Building: G - Classrooms 11-14 (FKA B)

Friable Yes/No	z	N/N	Z
Condition: Code & Comments	(1) (4) (6) ROOM 13 REPAIRED 2/00 WORK ORDER NUMBER E23746.	(4) CUSTODIAL ROOM.	
Ö	(1)	(1) (4) (7)	(1)
Location	CLASSROOMS 11-14	ALL CLASSROOMS AND BOTH RESTROOMS	CUSTODIAL ROOM AND RESTROOMS
Ft²/L.F.	4,500 S	5,000 S	1,200 S
% Asb.	1-5%	1-5%	ASSUMED
Homo. Mat. #	4	S.	31
Material	9" VFT	ACOUSTIC CEILING PLASTER	WALL PLASTER
Material Class	Σ	S	S

CONDITION CODE

(4) No (6) Repaired (1) Good Change in Condition: General Condition: Miscellaneous: Abated:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS
Z.IShannoni3-YEAR REINSPECTIONSICHIGO USDIZOOT/Fair View HS (FKA Partridge)/HMR.wpd

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Date of Inspection: May 10, 2007

Inspector: William Esparza

Building: F - MPR (911) (FKA C)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
F	PIPE WRAP STRAIGHT	က	70-75%	150 L	150 L KITCHEN, WATER HEATER ROOM, MPR STORAGE, AND CUSTODIAL ROOM	(6)	Z
Σ	9" VFT	4	1-5%	8'000'9	MPR, KITCHEN, AND ADMINISTRATION	(1) (4)	Z
တ	ACOUSTIC CEILING PLASTER	5	1-5%	1,400 S	HALLWAY OUTSIDE MPR	(1) (4)	z
F	MUD JOINT	7	ASSUMED	20 JOINTS	KITCHEN, WATER HEATER ROOM, MPR STORAGE, AND CUSTODIAL ROOM	(1) (4)	z
Σ	12" ACT	30	ASSUMED	UNDETERMINED	МРК	(1)	z
Σ	TRANSITE PIPE	66	ASSUMED	9 P	KITCHEN WATER HEATER ROOM	(1) (4)	Z

CONDITION CODE

	(9) Enclosed (10) Isolated & Restricted	(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
re)	(10) Iso	omments)
aged (25% or mo ints)	(9) Enclosed	(Explain under co
(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)	 Encapsulated 	
(2) Damaged (3)(5) Yes (If Yes, e)	(7) Removed (8) Encapsulated	ble, no inspection data
(1) Good (4) No	(6) Repaired	(11) Inaccessit
General Condition: Change in Condition:	Abated:	Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS
ZAShannonia-year Reinspectionsiche Usdzootyfeair View HS (FKA Partridge))HMR.wpd

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Inspector: William Esparza

Building: H - Classroom 17 (FKA D)

Date of Inspection: May 10, 2007

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Σ	LINOLEUM BEIGE	10	NONE DETECTED	100 S	100 S GIRL'S & BOY'S RESTROOMS	(13) SAMPLE HMS-PAR-08 COLLECTED ON 3-30-88.	N/A
Σ	DRYWALL & JOINT COMPOUND	32	ASSUMED	1,800 S	1,800 S CLASSROOM 17 AND GIRL'S & BOY'S RESTROOMS	(1)	Z
Σ	2' X 4' FCP'S	65	NONE DETECTED	S 006	900 S CLASSROOM 17	(13) SAMPLE HMS-CUSD-PART-200A COLLECTED 4-11-95.	N/A
Σ	12" VFT CREAM	103	ASSUMED	120 S	CLASSROOM 17	(1)	z
Ø	12" VFT CREAM	103	ASSUMED	S 009	600 S CLASSROOM 17	(1) (4)	z

CONDITION CODE

((sulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)) Encapsulated (9) Enclosed (12) Other (Explain under com
(2) Damaged (3) (5) Yes (If Yes, e.	(7) Removed (8) Encapsulated ble, no inspection data (12) Ott
(1) Good (4) No	(6) Repaired (11) Inaccessil
General Condition: Change in Condition:	Abated: Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Zischamonis-year reinspectionsichico usdizoonfair View HS (FKA Partridge)NHMR.wpd

Inspector: William Esparza

Building: I (FKA D)

Date of Inspection: May 10, 2007

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Σ	DRYWALL & JOINT COMPOUND	32	ASSUMED	2,500 S	ROOMS 15 & 16	(11) COVERED WITH TAGBOARD.	z
Σ	2' X 4' FCP'S	65	NONE DETECTED	1,800 S	ROOMS 15 & 16	(13) SAMPLE HMS-CUSD-PART-200A COLLECTED 4-11-95.	N/A
M	12" VFT CREAM	103	ASSUMED	240 S	ROOMS 15 & 16	(1) (4)	z

CONDITION CODE

	sulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
naged (25% or more) ents)	(9) Enclosed (10) Isolated & Restricted (Explain under comments) (13) Non-Asbest
(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)	incap
	gibl
n: (1) Good lion: (4) No	(6) Repaired (11) Inacces
General Condition: Change in Condition	Abated: Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS Zishannonis-year Reinspectionsical Usd/2007/Fair View HS (FKA Partridge))HMR.wpd

Inspector: William Esparza

Building: J (FKA D)

Date of Inspection: May 10, 2007

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Σ	2' X 8' ACT WOOD	50	NON- SUSPECT	480 S	SFA TRAILER (916) AND SPEECH TRAILER	(13)	N/A
Σ	2' X 4' FCP'S	65	NONE DETECTED	S 006	900 S LIBRARY/COMPUTER ROOM (917)	(13) SAMPLE HMS-CUSD-PART-200A COLLECTED 4-11-95.	N/A
Σ	DRYWALL	99	NONE DETECTED	400 S	COMPUTER ROOM (917)	(13) SAMPLE HMS-CUSD-PART-201A COLLECTED 4-11-95.	N/A

CONDITION CODE

more)	(9) Enclosed (10) Isolated & Restricted	(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(2) Damaged (3) Significantly Damaged (25% or more) (5) Yes (If Yes, explain under comments)		
(2) Damaged (3 (5) Yes (If Yes, e)	(7) Removed (8) Encapsulated	ble, no inspection data
(1) Good (4) No	(6) Repaired	(11) Inaccessi
General Condition: Change in Condition:	Abated:	Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS
Z.Sharinoni3-YEAR REINSPECTIONSICHICO USD/2007/Fair View HS (FKA Partridge))HMR.wpd

District: Chico Unified School District

Inspector: William Esparza

Date of Inspection: May 10, 2007

School: Fair View High School (FKA Partridge Elementary School)

Building: K - Portables 18 & 19

	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
,	32	ASSUMED	2,500 S	PORTABLES 18 & 19	(11) COVERED WITH TAGBOARD.	z
	51	ASSUMED	300 S	PORTABLES 18 & 19	(1) (4)	z
2' X 4' FCP'S	52	ASSUMED	1,800 S	1,800 S PORTABLES 18 & 19	(1) (4)	z

CONDITION CODE

ion: (1) Good dition: (4) No (6) Repaired	Signification uncontraction un
Aiscellaneous: (11) Inaccessible, no inspection data	ita (12) Other (Explain under comm

sulated (9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (11) Inaccessible, no inspection data

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS
ZAShannon3-YEAR REINSPECTIONSCAING USDIZGOTAFIAIT VIEW HS (FKA Partridge)NHMR.wpd

District: Chico Unified School District

School: Fair View High School (FKA Partridge Elementary School)

Date of Inspection: May 10, 2007

Inspector: William Esparza

Building: A - Unit 1

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	53	ASSUMED	S 006	PORTABLE 1	(1) (4)	z
M	12" VFT CREAM	61	ASSUMED	300 S	PORTABLE 1 - EAST SIDE	(1) (4) SLIGHT CRACKS AT ENTRY WAY.	Z
M	12" VFT CREAM	06	ASSUMED	900 S	PORTABLE 1 - WEST SIDE	(1)	Z
M	LINOLEUM	100	ASSUMED	60 S	LAUNDRY AND GIRL'S & BOY'S RESTROOMS	(1) (4)	Z
Μ	GYPSUM BOARD	101	ASSUMED	300 S	LAUNDRY AND GIRL'S & BOY'S RESTROOMS	(1) (4)	Z
N	GYPSUM BOARD	101	ASSUMED	2,000 S	PORTABLE 1	(11) COVERED WITH TAGBOARD.	Z

CONDITION CODE

(6) Repaired (1) Good (4) No Change in Condition: General Condition: Abated:

Miscellaneous:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected Enclosed (10) Isolated & Restricted (11) Inaccessible, no inspection data CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

ZISDRAINONIS-YEAR REINSPECTIONSICHIGO USD 2007/1Fair View HS (FKA Partridge) HMMR wpd

Date of Inspection: May 10, 2007

Inspector: William Esparza

Building: B - Portable 2

School: Fair View High School (FKA Partridge Elementary School)

District: Chico Unified School District

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Vee/No
တ	ACOUSTIC CEILING PLASTER	5	ASSUMED	1,000 S	1,000 S ROOM 2 - UNIT B	(1)	Z
S	WALL PLASTER	31	ASSUMED	UNDETERMI PORTABLE 2	PORTABLE 2	(1)	z
M	2' X 4' FCP'S	22	ASSUMED	S 009	600 S PORTABLE 2	(7) PLASTER CEILING.	N/A
M	9" VFT GREEN	. 63	ASSUMED	200 S	200 S PORTABLE 2	(1) (4)	z

CONDITION CODE

(1) Good	(4) No
General Condition:	Change in Condition:

Miscellaneous: Abated:

(2) Damaged (3) Significantly Damaged (25% or more)
(5) Yes (If Yes, explain under comments)
(7) Removed (8) Encapsulated (9) Enclosed (7)

(9) Enclosed (10) Isolated & Restricted

(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected (4) No
(5) Yes (If Yes, explain under comr
(6) Repaired
(7) Removed
(8) Encapsulated
(11) Inaccessible, no inspection data
(12) Oth

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: May 10, 2007

Inspector: William Esparza

Building: L - Portable 20

School: Fair View High School (FKA Partridge Elementary School)

District: Chico Unified School District

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
Σ	DRYWALL & JOINT COMPOUND	32	ASSUMED	1,250 S	1,250 S PORTABLE 20	(11) COVERED WITH TAGBOARD.	z
Ā	2' X 4' FCP'S FIBERGLASS	54	NON- SUSPECT	8 009	600 S PORTABLE 20	(13)	N/A
Σ	12" VFT WHITE	62	ASSUMED	S 006	900 S PORTABLE 20	(1) (4)	z


CONDITION CODE

or more)		(9) Enclosed (10) Isolated & Restricted	(12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected
(2) Damaged (3) Significantly Damaged (25% or more)	(5) Yes (If Yes, explain under comments)	(7) Removed (8) Encapsulated (9) Enck	
(1) Good (2) Damaged	(4) No (5) Yes (If Ye	(6) Repaired (7) Removed	(11) Inaccessible, no inspection data
General Condition:	Change in Condition:	Abated:	<u>Miscellaneous:</u>

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

ZISDAMOUNTS OF ASBESTOS

ZISDAMOUNTS OF ASBESTOS



FAIR VIEW HIGH SCHOOL

(at Jay Partridge site)

Updated 9/2006

THREE-YEAR REINSPECTION CONDUCTED BY WILLIAM ESPARZA OF ENTEK CONSULTING GROUP, INC. ON MAY 10, 2007