District: Chico Unified School District

Inspector: Jack DeLay

School: Nord Elementary School

Building: A - Administration

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACT - 1/8" HOLE PATTERN	1	NONE DETECTED	2,500 S	OFFICE (900), CLASSROOM 2, & LIBRARY	(13) SAMPLE HMS-NES-01 COLLECTED ON 3-29-88.	N/A
М	9" VFT BROWN	2	1-5%	2,400 S	OFFICE (900) AND CLASSROOM 2	(4) (11) COVERED WITH CARPET.	N
М	12" VFT TAN	3	TRACE	1,200 S	OFFICE (900) AND CLASSROOM 2	(1) (4)	N
S	WALL PLASTER	4	TRACE	2,950 S	OFFICE (900), BOYS & GIRLS RESTROOMS (903 & 904), AND STORAGE ROOM (902)	(1) (4)	N
М	2' X 4' FCP - FISSURE PATTERN	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2, LIBRARY	(1) (4)	N
8	STUCCO	150	ASSUMED	UNDETERMINED	COVERED WALKWAY	(1)	N
М	4" COVE BASE ADHESIVE	151	ASSUMED	UNDETERMINED	THROUGHOUT BUILDIING	(1)	N
М	CARPET ADHESIVE	152	ASSUMED	UNDETERMINED	LIBRARY	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\Nord\Nord.HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Nord Elementary School

Building: B - Portable 3

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	100	ASSUMED	900 F	PORTABLE 3	(1) (12) THIS PORTABLE WAS BROUGHT FROM FOREST RANCH. (NO I.D.)	N
М	12" VFT WHITE	101	ASSUMED	240 S	PORTABLE 3	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\Nord\Nord.HMR.wpd

District: Chico Unified School District

Inspector: Jack DeLay

School: Nord Elementary School

Building: C - MPR

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Conditio	n: Code & Comments	Friable Yes/No
М	12" ACT - SOLID PATTERN	1	NONE DETECTED	1,300 S	MPR (907)	(13)	REPRESENTED BY SAMPLE HMS-NES-01 COLLECTED ON 3-29-01.	N/A
S	WALL PLASTER	9	1-5%	1,000 S	STORAGE ROOM (909) & KITCHEN (908)	(1) (4) (2) (6)	FLAKING AND PHYSICAL DAMAGE AT SOUTH EAST CORNER AND NORTH WALL NEAR DOOR.	N
М	9" VFT DARK GRAY	10	1-5%	1,600 S	MPR (907) & KITCHEN (908)	(1) (4)		N
М	9" VFT OLIVE WITH PINK SPOTS	11	TRACE	100 S	MPR (EASTERN SIDE) (907)	(1) (4)		N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

District: Chico Unified School District

Inspector: Jack DeLay

School: Nord Elementary School Building: D - Portable 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLE 4	(12) THIS PORTABLE HAS BEEN CERTIFIED BY THE DISTRICT. ENTEK DOES NOT CURRENTLY HAVE A COPY OF THE CERTIFICATION LETTER ON FILE.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Z:\AHERA Inspections - Scanned\Chico USD\2010\Nord\Nord.HMR.wpd