

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist Leroy Christopher 2455 Carmichael Drive Chico, CA 95928					Client ID: Report Numb Date Received Date Analyzed Date Printed: First Reporte	d: 02/27/0 d: 02/28/0 02/28/0	06 06 06
Job ID/Site: Rosedale School - Roof P	roject				FASI Job ID:		_
Date(s) Collected: 02/22/2006					Total Samples Total Samples		1
Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
ROS01	10497377						
Layer: Beige Plaster			ND				
Layer: White Plaster			ND				
Layer: Paint			ND				



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

🖄 Forensic Anal	ytical				Ar	nalysis F	Request	Form
Client Name & Addres			P.O. #:	050289			2123	20 1
Chico Unified So	chool Dis	trict	Turn Aroun	od Timo:	he/ 42he	/ 24hr (48		- 00
2455 Carmichael	Drive		Due Date:		/ 1	Due Time:		am/pm
Chico, CA 95928				Standard /	Point C	ount	PCM: NIO	
Phone #: 530-89 Fax#: Ichristoc C (530) 891-3	apherse. 1-3195	~	TEM Air: ☐ AHERA / ☐ Yamate2 / ☐ NIOSH 7402 TEM Bulk: ☐ Quantitative / ☐ Qualitative / ☐ Chatfield TEM Water: ☐ Potable / ☐ Non-Potable / ☐ Wt % TEM Microvac					
(530) 891-3	hicowd.o 3190	rg	☐ Special	Project:				
Site: Rosedale			☐ Metals A	Analysis: Me	thod			
Job: Roof pr			Matrix:					
Comments:	spect		Analytes: _					
Sample ID	Date/ Time	Sample Location/De	scription			MPLES.ONL	Total	Sample Area or Air Volume
Rosol	2/22	skylight in ki	tchen	PC				voidine
				A P C	***************************************			
				A _P _			·	
		· · · · · · · · · · · · · · · · · · ·	V	A P				
				A P				
		West Avenue		A _P				·
				A P				.3
				A P				• .
		-		A P				
Sampled by: Leroy	Christon	chersen	Date:	~ ~ ~ ~		Time:	9 id	7 Am
Shipped via: ☐ Fed Ex	☐ Airborn	e 🗆 UPS 🗇 US N	/lail □ Co	urier 🛭 [Orop Off	 ☐ Other:		
Relinquished by:		Relinquished by:				shed by:	·	
Date / Time:	1	Date / Time:			Date / Ti	me:		
Received by	10/10	Received by:			Received	•		
Condition Acceptable?	4. 10 No	Date / Time: Condition Acceptal	ble? 🛘 Yes	□ No	Date / Ti		? 🛘 Yes	No

2921-91

Maintenance and Operations 2455 Carmichael Drive Chico, CA 95928 Phone: (530) 891-3195 Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 0974

February 24, 2006

Forensic Analytical Specialties, Inc. 3777 Depot Road, Suite 409 Hayward, CA 94545

Re: Chapman & Rosedale Elementary Schools

To Whom It May Concern:

Please test the enclosed samples from the kitchen skylights at Chapman and Rosedale Elementary Schools for asbestos. We would like a 48-hour turnaround on the samples. Please e-mail the results as soon as they are available to lchristo@chicousd.org.

Site Sampled:

Chapman Elementary School

Location:

Kitchen Skylight

Date Sampled:

February 22, 2006

Number of Samples:

One - #CHP01

Site Sampled:

Rosedale Elementary School

Location:

Kitchen Skylight

Date Sampled:

February 22, 2006

Number of Samples:

One - #ROS01

Thank you for your prompt response to this request.


Sincerely,

Leroy Christophersen

Safety & Loss Coordinator

Enclosures (2)

Rosedale Kitchen



Date of Inspection: _07/06/2006_

District: Chico Unified School District Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	100	ASSUMED	1,900 S	CLASSROOM 2 AND BOTH RESTROOMS	(1) (4)	N
М	2' X 4' FCP'S	94	ASSUMED	2,100 S	CLASSROOMS 1, 2A, 2B, AND 3	(1) (4)	N
М	12" VFT	95	ASSUMED	2,100 S	CLASSROOMS 1, 2A, 2B, AND 3	(1) (4)	N

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1) (4)	N
М	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM	(1) (4)	N
М	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: _07/06/2006_

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: K

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1) (4)	N
М	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24-28	(1) (4)	N
М	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24-28 AND LOUNGE	(1) (4)	N

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4)	N
М	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	(1) (4)	N
М	TRANSITE PIPE	90	ASSUMED	10 L	KITCHEN WATER HEATER CLOSET	(1) (4)	N
М	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1) (4)	N
М	12" VFT	93	ASSUMED	3,000 S	OFFICES AND MULTI-PURPOSE ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>07/06/2006</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Rosedale Elementary School

Building: C & D (Portables 3 & 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	103	ASSUMED	1,200 S	PORTABLE CLASSROOMS 3 & 4	(1) (4)	N

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13-18	(1) (4)	N
М	2' X 4' FCP'S	91	NONE DETECTED	6,500 S	CLASSROOMS 13-18 AND LIBRARY	(13) SAMPLE DONE 03/22/2005	N
М	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS AND TV/PARENT AREA	(1) (4)	N
М	12" ACT	102	ASSUMED	250 S	TV/PARENT AREA	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: _07/06/2006_

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: G (Classrooms 9-12)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT WHITE	18	NONE DETECTED	2,000 S	CLASSROOMS 9-12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S	105	ASSUMED	2,000 S	CLASSROOMS 9-12	(1) (4)	N

Building: F (Classrooms 6-8)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	18	NONE DETECTED	1,600 S	CLASSROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S	106	ASSUMED	1,600 S	CLASSROOMS 6, 7, & 8	(1) (4)	N

Building E: Portables 5 & 5B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLE CLASSROOMS 5 & 5B - RSP & READ RECOVERY	(1) (4)	Z

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: _12/28/06_

District: Chico Unified School District Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	100	ASSUMED	1,900 S	CLASSROOM 2 AND BOTH RESTROOMS	(1) (4)	N
М	2' X 4' FCP'S	94	ASSUMED	2,100 S	CLASSROOMS 1, 2A, 2B, AND 3	(1) (4)	N
М	12" VFT	95	ASSUMED	2,100 S	CLASSROOMS 1, 2A, 2B, AND 3	(1) (4)	N

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1) (4)	N
М	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM	(1) (4)	N
М	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19-23 AND WORK ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: _12/28/06_

District: Chico Unified School District Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: K

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1) (4)	N
М	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24-28	(1) (4)	N
М	2' X 4' FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24-28 AND LOUNGE	(1) (4)	N

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4)	N
М	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	(1) (4)	N
М	TRANSITE PIPE	90	ASSUMED	10 L	KITCHEN WATER HEATER CLOSET	(1) (4)	N
М	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1) (4)	N
М	12" VFT	93	ASSUMED	3,000 S	OFFICES AND MULTI-PURPOSE ROOM	(1) (4)	N
I			1	1	1		I

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/28/06

District: Chico Unified School District Inspector: Leroy Christophersen

School: Rosedale Elementary School

Building: C & D (Portables 3 & 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	103	ASSUMED	1,200 S	PORTABLE CLASSROOMS 3 & 4	(1) (4)	N

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13-18	(1) (4)	N
М	2' X 4' FCP'S	91	NONE DETECTED	6,500 S	CLASSROOMS 13-18 AND LIBRARY	(13) SAMPLE DONE 03/22/2005	N
М	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS AND TV/PARENT AREA	(1) (4)	N
М	12" ACT	102	ASSUMED	250 S	TV/PARENT AREA	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: _12/28/06_

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Rosedale Elementary School Building: G (Classrooms 9-12)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT WHITE	18	NONE DETECTED	2,000 S	CLASSROOMS 9-12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S	105	ASSUMED	2,000 S	CLASSROOMS 9-12	(1) (5) SOME STAINS	N

Building: F (Classrooms 6-8)

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	18	NONE DETECTED	1,600 S	CLASSROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
М	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
М	2' X 4' FCP'S	106	ASSUMED	1,600 S	CLASSROOMS 6, 7, & 8	(1) (4)	N

Building E: Portables 5 & 5B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLE CLASSROOMS 5 & 5B - RSP & READ RECOVERY	(1) (4)	Z

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

→ CUSD CORP YARD 図004 NU. j | 8 「、 対すいる

Thomson & Hendricks, Inc.
Rerooting of the Multi-purpose, Kindergarten & Relocatable Classroom Buildings at the Rosedale Elementary
School, #25060

CERTIFICATION OF COMPLIANCE FOR BUILDING MATERIALS

This is to certify, in accordance with the Environmental Protection Agency requirements, that the materials and equipment used in the construction of the: Reroofing at the Multi-Purpose, Kitchen and Relocatable Classrooms at the Rosedale Elementary School for the Chico Unified School District of Butte County, California, are asbestos free and are, therefore, not subject to monitoring for asbestos contamination.

Project Name: Reroofing at the Multi-Purpose, Kitchen and Relocatable Classrooms at the Rosedale Elementary School

Address: 100 Oak Street, Chico, CA 95928

Contractor: Legacy Roofing and Waterproofing

Address: 2950 Ramona Avenue, Sacramento, CA 95826

Signature: Tangard 8-27-06

Title: Project Manager

SEPARATE CERTIFICATE IS REQUIRED FOR EACH SITE

Certification of Compliance for Building Materials