

97245282
IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7555

GENERATOR

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address SPT of Remediation SHAWA TOWNSHIP SILVER		4. Generator's Phone ()		A. State Manifest Document Number 97245282	
5. Transporter 1 Company Name		6. US EPA ID Number		B. State Generator's ID	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID	
9. Designated Facility Name and Site Address SPT of Remediation SHAWA TOWNSHIP SILVER		10. US EPA ID Number		D. Transporter's Phone	
				E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility's ID	
				H. Facility's Phone	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. 1.0 LBS. OF ...		03	4	304	50 P
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
		a.		b.	
		c.		d.	
15. Special Handling Instructions and Additional Information JUL 11 1998					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name C.U.S.D. By R. Jones		Signature C.U.S.D. By R. Jones		Month Day Year 08/10/98	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name B. Jones		Signature B. Jones		Month Day Year 08/10/98	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name					
Signature		Month Day Year			

DO NOT WRITE BELOW THIS LINE.

NOTICE AND CERTIFICATION

The waste identified on manifest number 97245287 and bearing the California Waste Code 151 is subject to land disposal restrictions contained in Article 40, Title 22, California Code of Regulation (CRR). The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code (H&SC) Section 25179.3 (1) (2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration (STLC) values established in Article 11, Title 22, CCR; and the waste is not prohibited from land disposal as provided in H&SC Section 25179.6.

(Waste analysis is attached for these wastes, where available.)

As required by Article 40, Title 22, CCR the following certification is made for these restricted wastes:

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing or through knowledge of the waste to support this certification that the waste complies with the treatment standards specified in CCR Title 22, Division 4, Chapter 30, Article 41. I believe that the information I submitted is true, accurate and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of fine and imprisonment.

Signature C.U.S.D. By P. Jones

Title M/O Supervisor

Date 8-10-98

SIX-MONTH SURVEILLANCE

Page 1 of 2

DISTRICT Chico Unified School District

DATE December 20, 1996

7-16-98

SCHOOL Shasta Elementary

INSPECTOR Rob Peters

R.P.

HOMOG. ASBESTOS
BLDG. MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

A	9" VFT	5-10	Classrms,MPR,Kit,Storage	1-4	✓
A	PW Cnr	1-5	Attic	2-4	✓
A	PW Str	30-35	Attic	1-4	✓
A	PW Str	15-20	Main boiler room	1-4	✓
A	Lg Dia PW Cnr	Assumed	Main boiler room	1-4	✓
A	Sm Dia PW Cnr	5-10	Main boiler room	1-4	✓
A	Surf Plas	1-5	Storage (RR)	1-4	✓
A	Tran pipe	Assumed	Main boiler room	1-4	✓
A	Pipewrap	5-20	MPR Storage	1-4 (5) (7)	8/98
B	Tran panl	Assumed	Outside building	1-4	✓
C	Tran panl	Assumed	Outside building	1-4	

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

POSTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)
SIX-MONTH SURVEILLANCE

Page 2 of 2

DISTRICT Chico Unified School District DATE December 20, 1996 9/16/98

SCHOOL Shasta Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
C	Drywall	1-5 skim coat	All Rooms	1-4	✓
D	VFT	Assumed	Old portables	None present (carpet)	
Port	12" VFT	Assumed	Classrooms 16,17,18	1-4	✓
Port	2x4 FCP	Assumed	Classrooms 16,17,18	1-4	✓
Port	Drywall	Assumed	Classroom 16,17,18 behind tagboard	1-4	✓

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

120-98

RAM 1 2 files

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 4, 1996 1-20-98

SCHOOL Shasta Elementary INSPECTOR Ron Jones

BLDG.	HOMOG.		ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
	MAT.#					
A	9" VFT	5-10		Classrms,MPR,Kit,Storage	1-4	✓
A	PW Cnr	1-5		Attic	2-4	✓
A	PW Str	30-35		Attic	1-4	✓
A	PW Str	15-20		Main boiler room	1-4	✓
A	Lg Dia PW Cnr	Assumed		Main boiler room	1-4	✓
A	Sm Dia PW Cnr	5-10		Main boiler room	1-4	✓
A	Surf Plas	1-5		Storage (RR)	1-4	✓
A	Tran pipe	Assumed		Main boiler room	1-4	✓
A	Pipewrap	5-20		MPR Storage	1-4	✓
B	Tran panl	Assumed		Outside building	1-4	✓
C	Tran panl	Assumed		Outside building	1-4	✓

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)
SIX-MONTH SURVEILLANCE Page 2 of 2

DISTRICT Chico Unified School District

DATE

January 4, 1996

1-20-98

SCHOOL Shasta Elementary

INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
C	Drywall	1-5 skim coat	All Rooms	1-4	✓
D	VFT	Assumed	Old portables	None present (carpet)	✓
Port	12" VFT	Assumed	Classrooms 16,17,18	1-4	✓
Port	2x4 FCP	Assumed	Classrooms 16,17,18	1-4	✓
Port	Drywall	Assumed	Classroom 16,17,18 behind tagboard	1-4	✓

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

EOS ENVIRONMENTAL, INC.

ENVIRONMENTAL AND OCCUPATIONAL HEALTH SERVICES

507 MISSION STREET, SOUTH PASADENA, CA 91030
TEL. (626) 441-7050 * FAX (626) 441-0016

2110-21ST STREET #150, SACRAMENTO, CA 95814
TEL. (916) 452-5884 * FAX (916) 452-5912

**AHERA RE-INSPECTION
DOCUMENTATION**

CHICO UNIFIED SCHOOL DISTRICT

1998

Asbestos Three Year Re-Inspection

SHASTA ELEMENTARY SCHOOL

APRIL 10, 1998

TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY**
- II. MATERIAL INVENTORY**
- III. POSITIVE MATERIAL LIST**
- IV. MISSING MATERIAL LIST**
- V. DIAGRAMS**
- VI. FIELD NOTES**
- VII. INSPECTOR'S QUALIFICATIONS**

EXECUTIVE SUMMARY

EXECUTIVE SUMMARY

On April 10, 1998 , EOS Environmental, Inc. performed a visual re-inspection for asbestos containing building materials, (ACBM) at Shasta Elementary School. The purpose of the re-inspection was to comply with the U. S. Environmental Protection Agency (EPA) CRF 763 - AHERA requirement for a three year re-inspection.

Prior to the re-inspection, previous inspection reports were reviewed in order to determine which building materials had been previously tested and found to be asbestos containing, which were found not to contain asbestos, and if any materials had not been tested.

After the review of previous building inspections, a complete visual walk-through inspection of the site was performed. The visual inspection determined that conditions at Shasta were such that all non friables were in good condition. All friables were also in good condition at the time of this inspection.

MATERIAL INVENTORY

MATERIAL CODES

ACS - Acoustical Ceiling Spray
ACT - Acoustical Ceiling Tile
ACP - Acoustical Ceiling Panels
AIR - Air Cell
ASF - Asphalt
ASP - Asbestos Paper
BBM - Baseboard Mastic
BOI - Boiler Insulation
BOL - Blown-In Insulation
BRK - Brick
BUR - Built-up Roofing
CAP - Cement Asbestos Pipe
CAS - Cement Asbestos Siding
CIN - Cinder Block
CEM - Cement
CER - Ceramic
CUR - Curtains
DEB - Debris
DRY - Drywall
DTM - Drywall Taping Mud
ELB - Pipe Elbow (fittings)
EXP - Exterior Panels
FIR - Fire Rated Brick
FLT - Floor Tile
FRD - Fire Rated Door
FUR - Furnace Pad
GAS - Gasket
MAS - Mastic
MIS - Miscellaneous
MOR - Mortar
P/C - Pipe Cover
PLA - Plaster
SFL - Vinyl Floor Sheeting
SFP - Sprayed-on Fireproofing
SOL - Soil
STC - Stucco
TAP - Tape
TAR - Tar
RFS - Composite Roofing Shingles
RFT - Roofing Felt
ROL - Rolled Roofing Material
WOV - Woven Cloth Joint Expansion
WPY - Window Putty

MATERIAL INVENTORY

Pg.1

Shasta Elementary School

4-10-98

James M. Rich
96-2035

MAT. CODE	DESCRIPTION OF MATERIAL	AREA FOUND	CAT.	FRI.	ORIGINAL AMOUNT	AMOUNT LEFT	HAS AB.
FLT	9" VFT Beige	Bldg. A Classrooms, MPR, Kit., Storage	MISC	No	6000 SF	6000 SF	Yes
ELB	Pipe Fittings	Bldg. A Attic	TSI	Yes	35 ea.	35 ea.	Yes
P/C	Pipe Covering	Bldg. A Attic	TSI	Yes	150 LF	150 LF	Yes
P/C	Pipe Covering	Bldg. A Main Boiler Rm.	TSI	Yes	75 LF	75 LF	Yes
ELB	Pipe Fittings Lg.	Bldg. A Main Boiler Rm.	TSI	Yes	30 ea.	30 ea.	As.
ELB	Pipe Fittings Sm.	Bldg. A Main Boiler Rm.	TSI	Yes	30 ea.	30 ea.	Yes
PLA	Plaster	Bldg. A Storage (RR)	SUR	No	650 SF	650 SF	Yes
CAP	Transite Pipe	Bldg. A Main Boiler Rm.	MISC	No	10 LF	10 LF	As.
P/C	Pipe Covering	Bldg. A MPR Storage	TSI	Yes	20 LF	20 LF	Yes
EXP	Transite Panels	Bldg. B Outside Bldg.	MISC	No	25000 SF	25000 SF	As.
EXP	Transite Panels	Bldg. C Outside Bldg.	MISC	No	25000 SF	25000 SF	As.

Pg. 2

James M. Rich
96-2035

4-10-98

[illegible]

POSITIVE MATERIAL LIST

POSITIVE MATERIALS

Pg.1

Shasta Elementary School

James M. Rich
96-2035

4-10-98

AREA NAME	SPACE NAME	ORIG. AMOUNT	AMOUNT LEFT	UNIT	MAT. CODE	UNIT PRICE	BUDGET CALC.
Bldg. A	Classrooms, MPR, Kitchen, Storage	6000 SF	6000 SF	SF	FLT		
Bldg. A	Attic	35 ea	35 ea	ea	ELB		
Bldg. A	Attic	150 LF	150 LF	LF	P/C		
Bldg. A	Main Boiler Rm. Lg.	30 ea	30 ea	ea	ELB		
Bldg. A	Main Boiler Rm. Sm.	30 ea	30 ea	ea	ELB		
Bldg. A	Storage (RR)	650 SF	650 SF	SF	PLA		
Bldg. A	Main Boiler Rm.	10 LF	10 LF	LF	CAP		
Bldg. A	MPR Storage	20 LF	20 LF	LF	P/C		
Bldg. B	Outside Bldg.	25000 SF	25000 SF	SF	EXP		
Bldg. C	Outside Bldg.	25000 SF	25000 SF	Sf	EXP		
Bldg. A	Main Boiler Rm.	75 LF	75 LF	LF	P/C		

POSITIVE MATERIALS

Pg. 2

Shasta Elementary School

James M. Rich
96-2035

4-10-98

[illegible]

MISSING MATERIAL LIST

MISSING MATERIALS

Pg. 1








Shasta Elementary School

James M. Rich
96-2035

4-10-98

[illegible]

DIAGRAMS



SHASTA ELEMENTARY

FIELD NOTES

These levels should be used to establish both immediate and long range plans to act on the recommendations. The Priority Levels were selected for one of the following options:

Priority Level 1 - Isolate area, restrict access and respond as soon as possible.

Priority Level 2 - Schedule Response Action as soon as possible, reduce potential for disturbance.

Priority Level 3 - Schedule response Action as soon as practical, reduce potential for disturbance.

Priority Level 4 - Schedule Response Action as soon as practical.

Priority Level 5 - Schedule Response Action upon upgrade of system or material.

Cleaning Levels:

Level 1 - Initial cleaning should be done as soon as possible and additional cleaning should be done once every two months until the ACM is removed.

Level 2 - Initial cleaning should be done as soon as possible and additional cleaning should be done once every six months until the ACM is removed.

Level 3 - The material is non-friable therefore initial or additional cleaning is not necessary.

Level 4 - Initial or additional cleaning is not required for this material.

RESPONSE ACTIONS AND PRIORITY LEVELS:

Response Actions have been recommended for all friable or assumed friable ACM that was found during the inspection. The Response Actions were selected from one of the following options:

1. Removal
2. Repair
3. Enclosure
4. Encapsulation
5. Operations and Maintenance Program
6. Periodic Surveillance

Inspector: J.R.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material		Area:							
Material 12" VAT		Area: Portables - RM # 16, 17, 18							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	High		Good	Good	10000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes: Material Assumed

Inspector: J.R.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material		Area:							
Material 2x4 FCP		Area: Portables - RM # 16, 17, 18							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	Mod.		Good	Good	40000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector: J.R.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material		Area:							
Material Ray wall		Area: Portables - RM 16, 17, 18							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	Mod		Good	Good	10000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector:
Site:

Cert. #

Inspection Date

Material		Area:							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
							1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

Inspector: J.R.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material		Friable		Accessibility		Type		Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC		N		Med.				Good	Good	25,000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes: Material Assumed

Inspector: S.D.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material		Friable		Accessibility		Type		Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC		N		Low				Good	Good	2000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector: S.D.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material		Friable		Accessibility		Type		Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC		N		High				Good	Good	600	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector: S.D.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material		Friable		Accessibility		Type		Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC		N		Med				Good	Good	25,000	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

Inspector: J.R.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material		Area: Bldg A - Boiler Room							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	Low		Good	Good	10 L.F.T.	1 2 3 4 5	1 2 3 4	1 2 3 4 5

Justification:

Implementation

Start:

End:

Notes: Material Assumed

Inspector: S.H.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material Pipe Wagon		Area: Bldg A - MPR Storage							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
TSI	Y	Low		Good	Good	20 L.F.T.	1 2 3 4 5	1 2 3 4	1 2 3 4 5

Justification:

Implementation

Start:

End:

Notes:

Inspector: S.H.
Site: Shasta

Cert. #

Inspection Date 4-10-98

Material 2'x4' FCP		Area: Bldg B - All Rooms							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	Low		Good	Good	4500 L	1 2 3 4 5	1 2 3 4	1 2 3 4 5

Justification:

Implementation

Start:

End:

Notes:

Inspector: S.R.
Site: Shasta

Cert. #

Inspection Date 11-10-98

Material 12" Beige VAT		Area: Bldg B - All Rooms							
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC.	N	High		Good	Good	2500 L	1 2 3 4 5	1 2 3 4	1 2 3 4 5

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

Inspector: J.R.

Cert. #

Inspection Date 4-10-98

Site: Shasta

Material		Area: Bldg A - Boiler Room							
Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
TSI	Y	Low		Good	Good	75 lbf.	1 2 3 4 (5)	1 2 3 (4)	1 2 3 4 5 (6)

Justification:

Implementation

Start:

End:

Notes: Long Dia. pipes

Inspector: J.R.

Cert. #

Inspection Date 4-10-98

Site: Shasta

Material		Area: Bldg A - Boiler Room							
Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
TSI	Y	Low		Good	Good	30 Jnts	1 2 3 4 (5)	1 2 3 (4)	1 2 3 4 5 (6)

Justification:

Implementation

Start:

End:

Notes: All mudded joints large & small

Inspector: J.R.

Cert. #

Inspection Date 4-10-98

Site: Shasta

Material		Area: Bldg A - Boiler Room							
Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
SUR	N	Low		Good	Good	850 sq	1 2 3 4 (5)	1 2 3 (4)	1 2 3 4 5 (6)

Justification:

Implementation

Start:

End:

Notes:

Inspector: J.R.

Cert. #

Inspection Date 4-10-98

Site: Shasta

Material		Area: Bldg A - Storage (RR)							
Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
SUR	N	High		Good	Good	650 sq	1 2 3 4 (5)	1 2 3 (4)	1 2 3 4 5 (6)

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

Inspector: J.R.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material 1'x1' ACT				Area: Bldg A - All Classrooms, MPR, Kitchen, Storage					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC	N	Low		Good	Good	6000 SF	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector: J.R.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material 9" Beige VAT				Area: Bldg A - All Classrooms, MPR, Kitchen / Storage					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
MISC.	N	High		Good	Good	6000 SF	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

Inspector: J.R.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material Mudded Joints				Area: Bldg A - Attic					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
TSI	Y	Low		Good	Good	35 Jnts	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes: Some elbows have no canvas covering

Inspector: J.R.
Site: SHASTA

Cert. #

Inspection Date 4-10-98

Material Pipe Lagging				Area: Bldg A - Attic					
Material Code	Friable	Accessibility	Type	Current Condition	Potential Condition	Approx. Amount of ACM	Priority Level	Cleaning Level	Response Action
TSI	Y	Low		Good	Good	150 LFT	1 2 3 4 5	1 2 3 4	1 2 3 4 5 6

Justification:

Implementation

Start:

End:

Notes:

TSI: Thermal System Insulation SUR: Surface MISC: Miscellaneous

INSPECTOR'S QUALIFICATIONS

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT

2211 Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 FAX (916) 483-0572



608302035C

128 132

September 19, 1997

James Rich
E.O.S. Environmental Inc.
2110 21st Street, Suite 150
Sacramento, CA 95818

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. To maintain your certification, please abide by the rules printed on the back of the certification card.

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist

RA/dor

Attachment

cc: File

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

James M. Rich

Certification No. 66-2035

Expires on 11/8/98

This certification was issued by the Division of Occupational Safety and Health as authorized by Section 7149.5 of the Business and Professions Code.