

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					LETTER ON FILE →	BUILDING A - BURNED DOWN 10-06-00, REBUILT IN 2001. DISTRICT MUST CERTIFY.	

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	1	NONE DETECTED	4,500 S	LIBRARY AND CLASSROOMS 6, 9, AND 10	(13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	2,500 S	ENTIRE WING	(1) (4)	N
M	DRYWALL	80	ASSUMED	1,500 S	CLASSROOMS 6, 9, AND 10	(1) (4)	N
M	TRANSITE PANEL	99	ASSUMED	5,000 S	OUTSIDE BUILDING	(1) (4)	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP S	1	NONE DETECTED	7,000 S	OFFICE AND CLASSROOMS 7, 8, 11, 12, AND 13	(13) SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	600 S	OFFICE	(1) (4) CARPET OVER TILE IN PRINCIPAL OFFICE AND PART OF MAIN OFFICE.	N
S	PLASTER	86	ASSUMED	250 S	MEN S & WOMEN S RESTROOM CEILINGS	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	5,000 S	OUTSIDE BUILDING	(1) (4)	N

Building: Portables 4 and 19-21 (FKA 19-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	88	ASSUMED	3,200 S	PORTABLES 4 AND 19-21	(1) (4) THESE PORTABLES HAVE A MFG. DATE OF 4/97. DISTRICT CERTIFICATE REQUIRED (DMSI MFG.) LETTER ON FILE	N
M	12" VFT WHITE/BLUE	89	ASSUMED	3,200 S	PORTABLES 4 AND 19-21	(1) (4) THESE PORTABLES HAVE A MFG. DATE OF 4/97. DISTRICT CERTIFICATE REQUIRED (DMSI MFG.). LETTER ON FILE	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: Portables 22-24 (FKA 23-26)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	87	ASSUMED	2,800 S	PORTABLES 22-24	(1) (4) THESE PORTABLES HAVE A 1/98 MFG. DATE. DISTRICT CERTIFICATION REQUIRED. LETTER ON FILE	N
M	DRYWALL	111	ASSUMED	3,000 S	PORTABLES 22-24	(11) COULD BE BEHIND TAGBOARD.	N

Building: Portables 16-18

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	2,700 S	PORTABLES 16-18	(1) (4)	N
M	2' X 4' FCP S	110	ASSUMED	2,700 S	PORTABLES 16-18	(1) (4)	N
M	DRYWALL	111	ASSUMED	2,700 S	PORTABLES 16-18	(1) (4) (11) DRYWALL BEHIND TAGBOARD.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 06/16/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: Portables 14, 14A, and 15 (FKA Speech and Portable 14)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	60	NON SUSPECT	2,200 S	PORTABLES 14, 14A, AND 15	(13) FIBERGLASS - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT WHITE	70	ASSUMED	2,300 S	PORTABLES 14, 14A, AND 15	(11) COULD BE UNDER CARPET.	N

Building: Portables 25 & 26 (From Former Fair View/Cal Campus)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL		ASSUMED		(PORTABLE 12 - C5 from former FAIR VIEW) CLASSROOMS 25 & 26	(12) MANUFACTURES DATE 1989. DISTRICT CERTIFICATION REQUIRED (1)	
M	2' X 4' FCP'S		NON DETECT		CLASSROOMS 25 & 26	(13) CUSD SAMPLE #SH01 & SH03 7/29/2005	
M	12" VFT GREY		NON DETECT		CLASSROOMS 25 & 26	(13) CUSD SAMPLE #SH02 7/29/2005	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					LETTER ON FILE →	BUILDING A - BURNED DOWN 10-06-00, REBUILT IN 2001. DISTRICT MUST CERTIFY.	

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	1	NONE DETECTED	4,500 S	LIBRARY AND CLASSROOMS 3, 6, AND 7 **(FORMERLY NUMBERED 6, 9, & 10)	(13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	2,500 S	ENTIRE WING	(1) (4)	N
M	DRYWALL	80	ASSUMED	1,500 S	CLASSROOMS 6, 9, AND 10	(1) (4)	N
M	TRANSITE PANEL	99	ASSUMED	5,000 S	OUTSIDE BUILDING	(1) (4)	N

**CAMPUS WAS RENUMBERED IN AUGUST 2006.

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP S	1	NONE DETECTED	7,000 S	OFFICE AND CLASSROOMS 4, 5, 8, 9, AND 10 **FORMERLY 7, 8, 11, 12, AND 13)	(13) SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	600 S	OFFICE	(1) (4) CARPET OVER TILE IN PRINCIPAL OFFICE AND PART OF MAIN OFFICE.	N
S	PLASTER	86	ASSUMED	250 S	MEN S & WOMEN S RESTROOM CEILINGS	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	5,000 S	OUTSIDE BUILDING	(1) (4)	N

Building: Portables 4 and 19-21 (FKA 19-22)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	88	ASSUMED	3,200 S	PORTABLES 18 – 21 **(FORMERLY 4 AND 19-21)	(1) (4) THESE PORTABLES HAVE A MFG. DATE OF 4/97. (DMSI MFG.) LETTER ON FILE	N
M	12" VFT WHITE/BLUE	89	ASSUMED	3,200 S	PORTABLES 18 – 21 **(FORMERLY 4 AND 19-21)	(1) (4) THESE PORTABLES HAVE A MFG. DATE OF 4/97. (DMSI MFG.). LETTER ON FILE	N

**CAMPUS WAS RENUMBERED IN AUGUST 2006.

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary School

Building: Portables 22-24 (FKA 23-26)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	87	ASSUMED	2,800 S	PORTABLES 22-24	(1) (4) THESE PORTABLES HAVE A 1/98 MFG. DATE. DISTRICT CERTIFICATION REQUIRED. LETTER ON FILE	N
M	DRYWALL	111	ASSUMED	3,000 S	PORTABLES 22-24	(11) COULD BE BEHIND TAGBOARD.	N

Building: Portables 15-17 (Formerly 16-18)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	2,700 S	PORTABLES 15-17 (Formerly 16-18)**	(1) (4)	N
M	2' X 4' FCP S	110	ASSUMED	2,700 S	PORTABLES 15-17 (Formerly 16-18)**	(1) (4)	N
M	DRYWALL	111	ASSUMED	2,700 S	PORTABLES 15-17 (Formerly 16-18)**	(1) (4) (11) DRYWALL BEHIND TAGBOARD.	N

**CAMPUS WAS RENUMBERED IN AUGUST 2006.

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: Portables 13, 13A, 14 (FKA Portable 14, 14a & 15)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP S	60	NON SUSPECT	2,200 S	PORTABLES 13, 13A, AND 14 **(FORMERLY 14, 14A, AND 15)	(13) FIBERGLASS - NON SUSPECT ASBESTOS CONTAINING BUILDING MATERIAL.	N
M	12" VFT WHITE	70	ASSUMED	2,300 S	PORTABLES 13, 13A, AND 14 **(FORMERLY 14, 14A, AND 15)	(11) COULD BE UNDER CARPET.	N

Building: Portables 11 & 12 (From Former Fair View/Cal Campus)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL		ASSUMED		(PORTABLE 12 – C5 from former FAIR VIEW) CLASSROOMS 11 & 12	(12) MANUFACTURES DATE 1989. DISTRICT CERTIFICATION REQUIRED (1)	
M	2' X 4' FCP'S		NON DETECT		CLASSROOMS 11 & 12	(13) CUSD SAMPLE #SH01 & SH03 7/29/2005	
M	12" VFT GREY		NON DETECT		CLASSROOMS 11 & 12	(13) CUSD SAMPLE #SH02 7/29/2005	

**CAMPUS WAS RENUMBERED IN AUGUST 2006.

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Shasta Elementary

Building: Unit M (Restroom)






Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL		ASSUMED		RESTROOM	(12) MANUFACTURER 2006 – LETTER/CERTIFICATE NEEDED	N
M	2' X 4' FCP		ASSUMED T		RESTROOM	(12) MANUFACTURER 2006 – LETTER/CERTIFICATE NEEDED	N
M	12" VFT GREY		ASSUMED		RESTROOM	(12) MANUFACTURER 2006 – LETTER/CERTIFICATE NEEDED	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

UNIT L



ESPLANADE

Water

Cable Tv Amplifier

Electric Gas

Telephone

Cable fed from pole

PARKING

LEORA COURT



SHASTA ELEMENTARY SCHOOL

AS OF 2006/07 School Year

Updated 9/2006