

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary School

Building: B - Classrooms 3, 6, & 7

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	1	NONE DETECTED	4,500 S	LIBRARY (922) AND CLASSROOMS 3 (FKA 6), 6 (FKA 9), AND 7 (FKA 10)	(13) REPRESENTED BY SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT BEIGE	2	TRACE	2,500 S	ENTIRE WING	(1) (4)	N
M	DRYWALL	80	ASSUMED	1,500 S	ENTIRE WING	(11) COVERED WITH TAGBOARD.	N
M	TRANSITE PANEL	99	ASSUMED	100 S	OUTSIDE BUILDING ABOVE DOORS AT COVERED WALKWAYS	(1) (4)	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	500 L	LIBRARY, CLASSROOMS 3, 6 & 7	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	5,000 S	LIBRARY, CLASSROOMS 3, 6 & 7	(1)	N

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary School

Building: C - Classrooms 4, 5, & 8-10

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S FISSURE PATTERN	1	NONE DETECTED	7,000 S	OFFICE (915) AND CLASSROOMS 4 (FKA 7), 5 (FKA 8), 8 (FKA 11), 9 (FKA 12), AND 10 (FKA 13)	(13) SAMPLE HMS-SHA-01 COLLECTED IN 1988.	N/A
M	12" VFT CREAM	2	TRACE	600 S	OFFICE (915) AND PRINCIPAL OFFICE	(1) (4) (11) CARPET OVER TILE IN PRINCIPAL OFFICE.	N
S	PLASTER	86	ASSUMED	250 S	MEN'S (912) & WOMEN'S (914) RESTROOM CEILINGS	(1) (4)	N
M	TRANSITE PANELS	99	ASSUMED	200 S	ABOVE DOORS AT COVERED WALKWAYS	(1) (4)	N
M	DRYWALL	112	ASSUMED	UNDETERMINED	THROUGHOUT OFFICES & CLASSROOMS	(11) COVERED WITH TAGBOARD IN ALL CLASSROOMS - NOT INSPECTED	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	700 L	THROUGHOUT OFFICES & CLASSROOMS	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	5,000 S	THROUGHOUT OFFICES & CLASSROOMS	(1)	N

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary

Building: D - Portables 13, 13A, & 14

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S FIBERGLASS	60	NON-SUSPECT	2,200 S	PORTABLES 13, 13A, AND 14	(13)	N/A
M	12" VFT WHITE	70	ASSUMED	2,300 S	PORTABLES 13, 13A, AND 14	(11) ASSUMED TO EXIST BENEATH CARPET	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	325 L	PORTABLES 13, 13A, AND 14	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	1,650 S	PORTABLES 13, 13A, AND 14	(1)	N
						ROOM 14 - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1083.1 & 2 ROOM 13 - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1084 # 3 & # 2 ROOM 13A - DESIGNATED MOBILE SYSTEMS IND. 7/01 SERIAL # 20.1084 # 1	

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary School

Building: E - Classroom 15

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 15	(1) (4)	N
M	2' X 4' FCP'S FISSURE PATTERN	110	ASSUMED	900 S	CLASSROOM 15	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 15	(11) DRYWALL BEHIND TAGBOARD.	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	80 L	CLASSROOM 15	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	375 S	CLASSROOM 15	(1)	N
						BUILT BY HUFFMAN - AUG. 1987 - NO SERIAL #	

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary School

Building: F - Classroom 16

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 16	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 16	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 16	(11) DRYWALL BEHIND TAGBOARD.	N
M	4" COVE BASE ADHESIVE	150	ASSUMED	120 L	CLASSROOM 16	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	900 S	CLASSROOM 16	(1)	N
						BUILT BY: KRUSEMARK - JULY 1988 SERIAL # 8751-16 B & C	

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**

**THREE-YEAR REINSPECTION  
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 28, 2010

District: Chico Unified School District

Inspector: Jack DeLay

School: Shasta Elementary School

Building: G - Classroom 17

Material Class	Material	Homo. Mat. #	% Asb.	Ft <sup>2</sup> /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT TAN	109	ASSUMED	253 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	2' X 4' FCP'S	110	ASSUMED	900 S	CLASSROOM 17 (FKA 18)	(1) (4)	N
M	DRYWALL	111	ASSUMED	900 S	CLASSROOM 17	(11) DRYWALL BEHIND TAGBOARD	N
M	6" COVE BASE ADHESIVE	152	ASSUMED	120 L	CLASSROOM 17	(1)	N
M	CARPET ADHESIVE	151	ASSUMED	900 L	CLASSROOM 17	(1)	N
						UNKNOWN MANUFACTURER - UNKNOWN BUILD DATE SERIAL # 8888.10 A & B	

Z:\AHERA Inspections - Scanned\Chico USD\2010\ShastaElem\Shasta.HMR.wpd

**CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)  
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)  
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted  
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

**CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS**