



Forensic Analytical

San Francisco • Los Angeles • Paris

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Ron Jones

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B041641
Date Received: 07/19/02
Date Analyzed: 07/22/02
Date Printed: 07/22/02
First Reported: 07/22/02

FASI Job ID: 2921-48

Job ID / Site:	JOB: Rosedale Elem School	Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
----------------	---------------------------	---------------	------------	---------------	------------------	---------------	------------------	---------------	------------------

LR-1

Layer: Off-White Plaster
Layer: Grey Plaster

Total Composite Values of Fibrous Components: Asbestos:(ND)

Cellulose (Trace%)

Comment: Collected on 07/18/2002

10172855

ND
ND

LR-2

Layer: Off-White Plaster
Layer: Grey Plaster

Total Composite Values of Fibrous Components: Asbestos:(ND)

Cellulose (Trace%)

Comment: Collected on 07/18/2002

10172856

ND
ND

LR-3

Layer: Off-White Plaster

Total Composite Values of Fibrous Components: Asbestos:(ND)

Cellulose (Trace%)

Comment: Collected on 07/18/2002

10172857

ND

cc: Mary
Kip
Bob
Bob B.
Lab
Bentley (3)
Jim

JUL 30 2002

Jim Flores

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification (LOQ) = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Results, reports or copies of same will not be released by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested by the client. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical reserves the right to dispose of a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Handwritten: 700-2921-48

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

Chico Unified School District

July 18, 2002

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Rosedale Library Restroom

To Whom It May Concern:

Please test the enclosed samples from the Rosedale Elementary School Library Restroom for asbestos. We would like a 24-hour turn around on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled:	Rosedale Elementary School
Location:	Library Restroom Wall Plaster
Date Sampled:	July 18, 2002
Number of Samples:	Three (3) #LR-1, #LR-2, #LR-3

Sample Taken by: Robert Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

BULK SAMPLE REQUEST FORM

IT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/18/02
		Circle the Method and Turn Around Time	Results Needed:
		24 hr/12hr/24hr/48hr/Ext	
		<u>PCM</u> : Standard / Point Count	Gravimetry Prep
CONTACT: ROB PETERS		TEM: QUAL. / QUANT. / WATER	
P.O.# 2921	JOB #	AA/Flame AA/Furnace ICP	
SITE: Roseville		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
LR-1	7/18	LIBRARY RESTROOM WALL PLASTER
LR-2	7/18	LIBRARY RESTROOM WALL PLASTER
LR-3	7/18	LIBRARY RESTROOM WALL PLASTER

Sampled by: ROB P.	Date: 7/18/02 Time: 11:20
Relinquished by: ROB P.	Received By: [Signature] 7/19/02
Date/Time: 7/18/02 11:20.	Date/Time: 7/19/02 10:52am
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO
	Sealed Condition (circle one) YES / NO



Forensic Analytical
Analytical Report

Preliminary FAX

Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist
Ron Jones

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B041641
Date Received: 07/19/02
Date Analyzed: 07/22/02
Date Printed: 07/22/02

Job ID / Site: JOB: Rosedale Elem School

FAI Job ID: 2921-48

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
---------------	------------	---------------	------------------	---------------	------------------	---------------	------------------

LR-1	10172855						
Layer: Off-White Plaster			ND				
Layer: Grey Plaster			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**
Cellulose (Trace%)

LR-2	10172856						
Layer: Off-White Plaster			ND				
Layer: Grey Plaster			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**
Cellulose (Trace%)

LR-3	10172857						
Layer: Off-White Plaster			ND				

Total Composite Values of Fibrous Components: **Asbestos:(ND)**
Cellulose (Trace%)

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification (LOQ) = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Forensic Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) who provided the sample(s) on which this report is based. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

cc: Mary
Kip
Bob M
Bob B
Rob
Bridges (3)
Jill

Handwritten:
H00
2001-48

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

Chico Unified School District

July 18, 2002

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Rosedale Library Restroom

To Whom It May Concern:

Please test the enclosed samples from the Rosedale Elementary School Library Restroom for asbestos. We would like a 24-hour turn around on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled:	Rosedale Elementary School
Location:	Library Restroom Wall Plaster
Date Sampled:	July 18, 2002
Number of Samples:	Three (3) #LR-1, #LR-2, #LR-3

Sample Taken by: Robert Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures



Forensic Analytical

BULK SAMPLE REQUEST FORM

IT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928	PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/18/02
	Circle the Method and Turn Around Time 24 hr/12hr/4hr/48hr/Ext	Results Needed:
	PCM: Standard / Point Count	
	CONTACT: ROB PETERS	
P.O.# 203	JOB #	TEM: QUAL / QUANT. / WATER
SITE: Rosedale		AA/Flame AA/Furnace ICP
		METALS:

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
LR-1	7/18	LIBRARY RESTROOM WALL PLASTER
LR-2	7/18	LIBRARY RESTROOM WALL PLASTER
LR-3	7/18	LIBRARY RESTROOM WALL PLASTER

Sampled by: ROB P.	Date: 7/18/02 Time: 11:20
Relinquished by: ROB P.	Received By: [Signature] 7/19/02
Date/Time: 7/18/02 11:20	Date/Time: 7/19/02 10:15am
Sealed Condition (circle one) YES / NO	
Inquished by:	Received By:
Date/Time:	Date/Time:
Sealed Condition (circle one) YES / NO	

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

73
PU#

Chico Unified School District

July 18, 2002

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Rosedale Library Restroom

To Whom It May Concern:

Please test the enclosed samples from the Rosedale Elementary School Library Restroom for asbestos. We would like a 24-hour turn around on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Rosedale Elementary School
Location: Library Restroom Wall Plaster
Date Sampled: July 18, 2002
Number of Samples: Three (3) #LR-1, #LR-2, #LR-3

Sample Taken by: Robert Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

cc: Mary
Pip
Bob M.
Bob B.
Rob
Amiles (3)
Jill



BULK SAMPLE REQUEST FORM

IT NAME & ADDRESS: 2921 Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/18/02
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	Results Needed:
		PCM: Standard / Point Count	
		Gravimetry Prep	
CONTACT: ROB-PETERS		TEM: QUAL. / QUANT. / WATER	
P.O.#	JOB #	AA/Flame AA/Furnace ICP	
SITE: Rosedale		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
LR-1	7/18	LIBRARY RESTROOM WALL PLASTER
LR-2	7/18	LIBRARY RESTROOM WALL PLASTER
LR-3	7/18	LIBRARY RESTROOM WALL PLASTER

Sampled by: ROB P.		Date: 7/18/02	Time: 11:20
Relinquished by: ROB P.		Received By:	
Date/Time: 7/18/02 11:20		Date/Time:	
		Sealed Condition (circle one) YES / NO	
Shed by:		Received By:	
Date/Time:		Date/Time:	
		Sealed Condition (circle one) YES / NO	

HMS, INC.
HAZARD MANAGEMENT SERVICES, INC.

CHICO UNIFIED SCHOOL DISTRICT
ROSEDALE ELEMENTARY SCHOOL
AHERA THREE-YEAR REINSPECTION SUMMARY
APRIL, 1992

Attached you will find a computer print-out of your original "Homogeneous Materials Record Sheets". You will find these sheets easier to read than the original copies. If additional samples were collected at this site, the results are listed at the end of the new "homogeneous" sheets. A comment on drywall sampling and lab accreditation sheets are added as appropriate.

At this site all previously or currently identified asbestos-containing materials were in good condition, i.e., non-friable.

We have given you a new index to insert into your management plan to account for new sections VIII and IX. We have added section VIII in which you should include results of your six-month inspections. We have also included a sheet on drywall sampling with recommendations on handling drywall. We also want to remind you that new buildings or portables must either be inspected or exempted by letter by your architect or builder.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **ROSEDALE**

BUILDING: **A**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST	1	RM 2	01-05	1900 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					

MUD JNTs	11	RM 3 BLR RM	70-75	53 J	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **ROSEDALE**

BUILDING: **B**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST	1	LOUNGE	01-05	411 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
CEILING PLAST	1	RM 7	01-05	411 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
CEILING PLAST	1	RM 9	01-05	411 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
CEILING PLAST	1	RRs	01-05	411 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
9" VFTs	9	RM 1 (5 CLS RMS)	01-05	4844 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD

School: ROSEDALE

Date Inspected: 04/15/92

BUILDING: C

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
----------	------------------	-----------	-------	---------	-------

9" VFTs	9	RM 1 (5 CLS RMS)	01-05	4844 S	0-Y
---------	---	------------------	-------	--------	-----

3 Year Inspection Notes:

Condition of Material:

Change in Condition? YES Abated? REMOVED

Comments:

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: ROSEDALE

BUILDING: D

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
CEILING PLAST	1	ALL RMS EXCEPT KITCH	01-05	0 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
9" VFTs	3	RM 11 ADMIN	05-10	208 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
9" VFTs	3	RM 15 MPR	05-10	2304 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	3	RM 16 KITCHEN	05-10	566 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	3	RM 17 STORAGE	05-10	140 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
9" VFTs	3	RM 18 FOOD SERVICES	05-10	80 S	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
 Date Inspected: **04/15/92**

School: **ROSEDALE**

BUILDING: **D**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	3	RM 19 HALL	05-10	1012 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
9" VFTs	3	RM 20 HALL	05-10	455 S	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
PW DEBRIS	5	RM 19 HALL(RDTR ACS)	65-70	3 L	0-Y
3 Year Inspection Notes: Condition of Material: Change in Condition? YES Abated? REMOVED Comments:					
4" PW STR	6	RM 17 STORAGE	01-05	15 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:Water Heater Closet.					
PW CNR	7	RM 17 STORAGE	01-05	10 J	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					
TRANS PIPE	90	RM 18 WTR HTR CLST	01-99 (ASSUMED)	10 L	1-4
3 Year Inspection Notes: Condition of Material: GOOD Change in Condition? NO Abated? NO Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
 Change in Condition: (N or 4) No (Y) Yes (Please explain)
 Abated: (R) Repaired (M) Removed (E) Enclsd
 (I) Isolated and Restricted

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**

School: **ROSEDALE**

Date Inspected: **04/15/92**

BUILDING: **D**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **ROSEDALE**

BUILDING: **E**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTs	1	RM 3	01-05	2100 S	0-Y
3 Year Inspection Notes:					
Condition of Material:					
Change in Condition? YES Abated? REMOVED					
Comments:					
9" VFTs	9	RM 1	01-05	2100 S	0-Y
3 Year Inspection Notes:					
Condition of Material:					
Change in Condition? YES Abated? REMOVED					
Comments:					
9" VFTs	9	RM 2	01-05	2100 S	0-Y
3 Year Inspection Notes:					
Condition of Material:					
Change in Condition? YES Abated? REMOVED					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: **Mike Sharp**

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: ROSEDALE

BUILDING: F

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
----------	------------------	-----------	-------	---------	-------

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD

School: ROSEDALE

Date Inspected: 04/15/92

BUILDING: G

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
9" VFTS	14	RM 14 & CLSRMS	15-20	6500 S	1-
3 Year Inspection Notes:					
Condition of Material: GOOD					
Change in Condition? NO Abated? NO					
Comments:					

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**
Date Inspected: **04/15/92**

School: **ROSEDALE**

BUILDING: **H**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: Chico USD
Date Inspected: 04/15/92

School: ROSEDALE

BUILDING: I

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes
----------	------------------	-----------	-------	---------	-------

Codes:

General Condition:	(1) Good	(2) Damaged	(3) Sig. Damaged
Change in Condition:	(N or 4) No	(Y) Yes	(Please explain)
Abated:	(R) Repaired	(M) Removed	(E) Enclsd
	(I) Isolated and Restricted		

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRs.

AHERA THREE YEAR REINSPECTION

School Dist: **Chico USD**

School: **ROSEDALE**

Date Inspected: **04/15/92**

BUILDING: **SUPPORT TRLR**

Material	Homog. Mat. #	Locations	% Asb	Footage	Codes

Codes:

General Condition: (1) Good (2) Damaged (3) Sig. Damaged
Change in Condition: (N or 4) No (Y) Yes (Please explain)
Abated: (R) Repaired (M) Removed (E) Enclsd
(I) Isolated and Restricted

Inspected By: Mike Sharp

These Reports should be placed in your AHERA file. Do not throw away old HMRS.

UNIVERSITY OF CALIFORNIA BERKELEY UNIVERSITY EXTENSION

This is to certify that

MICHAEL C. SHARP

has attended the

AHERA Refresher Course for Asbestos Inspectors and
Management Planners
November 26, 1991

Certificate number:

1428

Valid until: November 26, 1992



Deloral DA.

Chair
Programs in Environmental Hazard
Management

UNIVERSITY OF CALIFORNIA BERKELEY UNIVERSITY EXTENSION

This is to certify that

MICHAEL C. SHARP

has attended the

AHERA Refresher Course for Asbestos Abatement Project Designers
October 22, 1991

Certificate number:

Valid until: October 22, 1992



Deloral DA.

Chair
Programs in Environmental Hazard
Management

SIX MONTH SURVEILLANCE HOMOGENEOUS ASBM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	100	ASSUMED	1,900 S	ROOM 2 AND BOTH RESTROOMS	(1) REPLACED THE PLASTER. 1- Reconstructed	N

School: Rosedale Elementary

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED PLASTER. 1- Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	N
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24 - 28	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24 - 28 AND LOUNGE	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4) ↑	N
M	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	Same	N
M	TRANSITE PIPE	90	ASSUMED	10 L	ROOM 13 WATER HEATER CLOSET	(1) (4)	N
M	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1)	N
M	12" VFT	93	ASSUMED	3,000 S	OFFICES AND CAFETERIA -MULTI-PURPOSE ROOM	(1)	N

Reconstructed

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	94	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1) Same	N
M	12" VFT	95	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1) REPLACED 9" VFT BEIGE. SAME 11/06/02	N

School: Rosedale Elementary

Building: F (PORTABLES 3 & 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	103	ASSUMED	1,200 S	PORTABLES 3 & 4	(1) (4) Same	N
						LETTER	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13 - 18	(1) (4)	N
M	2 X 4 FCP'S	91	ASSUMED	6,500 S	CLASSROOMS 13 - 18 AND LIBRARY	(1)	N
M	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS AND WORKROOM	(1)	N
M	12" ACT	102	ASSUMED	250 S	WORKROOM	(1) (4)	N

Same

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: H (ROOMS 9 - 12)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT WHITE	18	NONE DETECTED	2,000 S	ROOMS 9 - 12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	105	ASSUMED	2,000 S	ROOMS 9 - 12	(1) Same	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 1/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: I (ROOMS 6-8)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	18	NONE DETECTED	1,600 S	ROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	106	ASSUMED	1,600 S	ROOMS 6, 7, & 8	(1) Same	N

School: Rosedale Elementary

Building: PORTABLES 5 & 5A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLES 5 & 5A	(1) Same	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS VEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL	100	ASSUMED	1,900 S	ROOM 2 AND BOTH RESTROOMS	(1) REPLACED THE PLASTER. 1 - Reconstructed	N

School: Rosedale Elementary

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED PLASTER.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS VEILLANCE HOMOGENEOUS CBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	N
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24 - 28	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24 - 28 AND LOUNGE	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4) ↑	N
M	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	(1) (4) Same	N
M	TRANSITE PIPE	90	ASSUMED	10 L	ROOM 18 WATER HEATER CLOSET	(1) (4) Same	N
M	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1) ↓	N
M	12" VFT	93	ASSUMED	3,000 S	OFFICES AND CAFETERIA - MULTI-PURPOSE ROOM	(1) ↓	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS VEILLANCE HOMOGENEOUS CBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	94	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1) Same	N
M	12" VFT	95	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1) REPLACED 9" VFT BEIGE.	N

School: Rosedale Elementary

Building: F (PORTABLES 3 & 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	103	ASSUMED	1,200 S	PORTABLES 3 & 4	(1) (4) Same	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS VEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13 - 18	(1) (4) ←	N
M	2 X 4 FCP'S	91	ASSUMED	6,500 S	CLASSROOMS 13 - 18 AND LIBRARY	(1)	N
M	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS AND WORKROOM	(1) Same →	N
M	12" ACT	102	ASSUMED	250 S	WORKROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS VEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: H (ROOMS 9 - 12)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	12" VFT WHITE	18	NONE DETECTED	2,000 S	ROOMS 9 - 12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	105	ASSUMED	2,000 S	ROOMS 9 - 12	(1) Same	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTHS SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: I (ROOMS 6-8)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	12" VFT	18	NONE DETECTED	1,600 S	ROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	106	ASSUMED	1,600 S	ROOMS 6, 7, & 8	(1) Same	N

School: Rosedale Elementary

Building: PORTABLES 5 & 5A

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	2 X 4 FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLES 5 & 5A	(1) Same	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS