SIX MONTH S[illegible]LLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Done with Dan G.

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA	(13) SAMPLE HMS-CHS-01 COLLECTED ON 3-28-88.	N/A
M	12" VFT BEIGE	2	TRACE	5,700 S	RECEPTION AREA	(1) (4) SAME 11/5/02	N
M	12" ACT	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, DW, & ROOMS 102-107	(13) SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (ROOM 111)	(1) (4) SAME 11/5/02	N
T	MESH WRAP	8	12-20%	½ L	DARK ROOM ATTIC (ROOM 111)	(11) INACCESSIBLE.	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWELLS	(1) (5) PANELS PAINTED WHITE. SAME 11/5/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: A (Unit 200) Upstairs

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BEIGE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4) SAMPLE	N
M	2' X 4' FCP	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88.	N/A

School: Chico Senior High School

Building: B (Unit 100)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	13	NONE DETECTED	10, 000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON 3-28-88.	N/A
M	12" VFT	14	1-5%	9,430 S	ALL CLASSROOMS	(1) (4) SAME 11/5/02	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWAYS	(1) (5) PANELS PAINTED WHITE. SAME 11/5/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

District: Chico Unified School District

Date of Inspection: 11/05/2002
Inspector: Robert Peters

School: Chico Senior High School

Building: C (Unit 300)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	9,513 S	ALL CLASSROOMS	(1) (4) SAME 11/5/02	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	EXTERIOR OF BUILDING	(1) (5) PANELS PAINTED WHITE. SAME 11/5/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: D & H (Unit 700 Music & Home EC)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	BOILER INSULATION	37	25-35%	48 S	HOME EC & BOILER ROOM	(1) (6) REPAIRED 1-4 SAME 11/05/02	N
S	TROWELED ON CEILING	38	1-5%	300 S	INSTRUMENT STORAGE ROOM & BAND ROOM OFFICE	(1) (4)	N
M	9" VFT YELLOW	39	5-10%	1,410 S	MUSIC WING HALL, CHORAL ROOM UNDER RISERS, BAND ROOM OFFICE, & CHORAL ROOM STORAGE	(7) REPLACED WITH 12" VFT GREY. (1) (4) 9" VFT UNDER CARPET IN BAND ROOM OFFICE.	N/A N
M	TRANSITE PEG BOARD	41	15-20%	1,000 S	BAND PRACTICE ROOM & CUSTODIAL ROOM	(2) PIECES BROKEN & MISSING. 12/27/01 (2) (4) 11/5/02 (5) (9) TAG BOARD	N
T	PIPEWRAP STRAIGHT	80	75-80%	58 L	HOME EC STORAGE CLOSET	(1) (4) SAME 11/05/02	N
T	PIPEWRAP STRAIGHT	81	75-80%	120 L	2ND HOME EC STORAGE CLOSET	(1) (4) SAME 11/05/02	N
T	PIPEWRAP CORNER	82	75-80%	>1 EACH	HOME EC STORAGE CLOSET	(1) (4) SAME 11/05/02	N
M	FIRE DOOR	83	25-35%	1 EACH	HOME EC HEATER ROOM	(1) (4) SAME 11/05/02	N
M	HOLDING TANK	94	ASSUMED	72 S	HOME EC HEATER ROOM	(1) (4) SAME 11/05/02	N
M	12" VFT GREY	100	ASSUMED	810 S	MUSIC WING HALL	(1) SAME 11/05/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

District: Chico Unified School District

Date of Inspection: 11/05/2002
Inspector: Robert Peters

School: Chico Senior High School

Building: 700 (Music)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	84	5-10%	58 L	HOME EC HEATER ROOM	(1) (4) SAME 11/05/02	N
T	PIPEWRAP AIRCELL	97	ASSUMED	70 L	UNDER CHORAL RISERS	(10)	N
M	TRANSITE PIPE	98	ASSUMED	8 L	HOME EC HEATER ROOM	(1) (4)	N

School: Chico Senior High School

Building: L (Unit 400 Library)

aterial Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	1,000 S	LIBRARY ENTRY & OFFICE AREA	(1) (4) SAME 11/05/02	N
M	2' X 4' FCP	17	NONE DETECTED	11,155 S	ALL ROOMS	(13) SAMPLE HMS-CHS-17 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	19	5-10%	20 JOINTS	LIBRARY ATTIC	(1) (6) REPAIRED 1/27/01 (1) (4) SAME 11/05/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: F (Unit 500)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(1) (4)	N
M	2' X 4' FCP	59	NONE DETECTED	4,500 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	60	5-10%	12 L	ROOM F-1	(1) (4) Same	N
M	9" VFT	61	TRACE	4,500 S	ALL CLASSROOMS	(1) (4)	N
M	TRANSITE PANELS	95	ASSUMED	150 S	2 KILNS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: S (Unit 600 Science)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	22	NONE DETECTED	8,000 S	ALL ROOMS	(13) SAMPLE HMS-CHS-22 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	23	5-10%	40 JOINTS	ALL ROOMS	(1) (4)	N
M	9" VFT	24	1-5%	8,100 S	ALL ROOMS	(1) (4)	N
T	PIPE WRAP STRAIGHT	26	65-70%	12 L	ROOM 5 (STORE ROOM)	(1) (6)	N
M	BLACK COUNTER TOPS	99	ASSUMED	UNDETERMINED	IN ALL SCIENCE ROOMS	(1) (4)	N

Same

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: __11/05/2002__

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: LH-800

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	3 L	CUSTODIAL ROOM	(1) (4) SAME 11/05/02	N
T	MUD JOINTS	52	5-10%	10 EACH	UNDER STAGE	(1) (4) SAME 11/05/02	N
M	9" VFT GREY	55	1-5%	6,800 S	KITCHEN & MPR	(1) (6) REPAIRED.	N
S	TROWELED ON CEILING	57	1-5%	900 S	ALL ROOMS	(1) (6) PAINTED.	N
M	TRANSITE PANELS	95	ASSUMED	364 S	SNACK BAR, STAGE, & CAFE	(1) (4) SAME 11/05/02	N
M	9" VFT	101	ASSUMED	250 S	UNDER STAGE	(1) (4) **STAGE REMOVED**	N
T	MUD JOINTS	102	5-10%	10 EACH	TEACHER'S LOUNGE RESTROOMS	(1) (4) SAME 11/05/02	N
M	TRANSITE PIPE	103	ASSUMED	12 L	WATER HEATER ROOM (2 PIPES)	(1) (4) SAME 11/05/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: __11/05/2002__

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 900 GYM

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88. ADDITIONAL SAMPLES HMS-93103-03A-C COLLECTED ON 7-8-93.	N/A
T	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM & BOILER ROOM CRAWL SPACE	(10) ISOLATED & RESTRICTED	N
						Same	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: IT-1000

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	700 L	AUTO SHOP, LOFT, & WOOD SHOP	(1) (4) Same	N
T	BREECHING	90	ASSUMED	100 S	WOOD FINISHING ROOM	(1) (4)	N

School: Chico Senior High School

Building: AG-1100

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	46	1-5%	950 S	AG CLASSROOM 2 (SPACE 3)	(1) (4) Same	N
M	TRANSITE PANELS	48	15-20%	200 S	AG SHOP WELD BOOTHS & TABLES	(1) (4)	N
M	12" VFT	89	ASSUMED	400 S	CLASSROOM	(1) (4)	N
M	TRANSITE PIPES	96	ASSUMED	12 L	AG SHOP (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 11/05/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 17 Portable Classrooms and 2 Portable Restrooms on West Campus

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
					17 PORTABLE CLASSROOM AND 2 PORTABLE RESTROOMS	DISTRICT CERTIFICATION REQUIRED.	
						Same	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]VEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	1	NONE DETECTED	5,735 S	ADMINISTRATION AREA	(13) SAMPLE HMS-CHS-01 COLLECTED ON 3-28-88.	N/A
M	12" VFT BEIGE	2	TRACE	5,700 S	RECEPTION AREA	(1) (4)	N
M	12" ACT	3	NONE DETECTED	3,550 S	PRINCIPLES OFFICE, COMPTROLLER, DW, & ROOMS 102-107	(13) SAMPLE HMS-CHS-03 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	7	5-10%	20 JOINTS	DARK ROOM ATTIC (ROOM 111)	(1) (4)	N
T	MESH WRAP	8	12-20%	½ L	DARK ROOM ATTIC (ROOM 111)	(11) INACCESSIBLE.	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWELLS	(1) (5) PANELS PAINTED WHITE.	N

same

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH [illegible]EILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: A (Unit 200) Upstairs

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT BEIGE	2	TRACE	5,800 S	UPSTAIRS CLASSROOMS	(1) (4)	N
M	2' X 4' FCP	6	NONE DETECTED	10,000 S	UPSTAIRS CLASSROOMS	(13) SAMPLE HMS-CHS-06 COLLECTED ON 3-28-88.	N/A

School: Chico Senior High School

Building: B (Unit 100)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	13	NONE DETECTED	10, 000 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-13 COLLECTED ON 3-28-88.	N/A
M	12" VFT	14	1-5%	9,430 S	ALL CLASSROOMS	(1) (4) Same	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	ALONG WALKWAYS, JANITORS CLOSETS, RESTROOMS, & STAIRWAYS	(1) (5) PANELS PAINTED WHITE.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]VEILLANCE
HOMOGENEOUS ACBM RECORDS

District: Chico Unified School District

Date of Inspection: 05/15/2002
Inspector: Robert Peters

School: Chico Senior High School

Building: C (Unit 300)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	9,513 S	ALL CLASSROOMS	(1) (4) Same	N
M	TRANSITE PANELS	95	ASSUMED	1,300 S	EXTERIOR OF BUILDING	(1) (5) PANELS PAINTED WHITE.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]VEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: D & H (Unit 700 Music & Home EC)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	BOILER INSULATION	37	25-35%	48 S	HOME EC & BOILER ROOM	(1) (6) REPAIRED 1-4	N
S	TROWELED ON CEILING	38	1-5%	300 S	INSTRUMENT STORAGE ROOM & BAND ROOM OFFICE	(1) (4)	N
M	9" VFT YELLOW	39	5-10%	1,410 S	MUSIC WING HALL, CHORAL ROOM UNDER RISERS, BAND ROOM OFFICE, & CHORAL ROOM STORAGE	(7) REPLACED WITH 12" VFT GREY. (1) (4) 9" VFT UNDER CARPET IN BAND ROOM OFFICE.	N/A N
M	TRANSITE PEG BOARD	41	15-20%	1,000 S	BAND PRACTICE ROOM & CUSTODIAL ROOM	(2) PIECES BROKEN & MISSING. 12/27/01 (2) (4)	N
T	PIPEWRAP STRAIGHT	80	75-80%	58 L	HOME EC STORAGE CLOSET	(1) (4)	N
T	PIPEWRAP STRAIGHT	81	75-80%	120 L	2ND HOME EC STORAGE CLOSET	(1) (4)	N
T	PIPEWRAP CORNER	82	75-80%	>1 EACH	HOME EC STORAGE CLOSET	(1) (4)	N
M	FIRE DOOR	83	25-35%	1 EACH	HOME EC HEATER ROOM	(1) (4)	N
M	HOLDING TANK	94	ASSUMED	72 S	HOME EC HEATER ROOM	(1) (4)	N
M	12" VFT GREY	100	ASSUMED	810 S	MUSIC WING HALL	(1)	N

Same

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]EILLANCE
HOMOGENEOU[illegible]CBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 700 (Music)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	84	5-10%	58 L	HOME EC HEATER ROOM	(1) (4)	N
T	PIPEWRAP AIRCELL	97	ASSUMED	70 L	UNDER CHORAL RISERS	(10) Same	N
M	TRANSITE PIPE	98	ASSUMED	8 L	HOME EC HEATER ROOM	(1) (4)	N

School: Chico Senior High School

Building: L (Unit 400 Library)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	14	1-5%	1,000 S	LIBRARY ENTRY & OFFICE AREA	(1) (4) Same	N
M	2' X 4' FCP	17	NONE DETECTED	11,155 S	ALL ROOMS	(13) SAMPLE HMS-CHS-17 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	19	5-10%	20 JOINTS	LIBRARY ATTIC	(1) (6) REPAIRED 1/27/01 (1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]EILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: F (Unit 500)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	MUD JOINTS	52	5-10%	125 JOINTS	FINE ARTS	(1) (4)	N
M	2' X 4' FCP	59	NONE DETECTED	4,500 S	ALL CLASSROOMS	(13) SAMPLE HMS-CHS-59 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	60	5-10%	12 L	ROOM F-1	(1) (4) Same	N
M	9" VFT	61	TRACE	4,500 S	ALL CLASSROOMS	(1) (4)	N
M	TRANSITE PANELS	95	ASSUMED	150 S	2 KILNS	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: S (Unit 600 Science)

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	22	NONE DETECTED	8,000 S	ALL ROOMS	(13) SAMPLE HMS-CHS-22 COLLECTED ON 3-28-88.	N/A
T	MUD JOINTS	23	5-10%	40 JOINTS	ALL ROOMS	(1) (4)	N
M	9" VFT	24	1-5%	8,100 S	ALL ROOMS	(1) (4)	N
T	PIPE WRAP STRAIGHT	26	65-70%	12 L	ROOM 5 (STORE ROOM)	(1) (6)	N
M	BLACK COUNTER TOPS	99	ASSUMED	UNDETERMINED	IN ALL SCIENCE ROOMS	(1) (4)	N

Same

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: LH-800

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	3 L	CUSTODIAL ROOM	(1) (4)	N
T	MUD JOINTS	52	5-10%	10 EACH	UNDER STAGE	(1) (4)	N
M	9" VFT GREY	55	1-5%	6,800 S	KITCHEN & MPR	(1) (6) REPAIRED.	N
S	TROWELED ON CEILING	57	1-5%	900 S	ALL ROOMS	(1) (6) PAINTED.	N
M	TRANSITE PANELS	95	ASSUMED	364 S	SNACK BAR, STAGE, & CAFE	(1) (4)	N
M	9" VFT	101	ASSUMED	250 S	UNDER STAGE	(1) (4) **STAGE REMOVED**	N
T	MUD JOINTS	102	5-10%	10 EACH	TEACHER'S LOUNGE RESTROOMS	(1) (4)	N
M	TRANSITE PIPE	103	ASSUMED	12 L	WATER HEATER ROOM (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 900 GYM

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALLS & CEILING PLASTER	46	NONE DETECTED	2,000 S	ALL ROOMS EXCEPT BOILER	(13) SAMPLE HMS-CHS-46A-C COLLECTED ON 3-28-88. ADDITIONAL SAMPLES HMS-93103-03A-C COLLECTED ON 7-8-93.	N/A
T	PIPEWRAP STRAIGHT	50	50-55%	2,700 S	GIRL'S & BOY'S LOCKER ROOM & BOILER ROOM CRAWL SPACE	(10) ISOLATED & RESTRICTED	N
						Same	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]VEILLANCE
HOMOGENEOU[illegible]ACBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: IT-1000

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT	45	35-40%	700 L	AUTO SHOP, LOFT, & WOOD SHOP	(1) (4) Same	N
T	BREECHING	90	ASSUMED	100 S	WOOD FINISHING ROOM	(1) (4)	N

School: Chico Senior High School

Building: AG-1100

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	WALL PLASTER	46	1-5%	950 S	AG CLASSROOM 2 (SPACE 3)	(1) (4)	N
M	TRANSITE PANELS	48	15-20%	200 S	AG SHOP WELD BOOTHS & TABLES	(1) (4) Same	N
M	12" VFT	89	ASSUMED	400 S	CLASSROOM	(1) (4)	N
M	TRANSITE PIPES	96	ASSUMED	12 L	AG SHOP (2 PIPES)	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH[illegible]VEILLANCE
HOMOGENEOU[illegible]CBM RECORDS

Date of Inspection: 05/15/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Senior High School

Building: 17 Portable Classrooms and 2 Portable Restrooms on West Campus

Material Class	Material	Homo. Mat. #	% Asb.	Ft^2/L.F.	Location	Condition: Code & Comments	Friable Yes/No
					17 PORTABLE CLASSROOM AND 2 PORTABLE RESTROOMS	DISTRICT CERTIFICATION REQUIRED.	
						Same	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Final Report

Forensic Analytical

San Francisco • Los Angeles • Paris

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B043320
Date Received: 09/19/02
Date Analyzed: 09/20/02
Date Printed: 10/02/02
First Reported: 09/20/02

Job ID / Site: JOB: Chico High Portable Restroom

FASI Job ID: 2921-44

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
PR-1	10184533						
Layer: Beige Sheet Flooring			**ND**				
Layer: Fibrous Backing			**ND**				
Layer: Yellow Mastic			**ND**				
Total Composite Values of Fibrous Components: **Asbestos:(ND)**							
Cellulose (20%) Fibrous Glass (5%) Synthetic (10%)							
Comment: Collected on 09/18/2002							
[redacted]	10184534						
[redacted]: Beige Sheet Flooring			**ND**				
Layer: Fibrous Backing			**ND**				
Layer: Yellow Mastic			**ND**				
Total Composite Values of Fibrous Components: **Asbestos:(ND)**							
Cellulose (20%) Fibrous Glass (5%) Synthetic (10%)							
Comment: Collected on 09/18/2002							
PR-3	10184535						
Layer: Beige Sheet Flooring			**ND**				
Layer: Fibrous Backing			**ND**				
Layer: Yellow Mastic			**ND**				
Total Composite Values of Fibrous Components: **Asbestos:(ND)**							
Cellulose (20%) Fibrous Glass (5%) Synthetic (10%)							
Comment: Collected on 09/18/2002							

[redacted] cc- Binders (3)

OCT [illegible]

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B043320
Date Received: 09/19/02
Date Analyzed: 09/20/02
Date Printed: 10/02/02
First Reported: 09/20/02

Job ID / Site: JOB: Chico High Portable Restroom

FASI Job ID: 2921-44

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from [illegible] This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

3777 Depot Road, Suite 409, Hayward, California 94545-2761 • Telephone: 510/887-8828 800/827-FASI Fax: 510/887-4218