

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
M	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1) (4)	N
M	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, AND RESTROOM	(1) (4)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP'S	107	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" ACT	108	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" VFT SALMON	109	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT GREEN	101	ASSUMED	2,200 S	HALLWAY	(1) DISTRICT MUST CERTIFY.	N
M	2' X 4' FCP'S	110	ASSUMED	4,500 S	CLASSROOMS 1-5	(1) DISTRICT MUST CERTIFY.	N
M	12" ACT	111	ASSUMED	2,500 S	HALLWAY	(1) DISTRICT MUST CERTIFY.	N
M	12" VFT SALMON	112	ASSUMED	4,500 S	CLASSROOMS 1-5	(1) (4) DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
M	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
M	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (4) REPLACED 9" VFT.	N
M	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
T	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(11)	N
M	9" VFT RED	100	ASSUMED	50 S	ADMINISTRATION STORAGE	(1) (4)	

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
M	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

Building: Portable Library
Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) (4) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

Building: Portable 18
Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	105	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
M	12" VFT	106	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: 6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary

Building: Portables 19-21

Unit: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	101	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Leroy Christophersen

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B089065
Date Received: 08/17/06
Date Analyzed: 08/18/06
Date Printed: 08/18/06
First Reported: 08/18/06

Job ID/Site: Hooker Oak Elementary School - PO# 050289


FASI Job ID: 2921

Date(s) Collected: 08/16/2006

Total Samples Submitted: 4

Total Samples Analyzed: 4

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HO001	10550970						
Layer: Tan Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (95 %)							
HO002	10550971						
Layer: Tan Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (95 %)							
HO003	10550972						
Layer: Tan Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (95 %)							
HO004	10550973						
Layer: Tan Fibrous Material			ND				
Layer: Paint			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (95 %)							



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

Chico Unified School District

Fed Ex Airbill #8358 1795 1087


August 16, 2006

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Hooker Oak Elementary School

To Whom It May Concern:

Please test the enclosed samples from the Principal's Office at Hooker Oak Elementary School for asbestos. We would like a 24-hour turnaround on the sample. Please e-mail the results as soon as they are available to lchristo@chicousd.org.



Site Sampled:	Hooker Oak Elementary School
Location:	Principal's Office Wall
Date Sampled:	August 16, 2006
Number of Samples:	Four – HO001, HO002, HO003, HO004


Thank you for your prompt response to this request.

Sincerely,

Leroy Christophersen
Safety & Loss Coordinator

Enclosures (1)
dlg

Hooker Oak School Principal's Office





Client Name & Address: Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		P.O. #: 050289 Date: 8/16/06 Turn Around Time: <u>24hr</u> hr/ 12hr 48 hr / ext: _____ Due Date: / / Due Time: : am/pm <input checked="" type="checkbox"/> PLM: <input checked="" type="checkbox"/> Standard / <input type="checkbox"/> Point Count <input type="checkbox"/> PCM: NIOSH 7400
Contact: Leroy Christophersen Phone #: 530-891-3195 Fax#: (530) 891-3190 Site: Hooker Oak Job:	<input type="checkbox"/> TEM Air: <input type="checkbox"/> AHERA / <input type="checkbox"/> Yamate2 / <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> TEM Bulk: <input type="checkbox"/> Quantitative / <input type="checkbox"/> Qualitative / <input type="checkbox"/> Chatfield <input type="checkbox"/> TEM Water: <input type="checkbox"/> Potable / <input type="checkbox"/> Non-Potable / <input type="checkbox"/> Wt % <input type="checkbox"/> TEM Microvac <input type="checkbox"/> Special Project: <input type="checkbox"/> Metals Analysis: Method _____ Matrix: _____ Analytes: _____	

Comments:

Sample ID	Date/Time	Sample Location/Description	FOR AIR SAMPLES ONLY				Sample Area or Air Volume
			Type	Time On/Off	Avg. LPM	Total Time	
HO 001	8/16	Principal Office wall	A				
			P				
			C				
HO 002	8/16		A				
			P				
			C				
HO 003	8/16		A				
			P				
			C				
HO 004			A				
		P					
		C					
		A					
		P					
		C					
		A					
		P					
		C					

Sampled by: Leroy Christophersen Date: 8/16/06 Time: 11:40 AM
Shipped via: Fed Ex Airborne UPS US Mail Courier Drop Off Other:

Relinquished by: Date / Time:	Relinquished by: Date / Time:	Relinquished by: Date / Time:
Received by: Date / Time: Condition Acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Received by: Date / Time: Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Received by: Date / Time: Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
M	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1) (4)	N
M	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, AND RESTROOM	(1) (4)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	2' X 4' FCP'S	107	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" ACT	108	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" VFT SALMON	109	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
M	12" VFT GREEN	101	ASSUMED	2,200 S	HALLWAY	(1) (4) DISTRICT MUST CERTIFY.	N
M	2' X 4' FCP'S	110	ASSUMED	4,500 S	CLASSROOMS 1-5	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" ACT	111	ASSUMED	2,500 S	HALLWAY	(1) (4) DISTRICT MUST CERTIFY.	N
M	12" VFT SALMON	112	ASSUMED	4,500 S	CLASSROOMS 1-5	(1) (4) DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
M	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
M	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (4) REPLACED 9" VFT.	N
M	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
T	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(11)	N
M	9" VFT RED	100	ASSUMED	50 S	ADMINISTRATION STORAGE	(1) (4)	
M	DRYWALL		NONE DETECTED		PRINCIPAL'S OFFICE	(13) CUSD SAMPLE HO 001-004 COLLECTION 8/16/06	

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
M	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

Building: Portable Library
Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) (4) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

Building: Portable 18
Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	105	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
M	12" VFT	106	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: 6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/29/06

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary

Building: Portables 19-21
Unit: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	101	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS