

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District

DATE December 28, 1993

SCHOOL Fairview High School

INSPECTOR Ron Jones

HOMOG. ASBESTOS
MAT.# MATERIAL LOCATION

BLDG.	HOMOG.	ASBESTOS MAT.# MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good (4)
MPR	Mud Jnt	65-70	Kitchen	(7)
MPR	9" VFT	1-5	MPR (Green)	2-5 6 tile damaged sw door 2-5 12 tile damaged ne door
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good (4)
MPR	Ceill plas	1-5	MPR	(2) (4)
MPR	Boil Insl	75-80	Boiler Room	(1) Good (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) Good (4)
MPR	Mud Jnt	35-40	Boiler Room	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

8/3
Fax TO:
Paul Kravos 891-3290
Bill Matthews 891-0994

Chico Unified School District
1163 East Seventh Street
Chico, CA 95928-5999
(916) 891-3210

SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

SECTION I (to be completed by contractor)

Date: August 3, 1993
Contractor organization: Bill Matthews - Tel-Tec
Address: 1682 Oak Vista Avenue, Chico, CA 95926
Description of work to be performed:
Install single line set & flashing light in cafeteria @ Fair View High School
Location(s) of work:
Cafeteria Office, Kitchen, Multi-purpose Room

SECTION II (to be completed by school district)

Type, amount and location of ACBM in work area:

NO ACBM IN WALL PLASTER IN WORK LOCATION.

AVOID DAMAGING FLOOR TILE OR CEILING PLASTER

It is the explicit condition of the performance of this work that no asbestos be disturbed.

Paul R. James Date: 8/6/93
LEA Designee
(school district)

Date: _____
(Worker/Contractor Signature)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 13, 1993

SCHOOL Fairview High School INSPECTOR Ron Jones *RJ*

BLDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

A	9" VFT	1-5	Rooms 1 & 2 (Beige)	(1) Good (4)
B	9" VFT	1-5	Rooms 4, 5, 3, 2	(1) Good (4)
MPR	Mud Jnt	65-70	Kitchen	(7)
MPR	9" VFT	1-5	MPR (Green)	2-5 6 tile damaged sw door 2-5 12 tile damaged ne door
MPR	9" VFT	1-5	Food Storage, ARS Office	(1) Good (4)
MPR	9" VFT	1-5	S-storage & Food storage	(1) Good (4)
MPR	Ceill plas	1-5	MPR	(2) (4)
MPR	Boil Insl	75-80	Boiler Room	(1) Good (4)
MPR	Tran pipe	Assumed	Boiler Room	(1) Good (4)
MPR	Mud Jnt	35-40	Boiler Room	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)