

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/03/2001

District: Chico Unified School District

Inspector: Robert Peters

School: District Office

Building: District Office

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	6	1-5%	100 S	COMPUTER ROOM OFFICE	(7) REPLACED WITH CARPET.	N/A
T	PIPE WRAP STRAIGHT	7	80-85%	350 L	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS.	N
T	PIPE WRAP JOINT	7	10-15%	350 L	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS	N
T	PIPE WRAP DEBRIS	7	25-35%	25 S	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS.	Y


CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

HMS, Inc.
HAZARD MANAGEMENT SERVICES, INC.

August 24, 2001



Mr. Rob Peters
Chico Unified School District
1163 E. Seventh Street
Chico, CA 95928

RE: Fourth Triennial AHERA Three-Year Reinspection

Dear Mr. Peters:

Enclosed is the data obtained from the fourth AHERA three-year reinspections Hazard Management Services, Inc. (HMS, Inc.) conducted between May 1, 2001 and May 16, 2001. The documents included with this letter are the "Three-Year Reinspection Homogeneous ACBM Material Records" covering all buildings known from the original inspection to contain ACBM. The sites inspected were the District Office, Marigold Elementary, Nord Elementary, Neal Dow Elementary, Hooker Oak Elementary, Cohasset Elementary, and the Corporate Yard. These are also provided on the enclosed diskette as per our contract.

You should review the updated Homogeneous Materials Reports to familiarize yourself with the current status of asbestos containing materials and identified suspect asbestos materials. It is the District's responsibility to assure that the school's site copy of the Management Plan is up to date and consistent with the District's Management Plan for that site. This is very important and if not done can cause the District to be penalized during an EPA site visit or investigation.

HMS, Inc. wants to remind you that materials containing "trace" amounts of asbestos must be considered in the event of renovations or demolitions. Although building materials containing trace amounts of asbestos (<1%) are not regulated under EPA, Cal/OSHA does regulate work practices with materials containing 0.1% asbestos. The original AHERA inspection contains information regarding materials with trace amounts of asbestos.

When you provide your annual notification to parents and staff, include information regarding this three-year reinspection. Enclosed is a suggested format for your notification letter. Please note that you must include in your Management Plans a description of the steps you take to notify. It is also important that your Management Plans be updated after any and all actions conducted which impact asbestos containing materials.

Please remember that HMS, Inc. did not inspect new buildings or portable classrooms which were placed on the District sites since the original EPA AHERA inspection. It is the District's responsibility to obtain letters of certification from the Architect, Construction Superintendent, or manufacturer of new building materials, indicating there is no asbestos in the new buildings (constructed after October 12, 1988) or new building materials. A copy of these certification letters must be included in your Management Plans, both at the school site and at the LEA Designees office site. It is still required of School Districts to send a copy of these certification letters to the US EPA AHERA unit; Region IX in San Francisco.

4200 Rocklin Rd., Ste. 11A
Rocklin, CA 95677
(916) 632-6800
(916) 632-6841 Fax

367 Civic Drive, Ste. 7
Pleasant Hill, CA 94523-5501
(925) 363-3442
(925) 363-7897 Fax

P.O. Box 576848
Modesto, CA 95357-6848
(209) 551-2000
(209) 575-5657 Fax

371 E. Bullard Ave., Ste. 109
Fresno, CA 93710
(559) 436-0277
(559) 436-0279 Fax

P.O. Box 21471
Bakersfield, CA 93390
(661) 588-5551
(661) 588-3827 Fax

Mr. Rob Peters
Chico Unified School District
August 24, 2001
Page Two

It is not necessary to send a copy of the three-year reinspection to the OPSC or EPA. However, the report should be included in your Management Plan. I want to thank you for your cooperation. If you have any questions, please feel free to contact me at (916) 632-6800.

Sincerely,



Richard Beall, CIH, CSP
Certified Asbestos Consultant
DOSH #92-0032

Enclosures
A\FINAL LETTER.wpd

Following is a suggested letter to district personnel, building occupants, and parents in order to meet the AHERA requirement of annual notification. Whatever notification you use, you put a dated, signed copy in the Management Plan. You must also include in the Management Plan a brief statement describing the steps you take to notify. Include the date(s) you did the six-month surveillances, and include any other actions you have taken with regards to asbestos or AHERA.

Date:

To: Parents, PTA, Teachers, Maintenance, Staff

From: AHERA Designee

RE: Asbestos Hazard Emergency Response Act (AHERA) Asbestos Inspections and Management Plans.

Chico Unified School District has hired Hazard Management Services, Inc. (HMS, Inc.), a consulting company, to complete the required three-year reinspection of all asbestos-containing building materials in the District. The reinspections for the District Office, Cohasset Elementary, Marigold Elementary, Nord Elementary, Neal Dow Elementary, Hooker Oak Elementary, and the Corporate Yard were completed between May 1, 2001 and May 16, 2001 by an accredited inspector, and the reinspection data has been incorporated into the Management Plan.

Also, during the past year the District has performed the required six-month surveillances on _____ . This information is also incorporated into the Management Plan.

A copy of the District's Management Plan is available for review during normal office hours in the office of the _____. If copies of the plan are desired, a nominal duplicating fee may be charged.

Authorized Signature

Date

RECORD OF FRIABLE AND NONFRIABLE ACM
(FORM B)

Inspection Date(s)
May 4, 2001

THREE-YEAR REINSPECTION

CDS CODE
04-61424-0000000

SCHOOL
DISTRICT OFFICE

SCHOOL PHONE NUMBER
(530) 898-3000

ADDRESS
1163 E. Seventh Street

(NUMBER)

(STREET)

(CITY)
Chico, CA

(ZIP)
95928

-IMPORTANT-

Each building and functional space with friable ACM or friable assumed ACM listed on this form requires completion of FORM C (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACM OR FRIABLE ASSUMED ACM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

LINE	BUILDING NAME & FUNCTIONAL SPACE (Indicate Address if Different From Above)	CHECK ONE			CHECK ONE			
		SUR- FACING	TSI	MISC	ACBM		ASSUMED ACM	
					FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	DISTRICT OFFICE		X			X		
2.	BASEMENT CRAWL SPACE - PIPE WRAP DEBRIS		X		X			
3.								
4.								
5.								
6.								
7.								
8.								
9.								
10.								
11.								
12.								
13.								
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 4, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: District Office

Building: District Office

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	6	1-5%	100 S	COMPUTER ROOM OFFICE	(7) REPLACED WITH CARPET.	N/A
T	PIPE WRAP STRAIGHT	7	80-85%	350 L	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS.	N
T	PIPE WRAP JOINT	7	10-15%	350 L	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS	N
T	PIPE WRAP DEBRIS	7	25-35%	25 S	BASEMENT CRAWL SPACE	(10) COULD NOT ACCESS.	Y

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**HAZARD MANAGEMENT SERVICES, INC.
ASSESSMENT OF TSI and/or FRIABLE MATERIAL**

District: Chico Unified School District

Date: May 4, 2001

School: District Office

Inspector: Richard Beall & Cory Sanders

Building & Location(s): Basement Crawl Space (Functional Area)

Sample#: HMS-DO-07C

% Asbestos- 25-35%

Homogeneous Mat. #7

Material description: Pipe Wrap Debris

Total amount of material this location: 25 ft²

Amount of friable material this location: 25 ft²

Damage	Local		Distributed	X	Damaged	98 - 99%
Type of Damage	Air Erosion	X	Water	X	Flaking	X
	Deterioration	X	Physical	X	Delamination	

Probable cause(s) of damage: Pipe wrap laying on ground.

POTENTIAL FOR DISTURBANCE				RESPONSE ACTIONS		PREVENTIVE MEASURES	
	H	M	L				
				Isolate/Restrict		Fix leaks	X
Accessibility	X			Repair/Cleanup	X	Prevent water contact	X
Vibration			X	Enclose		Do not drill, cut, sand, or grind	X
Air Erosion		X		Remove	X	Do not affix signs	X
Water		X		Encapsulate		Avoid contact	X
Occupancy			X	O & M			

Assessment of Material Condition

Significantly Damaged (Poor)

Damaged (Fair)

Not damaged (Good)

Potential Damage:
Hazard Ranking:


High
1

High Mod Low
2 3 4

High Mod Low
5 6 7

--	--	--	--	--	--	--	--


Comments & Observations:



Current MAP

5/14/01

Jerry Anderson



MAIN
DOOR
Bldg

Mini Office

Accty

Comp Rm

Bathrooms

Hallway

Hallway →

Personnel

Accty

Personnel

RECP

Snip Office

Staff Rm

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT



Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 Fax (916) 483-0572

206150032C 10
Richard Anthony Beall
Hazard Management Services Inc.
4200 Rocklin Road, Ste. 11A
Rocklin CA 95677

6/13/2000

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, please abide by the rules printed on the back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist

RA/dor

Attachment

c: File

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Richard Anthony Beall

Name

Certification No. 92-0032

Expires on 7/7/2001



This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code

University of California, Berkeley

U N I V E R S I T Y E X T E N S I O N

This is to confirm that

Richard A. Beall

has attended the eight hour

AHERA Refresher Course for Asbestos Inspectors and Management Planners

and has completed the requisite training for asbestos accreditation under TSCA Title II

September 27, 2000

Certificate number: 17
Valid until: September 27, 2001
Cal/OSHA approval number: CA-002-08



Richard V. Tsina

Richard V. Tsina
Chair, Environmental Management
UC Berkeley Extension
1995 University Avenue
Berkeley, CA 94720
(510) 643-7143

University of California, Berkeley

UNIVERSITY EXTENSION

This is to confirm that


Cory Sanders

has attended and satisfactorily passed the examination for the forty hour AHERA approved course
Building Inspection and Management Planning for Asbestos

and has completed the requisite training for asbestos accreditation under TSCA Title II

May 7-11, 2001

Date of Exam: May 11, 2001
Expiration Date: May 11, 2002
Certificate number: 3091
CAL/OSHA approval number: CA-002-07



Richard V. Tsina

Richard V. Tsina
Chair, Environmental Management
UC Berkeley Extension
1995 University Avenue
Berkeley, CA 94720
(510) 643-7143