

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Hooker Oak Elementary

Building: A

Material Class	Material	Hom. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
M	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1)	N
M	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, & RESTROOM	(1)	N

School: Hooker Oak Elementary

Building: B

Material Class	Material	Hom. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(1)	N
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1)	N
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(1)	N

Abated

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Hooker Oak Elementary

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Fiabile Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	N
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(1)	N
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Hooker Oak Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
M	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
M	2' X4' FCP'S	92	ASSUMED	2,500 S	MPR AND CLASSROOMS 11 & 12	(7) 2' X 4' FCP WERE REPLACED WITH 12" ACT'S.	N
M	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (12) REPLACED WITH 2" VFT.	N
M	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1)	N
T	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(1) (4)	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Hooker Oak Elementary

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17 (LIBRARY)	(14) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
M	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17 (LIBRARY)	(1) N	N

School: Hooker Oak Elementary

Building: Portable Library

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Hooker Oak Elementary

Building: Portable 18

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	2' X 4' VFT	105	ASSUMED	900 S	PORTABLE 18	(1) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
M	12" VFT	106	ASSUMED	900 S	PORTABLE 18	(2) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

School: Hooker Oak Elementary

Building: Portables 19-21

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	12" VFT	101	ASSUMED	2,700 S	PORTABLES 19-21	(3) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES 19-21	(4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N


CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

HMS, Inc.
HAZARD MANAGEMENT SERVICES, INC.

August 24, 2001



Mr. Rob Peters
Chico Unified School District
1163 E. Seventh Street
Chico, CA 95928

RE: Fourth Triennial AHERA Three-Year Reinspection

Dear Mr. Peters:

Enclosed is the data obtained from the fourth AHERA three-year reinspections Hazard Management Services, Inc. (HMS, Inc.) conducted between May 1, 2001 and May 16, 2001. The documents included with this letter are the "Three-Year Reinspection Homogeneous ACBM Material Records" covering all buildings known from the original inspection to contain ACBM. The sites inspected were the District Office, Marigold Elementary, Nord Elementary, Neal Dow Elementary, Hooker Oak Elementary, Cohasset Elementary, and the Corporate Yard. These are also provided on the enclosed diskette as per our contract.

You should review the updated Homogeneous Materials Reports to familiarize yourself with the current status of asbestos containing materials and identified suspect asbestos materials. It is the District's responsibility to assure that the school's site copy of the Management Plan is up to date and consistent with the District's Management Plan for that site. This is very important and if not done can cause the District to be penalized during an EPA site visit or investigation.

HMS, Inc. wants to remind you that materials containing "trace" amounts of asbestos must be considered in the event of renovations or demolitions. Although building materials containing trace amounts of asbestos (<1%) are not regulated under EPA, Cal/OSHA does regulate work practices with materials containing 0.1% asbestos. The original AHERA inspection contains information regarding materials with trace amounts of asbestos.

When you provide your annual notification to parents and staff, include information regarding this three-year reinspection. Enclosed is a suggested format for your notification letter. Please note that you must include in your Management Plans a description of the steps you take to notify. It is also important that your Management Plans be updated after any and all actions conducted which impact asbestos containing materials.

Please remember that HMS, Inc. did not inspect new buildings or portable classrooms which were placed on the District sites since the original EPA AHERA inspection. It is the District's responsibility to obtain letters of certification from the Architect, Construction Superintendent, or manufacturer of new building materials, indicating there is no asbestos in the new buildings (constructed after October 12, 1988) or new building materials. A copy of these certification letters must be included in your Management Plans, both at the school site and at the LEA Designees office site. It is still required of School Districts to send a copy of these certification letters to the US EPA AHERA unit; Region IX in San Francisco.

4200 Rocklin Rd., Ste. 11A
Rocklin, CA 95677
(916) 632-6800
(916) 632-6841 Fax

367 Civic Drive, Ste. 7
Pleasant Hill, CA 94523-5501
(925) 363-3442
(925) 363-7897 Fax

P.O. Box 576848
Modesto, CA 95357-6848
(209) 551-2000
(209) 575-5657 Fax

371 E. Bullard Ave., Ste. 109
Fresno, CA 93710
(559) 436-0277
(559) 436-0279 Fax

P.O. Box 21471
Bakersfield, CA 93390
(661) 588-5551
(661) 588-3827 Fax

Mr. Rob Peters
Chico Unified School District
August 24, 2001
Page Two

It is not necessary to send a copy of the three-year reinspection to the OPSC or EPA. However, the report should be included in your Management Plan. I want to thank you for your cooperation. If you have any questions, please feel free to contact me at (916) 632-6800.

Sincerely,



Richard Beall, CIH, CSP
Certified Asbestos Consultant
DOSH #92-0032

Enclosures
A:\FINAL LETTER.wpd

Following is a suggested letter to district personnel, building occupants, and parents in order to meet the AHERA requirement of annual notification. Whatever notification you use, you put a dated, signed copy in the Management Plan. You must also include in the Management Plan a brief statement describing the steps you take to notify. Include the date(s) you did the six-month surveillances, and include any other actions you have taken with regards to asbestos or AHERA.

Date:

To: Parents, PTA, Teachers, Maintenance, Staff

From: AHERA Designee

RE: Asbestos Hazard Emergency Response Act (AHERA) Asbestos Inspections and Management Plans.

Chico Unified School District has hired Hazard Management Services, Inc. (HMS, Inc.), a consulting company, to complete the required three-year reinspection of all asbestos-containing building materials in the District. The reinspections for the District Office, Cohasset Elementary, Marigold Elementary, Nord Elementary, Neal Dow Elementary, Hooker Oak Elementary, and the Corporate Yard were completed between May 1, 2001 and May 16, 2001 by an accredited inspector, and the reinspection data has been incorporated into the Management Plan.

Also, during the past year the District has performed the required six-month surveillances on _____ . This information is also incorporated into the Management Plan.

A copy of the District's Management Plan is available for review during normal office hours in the office of the _____. If copies of the plan are desired, a nominal duplicating fee may be charged.

Authorized Signature

Date

RECORD OF FRIABLE AND NONFRIABLE ACM
(FORM B)

Inspection Date(s)
May 1, 2001

THREE-YEAR REINSPECTION

CDS CODE
04-61424-6003008

SCHOOL
Hooker Oak Elementary

SCHOOL PHONE NUMBER
(530) 891-3119

ADDRESS
1238 Arbutus Avenue

(NUMBER)

(STREET)

(CITY)

(ZIP)

Chico, CA

95926

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of **FORM C** (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

LINE	BUILDING NAME & FUNCTIONAL SPACE (Indicate Address if Different From Above)	CHECK ONE			CHECK ONE			
		SUR- FACING	TSI	MISC	ACBM		ASSUMED ACBM	
					FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	A			X		X		X
2.	B			X				X
3.	C			X				X
4.	D			X		X		X
5.	E			X		X		X
6.	PORTABLE LIBRARY			X				X
7.	PORTABLE 18			X				X
8.	PORTABLES 19-21			X				X
9.								
10.								
11.								
12.								
13.								
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
M	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1)	N
M	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, & RES ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: B

Material Class	Material	Hom. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(1)	N
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1)	N
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	N
M	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(1)	N
M	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
M	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
M	2' X4' FCP'S	92	ASSUMED	2,500 S	MPR AND CLASSROOMS 11 & 12	(7) 2' X 4' FCP WERE REPLACED WITH 12" ACT'S.	N
M	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (12) REPLACED WITH 9" VFT.	N
M	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1)	N
T	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17 (LIBRARY)	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
M	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17 (LIBRARY)	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: Portable Library

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: Portable 18

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' VFT	105	ASSUMED	900 S	PORTABLE 18	(1) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
M	12" VFT	106	ASSUMED	900 S	PORTABLE 18	(1) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: May 1, 2001

District: Chico Unified School District

Inspector: Richard Beall/Cory Sanders

School: Hooker Oak Elementary

Building: Portables 19-21

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	101	ASSUMED	2,700 S	PORTABLES 19-21	(1) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
M	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES 19-21	(1) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

#19





#20

#21

LIBRARY

18

2 SC




1-SC

Current MAP
 05/01/01
 Copy [Signature]

HOOKER OAK ELEMENTARY

N
 ↓

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT



11 Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 Fax (916) 483-0572

206150032C 10
Richard Anthony Beall
Hazard Management Services Inc.
4200 Rocklin Road, Ste. 11A
Rocklin CA 95677

6/13/2000

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. To maintain your certification, please abide by the rules printed on the back of the certification card.

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist


RA/dor

Attachment

cc: File

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Richard Anthony Beall
Name



Certification No. 92-0032

Expires on 7/7/2001

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code

University of California, Berkeley

U N I V E R S I T Y E X T E N S I O N

This is to confirm that

Richard A. Beall

has attended the eight hour

AFHERA Refresher Course for Asbestos Inspectors and Management Planners
and has completed the requisite training for asbestos accreditation under TSCA Title II

September 27, 2000

Certificate number: 17
Valid until: September 27, 2001
Cal/OSHA approval number: CA-002-08



Richard V. Tsina

Richard V. Tsina
Chair, Environmental Management
UC Berkeley Extension
1995 University Avenue
Berkeley, CA 94720
(510) 643-7143

University of California, Berkeley

UNIVERSITY EXTENSION

This is to confirm that

Cory Sanders


has attended and satisfactorily passed the examination for the forty hour AHERA approved course

Building Inspection and Management Planning for Asbestos

and has completed the requisite training for asbestos accreditation under TSCA Title II

May 7-11, 2001

Date of Exam: May 11, 2001
Expiration Date: May 11, 2002
Certificate number: 3091
CAL/OSHA approval number: CA-002-07



Richard V. Tsina

Richard V. Tsina
Chair, Environmental Management
UC Berkeley Extension
1995 University Avenue
Berkeley, CA 94720
(510) 643-7143