

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	DRYWALL	100	ASSUMED	1,900 S	ROOM 2 AND BOTH RESTROOMS	(1) REPLACED THE PLASTER. 1 - Reconstructed	N

School: Rosedale Elementary

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 19 - 23 AND LOUNGE	(1) REPLACED PLASTER. 1 - Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	97	ASSUMED	200 S	BOTH RESTROOMS	(1)	N
M	12" VFT	98	ASSUMED	4,000 S	CLASSROOMS 24 - 28	(1) REPLACED 9" VFT.	N
M	2 X 4 FCP'S	99	ASSUMED	4,000 S	CLASSROOMS 24 - 28 AND LOUNGE	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4)	N
M	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	(1) (4)	N
M	TRANSITE PIPE	90	ASSUMED	10 L	ROOM 18 WATER HEATER CLOSET	(1) (4)	N
M	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1)	N
M	12" VFT	93	ASSUMED	3,000 S	OFFICES AND CAFETERIA -MULTI-PURPOSE ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	94	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1)	N
M	12" VFT	95	ASSUMED	2,100 S	ROOMS 1, 2A, 2B, AND 3	(1) REPLACED 9" VFT BEIGE.	N

Building: F (PORTABLES 3 & 4)							Friable Yes/No
Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	103	ASSUMED	1,200 S	PORTABLES 3 & 4	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	15	15-20%	6,500 S	CLASSROOMS 13 - 18	(1) (4)	N
M	2 X 4 FCP'S	91	ASSUMED	6,500 S	CLASSROOMS 13 - 18 AND LIBRARY	(1)	N
M	DRYWALL	101	ASSUMED	500 S	BOTH RESTROOMS AND WORKROOM	(1)	N
M	12" ACT	102	ASSUMED	250 S	WORKROOM	(1) (4)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: H (ROOMS 9 - 12)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT WHITE	18	NONE DETECTED	2,000 S	ROOMS 9 - 12	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM TAN	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	105	ASSUMED	2,000 S	ROOMS 9 - 12	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 12/27/2001

District: Chico Unified School District

Inspector: Robert Peters

School: Rosedale Elementary

Building: I (ROOMS 6-8)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	18	NONE DETECTED	1,600 S	ROOMS 6, 7, & 8	(13) REPRESENTED SAMPLE HMS-RSD-18 WAS COLLECTED ON 3-31-88.	N/A
M	LINOLEUM	21	NONE DETECTED	375 S	BOTH RESTROOMS	(13) REPRESENTED SAMPLE HMS-RSD-21 WAS COLLECTED ON 3-31-88.	N/A
M	2 X 4 FCP'S	106	ASSUMED	1,600 S	ROOMS 6, 7, & 8	(1)	N

School: Rosedale Elementary

Building: PORTABLES 5 & 5A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2 X 4 FCP'S	107	ASSUMED	600 S	CEILING OF PORTABLES 5 & 5A	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

HMS, Inc.
HAZARD MANAGEMENT SERVICES, INC.

August 31, 2001

Mr. Rob Peters
Chico Unified School District
1163 E. Seventh Street
Chico, CA 95928

RE: Fourth Triennial AHERA Three-Year Reinspection

Dear Mr. Peters:


Enclosed is the data obtained from the fourth AHERA three-year reinspections Hazard Management Services, Inc. (HMS, Inc.) conducted between May 14 and May 31, 2001. The documents included with this letter are the "Three-Year Reinspection Homogeneous ACBM Material Records" covering all buildings known from the original inspection to contain ACBM. The sites enclosed are Bidwell Junior High, Partridge Elementary, Rosedale Elementary, and ~~Shasta Elementary~~.

You should review the updated Homogeneous Materials Reports to familiarize yourself with the current status of asbestos containing materials and identified suspect asbestos materials. It is the District's responsibility to assure that the school's site copy of the Management Plan is up to date and consistent with the District's Management Plan for that site. This is very important and if not done can cause the District to be penalized during an EPA site visit or investigation.

HMS, Inc. wants to remind you that materials containing "trace" amounts of asbestos must be considered in the event of renovations or demolitions. Although building materials containing trace amounts of asbestos (<1%) are not regulated under EPA, Cal/OSHA does regulate work practices with materials containing 0.1% asbestos. The original AHERA inspection contains information regarding materials with trace amounts of asbestos.

When you provide your annual notification to parents and staff, include information regarding this three-year reinspection. Enclosed is a suggested format for your notification letter. Please note that you must include in your Management Plans a description of the steps you take to notify. It is also important that your Management Plans be updated after any and all actions conducted which impact asbestos containing materials.

Please remember that HMS, Inc. did not inspect new buildings or portable classrooms which were placed on the District sites since the original EPA AHERA inspection. It is the District's responsibility to obtain letters of certification from the Architect, Construction Superintendent, or manufacturer of new building materials, indicating there is no asbestos in the new buildings (constructed after October 12, 1988) or new building materials. A copy of these certification letters must be included in your management plans, both at the school site and at the LEA Designees office site. It is still required of School Districts to send a copy of these certification letters to the US EPA AHERA unit; Region IX in San Francisco.



4200 Rocklin Rd., Ste. 11A
Rocklin, CA 95677
(916) 632-6800
(916) 632-6841 Fax

367 Civic Drive, Ste. 7
Pleasant Hill, CA 94523-5501
(925) 363-3442
(925) 363-7897 Fax

P.O. Box 576848
Modesto, CA 95357-6848
(209) 551-2000
(209) 575-5657 Fax


371 E. Bullard Ave., Ste. 109
Fresno, CA 93710
(559) 436-0277
(559) 436-0279 Fax

P.O. Box 21471
Bakersfield, CA 93390
(661) 588-5551
(661) 588-3827 Fax

Mr. Rob Peters
Chico Unified School District
August 31, 2001
Page Two

It is not necessary to send a copy of the three-year reinspection to the OPSC or EPA. However, the report should be included in your Management Plan. I want to thank you for your cooperation. If you have any questions, please feel free to contact me at (916) 632-6800.

Sincerely,



Douglas R. Colley
Senior Projects Manager
CAC #92-0222

Enclosures

C:\REINSPT\Chico.SD\00-01\FINAL LETTER.wpd

Following is a suggested letter to district personnel, building occupants, and parents in order to meet the AHERA requirement of annual notification. Whatever notification you use, you put a dated, signed copy in the Management Plan. You must also include in the Management Plan a brief statement describing the steps you take to notify. Include the date(s) you did the six-month surveillances, and include any other actions you have taken with regards to asbestos or AHERA.

Date:

To: Parents, PTA, Teachers, Maintenance, Staff

From: AHERA Designee

RE: Asbestos Hazard Emergency Response Act (AHERA) Asbestos Inspections and Management Plans.

Chico Unified School District has hired Hazard Management Services, Inc. (HMS, Inc.), a consulting company, to complete the required three-year reinspection of all asbestos-containing building materials in the District. The reinspection for Bidwell Junior High, Partridge Elementary, Rosedale Elementary, and Shasta Elementary was completed on May 31, 2001 by an accredited inspector, and the reinspection data has been incorporated into the Management Plan.

Also, during the past year the District has performed the required six-month surveillances on _____. This information is also incorporated into the Management Plan.

A copy of the District's Management Plan is available for review during normal office hours in the office of the Superintendent. If copies of the plan are desired, a nominal duplicating fee may be charged.

Authorized Signature

Date

**RECORD OF FRIABLE AND NONFRIABLE ACM
(FORM B)**

Inspection Date(s) 5-17-01

THREE-YEAR REINSPECTION

SCHOOL ROSEDALE ELEMENTARY					CDS CODE 04-61424-6003081
ADDRESS (NUMBER) (STREET) (CITY) (ZIP) 100 OAK STREET CHICO, CA 95928					SCHOOL PHONE NUMBER (530) 891-3104

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of **FORM C** (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

LINE	BUILDING NAME & FUNCTIONAL SPACE (Indicate Address if Different From Above)	CHECK ONE			CHECK ONE			
		SUR- FACING	TSI	MISC	ACBM		ASSUMED ACBM	
					FRIABLE	NON- FRIABLE	FRIABLE	NON- FRIABLE
1.	A			X				X
2.	B			X				X
3.	C			X				X
4.	D	X		X		X		X
5.	E			X				X
6.	F (PORTABLES 3 & 4)			X				X
7.	G			X		X		X
8.	H			X				X
9.	I			X				X
10.	PORTABLES 5 & 5A			X				X
11.								
12.								
13.								
14.								
15.								
16.								
17.								

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

THREE-YEAR INSPECTION

Date of Inspection: 5-17-01

Chico Unified School District

Inspector: Cory Sanders/Douglas R. Colley

Rosedale Elementary

Building: A

[illegible]

CONDITION CODE

General Condition:

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(5) Yes (If Yes, explain under comments)

Abated:

	(6) Repaired	(7) Removed	(8) Encapsulated	(9) Enclosed	(10) Isolated & Restricted
1. Structural					
2. Exterior					
3. Interior					
4. Roof					
5. Foundation					
6. Other					
7. Electrical					
8. Plumbing					
9. HVAC					
10. Other					
11. Other					
12. Other					
13. Other					
14. Other					
15. Other					
16. Other					
17. Other					
18. Other					
19. Other					
20. Other					
21. Other					
22. Other					
23. Other					
24. Other					
25. Other					
26. Other					
27. Other					
28. Other					
29. Other					
30. Other					
31. Other					
32. Other					
33. Other					
34. Other					
35. Other					
36. Other					
37. Other					
38. Other					
39. Other					
40. Other					
41. Other					
42. Other					
43. Other					
44. Other					
45. Other					
46. Other					
47. Other					
48. Other					
49. Other					
50. Other					
51. Other					
52. Other					
53. Other					
54. Other					
55. Other					
56. Other					
57. Other					
58. Other					
59. Other					
60. Other					
61. Other					
62. Other					
63. Other					
64. Other					
65. Other					
66. Other					
67. Other					
68. Other					
69. Other					
70. Other					
71. Other					
72. Other					
73. Other					
74. Other					
75. Other					
76. Other					
77. Other					
78. Other					
79. Other					
80. Other					
81. Other					
82. Other					
83. Other					
84. Other					
85. Other					
86. Other					

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 5-17-01

Inspector: Cory Sanders/Douglas R. Colley

Building: B

CONDITION CODE

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

General Condition:
Change in Condition:
Abated:
Miscellaneous:

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 5-17-01

District: Chico Unified School District

Inspector: Cory Sanders/Douglas R. Colley

School: Rosedale Elementary

Building: C

[illegible]

CONDITION CODE

General Condition:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired	(7) Removed	(8) Encapsulated	(9) Enclosed	(10) Isolated & Restricted
--------------	-------------	------------------	--------------	----------------------------

Miscellaneous:

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

THREE-YEAR INSPECTION HOMOGENEOUS ACBM RECORDS

Date of Inspection: 5-17-01

District: Chico Unified School District

Inspector: Cory Sanders/Douglas R. Colley

School: Rosedale Elementary

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frangible Yes/No
S	PLASTER	1	1-5%	350 S	CUSTODIAN ROOM	(1) (4)	N
M	9" VFT GREEN	3	5-10%	3,200 S	MULTI-PURPOSE ROOM, KITCHEN, KITCHEN STORAGE, AND STORAGE ROOM	(1) (4)	N
M	TRANSITE PIPE	90	ASSUMED	10 L	ROOM 18 WATER HEATER CLOSET	(1) (4)	N
M	12" VFT	92	ASSUMED	100 S	ENTRY OF OFFICE	(1)	N
M	12" VFT	93	ASSUMED	3,000 S	OFFICES AND CAFETERIA -MULTI-PURPOSE ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 5-17-01

Inspector: Cory Sanders/Douglas R. Colley

Building: E

Friable
Yes/No

General Condition:
Change in Condition:
Abated:
Miscellaneous:

(1) Good	(2) Damaged	(3) Significantly Damaged (25% or more)
(4) No	(5) Yes (If Yes, explain under comments)	
(6) Repaired	(7) Removed	(8) Encapsulated
(9) Isolated & Restricted	(10) Enclosed	(11) Inaccessible, no inspection data
(12) Other (Explain under comments)	(13) Non-Asbestos/Not Inspected	

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 5-17-01

Inspector: Cory Sanders/Douglas R. Colley

Building: G

Friable
Yes/No

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Building: H (ROOMS 9 - 12)

[illegible]

CONDITION CODE

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments)
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Enclosed under comments
 (11) Inaccessible, no inspection data (12) Other (Explain under comments)

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Date of Inspection: 5-17-01

Inspector: Cory Sanders/Douglas R. Colley

Building: 1 (ROOMS 6-8)

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

MAP OF ROSEDALE SCHOOL

Boiler


Spec Need	Quile Room
WIEGERT	
Gr 5	12
Gr 4	11
NICHOLS	
	10
	9
Gr 4	
NAAS	

Work Room

MURGIA	Gr 5/6	Gr 5/6	18
15	TV/PARENT AREA	MORRISON	17
OLSEN		Gr 6	FORESTER
14	SDC		16
13	Gr 3/4	DAVIS	Gr 3-6
HEES			

Gr 2	23	Gr 2	28
WILSON		HARRIS	
Gr 3	22	Gr 1/2	27
DUCHALA		GUALOTUNA	
Gr 1/2	21	Gr K/1	26
WARD		GUFFY	
Gr 3	20	MUSIC	25
LOWE/DUNCAN		Gr 1	24
FINE ARTS		NANNING	
Lounge	W	W	
	M	M	

Kitchen	RESTROOM	HEALTH
M/W	OFFICE (891-3104)	PRIN
OFFICE		



PM K PERSONETT

PM K TARESH

HEALTHY START

(895-2639)

Head Start

(895-2640)


Speech (895-7544)

Counselor (891-3160)

RESOURCE	5
ESL	2
SALAS	

Current MAP
05/17/01
Cory Sander

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT



Park Towne Circle, Suite 1
Sunnyvale, CA 95825
(415) 574-2993 Fax (916) 483-0572

207010222C 11
Douglas R Colley
Hazard Management Services Inc.
4200 Rocklin Road, Suite 11A
Rocklin CA 95767

8/14/2000

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, please abide by the rules printed on the back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist

RA/dor

Attachment

File

State of California
Division of Occupational Safety and Health

Certified Asbestos Consultant

Douglas R Colley

Name

Certification No. **92-0222**

Expires on **9/17/2001**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code



CAL

ENVIRONMENTAL

SERVICES

INC

This is to certify that

Douglas R. Colley

has successfully completed the EPA approved A.H.E.R.A. course for

Asbestos Building Inspector/Management Planner Refresher

as required under TSCA Title II

8/1/2000 to 8/1/2000

Course Date(s)

David Esparza

David Esparza - President

8/1/2001

Expiration Date

CA - 001 - 06

AC-22870

CA - 001 - 08

Certificate Number

Cal/OSHA Course Approval #

CAL INC 2040 Peabody Rd Vacaville, CA 95696 707-446-7996

CAL

ENVIRONMENTAL

SERVICES

INC

This is to certify that

Douglas R. Colley

has successfully completed the EPA approved A.H.E.R.A. course for
Asbestos Building Inspector/Management Planner Refresher
as required under TSCA Title II

8/1/2000 to 8/1/2000

Course Date(s)

David Esparza

David Esparza - President

8/1/2001

Expiration Date

CA - 001 - 06

AC-22870

CA - 001 - 08

Certificate Number

Cal/OSHA Course Approval #

CAL INC 2040 Peabody Rd Vacaville, CA 95696 707-446-7996

University of California, Berkeley

UNIVERSITY EXTENSION

This is to confirm that

Cory Sanders

has attended and satisfactorily passed the examination for the forty hour AHERA approved course

Building Inspection and Management Planning for Asbestos

and has completed the requisite training for asbestos accreditation under TSCA Title II

May 7-11, 2001

Date of Exam: May 11, 2001
Expiration Date: May 11, 2002
Certificate number: 3091
CAL/OSHA approval number: CA-002-07



Richard V. Tsina

Richard V. Tsina
Chair, Environmental Management
UC Berkeley Extension
1995 University Avenue
Berkeley, CA 94720
(510) 643-7143