

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: A

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET (New sheet in R/C of restroom)	(2) (5) CRACKS, PAINT PEELING	N

School: Sierra View Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) SAME 11/25/03	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

CONDITION CODE

General Condition:

(1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No (5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: C

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) <i>Same</i>	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) All Rooms Reconstructed	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: D

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN & STORAGE	(2) (5) CHIPPING - HOLES	N
T	PIPE WRAP AIR CELL	8	15-20%	13 L	MECHANICAL ROOM	(1) (4) SAME 11/25/03	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) Reconstructed	N
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) Reconstructed	N
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4) SAME 11/25/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: E

Reconstructed 1993 #8650.10 ,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(2) (5) CRACK	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(1) (4) SAME 11/25/03	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOM	(1) Reconstructed	N

School: Sierra View Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4)	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) Same	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(2) (5) FALLING OUT	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: G

Reconstructed 1993 #8650.10 ,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4) ↑	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) Same	N
M	2' X 4' FCP	95	ASSUMED	900 S	ROOM 12 (PORTABLE)	(2) (5) BROKE	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(2) (5) BROKE - SCRAPED	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) SAME 11/25/03	N

School: Sierra View Elementary School

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) (4) Same	N
M	12" VFT	94	ASSUMED	600 S	ROOM 6 (LAB) & ROOM 7 (RSP)	(1)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) Relocatables	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Sierra View Elementary School

Building: I

Reconstructed 1993 #8650.10 ,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(1) Same	N
M	12" VFT	105	ASSUMED	200 S	ROOMS 22, 23, & WORKROOM	(1) THESE ROOMS ARE PORTABLES WITH UNREADABLE I.D'S.	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	ROOMS 22, 23, & WORKROOM	(2) (5) HOLES	N

School: Sierra View Elementary School

Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	300 S	PORTABLES 24-26 (NEXT TO SINKS)	(1) (4) Same	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLES 24-26	(1) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLES 24-26	(1) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED. Letter on File	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 11-25-2003

District: Chico Unified School District
School: Sierra View Elementary School

Inspector: Robert Baughman
Building: Portable 27

Reconstructed 1993 #8650.10 ,
93-05, and 9610.21.5

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE 27	(1) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' x 4' FCP	85	ASSUMED	900 S	PORTABLE 27	(1) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N

Letters on File

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: A

Reconstructed 1993 #8650.10,
93-05, and 9610.21.5

Met with Gary

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
S	WALL PLASTER	4	ASSUMED	1,000 S	GIRL'S & BOY'S RESTROOM & CUSTODIAN CLOSET (New sheet in R/C of restroom)	(1) (4) Same	N

School: Sierra View Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes/No
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" VFT BLUE/WHITE	94	ASSUMED	500 S	WORKROOM & CLASSROOMS 18-21	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING MOST OF THE FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,000 S	WORKROOM & CLASSROOMS 18-21	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

CONDITION CODE

General Condition:

(1) Good

(2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition:

(4) No

(5) Yes (If Yes, explain under comments)

Abated:

(6) Repaired

(7) Removed (8) Encapsulated

(9) Enclosed (10) Isolated & Restricted

Miscellaneous:

(11) Inaccessible, no inspection data

(12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	TRANSITE PANELS	83	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) <i>Same</i>	N
M	12" VFT BLUE/WHITE	94	ASSUMED	750 S	STAFF ROOM & CLASSROOMS 13-17	(1) STRIPS AT ROOM ENTRANCES WITH CARPET COVERING THE MAJORITY OF FLOOR SPACE.	N
M	2' X 4' FCP	99	ASSUMED	4,500 S	STAFF ROOM & CLASSROOMS 13-17	(1) All Rooms Reconstructed	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1) Reconstructed	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	1,200 S	KITCHEN & STORAGE	(1) (4)	N
T	PIPE WRAP AIR CELL	8	15-20%	13 L	MECHANICAL ROOM	(1) (4) <i>Same</i>	N
M	12" VFT BLUE/WHITE	94	ASSUMED	3,500 S	OFFICE HALLWAY & MPR	(1) Reconstructed	N
M	12" ACT	97	ASSUMED	1,600 S	OFFICE HALLWAY CEILING & ALL THREE OFFICES	(1) Reconstructed	N
T	TRANSITE PIPE	98	ASSUMED	20 L	MECHANICAL ROOM	(1) (4) <i>Same</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: E

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	PLASTER	3	1-5%	500 S	CUSTODIAN CLOSET	(1) (4) <i>Same</i>	N
T	MUD JOINT	12	60-65%	30 L	BOILER ROOM	(1) (4)	N
M	DRYWALL & JOINT COMPOUND	96	ASSUMED	1,000 S	BOY'S & GIRL'S RESTROOM	(1) Reconstructed	N

School: Sierra View Elementary School

Building: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	400 S	SPEECH ROOM & BREAKROOM	(1) (4) <i>Same</i>	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4)	N
M	12" ACT	17	ASSUMED	2,000 S	CLASSROOMS 2-5, BREAKROOM, & SPEECH ROOM	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: G

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
S	PLASTER	3	1-5%	350 S	PIP ROOM	(1) (4) ←	N
M	9" VFT GREEN	14	1-5%	4,000 S	CLASSROOMS 8-11 & PIP ROOM	(1) (4)	N
T	TRANSITE PANELS	83	ASSUMED	16 PANELS	UNDER WINDOWS THROUGHOUT BUILDING	(1) (4) Same	N
M	2' X 4' FCP	95	ASSUMED	900 S	ROOM 12 (PORTABLE)	(1)	N
M	12" ACT	97	ASSUMED	2,400 S	CLASSROOMS 8-11	(1)	N
M	LINOLEUM	100	ASSUMED	50 S	RESTROOM	(1)	N

School: Sierra View Elementary School

Building: H

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	93	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) (4)	N
M	12" VFT	94	ASSUMED	600 S	ROOM 6 (LAB) & ROOM 7 (RSP)	(1)	N
M	12" ACT	97	ASSUMED	600 S	LIBRARY	(1)	N
M	2' X 4' FCP	99	ASSUMED	2,100 S	ROOM 6 (LAB), ROOM 7 (RSP), & ROOM 1	(1) Relocatables	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: I

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	LINOLEUM	102	ASSUMED	200 S	RESTROOMS	(1) Same	N
M	12" VFT	105	ASSUMED	200 S	ROOMS 22, 23, & WORKROOM	(1) THESE ROOMS ARE PORTABLES WITH UNREADABLE I.D'S.	N
M	2' X 4' FCP	106	ASSUMED	1,200 S	ROOMS 22, 23, & WORKROOM	(1)	N

School: Sierra View Elementary School

Building: Portables 24, 25, & 26

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" VFT	86	ASSUMED	300 S	PORTABLES 24-26 (NEXT TO SINKS)	(1) (4) Same	N
M	DRYWALL	87	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS, & PORTABLES 24-26	(1) DRYWALL COULD BE BEHIND THE TAGBOARD IN PORTABLES 24-26.	N
M	LINOLEUM	88	ASSUMED	1,400 S	BOY'S & GIRL'S RESTROOMS	(1) THESE RESTROOMS ARE ADJACENT TO PORTABLE 26.	N
M	2' X 4' FCP	89	ASSUMED	1,800 S	PORTABLES 24-26	(1) THESE UNITS WERE MANUFACTURED IN 8-89. DISTRICT CERTIFICATION REQUIRED. <i>Letter on File</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection 05/09/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Sierra View Elementary School

Building: Portable 27

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	84	ASSUMED	900 S	PORTABLE 27	(1) COULD BE BEHIND THE TAG BOARD. MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
M	2' x 4' FCP	85	ASSUMED	900 S	PORTABLE 27	(1) MANUFACTURES DATE 6-98. DISTRICT CERTIFICATION REQUIRED.	N
						Letters on File	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS



Forensic Analytical
Analytical Report

Preliminary FAX

Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist
Ron Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B048664
Date Received: 03/20/03
Date Analyzed: 03/21/03
Date Printed: 03/21/03

Job ID / Site: Sierra View Elem School

FAI Job ID: 2921-61

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
BR-1	10221841						
Layer: Off-White Plaster			ND				
Layer: Yellow Plaster			ND				
Layer: Paint			ND				

Total Composite Values of Fibrous Components: Asbestos:(ND)
Cellulose (Trace%)

C: Mary
Kip
Bob M.
Rob
Binkley (s)
Jill

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification (LOQ) = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written consent from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.



BULK SAMPLE REQUEST FORM

COMPANY NAME & ADDRESS: 2921 Chico Unified School District 41 2455 Carmichael Drive Chico, CA 95926		PHONE: (916) 891- FAX: (916) 891-3190	DATE:
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	Results Needed:
		PLM: <u>Standard</u> / Point Count	Gravimetry Prep
CONTACT: ROB PETERS		TEM: QUAL. / QUANT. / WATER	
P.O.#	JOB #	AA/Flame AA/Furnace ICP	
SITE:		METALS:	

[illegible]

Sampled by: 12013 PETERS	Date: 3/19/03 Time: 11:05 AM
Relinquished by:	Received By: [Signature] 3/20/03
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO



MAR 26 2003

COPY

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Ron Peters2455 Carmichael Drive
Chico, CA 95928Client ID: 2921
Report Number: B048664
Date Received: 03/20/03
Date Analyzed: 03/21/03
Date Printed: 03/21/03
First Reported: 03/21/03

Job ID / Site: Sierra View Elem School

FASI Job ID: 2921-61

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
BR-1	10221841						
Layer: Off-White Plaster			ND				
Layer: Yellow Plaster			ND				
Layer: Paint			ND				

Total Composite Values of Fibrous Components: Asbestos:(ND)

Cellulose (Trace%)

Comment: Collected on 03/19/2003

cc: Mary
Kip
Det M.
Rob
Ginsler (b)
Jill

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3095
Fax: (530) 891-3190

Chico Unified School District

March 19, 2003

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Sierra View Unit A Boiler Room

To Whom It May Concern:


Please test the enclosed sample from the Sierra View Elementary School Unit A Boiler Room ceiling plaster for asbestos. We would like a 24-hour turn around on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Sierra View Elementary School
Location: Unit A Boiler Room Ceiling Plaster
Date Sampled: March 19, 2003
Number of Samples: One - #BR-1

Sample Taken by: Robert Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures



Forensic Analytical
Analytical Report

Final FAX

Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Boiler Room

Client ID: 2921
Report Number: B052319
Date Received: 07/03/03
Date Analyzed: 07/07/03
Date Printed: 07/07/03

Job ID / Site: Sierra View Elem & Fairview High Sc

FASI Job ID: 2921-66

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
---------------	------------	---------------	------------------	---------------	------------------	---------------	------------------

BR-1	10248119						
Layer: Grey Fibrous Material		Chrysotile	95%				

Total Composite Values of Fibrous Components:	Asbestos:(95%)
Cellulose (Trace%)	

BR-2	10248120						
Layer: Grey Fibrous Material		Chrysotile	95%				

Total Composite Values of Fibrous Components:	Asbestos:(95%)
Cellulose (Trace%)	

BR-3	10248121						
Layer: Grey Fibrous Material		ND					

Total Composite Values of Fibrous Components:	Asbestos:(ND)
Cellulose (Trace%) Fibrous Glass (99%)	

*C: Mary
Kip
Bob M.
Rob
Dimitry (3)
dier*

Jim Flores

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921-66

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

Chico Unified School District

July 2, 2003

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Sierra View Elementary School & Fair View High School

To Whom It May Concern:

Please test the enclosed gasket and insulation material samples from Sierra View Elementary School for asbestos ONLY. In addition, please test the enclosed paint samples from Fair View High School for Lead ONLY. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Sierra View Elementary School
Location: Gasket Material
Date Sampled: July 2, 2003
Number of Samples: Two (#BR-1 & #BR-2)


Location: Boiler Insulation
Date Sampled: July 2, 2003
Number of Samples: One (#BR-3)

Site Sampled: Fair View High School
Location: Unit B - Paint
Date Sampled: July 2, 2003
Number of Samples: One (#FV-1)

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

Rec'd 7/3/03
E 1230 PM



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chilco Unified School District 2455 Carmichael Drive Chilco, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/2/03
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	Results Needed:
		PLM: Standard / Point Count	Gravimetry Prep
CONTACT: ROB PETERS		TEM: QUAL. / QUANT. / WATER	
P.O.#	JOB #	☒ AA/Flame	☐ AA/Furnace
SITE: Mariposa SIERRA VIEW + FAIR VIEW		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
B12-1	7/1/03	GASKET MATERIAL SIERRA VIEW
B12-2	7/1/03	GASKET MATERIAL SIERRA VIEW
B12-3	7/1/03	BOILER INSULATION SIERRA VIEW
FV-1	7/2/03	Fair View PAINT FROM UNIT B (LEAD ONLY)

Sampled by: ROB PETERS	Date: 7/2/03	Time: 9:45 am
Relinquished by:	Received By: <i>Melissa Cruz</i>	
Date/Time:	Date/Time: 7/3/03 12pm	
Relinquished by:	Sealed Condition (circle one) YES NO	
Date/Time:	Received By:	
Date/Time:	Sealed Condition (circle one) YES / NO	



Forensic Analytical
Analytical Report

Bulk Asbestos Analysis

(EPA Method 600/R-93-116)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B052454
Date Received: 07/09/03
Date Analyzed: 07/10/03
Date Printed: 07/10/03
FASI Job ID: 2921-69

Job ID / Site: Sierra View Elementary School, Boiler Room Vent Pipe

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
---------------	------------	---------------	------------------	---------------	------------------	---------------	------------------

BR-4	10249467		ND				
------	----------	--	----	--	--	--	--

Layer: Beige Non-Fibrous Material

Total Composite Values of Fibrous Components:
Cellulose (Trace%)

Asbestos:(ND)

C: Mary
Kip
Rob m.
Rob
Binders (3)
Chen

Jim Flores

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'. Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All



Forensic Analytical

BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS:

2921
Chico Unified School District
2455 Carmichael Drive
Chico, CA 95928

PHONE: (916) 891-
FAX: (916) 891-3190

DATE:

7/8/03

Circle the Method and
Turn Around Time

Results Needed:

24 hr/12hr/24hr/48hr/Ext

PLM: Standard / Point Count

Gravimetry Prep

TEM: QUAL. / QUANT. / WATER

AA/Flame AA/Furnace ICP

METALS:

CONTACT:

BOB PETERS

P.O.#

SIERRA VIEW

JOB

SITE:

SAMPLE NUMBER

DATE
COLLECTED

SAMPLE LOCATION/DESCRIPTION

BR-4

7/8/03

VENT PIPE.

Submitted by:

BOB PETERS

Submitted by:

Submitted by:

Submitted by:

Submitted by:

Date:

7/8/03

Time:

7:52

Received By:

Dennis L. Perry

Date/Time:

7/9/03 1:40PM

Sealed Condition (circle one) YES / NO

Received By:

Date/Time:

Sealed Condition (circle one) YES / NO

2921-69
Chico Unified School District

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

July 8, 2003

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Sierra View Elementary School

To Whom It May Concern:

Please test the enclosed vent pipe sample from the Sierra View Elementary School Boiler Room for asbestos. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Sierra View Elementary School
Location: Boiler Room Vent Pipe
Date Sampled: July 8, 2003
Number of Samples: One - #BR-4

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

Rec'd by [signature] 7/9/03
1400pm



Forensic Analytical

Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B052319
Date Received: 07/03/03
Date Analyzed: 07/07/03
Date Printed: 07/07/03
First Reported: 07/07/03
FASI Job ID: 2921-66

Job ID / Site: Sierra View Elem & Fairview High Sc

Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
---------------	------------	---------------	------------------	---------------	------------------

BR-1

Layer: Grey Fibrous Material

10248119

Chrysotile

95 %

Total Composite Values of Fibrous Components: Asbestos:(95%)
Cellulose (Trace%)

Comment: Collected on 07/01/2003

BR-2

Layer: Grey Fibrous Material

10248120

Chrysotile

95 %

Total Composite Values of Fibrous Components: Asbestos:(95%)
Cellulose (Trace%)

Comment: Collected on 07/01/2003

BR-3

Layer: Grey Fibrous Material

10248121

ND

Total Composite Values of Fibrous Components: Asbestos:(ND)
Cellulose (Trace%) Fibrous Glass (99%)

Comment: Collected on 07/01/2003

C. Mary
Kip
Burtm.
Rob
Binkley (3)
Alicia

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification (LOQ) = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'. All results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to endorse or NVLAP or any other agency of the U.S. Government. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. were received in acceptable condition unless otherwise noted.

2921-66

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

Chico Unified School District

July 2, 2003

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Sierra View Elementary School & Fair View High School
To Whom It May Concern:

Please test the enclosed gasket and insulation material samples from Sierra View Elementary School for asbestos ONLY. In addition, please test the enclosed paint samples from Fair View High School for Lead ONLY. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Sierra View Elementary School
Location: Gasket Material
Date Sampled: July 2, 2003
Number of Samples: Two (#BR-1 & #BR-2)

Location: Boiler Insulation
Date Sampled: July 2, 2003
Number of Samples: One (#BR-3)

Site Sampled: Fair View High School
Location: Unit B - Paint
Date Sampled: July 2, 2003
Number of Samples: One (#FV-1)

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

7/3/03
12:30pm



BULK SAMPLE REQUEST FORM

CLIENT NAME & ADDRESS: 2921 Chlco Unified School District 2455 Carmichael Drive Chico, CA 95928		PHONE: (916) 891- FAX: (916) 891-3190	DATE: 7/2/03
		Circle the Method and Turn Around Time 24 hr/12hr/24hr/48hr/Ext	Results Needed:
		PLM: Standard / Point Count	
		CONTACT: BOB PETERS	
P.O.#	JOB #	AA/Flame AA/Furnace ICP	
SITE: MARION SIERRA VIEW + FAIR VIEW		METALS:	

SAMPLE NUMBER	DATE COLLECTED	SAMPLE LOCATION/DESCRIPTION
BR-1	7/1/03	GASKET MATERIAL SIERRA VIEW
BR-2	7/1/03	GASKET MATERIAL SIERRA VIEW
BR-3	7/1/03	BOILER INSULATION SIERRA VIEW
FV-1	7/2/03	Fair View PAINT FROM UNIT B (LEAD ONLY)

Sampled by: BOB PETERS	Date: 7/2/03 Time: 9:45 am
Relinquished by:	Received By: Melissa Coya
Date/Time:	Date/Time: 7/3/03 12pm
	Sealed Condition (circle one) YES NO
Relinquished by:	Received By:
Date/Time:	Date/Time:
	Sealed Condition (circle one) YES / NO



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Rob Peters

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B052454
Date Received: 07/09/03
Date Analyzed: 07/10/03
Date Printed: 07/10/03
First Reported: 07/10/03

Job ID / Site: Sierra View Elementary School, Boiler Room Vent Pipe

FASI Job ID: 2921-69


Sample Number	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
BR-4	10249467						
Layer: Beige Non-Fibrous Material				ND			

Total Composite Values of Fibrous Components: Asbestos:(ND)

Cellulose (Trace%)

Comment: Collected on 07/08/2003

C. Mary
Kip
Bob M.
Rob
Bentley (3)
Chic



James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

Maintenance and Operations
2455 Carmichael Drive
Chico, CA 95928
Phone: (530) 891-3195
Fax: (530) 891-3190

2921-69
Chico Unified School District

July 8, 2003

Forensic Analytical Specialties, Inc.
3777 Depot Road, Suite 409
Hayward, CA 94545

Re: Sierra View Elementary School

To Whom It May Concern:

Please test the enclosed vent pipe sample from the Sierra View Elementary School Boiler Room for asbestos. We would like a 24-hour turnaround on the samples. Please fax the results to us as soon as soon as they are available. Our fax number is (530) 891-3190.

Site Sampled: Sierra View Elementary School
Location: Boiler Room Vent Pipe
Date Sampled: July 8, 2003
Number of Samples: One - #BR-4

Samples Taken by: Rob Peters

Thank you for your prompt response to this request.

Sincerely,



Rob Peters
Maintenance/Operations Supervisor

RP:dlg
Enclosures

Recy [Signature] 7/9/03
E. [Signature] 140pm



BULK SAMPLE REQUEST FORM

METALS:

VENT PIPE.

Date/Time: _____
Sealed Condition (circle one) YES / NO