

MEASURE E SCHOOL SITE SURVEY

PARKVIEW ELEMENTARY

Staff Recommendations	Parent Input
Electrical upgrading in Classrooms	Security Cameras
Solar Energy	Gymnasium added or expanded MPR
Security Cameras	Baseball backstops in the field
Drainage off buildings (downspouts not working well)	Field renovation: Gopher control, irrigation repair/redesign, turf re-seeding
Drainage on blacktop behind room 17	Security lighting outside campus especially in front circle area near MPR
Rebuilding of woodchip boxes	Emergency call boxes in classrooms
Interior lighting upgraded in library building	Exterior paint
Exterior lighting from MPR into parking lots	
Automatic doors for ADA accessibility	
Low flow toilets in adult bathrooms	
Hot water for student restrooms (health concern)	
Field refurbished	
Heating in women's adult restroom	
Upgraded playground structures on all playgrounds	