

MEASURE E SCHOOL SITE SURVEY

PTA=Parent- Teacher Association PAC=Parent Advisory Committee
SSC=School Site Council

SIERRA VIEW ELEMENTARY

Staff Recommendations	Student Input	PTA, PAC, & SSC Input
Structural-Major	Structural-Major	Structural-Major
Enlarge parking lot	Remodel Intermediate Courtyard rooms	Enlarge parking lot (According to Parent Surveys it is a huge need)
Remodel & update adult restrooms including plumbing	Drinking fountains replaced	Fence at the front of school (School Safety)
Replace portables (Health Issues-moldy)	Build a gym	Shade structure in Kindergarten area
Remodel room 22 to have office & storage (AM & PM K)	Locks on restroom doors	Drinking fountain on Kindergarten playground
Covering between breezeway (between rooms 8-10 & 13-16)	Automatic flushers	Remodel intermediate courtyard rooms
Restroom attached to room 27 (SH classroom)	Hand dryers	Covered bike racks
Heating and Air Conditioning updated	Replace basketball hoops	Storage (shed?)
Real Stage	New backstops	More goal posts with nets
Fence at the front of school (School Safety)	Replace edges in bark boxes	Electrical
Shade structure in Kindergarten area	Paint classrooms	Security lights (School Safety)
Drinking fountain on Kindergarten playground	More benches on playground	HD security cameras (School Safety)
Remodel Intermediate Courtyard rooms	Benches/tables under trees by bike rack	Electrical drops in classroom (update electrical)
Covered bike racks	Repaint playground	Infrastructure-replace backbone with fiber optics (Most needed)
Heater in men's restroom	Repaint a standard size basketball key	Yard Maintenance
"No peak" panels in women's restroom	New swings	Intermediate courtyard redone (School Safety-tripping hazard)
More goal posts with nets	New or update stage	Level field between goal posts to eliminate mud hole (Most Needed)
Electrical	Electrical	Level out track, replace with better materials (Tripping Hazard)
Security lights (School Safety)	Security lights (School Safety)	Safety Materials
HD security cameras (School Safety)	HD security cameras (School Safety)	New blinds for Kindergarten
Electrical drops in classroom (update electrical)	Electrical drops in classroom (update electrical)	Technology
Infrastructure-replace backbone with fiber optics (Most needed)	Infrastructure-replace with fiber optics (Most needed)	Update computer lab
Yard Maintenance	Yard Maintenance	
Intermediate courtyard redone (School Safety-tripping hazard)	Intermediate courtyard redone (School Safety)	
Level field between goal posts to eliminate mud hole (Most Needed)	Level field between goal posts (Most Needed)	
Level out track, replace with better materials (Tripping Hazard)	Redo track with better materials (Tripping Hazard)	
Fix or replace blacktop	Fix or replace blacktop	
Technology	Technology	
Update computer lab	Update computer lab and TV equipment	