СНООТ	Bidwell J	unior High	INSPECTOR_RO	bert Peters P.P.
LDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
100	Ceil Plas	1-5	All rooms except kitchen	1-4
100	9" VFT	Assumed	All rooms except store	1-4
100	PW Str	30-35	Chair Store Room	1-4
100	PW Cnr	Assumed	Kitchen B/R Room	1-4
100	B/R Lin	60-65	Kitchen B/R Room	1-4
100	Tran pipe	Assumed	Kitchen B/R Room	1-4
100	Fan Vent Insul	Assumed	Fan Rooms	1-4
200	9" VFT	Assumed	All Rooms	1-4
200	Plaster	1-5	All Rooms	1-4
300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4
300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	1-4

CONDITION CODES

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE) GENERAL CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

CHANGE IN CONDITION:

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

DISTRICT	Chico Un	ified Scho	ol District DATE Dec.	2, 1990
SCH00I	Bidwell J	unior High	INSPECTOR_RO	bert Peters
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
300	Ceil Plas	1-5	Rm 250, halls, rr, teach	1-4
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4 (room 105A - small holes)
300	Tran pipe	Assumed	Closet of Room 405	1-4
400	Tran panl	Assumed	Panels in both locker rooms	1-4
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4
400	Tank Wrap	Assumed	PE Boiler room	1-5 small piece of cover gone
500	Drywall	1	All rooms	1-4
500	9" VFT	Assumed	All rooms	1-4
500	Duct Insl	90-95	Duct work - ceil. & walls	1-4-10
600	Tran panl	Assumed	Metal Shop	1-4
600	9" VFT	Assumed	Room 8 and office	1-4

CONDITION CODES

GENERAL CONDITION:

(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION:

(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

DISTRICT	Chico Un	ified Scho	ol District DATE Dec.	2, 1990
SCHOOL	Bidwell J	unior High	INSPECTOR_RO	bert Peters
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
600	Asb. Curt	Assumed	Metal Shop	5-7 (removed)
600	Mud Jnts	1-5	Rm 208 near sink (Rm 9)	1-4
600	12" VFT	Assumed	Room 9	1-4
700	9" VFT	Assumed	All Classrooms	1-4
700	Mud Jnts	1-5	Rooms 408 & 409	1-4
800	9" VFT	Assumed	Library	1-4
900	PW Str	15-20	Gym, B/R, Storeroom	1-4
900	PW Cnr	5-10	Gym, B/R, Storeroom	1-4
	*			
			CONDITION CODES	
GENERAL	CONDITION:	(1)	GOOD (2) DAMAGED (3) SIGN	NIFICANTLY DAMAGED (25% OR MORE)
CHANGE I	N CONDITION	<u>(</u> 4)	NO (5) YES (IF YES, EXPLA	IN UNDER COMMENTS)
ABATED:	(6) REPAIRE	ED (7) REMO	OVED (8) ENCAPSULATED (9) ENC	LOSED (10) ISOLATED & RESTRICTED
MISC:	(11) INACCE	ESSIBLE, NO	SURVEILLANCE DATA (12) OTH	ER (EXPLAIN UNDER COMMENTS)

1	DISTRICT	Chico Un	ified Scho	ol District DATE July	6, 1990
:	SCHOOL_	Bidwell J	unior High	INSPECTOR_RO	bert Peters 12.6.
]	BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
	100	Ceil Plas	1-5	All rooms except kitchen	1-4
	100	9" VFT	Assumed	All rooms except store	1-4
	100	PW Str	30-35	Chair Store Room	1-4
	100	PW Cnr	Assumed	Kitchen B/R Room	1-4
	100	B/R Lin	60-65	Kitchen B/R Room	1-4
	100	Tran pipe	Assumed	Kitchen B/R Room	1-4
	100	Fan Vent Insul	Assumed	Fan Rooms	1-4
	200	9" VFT	Assumed	All Rooms	1-4
ĺ	200	Plaster	1-5	All Rooms	1-4
	300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4
	300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	1-4

CONDITION CODES

GENERAL CONDITION:	(1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION:	(4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED	(7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MICC. (11) INACCESS	TRIE NO SUBVETLIANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT	Chico Un	ified Scho	ol District DATE July	6, 1990
SCHOOL	Bidwell J	unior High	INSPECTOR_RO	bert Peters V.C.
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
300	Ceil Plas	1-5	Rm 250, halls, rr, teach	1-4
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4 (room 105A - small holes)
300	Tran pipe	Assumed	Closet of Room 405	1-4
400	Tran panl	Assumed	Panels in both locker rooms	1-4
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4
400	Tank Wrap	Assumed	PE Boiler room	1-4
500	Drywall	1	All rooms	1-4
500	9" VFT	Assumed	All rooms	1-4
500	Duct Insl	90-95	Duct work - ceil. & walls	1-4-10
600	Tran panl	Assumed	Metal Shop	1-4
600	9" VFT	Assumed	Room 8 and office	1-4
			CONDITION CODES	
GENERAL	CONDITION:	(1)	GOOD (2) DAMAGED (3) SIGN	IFICANTLY DAMAGED (25% OR MORE)
CHANGE I	N CONDITION	: (4)	NO (5) YES (IF YES, EXPLAI	N UNDER COMMENTS)
ABATED:	(6) REPAIRE	D (7) REMO	VED (8) ENCAPSULATED (9) ENCL	OSED (10) ISOLATED & RESTRICTED
MISC:	(11) INACCE	SSIBLE, NO	SURVEILLANCE DATA (12) OTHE	R (EXPLAIN UNDER COMMENTS)

LDG.	HOMOG. MAT.#		LOCATION	CONDITION: CODE & COMMENTS
600	Asb. Curt	Assumed	Metal Shop	5-7 (removed)
600	Mud Jnts	1-5	Rm 208 near sink (Rm 9)	1-4
600	12" VFT	Assumed	Room 9	1-4
700	9" VFT	Assumed	All Classrooms	1-4
700	Mud Jnts	1-5	Rooms 408 & 409	1-4
800	9" VFT	Assumed	Library	1-4
900	PW Str	15-20	Gym, B/R, Storeroom	1-4
900	PW Cnr	5-10	Gym, B/R, Storeroom	1-4
			<u>-</u>	
		-	CONDITION CODES	
ENERAL	CONDITION:	(1)	GOOD (2) DAMAGED (3) SIGN	NIFICANTLY DAMAGED (25% OR MORE
HANGE]	IN CONDITION	: (4)	NO (5) YES (IF YES, EXPLAI	IN UNDER COMMENTS)
BATED:	(6) REPAIRE	D (7) REMO	VED (8) ENCAPSULATED (9) ENCI	LOSED (10) ISOLATED & RESTRICTE

ADDRESS SCHOOL BIDWELL JR.

Mark Braises 11-15-90 SIGNATURE

APPLICATION NO.

SITE SUMMARY GRADES SERVED AT THIS SCHOOL

		ant conditions		NON-CHAPCEARIE	_	01.0	1 2 2				Τ
BLDG	UNIT	APPLICATION NO	TOTAL AREA	LEASE CO		UNDER 30	0VEK 30	SPEC. EDS	. T/S	LAB/S	1
100	ADMIN. & MULTI USE	#16134	13,123.02 S.F.			×					$\overline{}$
2002	CLASSROOM	16134	15,539.42 S.F.			×		3	13		T
300	SCIENCE & CLASSROOM	16134	18,491.90 S.F.			×			12	2	
400	SHOWER & LOCKER	16134	8,733.31 S.F.		<u></u>	×					\exists
500	MUSIC	25776	3,420.00 S.F.		-	X				2	1
009	SHOP WING	25776	5,829.10 S.F.			×				4	
700	HOMEMAKING	25776	5,851.38 S.F.			×		-		3	
800	LIBRARY	23515	3,572.80 S.F.			×					T
900	СУМ	23515	10,335.77 S.F.			×					\neg
	PORTABLES (2)(CLASSRMS)		1,920.00 S.F.		×				2		T
				1	•		TOTAL	4	27	=	·
	GREENHOUSE		704.00 S.F.		×	×					
	MAINTENANCE BLDG.		1,440.00 S.F.		×	×					
	MAINTENANCE BLDG.		84.40 S.F.		×	×					
	DIST. RELOCATABLES	54376 6/90	2,880.00 S.F.			×					
	DIST. RELOCATABLES	55149 10/90	960.00 S.F.	-		×					
	DIST. OWNED TRAILER		480.00 S.F.			×					
									·		
								,			
			i	10101	000	- C	1401	DEBOSE TOTAL SALE FOR STOLEN STATE OF STATE OF SECTION OF THE SECOND		05026	

PREPARED BY: THOMSON & HENDRICS / ARCHITECTS & PLANNERS/ (916) 342-5669 60 DECLARATION DRIVE CHICO. CALIF. 95926