DISTRICT Chico Unified School District DATE December 19, 1994  SCHOOL Bidwell Junior High INSPECTOR Ron Jones				
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
100	Ceil Plas	1-5	All rooms except kitchen	1-4
100	9" VFT	Assumed	All rooms except store	1-4
100	PW Str	30-35	Chair Store Room	1-4
100	PW Cnr	Assumed	Kitchen B/R Room	1-4
100	B/R Lin	60-65	Kitchen B/R Room	1-4
100	Tran pipe	Assumed	Kitchen B/R Room	1-4
100	Fan Vent Insul	Assumed	Fan Rooms	1-4
200	9" VFT	Assumed	All Rooms	1-4
200	Plaster	1-5	All Rooms	1-4
300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4
300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	1-4
CONDITION CODES				
GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)				
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)				
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED				
MISC:	MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)			

DISTRICT Chico Unified School District DATE July 7, 1994					
SCHOOL Ridwell Junior High INSPECTOR Ron Jones				n Jones	
BLDG.	HOMOG. MAT.#		LOCATION	CONDITION: CODE & COMMENTS	
300	Ceil Plas	1-5	Rm 250, halls, rr, teach	1-4	
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4	
300	Tran pipe	Assumed	Closet of Room 405	1-4	
400	Tran panl	Assumed	Panels in both locker rooms	1-4	
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4	
400	Tank Wrap	Assumed	PE Boiler room	1-4	
500	Drywall	1	All rooms	1-4	
500	9" VFT	Assumed	All rooms	1-4	
500	Duct Insl	90-95	Duct work - ceil. & walls	1-4-10	
600	Tran panl	Assumed	Metal Shop	1-4	
600	9" VFT	Assumed	Room 8 and office	1-4	
	CONDITION CODES				
GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)					
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)					
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED					
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)					

DISTRICT Chico Unified School District DATE July 7, 1994						
SCHOOL Bidwell Junior High INSPECTOR Ron Jones						
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS		
600	Asb. Curt	Assumed	Metal Shop	7		
600	Mud Jnts	1-5	Rm 208 near sink (Rm 9)	1-4		
600	12" VFT	Assumed	Room 9	1-4		
700	9" VFT	Assumed	All Classrooms	1-4		
700	Mud Jnts	1-5	Rooms 408 & 409	1-4		
800	9" VFT	Assumed	Library	1-4		
900	PW Str	15-20	Gym, B/R, Storeroom	1-4		
900	PW Cnr	5-10	Gym, B/R, Storeroom	1-4		
	CONDITION CODES					
GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)						
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)						
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED						
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)						

DISTRICT Chico Unified School District DATE July 7, 1994					
SCHOOL	SCHOOL Bidwell Junior High INSPECTOR Ron Jones				
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS	
100	Ceil Plas	1-5	All rooms except kitchen	1-4	
100	9" VFT	Assumed	All rooms except store	1-4	
100	PW Str	30-35	Chair Store Room	1-4	
100	PW Cnr	Assumed	Kitchen B/R Room	1-4	
100	B/R Lin	60-65	Kitchen B/R Room	1-4	
100	Tran pipe	Assumed	Kitchen B/R Room	1-4	
100	Fan Vent Insul	Assumed	Fan Rooms	1-4	
200	9" VFT	Assumed	All Rooms	1-4	
200	Plaster	1-5	All Rooms	1-4	
300	Drywall	Assumed	Rm 250, RR, Teach. room	1-4	
300	9" VFT	Assumed	Rm 250, halls, rr, teach. All Classrms except 105-6,7	1-4	
	CONDITION CODES				
GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)					
CHANGE IN CONDITION.					
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED					
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)					

DISTRICT Chico Unified School District DATE July 7, 1994				
SCHOOL.			INSPECTORRO	$\rho(\lambda)$
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
300	Ceil Plas	1-5	Rm 250, halls, rr, teach	1-4
300	Ceil Plas	1-5	All classrms except 105-6-7	1-4
300	Tran pipe	Assumed	Closet of Room 405	1-4
400	Tran panl	Assumed	Panels in both locker rooms	1-4
400	PW Cnr	Assumed	PE Boiler room & tunnel	1-4
400	Tank Wrap	Assumed	PE Boiler room	1-4
500	Drywall	1	All rooms	1-4
500	9" VFT	Assumed	All rooms	1-4
500	Duct Insl	90-95	Duct work - ceil. & walls	1-4-10
600	Tran panl	Assumed	Metal Shop	1-4
600	9" VFT	Assumed	Room 8 and office	1-4

### CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

(11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS) MISC:

DISTRICT Chico Unified School District DATE July 7, 1994				
SCHOOL Bidwell Junior High INSPECTOR Ron Jones				
BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
600	Asb. Curt	Assumed	Metal Shop	7
600	Mud Jnts	1-5	Rm 208 near sink (Rm 9)	1-4
600	12" VFT	Assumed	Room 9	1-4
700	9" VFT	Assumed	All Classrooms	1-4
700	Mud Jnts	1-5	Rooms 408 & 409	1-4
800	9" VFT	Assumed	Library	1-4
900	PW Str	15-20	Gym, B/R, Storeroom	1-4
900	PW Cnr	5-10	Gym, B/R, Storeroom	1-4
CONDITION CODES				
GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)				
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)				
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED				
MISC:	MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)			