Date of Inspection: 06/02/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
М	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1) (4)	N
M	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, AND RESTROOM	(1)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	2' X 4' FCP'S	107	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N
М	12" ACT	108	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1) DISTRICT MUST CERTIFY.	N
М	12" VFT SALMON	109	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>06/02/2005</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	on: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT GREEN	101	ASSUMED	2,200 S	HALLWAY	(1)	DISTRICT MUST CERTIFY.	N
М	2' X 4' FCP'S	110	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	DISTRICT MUST CERTIFY.	N
М	12" ACT	111	ASSUMED	2,500 S	HALLWAY	(2) (6)	DISTRICT MUST CERTIFY.	N
М	12" VFT SALMON	112	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	DISTRICT MUST CERTIFY.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>06/02/2005</u>

Unit: E

Unit: C

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
М	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
М	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (4) REPLACED 9" VFT.	N
М	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
Т	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(1) (4)	N
М	9" VFT RED	100	ASSUMED	50 S	ADMINISTRATION STORAGE	(1) (4)	

School: Hooker Oak Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
М	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17	(1) (4)	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District

Inspector: Leroy Christophersen

Building: Portable Library

Date of Inspection: 06/02/2005

Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) (4) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

Building: Portable 18

Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP	105	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
М	12" VFT	106	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175.  MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: 6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 06/02/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary

Building: Portables 19-21

Unit: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	101	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
М	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/29/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	9" VFT GREEN	13	1-5%	2,880 S	CLASSROOMS 13-16	(1) (4)	N
М	9" VFT BRIGHT GREEN	97	ASSUMED	400 S	SINK ROOM	(1) (4)	N
М	12" ACT	98	ASSUMED	2,880 S	CLASSROOMS 13-16, SINK ROOM, AND RESTROOM	(1) (4)	N

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" ACT	95	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 6-10	(7) REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	2' X 4' FCP'S	107	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N
М	12" ACT	108	ASSUMED	2,500 S	HALLWAY & STAFF ROOM	(1) (4) DISTRICT MUST CERTIFY.	N
М	12" VFT SALMON	109	ASSUMED	4,500 S	CLASSROOMS 6-10	(1) (4) DISTRICT MUST CERTIFY.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: 12/29/2005

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Unit: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition	on: Code & Comments	Friable Yes/No
М	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
М	12" VFT GREEN	101	ASSUMED	2,200 S	HALLWAY	(1)	DISTRICT MUST CERTIFY.	N
М	2' X 4' FCP'S	110	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	DISTRICT MUST CERTIFY.	N
М	12" ACT	111	ASSUMED	2,500 S	HALLWAY	(2) (6)	DISTRICT MUST CERTIFY.	N
М	12" VFT SALMON	112	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	DISTRICT MUST CERTIFY.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>12/29/2005</u>

Unit: E

Unit: C

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACT	2	NONE DETECTED	350 S	MPR (NORTH WALL)	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	N/A
М	LINOLEUM	17	5-10%	250 S	ADMINISTRATION OFFICE	(1) (4)	N
М	12" VFT GREEN-WHITE	93	ASSUMED	2,500 S	MPR	(1) (4) REPLACED 9" VFT.	N
М	12" VFT SALMON	96	ASSUMED	1,800 S	CLASSROOMS 11 & 12	(1) (4)	N
Т	BOILER LINER	8	50-55%	210 S	BOILER ROOM	(11)	N
М	9" VFT RED	100	ASSUMED	50 S	ADMINISTRATION STORAGE	(1) (4)	

School: Hooker Oak Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" ACT	14	NONE DETECTED	1,200 S	CLASSROOM 17	(13) SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
М	12" VFT CREAM	99	ASSUMED	1,200 S	CLASSROOM 17	(1) (4)	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District

Inspector: Leroy Christophersen

Building: Portable Library

Date of Inspection: 12/29/2005

Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP	104	ASSUMED	900 S	LIBRARY PORTABLE	(1) (4) MANUFACTURE DATE OF PORTABLE LIBRARY IS 6/95. I.D. #63260 DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

Building: Portable 18

Unit: D

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	2' X 4' FCP	105	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N
М	12" VFT	106	ASSUMED	900 S	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175.  MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: 6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Date of Inspection: <u>12/29/2005</u>

District: Chico Unified School District Inspector: Leroy Christophersen

School: Hooker Oak Elementary

Building: Portables 19-21

Unit: F

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
М	12" VFT	101	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N
М	2' X 4' FCP	102	ASSUMED	2,700 S	PORTABLES CLASSROOMS 19-21	(1) (4) MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	N

### **CONDITION CODE**

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

<u>Change in Condition:</u> (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

# HOMOGENEOUS ACBM RECORDS

Date of Inspection: 12/29/2005

Inspector: Leroy Christophersen

District: Chico Unified School District

School: Hooker Oak Elementary School

Material Class Ζ ⋜ ≤ Material 9" VFT BRIGHT GREEN 9" VFT GREEN 12" ACT Homo. Mat.# 97 13 98 % Asb. 1-5% ASSUMED ASSUMED Ft²/L.F. 2,880 S 2,880 S 400 S SINK ROOM CLASSROOMS 13-16, SINK ROOM, AND RESTROOM CLASSROOMS 13-16 Location (1) (<del>4</del>) (±) (±) (±) (1)(4)Condition: Code & Comments Friable Yes/No z Unit: C z z

z	(1) (4) DISTRICT MUST CERTIFY.	4,500 S CLASSROOMS 6-10 (1	4,500 S	ASSUMED	109	12" VFT SALMON	≤
z	(1) (4) DISTRICT MUST CERTIFY.	HALLWAY & STAFF ROOM (1	2,500 S	ASSUMED	108	12" ACT	Z
z	(1) (4) DISTRICT MUST CERTIFY.	CLASSROOMS 6-10 (1	4,500 S	ASSUMED	107	2' X 4' FCP'S	Z
N/A	) REMOVED ACCORDING TO CHICO USD RECORDS.	CLASSROOMS 6-10 (7	4,500 S	ASSUMED	96	12" VFT SALMON	≤
N/A	) REMOVED ACCORDING TO CHICO USD RECORDS.	HALLWAY & STAFF ROOM (7)	2,500 S	ASSUMED	95	12" ACT	K
N/A	) REMOVED ACCORDING TO CHICO USD RECORDS.	CLASSROOMS 6-10 (7)	4,500 S	ASSUMED	94	2' X 4' FCP'S	Z
Friable Yes/No	Condition: Code & Comments	Location	Fť/L.F.	% Asb.	Homo. Mat. #	Material	Material Class
Building: B		THE PROPERTY OF THE PROPERTY O					

# CONDITION CODE

Abated: Miscellaneous: General Condition: Change in Condition:

 (1) Good
 (2) Damaged
 (3) Significantly Damaged (25% or more)

 (4) No
 (5) Yes (If Yes, explain under comments)

 (6) Repaired
 (7) Removed
 (8) Encapsulated
 (9) Enclosed
 (10) Isolated & Restricted

 (11) Inaccessible, no inspection data
 (12) Other (Explain under comments)
 (13) Non

(13) Non-Asbestos/Not Inspected

### **HOMOGENEOUS ACBM RECORDS** SIX MONTH SURVEILLANCE

Date of Inspection: 12/29/2005

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Hooker Oak Elementary School Unit: E

	(1) (4)	50 S.   ADMINISTRATION STORAGE	50 S <sub>1</sub>	ASSUMED	100	9" VFT RED	Z
z	(11)	BOILER ROOM	210 S	50-55%	8	BOILER LINER	
z	(1)(4)	1,800 S CLASSROOMS 11 & 12	1,800 S	ASSUMED	96	12" VFT SALMON	3
z	(1)(4) REPLACED 9" VFT.	MPR	2,500 S	ASSUMED	93	12" VFT GREEN-WHITE	<b>S</b>
z	(1) (4)	ADMINISTRATION OFFICE	250 S	5-10%	17	LINOLEUM	М
N/A	(13) SAMPLE HMS-HKR-02 COLLECTED ON 3-29-88.	MPR (NORTH WALL)	350 S	NONE DETECTED	2	12" ACT	×
Friable Yes/No	Condition: Code & Comments	Location	Fť/L.F.	% Asb.	Homo. Mat. #	Material	Material Class

			-					
Material Class	Material	Homo. Mat. #	% Asb.	F <del>(</del> ²/L.F.	Location	Condition: (	Condition: Code & Comments	Friable Yes/No
×	12" ACT	14	NONE DETECTED	1,200 S	1,200 S CLASSROOM 17	(13)	SAMPLE HMS-HKR-14 COLLECTED ON 3-29-88.	N/A
X	12" VFT CREAM	99	ASSUMED	1,200 S	1,200 S CLASSROOM 17	(1)(4)		z

# CONDITION CODE

Abated: Miscellaneous: General Condition: Change in Condition: ion: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

dition: (4) No (5) Yes (If Yes, explain under comments)
(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
(11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

District: Chico Unified School District

School: Hooker Oak Elementary

Date of Inspection: <u>12/29/2005</u>

Inspector: Leroy Christophersen

Building: Portables 19-21 Unit: F

z	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	(1) (4)	2,700 S PORTABLES CLASSROOMS 19-21	2,700 S	ASSUMED	102	2' X 4' FCP	×
z	MANUFACTURE DATE OF PORTABLES IS 6/97. DMSI CONSTRUCTION DISTRICT CERTIFICATION REQUIRED.	(1) (4)	2,700 S PORTABLES CLASSROOMS 19-21	2,700 S	ASSUMED	101	12" VFT	M
Friable Yes/No	Condition: Code & Comments	Conditio	Location	Fť/L.F.	% Asb.	Homo. Mat. #	Material	Material Class
0.35								

## CONDITION CODE

Abated: Miscellaneous: Change in Condition: General Condition: (6) Repaired (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
(4) No (5) Yes (If Yes, explain under comments)
aired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted (11) Inaccessible, no inspection data (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

### Page 4 of 5

# SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

District: Chico Unified School District

Date of Inspection: 12/29/2005

Inspector: Leroy Christophersen

Building: Portable Library

Condition: Code & Comments
(1) (4)

Building: Portable 18

							Unit: D
Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	105	ASSUMED	S 006	900 S PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	z
Σ	12" VFT	106	ASSUMED	S 006	PORTABLE CLASSROOM 18	(1) (4) SUN SERI CONSTRUCTION OSA #47175. MANUFACTURE DATE OF PORTABLE 18 IS 8/86.	z

## CONDITION CODE

	(4) No	
eneral Condition	hange in Condition:	

Miscellaneous:

(1) Good
(2) Damaged
(3) Significantly Damaged
(4) No
(5) Yes (If Yes, explain under comments)
(6) Repaired
(7) Removed
(8) Encapsulated
(9) Enclosed
(10) Isolated & Restricted
(11) Inaccessible, no inspection data
(12) Other (Explain under comments)
(13) Non-

(13) Non-Asbestos/Not Inspected

District: Chico Unified School District

Inspector: Leroy Christophersen

Date of Inspection: 12/29/2005

Unit: A

School: Hooker Oak Elementary School

Material Class	Material	Homo. Mat. #	% Asb.	Ft?L.F.	Location	Conditic	Condition: Code & Comments	Friable Yes/No
Σ	2' X 4' FCP'S	94	ASSUMED	4,500 S	CLASSROOMS 1-5	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
Σ	12" ACT	95	ASSUMED	2,500 S	HALLWAY	(7)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
Z	12" VFT SALMON	96	ASSUMED	4,500 S	CLASSROOMS 1-5	(2)	REMOVED ACCORDING TO CHICO USD RECORDS.	N/A
Σ	12" VFT GREEN	101	ASSUMED	2,200 S	HALLWAY	(1)	DISTRICT MUST CERTIFY.	Z
Σ	2' X 4' FCP'S	110	ASSUMED	4,500 S	CLASSROOMS 1-5	£	DISTRICT MUST CERTIFY.	z
Ø	12" ACT	111	ASSUMED	2,500 S	HALLWAY	(2) (6)	DISTRICT MUST CERTIFY.	Z
Σ	12" VFT SALMON	112	ASSUMED	4,500 S	CLASSROOMS 1-5	(1)	DISTRICT MUST CERTIFY.	Z

## CONDITION CODE

(1) Good (2) Damaged (3) Significantly Damaged (25% or more) (4) No (5) Yes (If Yes, explain under comments) vaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated (11) Inaccessible, no inspection data (12) Other (Explain under comm Change in Condition: General Condition:

(9) Enclosed (10) Isolated & Restricted (12) Other (Explain under comments)

(13) Non-Asbestos/Not Inspected

(6) Repaired

Miscellaneous: