MEASURE E SCHOOL SITE SURVEY

LOMA VISTA SCHOOL

Staff Recommendations
Playground expansionnew equipmentrecycled turfshade
New shed for storage of equipment on playground
Specialized flooring on playground so all students have access (ADA compliant)
Change classroom door locks to inside for safety
Carpet, flooring, lighting throughout building
iPads/touch screens updated technology for staff and students
New roof
New A/C and heating system
New dishwasher and laundry facility including commercial washer/dryer to comply with regulations for preschool setting
Windows in bathrooms
New portable with kitchen/bathroom life skills
New drinking fountains throughout building
Additional office space
Storage for additional materials and equipment
3 portable classrooms
Handicapped accessible entrance doorsthree doors
Exterior lighting
Confidential storage for files, exited students
Updated/upgraded staff/student restrooms
Removal of old A/C, boiler room equipment
Built-in storage
Covered sandbox for big playground
Heated water in all sinks
New playground boxes around equipment
Increase size of playground areas
Fences for exterior of school
New landscapelawn for playground

Shape areas for playground
Paint interior and exterior walls on room 2 patio area
New carpet in room 2
Replace back door room 2
Replace slats in back patio area
Kitchen equipment in room 2
Built-in study carrels in classrooms (room 2)
Gross motor skills equipment
Computersupdated
Shelves in bathrooms
Install an updated telephone system in the school
Remove bathtub and pipes from speech room
Reconfigure partitions in classroom (room 2)
Parent Feedback
Redo parking to increase the amount of parking spaces
Redo outside play yard: level and increase size
Redo bathrooms
Restructure classrooms to make a 2:1 classroom/bathroom ratio

Make a larger indoor gross motor area to teach play/sports