

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Citrus Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	CLASSROOM & STAFF ROOM	(1) (4)	N
M	9" VFT		1-5%	UNDETERMINED	WORKROOM OF LIBRARY	(1) (4) CARPET OVER TILE.	N
M	9" VFT		1-5%	UNDETERMINED	SPEECH ROOM	(1) (4) CARPET OVER TILE.	N
M	VENT DUCT CONNECTOR		35-40%	UNDETERMINED	RESTROOM ATTIC	(1) (4) Same as 5/11/02	N

School: Citrus Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT		40-50%	UNDETERMINED	BASEMENT & STORAGE	(1) (4) Same as 5/11/02	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (if Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 11/06/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Citrus Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	MPR (GREEN)	(1) (4) (Same as 12/06/01)	N
M	DUCT VENT CONNECTOR		35-40%	UNDETERMINED	MPR - STAGE OFFICE	(1) (4) 12/06/01 (7)	N
T	PIPEWRAP JOINT		ASSUMED	UNDETERMINED	KITCHEN STORAGE	(1) (4) 12/06/01 (7)	N
T	PIPEWRAP		ASSUMED	UNDETERMINED	STAGE FAN ROOMS	(1) (4) 12/06/01 (7)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTHS SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 05/14/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Citrus Elementary School

Building: B

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	CLASSROOM & STAFF ROOM	(1) (4)	N
M	9" VFT		1-5%	UNDETERMINED	WORKROOM OF LIBRARY	(1) (4) CARPET OVER TILE.	N
M	9" VFT		1-5%	UNDETERMINED	SPEECH ROOM	(1) (4) CARPET OVER TILE.	N
M	VENT DUCT CONNECTOR		35-40%	UNDETERMINED	RESTROOM ATTIC	(1) (4) Same as 12/09/01	N

School: Citrus Elementary School

Building: C

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPEWRAP STRAIGHT		40-50%	UNDETERMINED	BASEMENT & STORAGE	(1) (4) Same as 12/09/01	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTHS SURVEILLANCE
HOMOGENEOUS ACM RECORDS**

Date of Inspection: 05/14/2002

District: Chico Unified School District

Inspector: Robert Peters

School: Citrus Elementary School

Building: D

Material Class	Material	Homo. Mat. #	% Asb.	FT ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT		1-5%	UNDETERMINED	MPR (GREEN)	(1) (4) (Same as 12/06/01)	N
M	DUCT VENT CONNECTOR		35-40%	UNDETERMINED	MPR - STAGE OFFICE	(1) (4) 12/06/01 (7)	N
T	PIPEWRAP JOINT		ASSUMED	UNDETERMINED	KITCHEN STORAGE	(1) (4) 12/06/01 (7)	N
T	PIPEWRAP		ASSUMED	UNDETERMINED	STAGE FAN ROOMS	(1) (4) 12/06/01 (7)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS