

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: MPR (AKA Building A)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT	1	1-5%	UNDETERMINED	KITCHEN OFFICE, MAIN HALLWAY, MPR, TEACHER'S LOUNGE, & FAN ROOMS	(7) RENOVATION TOOK PLACE IN THE SUMMER OF 2000.	N/A
T	MUDDIED JOINTS	6	1-5%	UNDETERMINED	WATER TANK ROOMS	(7) RENOVATION TOOK PLACE IN THE SUMMER OF 2000.	N/A
S	CEILING PLASTER	8	1-5%	UNDETERMINED	TEACHER'S LOUNGE, MPR, REST OF THE WING, & REFRIGERATOR ROOM	(1) (4) SAME 11-21-03 (7) THE PLASTER WAS REMOVED FROM THE CEILING IN THE REFRIGERATOR ROOM, PART OF THE RENOVATION IN THE SUMMER OF 2000.	N N/A
T	TANK WRAP	16	40-45%	UNDETERMINED	HOT WATER CLOSET	(7)	N/A
M	DRYWALL	104	ASSUMED	UNDETERMINED	THROUGH UNIT	(1) (7) Abated	N

School: Chico Junior High School

Building: B (AKA Hallways)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	HALLWAY & UPPER WALLS	(7) From fire doors south (1) (4) SAME 11-21-03	N/A

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: Rooms 200, 202, 204, 206, & 208 (AKA Wing C)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	ROOM 11 (TITLE ONE OFFICE) & BOYDS RESTROOM	(2) (5) CEILING PLASTER CRACKED & BULGING - HOLE IN PLASTER WALL 11-21-03	N
M	9" VFT BROWN	20	5-10%	UNDETERMINED	ROOMS 200, 202, 206, & 208	(7) REPLACED WITH 12" CREAM VFT.	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 11-21-03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ROOMS 200, 202, 206, & 208	(1) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
M	2 X 4 FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOM WING	(1) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS. CONTAINING)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Letter on File

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: Rooms 300, 302, 304, & 306 (AKA Wing D)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	JANITOR CLOSET (ROOM 310)	(1) (4) Letter on File SAME 11-21-03	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	ROOM 311 (ROOM 11)	(2) (5) HOLES IN CEILING & WALLS	N
M	9" VFT GREY	24	1-5%	UNDETERMINED	ROOMS 300, 302, 304, 306, & 308	(7) REPLACED WITH 12" CREAM VFT DURING THE SUMMER OF 2000. SAME 5/12/03	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 11-21-03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ROOMS 300, 302, 304, 306, & 308	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N
M	2 X 4 FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Letter on File

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: Rooms 500, 502, 504, & 506 (AKA Wing F)

Material Class	Material	Homo. Mat. #	% Asb.	FF/L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE	(1) (4) Letter	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE & GIRLS RESTROOM	(1) (4) Letter on File	N
M	9" VFT LIGHT BROWN	20	5-10 %	UNDETERMINED	ROOMS 500, 502, 504, & 506	(7) 12" VFT WAS PUT IN PLACE AFTER THE REMOVAL OF THE 9" VFT DURING THE SUMMER OF 2000.	N/A
T	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	ROOM 502	(11) Letter on File	N
T	PIPER WRAP STRAIGHT	95	ASSUMED	UNDETERMINED	ROOM 506	(11) Letter on File	N
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) Letter on File	N
M	12" VFT	98	ASSUMED	UNDETERMINED	ROOMS 500, 502, 504, & 506	(1) THE DISTRICT MUST CERTIFY THIS IS A NON-ASBESTOS CONTAINING MATERIAL.	N

School: Chico Junior High School

Building: Maintenance (AKA Wing G)

Material Class	Material	Homo. Mat. #	% Asb.	FF/L.F.	Location	Condition: Code & Comments	Friable Yes / No
T	BOILER REFRACTORY	100	ASSUMED	UNDETERMINED	TWO BOILER UNITS	(1) (4) Same	N
						Letter on File	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: 501 (AKA Unit H-Industrial Arts/Wood Shop),
503 & 505(AKA Unit N-Durst Theatre & Music Room)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT BEIGE	14	1-5%	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC ROOM, & PRACTICE ROOMS 1-5	(7) REMOVED AND REPLACED WITH 12" VFT DURING SUMMER OF 2000.	N/A
M	12" ACT	17	NONE DETECTED	UNDETERMINED	WOOD SHOP, DURST THEATRE, MUSIC ROOM, & PRACTICE ROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988.	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 11-21-03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC ROOM, & PRACTICE ROOMS 1-5	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N
						LETTER ON FILE	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: J (AKA Main Office Building)

Material Class	Material	Homo. Mat. #	% Asb.	FF ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, & LIBRARY	(7) REMOVED AND REPLACED WITH 12" CREAM VFT DURING SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N/A
S	CEILING PLASTER	8	1-5%	UNDETERMINED	LIBRARY	(1) THE PLASTER FROM ALL ROOMS EXCEPT (7) THE LIBRARY HAS BEEN REMOVED.	N N/A
T	PIPE WRAP	10	25-50%	UNDETERMINED	WORK ROOM CLOSET	(7)	N/A
T	PIPE WRAP	11	50-55%	UNDETERMINED	WORK ROOM CLOSET	(7)	N/A
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, & LIBRARY	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N
M	DRYWALL	101	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

LETTER ON FILE

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: K (AKA Rooms 201, 203, 205, 207, 209, & 211)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT	18	1-5%	UNDETERMINED	ROOMS 201, 203, 205, 207, & 209	(7)	N/A
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	102	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

LETTER ON FILE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE

HOMOGENEOUS ACBI MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: L (AKA Rooms 301, 303, 305, 307, 309, & 311)

Material Class	Material	Homo. Mat. #	% Asb.	FF/L.F.	Location	Condition: Code & Comments	Friable Yes / No
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 11-21-03	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition:

Change in Condition:

Abated:

Miscellaneous:

- (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

LETTER ON FILE

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School

Building: M (AKA Rooms 401, 403, 405, 407, & 409)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT TAN	23	5-10%	UNDETERMINED	ROOMS 401, 403, 405, 407, & 409	(7)	N/A
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 11-21-03	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

LETTER ON FILE

School: Chico Junior High School

Building: O (AKA Gymnasium)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT GREEN	5	1-5%	UNDETERMINED	RESTROOMS	(1) (4) Same 11-21-03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 11-21-2003

District: Chico Unified School District

Inspector: Robert Baughman

School: Chico Junior High School Building: P (AKA PE Locker Rooms)

Material Class	Material	Homo. Mat. #	% Asb.	FF/L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT GREEN	5	1-5%	UNDETERMINED	ROOM 18 STORAGE	(12) COULD NOT FIND DURING TIME OF INSPECTION.	N
T	PIPE WRAP	105	ASSUMED	UNDETERMINED	IN CEILING PIPE CHASE	(10) <i>same</i> <i>11-21-03</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: MPR (AKA Building A)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT	1	1-5%	UNDETERMINED	KITCHEN OFFICE, MAIN HALLWAY, MPR, TEACHER'S LOUNGE, & FAN ROOMS	(7) RENOVATION TOOK PLACE IN THE SUMMER OF 2000.	N/A
T	MUDDIED JOINTS	6	1-5%	UNDETERMINED	WATER TANK ROOMS	(7) RENOVATION TOOK PLACE IN THE SUMMER OF 2000.	N/A
S	CEILING PLASTER	8	1-5%	UNDETERMINED	TEACHER'S LOUNGE, MPR, REST OF THE WING, & REFRIGERATOR ROOM	(1) (4) (7) THE PLASTER WAS REMOVED FROM THE CEILING IN THE REFRIGERATOR ROOM, PART OF THE RENOVATION IN THE SUMMER OF 2000.	N N/A
T	TANK WRAP	16	40-45%	UNDETERMINED	HOT WATER CLOSET	(7)	N/A
M	DRYWALL	104	ASSUMED	UNDETERMINED	THROUGH UNIT	(1) (7) Abated	N

School: Chico Junior High School

Building: B (AKA Hallways)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /l.f.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	HALLWAY & UPPER WALLS	(7) From fire doors south (1) (4)	N/A

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: Rooms 200, 202, 204, 206, & 208 (AKA Wing C)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
S	CEILING PLASTER	8	1-5%	UNDETERMINED	ROOM 11 (TITLE ONE OFFICE) & BOY S RESTROOM	(1) (4) MINOR CRACKS IN THE MIDDLE AREA. SAME 5/12/03	N
M	9" VFT BROWN	20	5-10%	UNDETERMINED	ROOMS 200, 202, 206, & 208	(7) REPLACED WITH 12" CREAM VFT.	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ROOMS 200, 202, 206, & 208	(1) THE DISTRICT MUST CERTIFY. SAME 5/12/03	N
M	2 X 4 FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOM WING	(1) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS. CONTAINING)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

Letter on File

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: Rooms 300, 302, 304, & 306 (AKA Wing D)

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	JANITOR S CLOSET (ROOM 310)	(1) (4) Letter on File SAME 5/12/03	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	ROOM 311 (ROOM 11)	(1) (4) SAME 5/12/03	N
M	9" VFT GREY	24	1-5%	UNDETERMINED	ROOMS 300, 302, 304, 306, & 308	(7) REPLACED WITH 12" CREAM VFT DURING THE SUMMER OF 2000. SAME 5/12/03	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ROOMS 300, 302, 304, 306, & 308	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N
M	2 X 4 FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) NEW MATERIAL. THE DISTRICT MUST CERTIFY THIS MATERIAL IS NON-ASBESTOS CONTAINING.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

Letter on File

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: Rooms 500, 502, 504, & 506 (AKA Wing F)

Material Class	Material	Homo. Mat. #	% Asb.	FI ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE	(1) (4) Letter <i>Letter on File</i>	N
S	CEILING PLASTER	8	1-5%	UNDETERMINED	MIGRANT EDUCATION OFFICE S & GIRL S RESTROOM	(1) (4)	N
M	9" VFT LIGHT BROWN	20	5-10 %	UNDETERMINED	ROOMS 500, 502, 504, & 506	(7) 12" VFT WAS PUT IN PLACE AFTER THE REMOVAL OF THE 9" VFT DURING THE SUMMER OF 2000.	N/A
T	PIPE WRAP STRAIGHT	26	40-45%	UNDETERMINED	ROOM 502	(11) <i>Letter on File</i>	N
T	PIPER WRAP STRAIGHT	95	ASSUMED	UNDETERMINED	ROOM 506	(11)	N
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1)	N
M	12" VFT	98	ASSUMED	UNDETERMINED	ROOMS 500, 502, 504, & 506	(1) THE DISTRICT MUST CERTIFY THIS IS A NON-ASBESTOS CONTAINING MATERIAL.	N

School: Chico Junior High School

Building: Maintenance (AKA Wing G)

Material Class	Material	Homo. Mat. #	% Asb.	FI ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
T	BOILER REFRACTORY	100	ASSUMED	UNDETERMINED	TWO BOILER UNITS	(1) (4) Same <i>Letter on File</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: 501 (AKA Unit H-Industrial Arts/Wood Shop),
503 & 505(AKA Unit N-Durst Theatre & Music Room)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT BEIGE	14	1-5%	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC ROOM, & PRACTICE ROOMS 1-5	(7) REMOVED AND REPLACED WITH 12" VFT DURING SUMMER OF 2000. SAME 5/12/03	N/A
M	12" ACT	17	NONE DETECTED	UNDETERMINED	WOOD SHOP, DURST THEATRE, MUSIC ROOM, & PRACTICE ROOMS 1-5	(13) SAMPLE HMS-CJH-17 COLLECTED IN 1988.	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	COMPUTER ROOM, MATERIAL STORAGE, & STAFF OFFICE, DURST THEATRE, OFFICES, MUSIC ROOM, & PRACTICE ROOMS 1-5	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL. SAME 5/12/03	N
						LETTER ON FILE	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: J (AKA Main Office Building)

Material Class	Material	Homo. Mat. #	% Asb.	FI ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT RED	2	1-5%	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, & LIBRARY	(7) REMOVED AND REPLACED WITH 12" CREAM VFT DURING SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING	N/A
S	CEILING PLASTER	8	1-5%	UNDETERMINED	LIBRARY	(1) (7) THE PLASTER FROM ALL ROOMS EXCEPT THE LIBRARY HAS BEEN REMOVED.	N N/A
T	PIPE WRAP	10	25-50%	UNDETERMINED	WORK ROOM CLOSET	(7)	N/A
T	PIPE WRAP	11	50-55%	UNDETERMINED	WORK ROOM CLOSET	(7)	N/A
M	12" VFT CREAM	97	ASSUMED	UNDETERMINED	ADMINISTRATION OFFICES, HALLWAY, & LIBRARY	(1) THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N
M	DRYWALL	101	ASSUMED	UNDETERMINED	THROUGHOUT UNIT	(1) NEW DRYWALL WAS PUT INTO THIS UNIT DURING THE RENOVATION IN THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY THIS MATERIAL AS NON-ASBESTOS CONTAINING MATERIAL.	N

CONDITION CODE

LETTER ON FILE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: K (AKA Rooms 201, 203, 205, 207, 209, & 211)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
M	9" VFT	18	1-5%	UNDETERMINED	ROOMS 201, 203, 205, 207, & 209	(7)	N/A
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	102	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

LETTER ON FILE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: L (AKA Rooms 301, 303, 305, 307, 309, & 311)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /L.F.	Location	Condition: Code & Comments	Friable Yes / No
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1)	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

LETTER ON FILE

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: M (AKA Rooms 401, 403, 405, 407, & 409)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT TAN	23	5-10%	UNDETERMINED	ROOMS 401, 403, 405, 407, & 409	(7)	N/A
T	PIPE WRAP STRAIGHTS	75	ASSUMED	UNDETERMINED	ENCLOSED UNDER CABINETS	(7)	N/A
M	TRANSITE PANELS	96	ASSUMED	UNDETERMINED	EXTERIOR OF UNIT	(1) SAME 5/12/03	N
M	2' X 4' FCP	99	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
M	12" VFT GREY	103	ASSUMED	UNDETERMINED	THROUGHOUT CLASSROOMS	(1) RENOVATED DURING THE SUMMER OF 2000. THE DISTRICT MUST CERTIFY.	N
LETTER ON FILE							

School: Chico Junior High School

Building: O (AKA Gymnasium)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT GREEN	5	1-5%	UNDETERMINED	RESTROOMS	(1) (4) Same 5/12/03	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM MATERIAL RECORDS

Date of Inspection: 5/12/2003

District: Chico Unified School District

Inspector: Robert Peters

School: Chico Junior High School

Building: P (AKA PE Locker Rooms)

Material Class	Material	Homo. Mat. #	% Asb.	Fr ² /L.F.	Location	Condition: Code & Comments	Frable Yes / No
M	9" VFT GREEN	5	1-5%	UNDETERMINED	ROOM 18 STORAGE	(12) COULD NOT FIND DURING TIME OF INSPECTION.	N
T	PIPE WRAP	105	ASSUMED	UNDETERMINED	IN CEILING PIPE CHASE	(10) <i>Same</i>	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
 Change in Condition: (4) No (5) Yes (If Yes, explain under comments) (13) Non-Asbestos/Not Inspected
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS