

CLEANING/REPAIR REPORT - AHERA

40 CFR 763.91(c) (INITIAL CLEANING) Unless the building has been cleaned using equivalent methods within the previous 6 months, all areas of a school building where friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM are present shall be cleaned at least once after the completion of the inspection ... and before the initiation of any response action, other than O & M activities or repair, according to the following procedures:

(i) HEPA-vacuum or steam-clean all carpets. (ii) HEPA-vacuum or wet-clean all other horizontal surfaces. (iii) Dispose of all debris, filters, mopheads, and cloths in sealed, leak-tight containers.

CLEANING

REPAIR

Date of cleaning/repair: 1/10/91

Person performing the cleaning/repair: Mike Fender

Location of cleaning/repair: Rosedale Elementary School kitchen under sink work order #29062

Method of cleaning/repair: remove damaged tile, HEPA vacuum



Signature, Title of Authorizing Person

40 CFR 763.91(c)(2) (ADDITIONAL CLEANING) The accredited management planner shall make a written recommendation to the local education agency whether additional cleaning is needed, and if so, the method and frequency of such cleaning.

Date of cleaning/repair:

Person performing the cleaning/repair:

Location of cleaning/repair:

Method of cleaning/repair:

Signature, Title of Authorizing Person

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1991
 SCHOOL Rosedale Elementary INSPECTOR Robert Peters *R.P.*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Room 2, both RR	(7) Removed
A	Mud Jnts	70-75	Room 3, Boiler Room	(7) Removed
B	Ceill Plas	1-5	Room 9 & 7, Lounge & RR	(7) Removed
B	9" VFT Bg	1-5	Room 1 (5 classrooms)	(7) Removed
C	9" VFT Bg	1-5	Room 1 (5 classrooms)	(7) Removed
D	Ceill Plas	1-5	Unit D all rooms except Kitchen area	(7) Removed
D	9" VFT Gn	5-10	Rm 11,19,15,17,16,18,20	(5)-(7)
D	9" VFT Gn	5-10	Rm 20,19,10,11,12,13	(7) Removed
D	PW Debris	65-70	Rm 19 access to radiator	(7) Removed
D	PW Str 4"	1-5	Rm 17 storage (MP)	(7) Removed
D	PW Cnr	1-5	Rm 17 storage (MP)	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 27, 1991

SCHOOL Rosedale Elementary INSPECTOR Robert Peters

HOMOG. ASBESTOS CONDITION: CODE & COMMENTS
 BLDG. MAT.# MATERIAL LOCATION

E	9" VFT Bg	1-5	Rm 2 A&B, Rms 1 & 3	(7) Removed
G	9" VFT Wh	15-20	Rm 14 and classrooms	(1) - (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE June 26, 1991

SCHOOL Rosedale Elementary INSPECTOR Robert Peters R.P.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	Ceill Plas	1-5	Room 2, both RR	(7) Removed
A	Mud Jnts	70-75	Room 3, Boiler Room	(7) Removed
B	Ceill Plas	1-5	Room 9 & 7, Lounge & RR	(7) Removed
B	9" VFT Bg	1-5	Room 1 (5 classrooms)	(7) Removed
C	9" VFT Bg	1-5	Room 1 (5 classrooms)	(7) Removed
D	Ceill Plas	1-5	Unit D all rooms except Kitchen area	(7) Removed
D	9" VFT Gn	5-10	Rm 11,19,15,17,16,18,20	(5)-(7)
D	9" VFT Gn	5-10	Rm 20,19,10,11,12,13	(7) Removed
D	PW Debris	65-70	Rm 19 access to radiator	(7) Removed
D	PW Str 4"	1-5	Rm 17 storage (MP)	(7) Removed
D	PW Cnr	1-5	Rm 17 storage (MP)	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE June 26, 1991

SCHOOL Rosedale Elementary INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
E	9" VFT Bg	1-5	Rm 2 A&B, Rms 1 & 3	(7) Removed
G	9" VFT Wh	15-20	Rm 14 and classrooms	(1) Good (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)