

MEASURE E SCHOOL SITE SURVEY

BIDWELL JR. HIGH SCHOOL

Staff Recommendations
Upgrade water drainage systems (400 wing)
New gym floor
New gym lighting
New HVAC in gym
Fix fields/flatten
Hot water in bathrooms
HVAC upgrade in all buildings
Update office
Move technology for common core testing
Men's restroom in the 200/300 wing
Less chain link
Move garbage away from gym
Bike racks needed
Lawn maintenance
Beatification of campus
Complete Wi-Fi throughout entire campus including gym
Counseling, main office, health complex remodel
Replace antiquated locks
Smart Boards, computer/iPads
Carpet in library
Lobby-dark, dingy, flooring, color
Main office-take out swinging half door
Improved lighting in hallways=safety
Clear ceiling over main hall
Technology-rolling carts with laptops
Projectors for all classrooms
Remodel bathrooms in entrance (main lobby)
Handryers
Thermostats in classrooms-teachers get sick because in winter they blow cold air

Water fountains
Fix bb gun windows
Fire drill numbers clear
Carpeted classrooms
Bathroom sinks and stalls
Digital Marquee
Display cases
Art room lockers
Art room shelves/countertops
Gutters
Running track paved
Shipping containers
Working irrigation
More sustainable yards and grounds (i.e.: compost grass clippings at all large campuses, upgrade District equipment, mowers with pick-up ability)
Cargo containers on back of campus removed
REUSE what the schools/District already have, repair, recycle broken stuff
Fix staff bathrooms (heat and hot water, plumbing)
Fill holes on access road by 100 wing
Remove bullet holes in Library and other rooms
Sandblast and repaint the fairy wall
Front boy's and girl's bathroom
Fix bell/clock system
Fix tables in lunchrooms
Increase curb appeal (paint, downspouts, cyclone fence by bike rack, new hallway doors)
Finish wrought iron fence
Remove paint/spray paint from windows
Check plumbing in the science room