

MEASURE E SCHOOL SITE SURVEY

CHICO JR. HIGH SCHOOL

Staff Recommendations
Replace/fix/re-roof hallway overhangs
Redo entryways into the boy's and girl's locker rooms
Update the boy's and girl's locker rooms
Update library carpet and create central computer lab in library
Update 505
Fix leaks in Media Center in 505
Fix leaks in gym/new addition
Replace all drinking fountains install bottle refill stations
Update electrical power to accommodate computer labs in all the classrooms (preparation for possible 2014-15 Computerized State Assessment)
New infrastructure in the classrooms to accommodate more computers
Remodel bathrooms in the main hallway
Redo all locks to all the classrooms to allow them to be locked from the inside