

MEASURE E SCHOOL SITE SURVEY

INSPIRE SCHOOL OF ARTS & SCIENCES

Staff Recommendations	Student Government	Parent and Inspire Foundation Board Input
Hot water in the bathrooms	Air conditioning/heater repair	Deferred Maintenance
HVACs need work	Get rid of Inspire Lake (get a drain)	Provide proper drainage
New paint in classrooms	Hot water needed	Repair old ceiling tiles and dry rot
New floors in classrooms	Toilet paper protectors	Repair ramps into the portables
Security Cameras	First row of classrooms should be moved to face Inspire	Refurbish and paint for the older portables
Technology- iPads?	Air dryers for the bathrooms	Provide hot water to the campus
New desks	New desks	Replace doorknobs with ones that lock from inside
Leaky roofs	Picnic tables and benches	Modernization
Dripping awnings over ramps	Food truck for Inspire	Structures to protect students from the elements
Slick/slippery ramps (repair or replace)	Fix the roofs	Adequate lighting at night
"Lake Inspire"	Chipping paint needs to be fixed	Security cameras
Mud on the south side of campus	Pope's room is leaking (PC 16)	Fencing around the perimeter
Practice & storage areas for music room	Henderson's room is leaking (PC 9)	Landscaping
Landscaping	Student store space needed	Solar
Concrete around buildings	Floors need to be fixed	Awnings over windows
Smart Boards in classrooms	Tile replacement	Technology
Update video projectors in classrooms as needed	Marquee for Inspire	Move to electronic textbooks on iPad or tablet
Mac Computers for audio	Filtered water	
Proper windows blinds for Code Red	Hoses	
Materials to help organize & tame unruly computer cords	Better tech support	
New windows	Trees	
New ceiling tiles	More bike racks	
Covered area for kids to congregate	Concrete walkways	
More bike racks that are not in standing water		
Fix HVAC in wrestling/matt room & weight room		
Cover or insulated fans in wrestling/matt/weight room		
Adequate lighting along path from student parking to gym		
Outdoor seating for students at lunch time		