

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT TAN	2	1-5%	980 S	MECHANICS OFFICE & MAINTENANCE OFFICE	(1) (4) SAMPLE HMS COP-02 4/5/1988	N
M	12" VFT BEIGE	4	TRACE	40 S	UPSTAIRS RESTROOM	(1) (4) SAMPLE HMS-COP-04 COLLECTED IN 1988.	N
M	12" VFT BEIGE	6	TRACE	180 S	TRANSPORTATION OFFICE	(1) (4) SAMPLE HMS-COP-06 COLLECTED IN 1988.	N
M	12" ACT	7	NONE DETECTED	680 S	DRIVERS LOUNGE & TRANSPORTATION OFFICE	(13) SAMPLE HMS-COP-07 COLLECTED IN 1988.	N/A
M	9" VFT TAN	62	ASSUMED	500 S	KEY SMITH SHOP	(1) (4)	N
M	DRYWALL	77	NONE DETECTED	5,000 S	ALL ROOMS	(13) SAMPLE HMS-CUSD-CORP-77A COLLECTED ON 5-20-92.	N/A
M	12" VFT WHITE	78	NONE DETECTED	150 S	DRIVERS LOUNGE	(13) HMS COP-08 DATED 4/5/1988	N
M	GLAZING COMPOUND	79	ASSUMED	50 L	GROUND SHED WINDOWS	(2) GLAZING DETERIORATED	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 07/06/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: E - Paint Shop

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	1-5% IN SKIM COAT	2,000 S	PAINT SHOP - ALL AREAS	(1) (4) HMS – 178890 – DATED 5/20/1992	N

Building: D - Poison Storage

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	76	NONE DETECTED	500 S	ALL ROOMS	(13) HMS – 178890 – DATED 5/20/1992	N/A

Building: Bakery

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					BAKERY	LETTER ON FILE FROM R.J. HEUTON CONSTRUCTION – NO ASBESTOS	N/A

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS



Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Chico Unified School Dist
Leroy Christophersen

2455 Carmichael Drive
Chico, CA 95928

Client ID: 2921
Report Number: B090666
Date Received: 10/02/06
Date Analyzed: 10/03/06
Date Printed: 10/04/06
First Reported: 10/04/06

Job ID/Site: Corp Yard - PO# 050289

FASI Job ID: 2921

Date(s) Collected: 09/29/2006

Total Samples Submitted: 1

Total Samples Analyzed: 1

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
CWH01	10564059						
Layer: Yellow Fibrous Material			ND				
Layer: Brown Fibrous Material			ND				
Layer: Silver Foil			ND				

Total Composite Values of Fibrous Components: **Asbestos (ND)**
 Cellulose (10 %) Fibrous Glass (75 %)

James Flores, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by Forensic Analytical to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by Forensic Analytical. The client is solely responsible for the use and interpretation of test results and reports requested from Forensic Analytical. This report must not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government. Forensic Analytical is not able to assess the degree of hazard resulting from materials analyzed. Forensic Analytical reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

2921



Forensic Analytical

Analysis Request Form

Client Name & Address: Chico Unified School District 2455 Carmichael Drive Chico, CA 95928		P.O. #: 050289	Date: 9/29/06
Contact: Leroy Christophersen		Turn Around Time: ___ hr / 12hr / 24hr (48 hr) / ext: _____	Due Date: / / Due Time: : am/pm
Phone #: 530-891-3195	Fax#: (530) 891-3190	<input checked="" type="checkbox"/> PLM: <input checked="" type="checkbox"/> Standard / <input type="checkbox"/> Point Count <input type="checkbox"/> PCM: NIOSH 7400 <input type="checkbox"/> TEM Air: <input type="checkbox"/> AHERA / <input type="checkbox"/> Yamate2 / <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> TEM Bulk: <input type="checkbox"/> Quantitative / <input type="checkbox"/> Qualitative / <input type="checkbox"/> Chatfield <input type="checkbox"/> TEM Water: <input type="checkbox"/> Potable / <input type="checkbox"/> Non-Potable / <input type="checkbox"/> Wt % <input type="checkbox"/> TEM Microvac <input type="checkbox"/> Special Project:	
Site: Corp Yard	Job:	<input type="checkbox"/> Metals Analysis: Method _____ Matrix: _____ Analytes: _____	

Comments: e-mail to lchristo@mail.chico.usd.org

Sample ID	Date/Time	Sample Location/Description	FOR AIR SAMPLES ONLY				Sample Area or Air Volume
			Type	Time On/Off	Avg. LPM	Total Time	
CWH01	9/28	Insulation	A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				
			A P C				

Sampled by: Leroy Christophersen Date: 9/28/06 Time: :
 Shipped via: Fed Ex Airborne UPS US Mail Courier Drop Off Other:

Relinquished by:	Relinquished by:	Relinquished by:
Date / Time:	Date / Time:	Date / Time:
Received by: Strange FK	Received by:	Received by:
Date / Time: 10-02-06 10:30A	Date / Time:	Date / Time:
Condition Acceptable? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No	Condition Acceptable? <input type="checkbox"/> Yes <input type="checkbox"/> No

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT TAN	2	1-5%	980 S	MECHANICS OFFICE & MAINTENANCE OFFICE	(1) (4) SAMPLE HMS COP-02 4/5/1988	N
M	12" VFT BEIGE	4	TRACE	40 S	UPSTAIRS RESTROOM	(1) (4) SAMPLE HMS-COP-04 COLLECTED IN 1988.	N
M	12" VFT BEIGE	6	TRACE	180 S	TRANSPORTATION OFFICE	(1) (4) SAMPLE HMS-COP-06 COLLECTED IN 1988.	N
M	12" ACT	7	NONE DETECTED	680 S	DRIVERS LOUNGE & TRANSPORTATION OFFICE	(13) SAMPLE HMS-COP-07 COLLECTED IN 1988.	N/A
M	9" VFT TAN	62	ASSUMED	500 S	KEY SMITH SHOP	(1) (4)	N
M	DRYWALL	77	NONE DETECTED	5,000 S	ALL ROOMS	(13) SAMPLE HMS-CUSD-CORP-77A COLLECTED ON 5-20-92.	N/A
M	12" VFT WHITE	78	NONE DETECTED	150 S	DRIVERS LOUNGE	(13) HMS COP-08 DATED 4/5/1988	N
M	GLAZING COMPOUND	79	ASSUMED	50 L	GROUND SHED WINDOWS	(2) GLAZING DETERIORATED	N
M	INSULATION		NONE DETECTED		CEILING INSULATION	(13) SAMPLE CWH01 COLLECTION 09/29/06 LETTER ON FILE FOR REPLACEMENT MATERIALS	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/2006

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Corporate Yard

Building: E - Paint Shop

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	1-5% IN SKIM COAT	2,000 S	PAINT SHOP - ALL AREAS	(1) (4) HMS – 178890 – DATED 5/20/1992	N

Building: D - Poison Storage

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	76	NONE DETECTED	500 S	ALL ROOMS	(13) HMS – 178890 – DATED 5/20/1992	N/A

Building: Bakery

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					BAKERY	LETTER ON FILE FROM R.J. HEUTON CONSTRUCTION – NO ASBESTOS	N/A

CONDITION CODE

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS