SIX MONTH SURVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: <u>12/15/2005</u>

District: Chico Unified School District

School: District Office

Inspector: Leroy Christophersen

Building: District Office

Material Class	Material	Homo. Mat. #	% Asb.	Ft²/L.F.	Location	Condition: Code & Comments	Friable Yes/No
т	PIPE WRAP STRAIGHT	7	80-85%	350 L	BASEMENT CRAWL SPACE	(10)	Ν
т	PIPE WRAP JOINT	7	10-15%	350 L	BASEMENT CRAWL SPACE	(10)	Ν
т	PIPE WRAP DEBRIS	7	25-35%	25 S	BASEMENT CRAWL SPACE	(10)	Y

CONDITION CODE

General Condition:	(1) Good	(2) Damaged	(3) Significan	tly Damaged (25	% or more)			
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)								
Abated: (6) Re	paired (7) R	lemoved (8) Ei	ncapsulated	(9) Enclosed	(10) Isolated &	Restricted		
Miscellaneous:	(11) Inaccess	ible, no inspectio	n data (12	2) Other (Explain	under comments)	s) (13) Non-Asbestos/Not Inspected		

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS