

Chico Unified School District  
1163 East Seventh Street  
Chico, CA 95928-5999  
(916) 891-3210

## SHORT-TERM WORKER NOTIFICATION UNDER AHERA

40 CFR PART 763.84(d) Requires that the local education agency shall ensure that short-term workers (e.g. telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

### SECTION I (to be completed by contractor)

Date: 1-24-94

Contractor organization: Thomson Telephone Service

Address: 317 Yolo St, Colusa, CA 95963

Description of work to be performed:

Install new line to Christie Hart's trailer - 15' overhead.

Location(s) of work:

Install phone wire from phone terminal to new trailer  
CHAPMAN

### SECTION II (to be completed by school district)

Type, amount and location of ACBM in work area:

ALL CLEAR.

It is the explicit condition of the performance of this work that no asbestos be disturbed.

Handwritten Signature R.P. Date: 11/21/93  
LEA Designee  
(school district)

\_\_\_\_\_  
(Worker/Contractor Signature) Date:

waiting for OK  
from J Bowers -  
\$ 120 estimate

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 19, 1994

SCHOOL Chapman Elementary INSPECTOR Ron Jones *AJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	TSI	75-80	Room 7	(7) Removed
A	PW St	85-90	Room 5	(7) Removed
A	PW CNR	75-80	Room 7	(7) Removed
A	Transite Pipe	Assumed	Room 7	(7) Removed
A	9" VFT	10-15	Room 5 Brown	(1) Good (4)
A	9" VFT	10-15	Room 4	(1) Good (4)
A	9" VFT	10-15	Restroom 1	(7) Removed
A	12" VFT	1-5	MPR Blue	(7) Removed
A	A/C Plast	1-5	Room 3 MPR	(7) Removed
A	A/C Plast	1-5	Rooms 1,8,2	(7) Removed
A	PW Jnt	1-5	Room 4 Storage	None found

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 19, 1994  
 SCHOOL Chapman Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	5-10	Room 4 Storage	None found
A	PW Str	5-10	Pantry	None found
B	9" VFT	10-15	Room 14 Gray	(7) Removed
B	9" VFT	10-15	Room 13, 15, 16	(7) Removed
B	Transite panel	Assumed	Exterior	(1) Good (4)
C	A/C Plas	1-5	Room 14, 13 Staff Restrooms	(7) Removed
C	9" VFT	10-15	Room 9-12	(7) Removed
D	Mud jnt	65-80	Room 15 Boiler Room	(7) Removed
D	Mud jnt	75-80	Room 15 Boiler Room	(7) Removed
D	PW Str	55-60	Room 15 Boiler Room	(7) Removed
D	PW Str	50-55	Room 15 Boiler Room	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE December 19, 1994

SCHOOL Chapman Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Board B/R	85-90	Room 15 Boiler Room	(7) Removed
D	A/C Plas	1-5	Room 15, 16	(7) Removed
E	9" VFT	10-15	Room 17, 18	(7) Removed
F	9" VFT	1-5	Room 3 (classroom #68)	(1) Good (4)
F	9" VFT	1-5	Room 1 (classroom #5,7)	(1) Good (4)
F	Tran panl	Assumed	Above Doors	(1) Good (4)
G	Mud jnt	1-5	Room 3,4,2,1	(1) Good (4)
G	Tran panl	Assumed	Room 1,2,3,4	(1) Good (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE June 30, 1994

SCHOOL Chapman Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	TSI	75-80	Room 7	(7) Removed
A	PW St	85-90	Room 5	(7) Removed
A	PW CNR	75-80	Room 7	(7) Removed
A	Transite Pipe	Assumed	Room 7	(7) Removed
A	9" VFT	10-15	Room 5 Brown	(1) Good (4)
A	9" VFT	10-15	Room 4	(1) Good (4)
A	9" VFT	10-15	Restroom 1	(7) Removed
A	12" VFT	1-5	MPR Blue	(7) Removed
A	A/C Plast	1-5	Room 3 MPR	(7) Removed
A	A/C Plast	1-5	Rooms 1,8,2	(7) Removed
A	PW Jnt	1-5	Room 4 Storage	None found

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE June 30, 1994

SCHOOL Chapman Elementary INSPECTOR Ron Jones *RJ*

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	5-10	Room 4 Storage	None found
A	PW Str	5-10	Pantry	None found
B	9" VFT	10-15	Room 14 Gray	(7) Removed
B	9" VFT	10-15	Room 13, 15, 16	(7) Removed
B	Transite panel	Assumed	Exterior	(1) Good (4)
C	A/C Plas	1-5	Room 14, 13 Staff Restrooms	(7) Removed
C	9" VFT	10-15	Room 9-12	(7) Removed
D	Mud jnt	65-80	Room 15 Boiler Room	(7) Removed
D	Mud jnt	75-80	Room 15 Boiler Room	(7) Removed
D	PW Str	55-60	Room 15 Boiler Room	(7) Removed
D	PW Str	50-55	Room 15 Boiler Room	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE June 30, 1994

SCHOOL Chapman Elementary INSPECTOR Ron Jones



HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Board B/R	85-90	Room 15 Boiler Room	(7) Removed
D	A/C Plas	1-5	Room 15, 16	(7) Removed
E	9" VFT	10-15	Room 17, 18	(7) Removed
F	9" VFT	1-5	Room 3 (classroom #68)	(1) Good (4)
F	9" VFT	1-5	Room 1 (classroom #5,7)	(1) Good (4)
F	Tran panl	Assumed	Above Doors	(1) Good (4)
G	Mud jnt	1-5	Room 3,4,2,1	(1) Good (4)
G	Tran panl	Assumed	Room 1,2,3,4	(1) Good (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)