

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chapman Elementary INSPECTOR Rob Peters VP

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	TSI	75-80	Room 7	(7)
A	PW St	85-90	Room 5	(7)
A	PW CNR	75-80	Room 7	(7)
A	Transite Pipe	Assumed	Room 7	(7)
A	9" VFT	10-15	Room 5 Brown	(1) (4)
A	9" VFT	10-15	Room 4	(7)
A	9" VFT	10-15	Restroom 1	(7)
A	12" VFT	1-5	MPR Blue	(7)
A	A/C Plast	1-5	Room 3 MPR	(7)
A	A/C Plast	1-5	Rooms 1,8,2	(7)
A	PW Jnt	1-5	Room 4 Storage	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chapman Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	5-10	Room 4 Storage	(7)
A	PW Str	5-10	Pantry	(7)
B	9" VFT	10-15	Room 14 Gray	(7)
B	9" VFT	10-15	Room 13, 15, 16	(7)
B	Tran panl	Assumed	Exterior	(1) (4)
C	A/C Plas	1-5	Room 14, 13 Staff Restrooms	(7)
C	9" VFT	10-15	Room 9-12	(7)
C	Tran panl	Assumed	Exterior	(1) (4)
D	Mud jnt	65-80	Room 15 Boiler Room	(7)
D	Mud jnt	75-80	Room 15 Boiler Room	(7)
D	PW Str	55-60	Room 15 Boiler Room	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 5, 1996

SCHOOL Chapman Elementary INSPECTOR Rob Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Board B/R	85-90	Room 15 Boiler Room	(7)
D	A/C Plas	1-5	Room 15, 16	(7)
D	PW Str	50-55	Room 15 Boiler Room	(7)
E	9" VFT	10-15	Room 17, 18	(7)
F	9" VFT	1-5	Room 3 (classroom #68)	(1) (4)
F	9" VFT	1-5	Room 1 (classroom #5,7)	(1) (4)
F	Tran panl	Assumed	Exteriors	(1) (4)
G	Mud jnt	1-5	Room 3,4,2,1	(1) (4)
G	Tran panl	Assumed	Room 1,2,3,4	(11) Could not find

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 6, 1996  
 SCHOOL Chapman Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

BLDG.	MAT.#	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	TSI	75-80	Room 7	(7)
A	PW St	85-90	Room 5	(7)
A	PW CNR	75-80	Room 7	(7)
A	Transite Pipe	Assumed	Room 7	(7)
A	9" VFT	10-15	Room 5 Brown	(1) (4)
A	9" VFT	10-15	Room 4	(7)
A	9" VFT	10-15	Restroom 1	(7)
A	12" VFT	1-5	MPR Blue	(7)
A	A/C Plast	1-5	Room 3 MPR	(7)
A	A/C Plast	1-5	Rooms 1, 8, 2	(7)
A	PW Jnt	1-5	Room 4 Storage	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 6, 1996

SCHOOL Chapman Elementary INSPECTOR Ron Jones

HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

A	PW Str	5-10	Room 4 Storage	(7)
A	PW Str	5-10	Pantry	(7)
B	9" VFT	10-15	Room 14 Gray	(7)
B	9" VFT	10-15	Room 13, 15, 16	(7)
B	Tran panl	Assumed	Exterior	(1) (4)
C	A/C Plas	1-5	Room 14, 13 Staff Restrooms	(7)
C	9" VFT	10-15	Room 9-12	(7)
C	Tran panl	Assumed	Exterior	(1) (4)
D	Mud jnt	65-80	Room 15 Boiler Room	(7)
D	Mud jnt	75-80	Room 15 Boiler Room	(7)
D	PW Str	55-60	Room 15 Boiler Room	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)


ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 6, 1996

SCHOOL Chapman Elementary INSPECTOR Ron Jones



BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
D	Board B/R	85-90	Room 15 Boiler Room	(7)
D	A/C Plas	1-5	Room 15, 16	(7)
D	PW Str	50-55	Room 15 Boiler Room	(7)
E	9" VFT	10-15	Room 17, 18	(7)
F	9" VFT	1-5	Room 3 (classroom #68)	(1) (4)
F	9" VFT	1-5	Room 1 (classroom #5,7)	(1) (4)
F	Tran panl	Assumed	Exteriors	(1) (4)
G	Mud jnt	1-5	Room 3,4,2,1	(1) (4)
G	Tran panl	Assumed	Room 1,2,3,4	(11) Could not find

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)  
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)  
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED  
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)