

SIX MONTH RVEILLANCE HOMOGENEOUS ACBM RECORDS

Date of Inspection: 6-25-82

District: Chico Unified School District
School: Corporate Yard

Inspector: Don Hunt Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	9" VFT	2	1-5%	980 S	MECHANICS OFFICE & MAINTENANCE OFFICE	(2) 4 DAMAGED UNDER CHAIR AT DESK. NEEDS WAS	N
M	12" VFT BEIGE	4	TRACE	60 S	UPSTAIRS RESTROOM	(1) (4) SAMPLE HMS-COP-04 COLLECTED IN 1988.	N
M	12" VFT YELLOW	6	TRACE	200 S	TRANSPORTATION OFFICE, ROLLING CHAIR WEAR-OUT	(2) SAMPLE HMS-COP-06 COLLECTED IN 1988. NEEDS WAS	N
M	12" ACT	7	NONE DETECTED	680 S	DRIVERS LOUNGE & TRANSPORTATION OFFICE	(13) SAMPLE HMS-COP-07 COLLECTED IN 1988.	N/A
M	12" VFT GREY	8	ASSUMED	260 S	TRANSPORTATION OFFICE	(1) 4	N
S	TEXTURE	9	ASSUMED	200 S	TRANSPORTATION OFFICE	(1) 4	N
M	9" VFT PINK	62	ASSUMED	500 S	KEY SMITH SHOP	(1) (4) 4	N
M	DRYWALL	77	NONE DETECTED	5,000 S	ALL ROOMS	(13) SAMPLE HMS-CUSD-CORP-77A COLLECTED ON 5-20-92.	N/A
M	12" VFT CREAM	78	ASSUMED	100 S	DRIVERS LOUNGE	(1) (4) 4	N
M	GLAZING COMPOUND	79	ASSUMED	50 L	GROUND SHED WINDOWS	(2) NEEDS TO BE RE-GLAZED, OLD GLAZE FALLING OUT 4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: _____

Inspector: Don Hunt

District: Chico Unified School District

School: Corporate Yard

Building: E - Paint Shop

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	75	1-5% IN SKIM COAT	2,000 S	PAINT SHOP - ALL AREAS	(1) (4) 4	N

School: Corporate Yard

Building: D - Poison Storage

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	76	NONE DETECTED	500 S	ALL ROOMS	(13)	N/A

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 6-25-12

District: Chico Unified School District

Inspector: Don Hunt

School: District Office

Building: District Office

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP DEBRIS	7	25-35%	25 S	BASEMENT CRAWL SPACE	(11) COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. SAMPLE HMS-DO-07C COLLECTED ON 4-1-88.	Y
T	PIPE WRAP STRAIGHT	8	80-85%	350 L	BASEMENT CRAWL SPACE	(11) COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. (FORMALLY KNOWN AS HOMO MAT. #7.) SAMPLE HMS-DO-07A COLLECTED ON 4-1-88.	Y
T	PIPE WRAP JOINT	9	10-15%	350 L	BASEMENT CRAWL SPACE	(11) COULD NOT FIND POSSIBLE REMOVED. DID NOT ACCESS. (FORMALLY KNOWN AS HOMO MAT. #7.) SAMPLE HMS-DO-07B COLLECTED ON 4-1-88.	Y

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS