

**SIX MONTH .VEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec. 2011

Inspector: Daniel Hunt

District: Chico Unified School District

School: Nord Elementary School

Building: D - Portable 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
					PORTABLE 4	(12) THIS PORTABLE HAS BEEN CERTIFIED BY THE DISTRICT. ENTEK DOES NOT CURRENTLY HAVE A COPY OF THE CERTIFICATION LETTER ON FILE.	

School: Nord Elementary School

Building: F - Restrooms

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
			Certified Non-Asbestos		PORTABLE Restroom	(13) THIS PORTABLE HAS BEEN CERTIFIED BY THE DISTRICT. Letter on file.	

School: Nord Elementary School

Building: E & G – Portables 6-9

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
			Non-Asbestos		BLDG E PORTABLE CLASSROOMS 6-7 BLDG G PORTABLE CLASSROOMS 8-9	MANUFACTURER LETTER ON FILE	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS CBM RECORDS**

Date of Inspection... Dec - 2011

District: Chico Unified School District

Inspector: David Hunt

School: Nord Elementary School

Building: A - Administration

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	1	NONE DETECTED	2,500 S	OFFICE (900) AND CLASSROOMS 1 & 2	(13) SAMPLE HMS-NES-01 COLLECTED ON 3-29-88.	N/A
M	9" VFT BROWN	2	1-5%	2,400 S	OFFICE (900) AND CLASSROOM 2	(11) COVERED WITH CARPET. 4	N
M	12" VFT TAN	3	NON ASBESTOS	1,200 S	OFFICE (900) AND CLASSROOM 2	(1) (4) MANUFACTURER LETTER ON FILE MODERNIZATION 1989	N
S	WALL PLASTER	4	TRACE	2,950 S	OFFICE (900), BOYS & GIRLS RESTROOMS (903 & 904), AND STORAGE ROOM (902)	(1) (4) 1,4	N
M	2' X 4' FCP	102	ASSUMED	1,500 S	CLASSROOMS 1 & 2	(1) (4) 1,4	N

School: Nord Elementary School

Building: B - Portable 3 (FKA Portables 3 & 4)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	2' X 4' FCP	100	ASSUMED	900 F	PORTABLE 3	(1) (12) THIS PORTABLE WAS BROUGHT FROM FOREST RANCH. (NO I.D.) 1	N
M	12" VFT WHITE	101	ASSUMED	240 S	PORTABLE 3	(1) (4) 1,4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: Dec 2011

District: Chico Unified School District

Inspector: Daniel Hunt

School: Nord Elementary School

Building: C - MPR (FKA B)

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	12" ACT	1	NONE DETECTED	1,300 S	MPR (907)	(13) REPRESENTED BY SAMPLE HMS-NES-01 COLLECTED ON 3-29-01.	N/A
S	WALL PLASTER	9	1-5%	1,000 S	STORAGE ROOM (909) & KITCHEN (908)	(2) (5) DAMAGE ABOVE WINDOW IN STORAGE ROOM 4	N
M	9" VFT DARK GRAY	10	1-5%	1,600 S	MPR (907) & KITCHEN (908)	(1) (4) 1,4	N
M	9" VFT OLIVE WITH PINK SPOTS	11	TRACE	100 S	MPR (EASTERN SIDE) (907)	(1) (4) 1,4	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS