

PROJECT: SP 1-A
 ADDRESS: CHICO JR. HIGH SCHOOL

SIGNATURE: _____
 DATE: 11-15-90

APPLICATION NO. _____

SITE SUMMARY
 GRADES SERVED AT THIS SCHOOL

BLDG	UNIT DESCRIPTION	CONSTRUCTED APPLICATION NO	TOTAL AREA	NON-CHARGEABLE		UNDER 30	OVER 30	SPEC. EDS.	T/S	LAB/S
				LEASE	NON-CONFORM					
A	MULTI-USE	#9336	10,167.83 S.F.				X			
B	ENTRY	9336	5,542.00 S.F.				X			
C	CLASSROOMS	9336	5,300.20 S.F.				X		5	
D	CLASSROOMS	9336	5,300.20 S.F.				X		3	2
E	CLASSROOMS	9336	5,300.20 S.F.				X		5	
F	HOMEMAKING	9336	5,300.20 S.F.				X		1	2
G	BOILER ROOM	9336	1,650.00 S.F.				X			
H	WOOD SHOP	9336	4,924.80 S.F.				X			1
I										
J	ADMIN. & LIBRARY	9337	7,629.19 S.F.				X			
K	CLASSROOMS	13037	5,803.40 S.F.				X	2	4	
L	CLASSROOMS	9337	5,803.40 S.F.				X		6	
M	CLASSROOMS	9337	5,803.40 S.F.				X		5	
N	BAND & CHORAL	9337	4,950.45 S.F.				X			2
O	GYM	9337	10,851.46 S.F.				X			
P	SHOWER & LOCKER	9337	8,234.80 S.F.				X			
							TOTAL	2	29	7
	PORTABLE (BUTTE CO.)		960.00 S.F.	X			X			
	STORAGE BLDG.		800.00 S.F.		X		X			
	TRAILER (BUTTE CO.)		200.00 S.F.	X	X		X			

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters R.P.

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT W	1-5	Kitchen office	(1) Good - (4)
A	9" VFT R	1-5	Kitchen office	(1) Good - (4)
A	9" VFT	1-5	Main Hallway	(1) Good - (4)
A	9" VFT	1-5	MPR (Green)	(1) Good - (4)
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) Good - (4)
A	9" VFT	1-5	Fan rooms (Green)	(1) Good - (4)
A	Mud Jnts	1-5	Water Tank room	(2) Damaged - (4)
A	Ceill Plas	1-5	Teacher's Lounge	(1) Good - (4)
A	Ceill Plas	1-5	MPR	(1) Good - (4)
A	Ceill Plas	1-5	Rest of Wing	(1) Good - (4)
A	Ceill Mat.	1-5	Refrigerator room	(1) Good - (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT. #	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	25-50	South & North Fan Rooms	(1) Good - (4)
A	Mud Jnt	50-55	South & North Fan Rooms	(1) Good - (4)
A	9" VFT	1-5	Teacher's Lounge	(1) Good (5) Carpet Over
A	Tank Wrap	40-45	Hot water closet	Couldn't find any
A	PW Str	Assumed	Stage area	(1) Good - (4)
A	Light cords	Assumed	Stage lighting	(1) Good - (4)
B	Ceill plas	1-5	Hallway & Upper wall	(1) Good - (4)
B	9" VFT R	1-5	Hallway	(1) Good - (4)
B	12" VFT R	1-5	Hallway	(1) Good - (4)
C	9" VFT R	1-5	Janitor's storage	(1) Good - (4)
C	Ceill Plas	1-5	Room 11	(1) Good - (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters

BLDG.	HOMOG.	ASBESTOS	MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
MAT.#					
C	9" VFT Br	5-10		Rms 200, 202, 204, 206, 208	(7) Removed
C	9" VFT Br	5-10		Rm 202	(7) Removed
D	9" VFT R	1-5		Rm 10 - Janitor storage	(1) Good - (4)
D	Ceill Plas	1-5		Rm 11	(1) Good - (4)
D	9" VFT Gr	1-5		Rms 300, 302, 304, 306, 308	(7) Removed
E	9" VFT Rd	1-5		Janitor's Storage	(1) Good - (4)
E	Ceill Plas	1-5		Rm 8	(1) Good - (4)
E	9" VFT	5-10		Rms 400, 402, 404, 406, 408	(7) Removed
F	9" VFT Rd	1-5		Room 1	(7) Removed
F	Ceill Plas	1-5		Room 2	(1) Good - (4)
F	9" VFT Br	5-10		Rms 500, 502, 504, 506	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45	Room 502	(7) Removed
F	9" VFT BR	5-10	Room 504	(7) Removed
F	PW Str	Assumed	Room 506	(7) Removed
G	PW Str	55-70	Boiler Room	(7) Removed
G	8" Str	60-70	Boiler Room	(7) Removed
G	Tank Wrap	60-70	Boiler Room	(7) Removed
G	4" Str	35-40	Boiler Room	(7) Removed
G	4" Str	35-40	Shop Storage	(7) Removed
H	Ceill Plas	1-5	Wood shop offices	(7) Removed
H	9" VFT	1-5	Wood shop office & classrms	(7) Removed
J	9" VFT Rd	1-5	Admin. offices	(1) Good (5) Carpet Over

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
J	9" VFT Rd	1-5	Hallway and Library	(1) Good - (4)
J	Ceill Plas	1-5	All rooms in wing	(1) Good - (4)
J	PW Str	25-50	Work room closet	(1) Good - (4)
J	PW Cnr	50-55	Work room closet	(1) Good - (5) small tear
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) Good - (4)
L	9" VFT Br	5-10	301,303,305,307,309	(1) Good - (4)
M	9" VFT Tn	5-10	401,403,405,407,409	(1) Good - (4)
N	Ceill Plas	1-5	Office area	(7) Removed
N	Ceill Plas	1-5	Storage	(1) Good - (4)
N	9" VFT Bg	1-5	Choral Room	(7) Removed
N	9" VFT Bg	1-5	Offices	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE Dec. 3, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters

BLDG.	HOMOG. MAT. #	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
N	9" VFT Br	5-10	Rm 503, Practice rooms	(7) Removed
N	PW Str	25-50	Under raised floor	(7) Removed
O	9" VFT Gn	1-5	RRs	(1) Good - (4)
O	PW Str	60-70	Inside metal cabinets	(7) Removed
O	PW Crn	60-70	Inside metal cabinets	(7) Removed
P	9" VFT Gn	1-5	Room 18 storage	None found
P	PW Str	50-70	Boiler Room	(7) Removed
P	PW Str 5"	45-50	Boiler Room	(7) Removed
P	PW Str 5"	45-50	Men & Women's locker rooms	(7) Removed
P	Tank Wrap	20-30	Boiler Room	(7) Removed
P	PW Str Cn	Assumed	Crawlspace between locker rooms	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters *R.P.*

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT W	1-5	Kitchen office	(1) Good
A	9" VFT R	1-5	Kitchen office	(1) Good
A	9" VFT	1-5	Main Hallway	(1) Good
A	9" VFT	1-5	MPR (Green)	(1) Good
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) Good
A	9" VFT	1-5	Fan rooms (Green)	(1) Good
A	Mud Jnts	1-5	Water Tank room	(2) Damaged
A	Ceill Plas	1-5	Teacher's Lounge	(1) Good
A	Ceill Plas	1-5	MPR	(1) Good
A	Ceill Plas	1-5	Rest of Wing	(1) Good
A	Ceill Mat.	1-5	Refrigerator room	(1) Good

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters V.S.

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	25-50	South & North Fan Rooms	(1) Good
A	Mud Jnt	50-55	South & North Fan Rooms	(1) Good
A	9" VFT	1-5	Teacher's Lounge	(1) Good (5) Carpet Over
A	Tank Wrap	40-45	Hot water closet	Couldn't find any
A	PW Str	Assumed	Stage area	(1) Good
A	Light cords	Assumed	Stage lighting	(1) Good
B	Ceill plas	1-5	Hallway & Upper wall	(1) Good
B	9" VFT R	1-5	Hallway	(1) Good
B	12" VFT R	1-5	Hallway	(1) Good
C	9" VFT R	1-5	Janitor's storage	(1) Good
C	Ceill Plas	1-5	Room 11	(1) Good

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters R.P.

BLDG. HOMOG. ASBESTOS MATERIAL LOCATION CONDITION: CODE & COMMENTS

C	9" VFT Br	5-10	Rms 200,202,204,206,208	(7) Removed
C	9" VFT Br	5-10	Rm 202	(7) Removed
D	9" VFT R	1-5	Rm 10 - Janitor storage	(1) Good
D	Ceill Plas	1-5	Rm 11	(1) Good
D	9" VFT Gr	1-5	Rms 300,302,304,306,308	(7) Removed
E	9" VFT Rd	1-5	Janitor's Storage	(1) Good
E	Ceill Plas	1-5	Rm 8	(1) Good
E	9" VFT	5-10	Rms 400,402,404,406,408	(7) Removed
F	9" VFT Rd	1-5	Room 1	(7) Removed
F	Ceill Plas	1-5	Room 2	(1) Good
F	9" VFT Br	5-10	Rms 500,502,504,506	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters V.S.

BLDG.	HOMOG. MAT. #	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45	Room 502	(7) Removed
F	9" VFT BR	5-10	Room 504	(7) Removed
F	PW Str	Assumed	Room 506	(7) Removed
G	PW Str	55-70	Boiler Room	(7) Removed
G	8" Str	60-70	Boiler Room	(7) Removed
G	Tank Wrap	60-70	Boiler Room	(7) Removed
G	4" Str	35-40	Boiler Room	(7) Removed
G	4" Str	35-40	Shop Storage	(7) Removed
H	Ceill Plas	1-5	Wood shop offices	(7) Removed
H	9" VFT	1-5	Wood shop office & classrms	(7) Removed
J	9" VFT Rd	1-5	Admin. offices	(1) Good (5) Carpet Over

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
 MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters *R.P.*

BLDG.	HOMOG. MAT. #	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
J	9" VFT Rd	1-5	Hallway and Library	(1) Good
J	Ceill Plas	1-5	All rooms in wing	(1) Good
J	PW Str	25-50	Work room closet	(1) Good
J	PW Cnr	50-55	Work room closet	(1) Good
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) Good
L	9" VFT Br	5-10	301,303,305,307,309	(1) Good
M	9" VFT Tn	5-10	401,403,405,407,409	(1) Good
N	Ceill Plas	1-5	Office area	(7) Removed
N	Ceill Plas	1-5	Storage	(1) Good
N	9" VFT Bg	1-5	Choral Room	(7) Removed
N	9" VFT Bg	1-5	Offices	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE July 6, 1990

SCHOOL Chico Junior High INSPECTOR Robert Peters V.S.

BLDG.	HOMOG.	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
N	9" VFT Br	5-10	Rm 503, Practice rooms	(7) Removed
N	PW Str	25-50	Under raised floor	(7) Removed
O	9" VFT Gn	1-5	RRS	(1) Good
O	PW Str	60-70	Inside metal cabinets	(7) Removed
O	PW Crn	60-70	Inside metal cabinets	(7) Removed
P	9" VFT Gn	1-5	Room 18 storage	None found
P	PW Str	50-70	Boiler Room	(7) Removed
P	PW Str 5"	45-50	Boiler Room	(7) Removed
P	PW Str 5"	45-50	Men & Women's locker rooms	(7) Removed
P	Tank Wrap	20-30	Boiler Room	(7) Removed
P	PW Str Cn	Assumed	Crawlspace between locker rooms	(7) Removed

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

