

DEPARTMENT OF INDUSTRIAL RELATIONS
DIVISION OF OCCUPATIONAL SAFETY AND HEALTH
ASBESTOS CONSULTANT CERTIFICATION UNIT



Park Towne Circle, Suite 1
Sacramento, CA 95825
(916) 574-2993 FAX (916) 483-0572

412301572C 99
Christian Gerber
5021 Cabrillo Way
Sacramento, CA 95820

December 16, 1997

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. To maintain your certification, please abide by the rules printed on the back of the certification card.

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card.

Please hold and do not send copies of your required AHERA refresher renewal certificates to the Division until you apply for renewal of your certification.

Please inform the Division of any changes in your mailing address or work address within 15 days.

Sincerely,

Rick Axe, CIH
Senior Industrial Hygienist

RA/dor

Attachment

cc: File


State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Christian C. Gerber
Name

Certification No. 94-1572

Expires on 1/10/99

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



CAL

ENVIRONMENTAL

SERVICES

INC


This is to certify that

Christian Gerber

has successfully completed the EPA approved A.H.E.R.A. course for
Asbestos Building Inspector - Refresher
as required under TSCA Title II

4/1/98 to 4/1/98
Course Date(s)

4/1/99
Expiration Date



Authorized CAL INC Signature

AC-17753
Certificate Number

CAL INC PO Box 6327 Vacaville, CA 95696 707-446-7996

CERTIFICATE OF COMPLETION

MED-TOX

ASSOCIATES, INC.

OCCUPATIONAL AND ENVIRONMENTAL HEALTH SERVICES

THIS IS TO CERTIFY THAT

CHRIS GERBER

WITH MED-TOX ASSOCIATES, INC.

HAS COMPLETED 30 HOURS OF:

SAMPLING & EVALUATING AIRBORNE ASBESTOS DUST (NIOSH 582 EQUIVALENT)

0582-3

JANUARY 11, 1988

CERTIFICATE NUMBER

DATE

Thomas U. Egenhardt, Jr.
DIRECTOR

DISTRICT Chico Unified School District DATE July 15, 1997

INSPECTOR Ron Jones

SCHOOL Chico Junior High

INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT W	1-5	Kitchen office	(1) (4)
A	9" VFT R	1-5	Kitchen office	(1) (4)
A	9" VFT	1-5	Main Hallway	(7)
A	9" VFT	1-5	MPR (Green)	(1) (4)
A	9" VFT	1-5	Teacher's Lounge (Green)	(1) (4)
A	9" VFT	1-5	Fan rooms (Green)	(1) (4)
A	Mud Jnts	1-5	Water Tank room	(1) (4)
A	Ceill Plas	1-5	Teacher's Lounge	1-4 Roof & Ceiling Repaired
A	Ceill Plas	1-5	MPR	1-4 Roof & Ceiling Repaired
A	Ceill Plas	1-5	Rest of Wing	(1-4 Roof & Ceiling Repaired
A	Ceill Mat.	1-5	Refrigerator room	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 8, 1996 7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	PW Str	25-50	South & North Fan Rooms	(1) (4)
A	Mud Jnt	50-55	South & North Fan Rooms	(1) (4)
A	9" VFT	1-5	Teacher's Lounge	(1) (4)
A	Tank Wrap	40-45	Hot water closet	(11)
A	PW Str	Assumed	Stage area	(7)
A	Light cords	Assumed	Stage lighting	(7)
B	Ceill plas	1-5	Hallway & Upper wall	1-4 Roof & Ceiling <u>Repaired</u>
B	9" VFT R	1-5	Hallway	(7)
B	12" VFT R	1-5	Hallway	(7)
C	9" VFT R	1-5	Chapter One Office	(7)
C	Ceill Plas	1-5	Room 11	(1) (4)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

DISTRICT Chico Unified School District DATE January 8, 1996 7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
C	9" VFT Br	5-10	Rms 200,202,204,206,208	(7)
C	9" VFT Br	5-10	Rm 202	(7)
D	9" VFT R	1-5	Rm 10 - Janitor storage	(1) (4)
D	Ceill Plas	1-5	Rm 11	(1) (4)
D	9" VFT Gr	1-5	Rms 300,302,304,306,308	(7)
E	9" VFT Rd	1-5	Janitor's Storage	(1) (4)
E	Ceill Plas	1-5	Rm 8	(1) (4)
E	9" VFT	5-10	Rms 400,402,404,406,408	(7)
F	9" VFT Rd	1-5	Room 1	(1) (4)
F	Ceill Plas	1-5	Room 2	(1) (4)
F	9" VFT Br	5-10	Rms 500,502,504,506	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

Page 4 of 7

DISTRICT Chico Unified School District DATE January 8, 1996

7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

HOMOG. ASBESTOS
BLDG. MAT.# MATERIAL LOCATION

CONDITION: CODE & COMMENTS

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
F	PW Str	40-45	Room 502	(11)
F	9" VFT BR	5-10	Room 504	(7)
F	PW Str	Assumed	Room 506	(11)
G	PW Str	55-70	Boiler Room	(7)
G	8" Str	60-70	Boiler Room	(7)
G	Tank Wrap	60-70	Boiler Room	(7)
G	4" Str	35-40	Boiler Room	(7)
G	4" Str	35-40	Shop Storage	(7)
H	Ceill Plas	1-5	Wood shop offices	(7)
H	9" VFT	1-5	Wood shop office & classrms	(7)
J	9" VFT Rd	1-5	Admin. offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 8, 1996 7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
J	9" VFT Rd	1-5	Hallway and Library	(7)
J	Ceill Plas	1-5	All rooms in wing	(1) (4)
J	PW Str	25-50	Work room closet	(1) (4)
J	PW Cnr	50-55	Work room closet	(1) (4)
K	9" VFT Gn	1-5	Rms 201,203,205,207,209	(1) (4)
L	9" VFT Br	5-10	301,303,305,307,309	(1) (4)
M	9" VFT Tn	5-10	401,403,405,407,409	(1) (4)
N	Ceill Plas	1-5	Office area	(1) (4)
N	Ceill Plas	1-5	Storage	(1) (4)
N	9" VFT Bg	1-5	Choral Room	(7)
N	9" VFT Bg	1-5	Offices	(7)

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE January 8, 1996 7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
N	9" VFT Br	5-10	Rm 503, Practice rooms	(7)
N	PW Str	25-50	Under raised floor	(7)
O	9" VFT Gn	1-5	RRs	(1) (4)
O	PW Str	60-70	Inside metal cabinets	(7)
O	PW Crn	60-70	Inside metal cabinets	(7)
P	9" VFT Gn	1-5	Room 18 storage	(11)
P	PW Str	50-70	Boiler Room	(7)
P	PW Str 5"	45-50	Boiler Room	(7)
P	PW Str 5"	45-50	Men & Women's locker rooms	(7)
P	Tank Wrap	20-30	Boiler Room	(7)

P	PW Str Cn	Assumed	Crawlspace between locker rooms	(7)
---	-----------	---------	---------------------------------	-----

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED
MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)
 SIX-MONTH SURVEILLANCE Page 7 of 7

DISTRICT Chico Unified School District DATE January 8, 1996 7-14-97

SCHOOL Chico Junior High INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
Main Hall Tunl	PW Str	Assumed	Pipe tunnel from front to back	(7)
P	Pipewrap	Assumed	In Ceiling Pipe Chase	10
K,L,M	Pipewrap	Assumed	Enclosed under Cabinets	10

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)

CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)

ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)