

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/07

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Cohasset Elementary School

Building: A

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
T	PIPE WRAP CORNER	1	10-15%	5 L	ATTIC ABOVE ROOMS 900, 901, 902, 903, AND 904	(11) SAMPLES HMS-COH-01A-C COLLECTED ON 3/29/88.	Y
M	12" VFT	2	5-10%	3,000 S	ROOMS 1, 2, 3, 900, 905, 906, 907, 910, AND LIBRARY	(1) (4) SAMPLE HMS-COH-02 COLLECTED ON 3/29/88. (11) Rm 1 & 2 – Carpet covering VET	N
M	DRYWALL & JOINT COMPOUND	101	ASSUMED	UNDETERMINED	ROOMS 1-3 AND 900-910	(1)	N
M	12" ACT	102	ASSUMED	3,000 S	ROOMS 1-3, 900, 906, 907, AND 910	(1)	N

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**SIX MONTH SURVEILLANCE
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: 12/27/07

District: Chico Unified School District

Inspector: Leroy Christophersen

School: Cohasset Elementary School

Building: B - Portable Classroom 4

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	DRYWALL	98	ASSUMED	1,000 S	PORTABLE CLASSROOM 4	(11) COVERED WITH TAGBOARD.	N
M	2' X 4' FCP	99	ASSUMED	900 S	PORTABLE CLASSROOM 4	(1) (4)	N
M	12" VFT	100	ASSUMED	165 S	PORTABLE CLASSROOM 4	(1) (4)	N
						NOTE: THIS PORTABLE WAS MANUFACTURED IN 1986, WHICH MEANS THAT CERTIFICATION LETTERS CANNOT BE OBTAINED FOR THE BUILDING. ALL MATERIALS WILL BE ASSUMED UNTIL PROPER SAMPLING OF SUSPECT MATERIALS IS CARRIED OUT.	

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)

Change in Condition: (4) No (5) Yes (If Yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS