

SIX-MONTH SURVEILLANCE

DISTRICT Chico Unified School District DATE July 10, 1997

~~January 11, 1996~~

SCHOOL Corporation Yard INSPECTOR Ron Jones

BLDG.	HOMOG. MAT.#	ASBESTOS MATERIAL	LOCATION	CONDITION: CODE & COMMENTS
A	9" VFT	1-5	Mechanics Office	1-4
A	9" VFT	1-5	Maintenance Office	1-4
A	Asbestos curtain	Assumed	Welding Booth	(7)
Paint Shop	Drywall	1-5 skim coat	Paint Shop	1-4

CONDITION CODES

GENERAL CONDITION: (1) GOOD (2) DAMAGED (3) SIGNIFICANTLY DAMAGED (25% OR MORE)
 CHANGE IN CONDITION: (4) NO (5) YES (IF YES, EXPLAIN UNDER COMMENTS)
 ABATED: (6) REPAIRED (7) REMOVED (8) ENCAPSULATED (9) ENCLOSED (10) ISOLATED & RESTRICTED

MISC: (11) INACCESSIBLE, NO SURVEILLANCE DATA (12) OTHER (EXPLAIN UNDER COMMENTS)